

City of Newburyport, Massachusetts
Department of Public Services

Sidewalk & Curb Ramp GIS-based Inventory/Assessment

February 8, 2017

FINAL REPORT



Anthony J. Furnari – Director of Public Services
Wayne S. Amaral – Deputy Director/Director of Operations

Prepared by:



City of Newburyport, Massachusetts
Department of Public Services

***Sidewalk & Curb Ramp
GIS-based Inventory/Assessment***

Table of Contents

Section 1 Project Overview

Sidewalks

- Section 2 City-wide Existing Conditions & Backlog Reports**
- Sidewalk Condition Rankings and Unit Costs by Material Type
 - Sidewalk Backlog and Condition Summary by Material Type
 - Downtown Overlay District (DOD) Backlog and Condition Summary by Material Type
- Section 3 Ward-Based Existing Conditions and Backlog Reports**
- Sidewalk Location and Length Summary
 - Sidewalk Backlog and Condition Summary by Material Type
 - Sidewalk Gap Summary
 - Sidewalk Section Gaps Estimated Costs (Brick and Concrete)
- Section 4 Sidewalk Condition Summary Reports**
- Sidewalk Condition by Material Type (5 Reports)
 - DOD Sidewalk Condition and Estimated Replacement Costs (Brick Only)

Curb Ramps

- Section 5 City-wide Existing Conditions and Backlog Reports**
- Ramp Totals by Street
 - Ramp Totals by Street with Inspection Data
 - Intersections with Sidewalks and No Ramps
 - Ramp Locations with Obstructions
- Section 6 Ramp Inventory Tracking Form**
- Appendix Ramp Inventory Data and Picture**

Section 1 – Project Overview

Introduction

The City of Newburyport retained BETA Group, Inc. (BETA) in July, 2016 to provide GIS services to inventory and evaluate the condition of sidewalks and curb ramps located along City- maintained roadways. This effort was undertaken to expand the City's Asset Management Program (AMP), which consisted of a Pavement Management Program (PMP).

Methodology

BETA's Microsoft Access-based AMP, coupled with the ESRI suite of GIS mapping products (i.e. ArcGIS), was used as the framework for this project. In conjunction with the City's roadway centerline file utilized in the PMP, the City's parcel, building and other available GIS layers served as the framework for field data collection and analysis. Once the database was properly formatted, the sidewalk and curb ramp inventory and inspection portion of the project was initiated. BETA performed field data collection efforts for both sidewalks and curb ramps in August 2016.

The following attribute information was collected for **sidewalks** as part of this inventory:

- *Street Name and Segment*
- *Length of Sidewalk Section (feet)*
- *Average Sidewalk Width (feet)*
- *Sidewalk Condition (New, Good, Fair, Poor, Sidewalk Gap)*
- *Material Type (Asphalt, Brick, Concrete, Mix Materials, Pavers)*
- *Curb Type (Asphalt, Granite, CC Berm, etc.)*
- *Curb Condition (Good, Fair, Poor, Replace)*

A sidewalk network has been digitized in linear format in GIS to represent the location and attributes of each sidewalk segment. Based on existing conditions, each sidewalk segment was placed into a repair category, and estimated costs to repair the segments have been developed, allowing for network maintenance and backlog costs to be calculated.

The following attribute information was collected for **curb ramps** as part of this inventory:

- *Location (Street Name, Street Segment, Intersecting Street)*
- *Material (Concrete, Asphalt, Brick, Other)*
- *Condition (Good, Fair, Poor)*
- *Presence of Detectable Warning Panel (Y/N)*
- *Visible Obstructions (Utility Pole, Sign, Manhole, Hydrant, etc.)*
- *Crosswalk Exists (Y/N)*
- *Photograph of Ramp*

A GIS point feature was generated representing the spatial location and attributes of each curb ramp. Curb ramps along priority routes will be identified and cost estimates will be developed for prioritization and Capital Planning purposes.

Sidewalk and curb ramp conditions were assessed and categorized by the following condition types:

- *New – No physical distresses present (sidewalks only)*
- *Good – Very few minor physical distresses*
- *Fair – Some physical distresses*
- *Poor – Significant distresses present*

Inventory Summary & Data

A total of approximately 62 miles of sidewalk and 798 curb ramps were located and assessed by BETA. All data has been coded to each corresponding City Ward District and presented in the form of Reports and Maps. A total of 1.25 miles of sidewalk gaps were also identified as part of this inventory.

The following sections of this report display both summary and detailed information regarding the data collected as part of this project. Sections 2 thru 4 provide a series of reports related to the sidewalk inventory data while Sections 5 & 6 provides reports regarding the curb ramp findings. Additional curb ramp inspection data and photographs are appended to this report.

Conclusion

By adding the sidewalk and curb ramp modules to the City of Newburyport's AMP, City decision makers are afforded an enhanced picture of existing infrastructure network conditions. The sidewalk and curb modules provide budgetary figures for protecting infrastructure in good condition and a data-driven capital improvement strategy for correcting sidewalk and curb ramp deficiencies. Overall, the AMP should serve as a valuable tool to the City and in their progressive approach to actively managing sidewalk and curb ramp infrastructure.

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Condition Rankings and Unit Costs By - Material Type

Condition	Repair	*Cost New GC	*Cost Adjust GC	*Cost No GC Required
Asphalt Replace With: Concrete				
Gap	Gap	\$125.00	\$0.00	\$0.00
Poor	Rehabilitation	\$125.00	\$105.00	\$75.00
Fair	Surface Treatment	\$125.00	\$105.00	\$75.00
Good	Routine Maintenance	\$30.00	\$30.00	\$30.00
New	Defer Maintenance	\$0.00	\$0.00	\$0.00
Brick Replace With: Brick				
Gap	Gap	\$195.00	\$0.00	\$0.00
Poor	Rehabilitation	\$195.00	\$175.00	\$135.00
Fair	Surface Treatment	\$195.00	\$135.00	\$135.00
Good	Routine Maintenance	\$30.00	\$60.00	\$30.00
New	Defer Maintenance	\$0.00	\$0.00	\$0.00
Concrete Replace With: Concrete				
Gap	Gap	\$125.00	\$0.00	\$0.00
Poor	Rehabilitation	\$125.00	\$105.00	\$75.00
Fair	Surface Treatment	\$125.00	\$105.00	\$75.00
Good	Routine Maintenance	\$30.00	\$30.00	\$30.00
New	Defer Maintenance	\$0.00	\$0.00	\$0.00
Mix Materials Replace With: Concrete				
Gap	Gap	\$125.00	\$0.00	\$0.00
Poor	Rehabilitation	\$125.00	\$105.00	\$75.00
Fair	Surface Treatment	\$125.00	\$105.00	\$75.00
Good	Routine Maintenance	\$30.00	\$30.00	\$30.00
New	Defer Maintenance	\$0.00	\$0.00	\$0.00
Pavers Replace With: Brick				
Gap	Gap	\$195.00	\$0.00	\$0.00
Poor	Rehabilitation	\$195.00	\$175.00	\$135.00
Fair	Surface Treatment	\$195.00	\$135.00	\$135.00
Good	Routine Maintenance	\$30.00	\$60.00	\$30.00
New	Defer Maintenance	\$0.00	\$0.00	\$0.00

* Unit Costs Repairs are for a 5'wide sidewalk by 1' long

* GC = Granite Curb

These costs are based on the, City of Newburyport 2016-2018 Downtown Sidewalk
Rehabilitation Contract awarded to Allied Paving Corp.

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Backlog and Condition Summary By - Material Type

Condition	Repair Type	Length (Miles)	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Asphalt Replace With: Concrete					
Gap	Gap	0.78	\$219,983.65	\$0.00	\$0.00
Poor	Rehabilitation	8.21	\$2,367,092.23	\$1,988,357.48	\$1,420,255.34
Fair	Surface Treatment	12.74	\$3,792,452.60	\$3,185,660.19	\$2,275,471.56
Good	Routine Maintenance	2.84	\$201,655.80	\$201,655.80	\$201,655.80
New	Defer Maintenance	0.94	\$0.00	\$0.00	\$0.00
		25.51	\$6,581,184.29	\$5,375,673.46	\$3,897,382.70
Brick Replace With: Brick					
Gap	Gap	0.09	\$43,559.01	\$0.00	\$0.00
Poor	Rehabilitation	2.23	\$1,247,900.67	\$1,119,910.86	\$863,931.23
Fair	Surface Treatment	4.67	\$2,799,622.11	\$1,938,199.92	\$1,938,199.92
Good	Routine Maintenance	5.53	\$443,928.78	\$887,857.55	\$443,928.78
New	Defer Maintenance	0.86	\$0.00	\$0.00	\$0.00
		13.37	\$4,535,010.57	\$3,945,968.33	\$3,246,059.93
Concrete Replace With: Concrete					
Gap	Gap	0.38	\$100,138.42	\$0.00	\$0.00
Poor	Rehabilitation	2.02	\$608,553.92	\$511,185.29	\$365,132.35
Fair	Surface Treatment	12.20	\$3,641,484.18	\$3,058,846.72	\$2,184,890.51
Good	Routine Maintenance	5.91	\$421,225.72	\$421,225.72	\$421,225.72
New	Defer Maintenance	2.73	\$0.00	\$0.00	\$0.00
		23.23	\$4,771,402.24	\$3,991,257.73	\$2,971,248.58
Mix Materials Replace With: Concrete					
Poor	Rehabilitation	0.48	\$141,274.79	\$118,670.82	\$84,764.87
Fair	Surface Treatment	0.62	\$187,070.49	\$157,139.21	\$112,242.30
Good	Routine Maintenance	0.17	\$12,833.39	\$12,833.39	\$12,833.39
		1.27	\$341,178.67	\$288,643.43	\$209,840.56
Pavers Replace With: Brick					
Fair	Surface Treatment	0.01	\$6,725.36	\$4,656.02	\$4,656.02
Good	Routine Maintenance	0.18	\$11,685.87	\$23,371.74	\$11,685.87
		0.19	\$18,411.22	\$28,027.75	\$16,341.88
Total		63.59	\$16,247,186.99	\$13,629,570.70	\$10,340,873.65

* GC = Granite Curb

City of Newburyport, Massachusetts

Sidewalk Management Program

DOD Sidewalk Backlog and Condition Summary By - Material Type

Condition	Repair Type	Length (Miles)	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Brick	Replace With:	Brick			
Fair	Surface Treatment	1.62	\$1,045,509.44	\$723,814.22	\$723,814.22
Poor	Rehabilitation	0.74	\$369,823.65	\$331,893.02	\$256,031.76
Good	Routine Maintenance	2.54	\$224,765.37	\$449,530.73	\$224,765.37
New	Defer Maintenance	0.33	\$0.00	\$0.00	\$0.00
		5.23	\$1,640,098.45	\$1,505,237.98	\$1,204,611.35
Total		5.23	\$1,640,098.45	\$1,505,237.98	\$1,204,611.35

* GC = Granite Curb

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Location and Length Summary

Sidewalk Location	Length (Miles)
Ward: 1	
Even	4.26
Odd	5.39
Total:	9.65
Ward: 2	
Even	6.51
Odd	6.49
Total:	13.00
Ward: 3	
Even	6.03
Odd	5.66
Total:	11.69
Ward: 4	
Even	8.60
Odd	5.89
Total:	14.48
Ward: 5	
Even	4.04
Odd	3.53
Total:	7.57
Ward: 6	
Even	4.04
Odd	1.91
Total:	5.95
Total:	62.34

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Backlog and Condition Summary By - Material Type

Condition	Repair Type	Length (Miles)	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Ward: 1					
Asphalt	Replace With:	Concrete			
Gap	Gap	0.17	\$41,397.07	\$0.00	\$0.00
Poor	Rehabilitation	1.25	\$376,235.59	\$316,037.89	\$225,741.35
Fair	Surface Treatment	1.33	\$414,417.85	\$348,110.99	\$248,650.71
Good	Routine Maintenance	0.56	\$40,202.36	\$40,202.36	\$40,202.36
New	Defer Maintenance	0.02	\$0.00	\$0.00	\$0.00
		3.33	\$872,252.86	\$704,351.24	\$514,594.42
Brick	Replace With:	Brick			
Gap	Gap	0.02	\$11,361.55	\$0.00	\$0.00
Poor	Rehabilitation	0.01	\$5,438.75	\$4,880.93	\$3,765.29
Fair	Surface Treatment	0.49	\$279,629.27	\$193,589.49	\$193,589.49
Good	Routine Maintenance	0.77	\$56,389.55	\$112,779.10	\$56,389.55
New	Defer Maintenance	0.05	\$0.00	\$0.00	\$0.00
		1.34	\$352,819.12	\$311,249.52	\$253,744.33
Concrete	Replace With:	Concrete			
Gap	Gap	0.12	\$36,665.68	\$0.00	\$0.00
Poor	Rehabilitation	1.07	\$313,165.06	\$263,058.65	\$187,899.03
Fair	Surface Treatment	2.16	\$659,027.54	\$553,583.13	\$395,416.52
Good	Routine Maintenance	0.92	\$65,518.53	\$65,518.53	\$65,518.53
New	Defer Maintenance	0.18	\$0.00	\$0.00	\$0.00
		4.45	\$1,074,376.81	\$882,160.31	\$648,834.09
Mix Materials	Replace With:	Concrete			
Poor	Rehabilitation	0.48	\$141,274.79	\$118,670.82	\$84,764.87
Fair	Surface Treatment	0.29	\$88,759.37	\$74,557.87	\$53,255.62
Good	Routine Maintenance	0.04	\$2,926.22	\$2,926.22	\$2,926.22
		0.82	\$232,960.38	\$196,154.91	\$140,946.71
Pavers	Replace With:	Brick			
Good	Routine Maintenance	0.03	\$2,098.85	\$4,197.70	\$2,098.85
		0.03	\$2,098.85	\$4,197.70	\$2,098.85
		9.97	\$2,534,508.01	\$2,098,113.69	\$1,560,218.40
Ward: 2					
Asphalt	Replace With:	Concrete			
Poor	Rehabilitation	0.45	\$140,221.05	\$117,785.68	\$84,132.63
Fair	Surface Treatment	1.34	\$411,706.66	\$345,833.60	\$247,024.00
Good	Routine Maintenance	0.18	\$12,768.07	\$12,768.07	\$12,768.07
New	Defer Maintenance	0.17	\$0.00	\$0.00	\$0.00
		2.14	\$564,695.78	\$476,387.35	\$343,924.70
Brick	Replace With:	Brick			
Gap	Gap	0.01	\$9,472.82	\$0.00	\$0.00
Poor	Rehabilitation	1.05	\$557,039.25	\$499,907.02	\$385,642.56
Fair	Surface Treatment	2.76	\$1,712,605.70	\$1,185,650.10	\$1,185,650.10
Good	Routine Maintenance	3.68	\$309,092.89	\$618,185.79	\$309,092.89
New	Defer Maintenance	0.53	\$0.00	\$0.00	\$0.00

Condition	Repair Type	Length (Miles)	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
		8.03	\$2,588,210.66	\$2,303,742.91	\$1,880,385.55
Concrete	Replace With:	Concrete			
Gap	Gap	0.02	\$5,995.71	\$0.00	\$0.00
Poor	Rehabilitation	0.16	\$48,408.17	\$40,662.87	\$29,044.90
Fair	Surface Treatment	1.23	\$353,020.26	\$296,537.02	\$211,812.16
Good	Routine Maintenance	0.85	\$61,068.65	\$61,068.65	\$61,068.65
New	Defer Maintenance	0.40	\$0.00	\$0.00	\$0.00
		2.66	\$468,492.79	\$398,268.53	\$301,925.71
Mix Materials	Replace With:	Concrete			
Fair	Surface Treatment	0.14	\$43,959.75	\$36,926.19	\$26,375.85
Good	Routine Maintenance	0.04	\$2,783.25	\$2,783.25	\$2,783.25
		0.18	\$46,742.99	\$39,709.44	\$29,159.10
Pavers	Replace With:	Brick			
Good	Routine Maintenance	0.02	\$1,338.71	\$2,677.42	\$1,338.71
		0.02	\$1,338.71	\$2,677.42	\$1,338.71
		13.03	\$3,669,480.94	\$3,220,785.65	\$2,556,733.77
Ward: 3					
Asphalt	Replace With:	Concrete			
Gap	Gap	0.14	\$40,295.99	\$0.00	\$0.00
Poor	Rehabilitation	1.26	\$412,456.35	\$346,463.33	\$247,473.81
Fair	Surface Treatment	1.72	\$579,833.31	\$487,059.98	\$347,899.99
Good	Routine Maintenance	0.35	\$27,393.37	\$27,393.37	\$27,393.37
New	Defer Maintenance	0.05	\$0.00	\$0.00	\$0.00
		3.52	\$1,059,979.02	\$860,916.68	\$622,767.17
Brick	Replace With:	Brick			
Gap	Gap	0.02	\$7,545.25	\$0.00	\$0.00
Poor	Rehabilitation	0.55	\$318,532.01	\$285,862.06	\$220,522.16
Fair	Surface Treatment	0.99	\$551,890.04	\$382,077.72	\$382,077.72
Good	Routine Maintenance	0.47	\$35,362.47	\$70,724.95	\$35,362.47
New	Defer Maintenance	0.09	\$0.00	\$0.00	\$0.00
		2.11	\$913,329.78	\$738,664.73	\$637,962.36
Concrete	Replace With:	Concrete			
Gap	Gap	0.01	\$1,596.30	\$0.00	\$0.00
Poor	Rehabilitation	0.52	\$168,536.48	\$141,570.65	\$101,121.89
Fair	Surface Treatment	3.71	\$1,154,510.05	\$969,788.44	\$692,706.03
Good	Routine Maintenance	1.01	\$76,807.43	\$76,807.43	\$76,807.43
New	Defer Maintenance	0.72	\$0.00	\$0.00	\$0.00
		5.96	\$1,401,450.27	\$1,188,166.52	\$870,635.35
Mix Materials	Replace With:	Concrete			
Fair	Surface Treatment	0.15	\$42,366.43	\$35,587.80	\$25,419.86
Good	Routine Maintenance	0.04	\$3,158.31	\$3,158.31	\$3,158.31
		0.18	\$45,524.74	\$38,746.11	\$28,578.17
Pavers	Replace With:	Brick			
Fair	Surface Treatment	0.01	\$6,725.36	\$4,656.02	\$4,656.02
Good	Routine Maintenance	0.06	\$4,143.90	\$8,287.81	\$4,143.90
		0.07	\$10,869.26	\$12,943.82	\$8,799.92
		11.85	\$3,431,153.06	\$2,839,437.87	\$2,168,742.96
Ward: 4					
Asphalt	Replace With:	Concrete			

Condition	Repair Type	Length (Miles)	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Gap	Gap	0.12	\$35,381.25	\$0.00	\$0.00
Poor	Rehabilitation	1.97	\$526,252.32	\$442,051.95	\$315,751.39
Fair	Surface Treatment	2.58	\$737,155.35	\$619,210.49	\$442,293.21
Good	Routine Maintenance	0.34	\$22,179.55	\$22,179.55	\$22,179.55
New	Defer Maintenance	0.06	\$0.00	\$0.00	\$0.00
		5.06	\$1,320,968.46	\$1,083,441.98	\$780,224.15
Brick Replace With: Brick					
Gap	Gap	0.03	\$15,179.40	\$0.00	\$0.00
Poor	Rehabilitation	0.62	\$366,890.66	\$329,260.85	\$254,001.22
Fair	Surface Treatment	0.44	\$255,497.10	\$176,882.61	\$176,882.61
Good	Routine Maintenance	0.49	\$35,396.46	\$70,792.92	\$35,396.46
New	Defer Maintenance	0.14	\$0.00	\$0.00	\$0.00
		1.73	\$672,963.61	\$576,936.37	\$466,280.29
Concrete Replace With: Concrete					
Gap	Gap	0.19	\$43,930.54	\$0.00	\$0.00
Poor	Rehabilitation	0.23	\$65,123.48	\$54,703.73	\$39,074.09
Fair	Surface Treatment	4.64	\$1,337,464.03	\$1,123,469.79	\$802,478.42
Good	Routine Maintenance	1.55	\$107,286.83	\$107,286.83	\$107,286.83
New	Defer Maintenance	1.27	\$0.00	\$0.00	\$0.00
		7.88	\$1,553,804.88	\$1,285,460.34	\$948,839.34
Mix Materials Replace With: Concrete					
Fair	Surface Treatment	0.04	\$11,984.95	\$10,067.36	\$7,190.97
Good	Routine Maintenance	0.04	\$2,739.00	\$2,739.00	\$2,739.00
		0.08	\$14,723.95	\$12,806.36	\$9,929.97
Pavers Replace With: Brick					
Good	Routine Maintenance	0.07	\$4,104.41	\$8,208.82	\$4,104.41
		0.07	\$4,104.41	\$8,208.82	\$4,104.41
		14.83	\$3,566,565.32	\$2,966,853.87	\$2,209,378.15
Ward: 5					
Asphalt Replace With: Concrete					
Gap	Gap	0.09	\$27,298.16	\$0.00	\$0.00
Poor	Rehabilitation	2.11	\$588,887.60	\$494,665.59	\$353,332.56
Fair	Surface Treatment	3.45	\$1,010,679.47	\$848,970.76	\$606,407.68
Good	Routine Maintenance	0.98	\$68,876.96	\$68,876.96	\$68,876.96
		6.64	\$1,695,742.19	\$1,412,513.30	\$1,028,617.20
Brick Replace With: Brick					
Good	Routine Maintenance	0.08	\$5,638.54	\$11,277.08	\$5,638.54
New	Defer Maintenance	0.05	\$0.00	\$0.00	\$0.00
		0.13	\$5,638.54	\$11,277.08	\$5,638.54
Concrete Replace With: Concrete					
Gap	Gap	0.04	\$11,950.18	\$0.00	\$0.00
Poor	Rehabilitation	0.05	\$13,320.72	\$11,189.41	\$7,992.43
Fair	Surface Treatment	0.21	\$61,068.99	\$51,297.95	\$36,641.40
Good	Routine Maintenance	0.48	\$34,097.69	\$34,097.69	\$34,097.69
New	Defer Maintenance	0.14	\$0.00	\$0.00	\$0.00
		0.92	\$120,437.59	\$96,585.05	\$78,731.52
Mix Materials Replace With: Concrete					
Good	Routine Maintenance	0.01	\$1,226.61	\$1,226.61	\$1,226.61
		0.01	\$1,226.61	\$1,226.61	\$1,226.61

Condition	Repair Type	Length (Miles)	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
		7.70	\$1,823,044.93	\$1,521,602.04	\$1,114,213.87
Ward: 6					
Asphalt	Replace With:	Concrete			
Gap	Gap	0.26	\$75,611.18	\$0.00	\$0.00
Poor	Rehabilitation	1.17	\$323,039.33	\$271,353.04	\$193,823.60
Fair	Surface Treatment	2.31	\$638,659.96	\$536,474.37	\$383,195.98
Good	Routine Maintenance	0.43	\$30,235.49	\$30,235.49	\$30,235.49
New	Defer Maintenance	0.65	\$0.00	\$0.00	\$0.00
		4.81	\$1,067,545.97	\$838,062.90	\$607,255.07
Brick	Replace With:	Brick			
Good	Routine Maintenance	0.03	\$2,048.86	\$4,097.72	\$2,048.86
		0.03	\$2,048.86	\$4,097.72	\$2,048.86
Concrete	Replace With:	Concrete			
Fair	Surface Treatment	0.26	\$76,393.31	\$64,170.38	\$45,835.99
Good	Routine Maintenance	1.09	\$76,446.59	\$76,446.59	\$76,446.59
New	Defer Maintenance	0.02	\$0.00	\$0.00	\$0.00
		1.36	\$152,839.90	\$140,616.97	\$122,282.58
		6.21	\$1,222,434.73	\$982,777.59	\$731,586.51
Total		63.59	\$16,247,186.99	\$13,629,570.70	\$10,340,873.65

* GC = Granite Curb

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Gap Summary By - Ward

	Street Segment	Location	Length (Miles)
Ward: 1			
BEACON AVENUE	BEACON AVE-04	Even	0.05
GUILD STREET	GUILD ST	Odd	0.06
HARRISON STREET	HARRISON ST	Odd	0.07
REILLY AVENUE	REILLY AVE-01	Even	0.05
SALEM STREET	SALEM ST	Even	0.05
SMITH'S STREET	SMITH'S ST	Even	0.02
UNION STREET	UNION ST-02	Even	0.00
WATER STREET	WATER ST-07	Odd	0.01
			0.32
Ward: 2			
GREENLEAF STREET	GREENLEAF ST-04	Odd	0.01
INDEPENDENT STREET	INDEPENDENT ST-01	Even	0.02
			0.03
Ward: 3			
CARTER STREET	CARTER ST-05	Odd	0.01
JOHNSON STREET	JOHNSON ST	Odd	0.14
RUSSIA STREET	RUSSIA ST-01	Odd	0.02
			0.16
Ward: 4			
BEACON STREET	BEACON ST	Odd	0.02
CHAPEL STREET	CHAPEL ST-01	Even	0.02
COLLINS STREET	COLLINS ST	Odd	0.03
DEXTER STREET	DEXTER ST	Odd	0.03
HOWARD STREET	HOWARD ST-03	Even	0.07
MAGNOLIA STREET	MAGNOLIA ST	Odd	0.06
WILLOW AVENUE	WILLOW AVE	Odd	0.09
ZABRISKIE DRIVE	ZABRISKIE DR-01	Odd	0.03
			0.34
Ward: 5			
BROOKS COURT	BROOKS CT	Odd	0.04
MURPHY AVENUE	MURPHY AVE-01	Even	0.04
NORTH ATKINSON STREET	NORTH ATKINSON ST-04	Even	0.05
			0.13
Ward: 6			
BOURBEAU TERRACE	BOURBEAU TER	Even	0.01
DENNETT DRIVE	DENNETT DR-03	Odd	0.12
EVERETTE DRIVE	EVERETTE DR-01	Even	0.03
PHILLIPS DRIVE	PHILLIPS DR-05	Even	0.07
SULLIVAN DRIVE	SULLIVAN DR	Even	0.02
WINDWARD DRIVE	WINDWARD DR	Even	0.01
			0.26
Total			1.25

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Section Gaps Estimated Costs - (Brick and Concrete)

	Location	GS	GS Width	Curb Type	Repair Type	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Ward: 1										
BEACON AVENUE										
BEACON AVE-04	Even	No	0	Concrete	Concrete	4	252.91	\$14,050.70	\$0.00	\$0.00
						Length:	252.91	\$14,050.70	\$0.00	\$0.00
GUILD STREET										
GUILD ST	Odd	Yes	2	Concrete	Concrete	2	314.89	\$8,746.97	\$0.00	\$0.00
						Length:	314.89	\$8,746.97	\$0.00	\$0.00
HARRISON STREET										
HARRISON ST	Odd	Yes	2	Concrete	Concrete	4	54.07	\$3,003.71	\$0.00	\$0.00
HARRISON ST	Even	No	0	Concrete	Concrete	4	340.63	\$18,923.92	\$0.00	\$0.00
						Length:	394.70	\$21,927.63	\$0.00	\$0.00
REILLY AVENUE										
REILLY AVE-01	Even	Yes	2	None	Concrete	4	282.43	\$15,690.82	\$0.00	\$0.00
						Length:	282.43	\$15,690.82	\$0.00	\$0.00
SALEM STREET										
SALEM ST	Even	No	0	Granite	Concrete	4	265.28	\$14,738.04	\$0.00	\$0.00
						Length:	265.28	\$14,738.04	\$0.00	\$0.00
SMITH'S STREET										
SMITH'S ST	Even	No	0	Granite	Brick	4	131.09	\$11,361.55	\$0.00	\$0.00
						Length:	131.09	\$11,361.55	\$0.00	\$0.00
UNION STREET										
UNION ST-02	Even	No	0	Concrete	Concrete	3	25.60	\$1,066.48	\$0.00	\$0.00
						Length:	25.60	\$1,066.48	\$0.00	\$0.00
WATER STREET										
WATER ST-07	Odd	No	0	Granite	Concrete	4	33.16	\$1,842.10	\$0.00	\$0.00
						Length:	33.16	\$1,842.10	\$0.00	\$0.00
Ward: 2										
GREENLEAF STREET										
GREENLEAF ST-04	Odd	No	0	Granite	Brick	7	62.46	\$9,472.82	\$0.00	\$0.00
						Length:	62.46	\$9,472.82	\$0.00	\$0.00

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Repair Type	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
INDEPENDENT STREET										
INDEPENDENT ST-01	Even	No	0	Concrete	Concrete	4	107.92	\$5,995.71	\$0.00	\$0.00
						Length:	107.92	\$5,995.71	\$0.00	\$0.00
Ward: 3										
CARTER STREET										
CARTER ST-05	Odd	Yes	2	Concrete	Concrete	4	28.73	\$1,596.30	\$0.00	\$0.00
						Length:	28.73	\$1,596.30	\$0.00	\$0.00
JOHNSON STREET										
JOHNSON ST	Odd	No	0	Concrete	Concrete	4	725.33	\$40,295.99	\$0.00	\$0.00
						Length:	725.33	\$40,295.99	\$0.00	\$0.00
RUSSIA STREET										
RUSSIA ST-01	Odd	No	0	Granite	Brick	4	87.06	\$7,545.25	\$0.00	\$0.00
						Length:	87.06	\$7,545.25	\$0.00	\$0.00
Ward: 4										
BEACON STREET										
BEACON ST	Odd	Yes	2	None	Concrete	2	80.91	\$2,247.45	\$0.00	\$0.00
						Length:	80.91	\$2,247.45	\$0.00	\$0.00
CHAPEL STREET										
CHAPEL ST-01	Even	Yes	2	Concrete	Concrete	4	87.08	\$4,837.89	\$0.00	\$0.00
						Length:	87.08	\$4,837.89	\$0.00	\$0.00
COLLINS STREET										
COLLINS ST	Odd	No	0	Granite	Concrete	4	181.19	\$10,066.26	\$0.00	\$0.00
						Length:	181.19	\$10,066.26	\$0.00	\$0.00
DEXTER STREET										
DEXTER ST	Odd	No	0	Mix	Concrete	4	139.00	\$7,722.06	\$0.00	\$0.00
						Length:	139.00	\$7,722.06	\$0.00	\$0.00
HOWARD STREET										
HOWARD ST-02	Odd	Yes	2	Granite	Concrete	4	119.87	\$6,659.21	\$0.00	\$0.00
HOWARD ST-01	Even	No	0	Granite	Concrete	4	60.41	\$3,355.89	\$0.00	\$0.00
HOWARD ST-03	Even	No	0	Granite	Brick	4	175.15	\$15,179.40	\$0.00	\$0.00
						Length:	355.42	\$25,194.49	\$0.00	\$0.00
MAGNOLIA STREET										
MAGNOLIA ST	Odd	Yes	2	None	Concrete	2	325.50	\$9,041.80	\$0.00	\$0.00
						Length:	325.50	\$9,041.80	\$0.00	\$0.00
WILLOW AVENUE										

	Location	GS	GS Width	Curb Type	Repair Type	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
WILLOW AVE	Odd	No	0	Granite	Concrete	4	383.32	\$21,295.64	\$0.00	\$0.00
WILLOW AVE	Even	No	0	Granite	Concrete	4	110.12	\$6,117.66	\$0.00	\$0.00
							Length:	493.44	\$27,413.30	\$0.00
ZABRISKIE DRIVE										
ZABRISKIE DR-01	Odd	No	0	Granite	Concrete	4	143.42	\$7,967.95	\$0.00	\$0.00
							Length:	143.42	\$7,967.95	\$0.00
Ward: 5										
BROOKS COURT										
BROOKS CT	Odd	No	0	Granite	Concrete	4	215.10	\$11,950.18	\$0.00	\$0.00
							Length:	215.10	\$11,950.18	\$0.00
MURPHY AVENUE										
MURPHY AVE-01	Even	No	0	Granite	Concrete	4	235.18	\$13,065.34	\$0.00	\$0.00
							Length:	235.18	\$13,065.34	\$0.00
NORTH ATKINSON STREET										
NORTH ATKINSON ST-04	Odd	No	0	Granite	Concrete	4	90.44	\$5,024.57	\$0.00	\$0.00
NORTH ATKINSON ST-04	Even	No	0	Granite	Concrete	4	165.75	\$9,208.26	\$0.00	\$0.00
							Length:	256.19	\$14,232.83	\$0.00
Ward: 6										
BOURBEAU TERRACE										
BOURBEAU TER	Even	Yes	2	CC Berm	Concrete	4	41.46	\$2,303.32	\$0.00	\$0.00
							Length:	41.46	\$2,303.32	\$0.00
DENNETT DRIVE										
DENNETT DR-03	Odd	Yes	8	None	Concrete	4	625.24	\$34,735.80	\$0.00	\$0.00
							Length:	625.24	\$34,735.80	\$0.00
EVERETTE DRIVE										
EVERETTE DR-01	Even	Yes	2	CC Berm	Concrete	4	155.55	\$8,641.65	\$0.00	\$0.00
							Length:	155.55	\$8,641.65	\$0.00
PHILLIPS DRIVE										
PHILLIPS DR-04	Even	Yes	4	None	Concrete	4	191.77	\$10,654.15	\$0.00	\$0.00
PHILLIPS DR-05	Even	Yes	2	None	Concrete	4	75.98	\$4,221.23	\$0.00	\$0.00
PHILLIPS DR-06	Even	Yes	4	None	Concrete	4	76.22	\$4,234.55	\$0.00	\$0.00
							Length:	343.98	\$19,109.94	\$0.00
SULLIVAN DRIVE										
SULLIVAN DR	Even	Yes	3	None	Concrete	4	48.97	\$2,720.76	\$0.00	\$0.00
SULLIVAN DR	Even	Yes	3	None	Concrete	4	67.95	\$3,774.80	\$0.00	\$0.00
							Length:	116.92	\$6,495.56	\$0.00

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Repair Type	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
WINDWARD DRIVE										
WINDWARD DR	Even	Yes	2	Asphalt	Concrete	4	39.11	\$2,172.51	\$0.00	\$0.00
WINDWARD DR	Even	Yes	2	Asphalt	Concrete	4	38.74	\$2,152.39	\$0.00	\$0.00
						Length:	77.85	\$4,324.90	\$0.00	\$0.00

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Condition and Estimated Replacement Costs - Asphalt (Replace With Concrete)

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Ward: 1											
BEACON AVENUE											
BEACON AVE-03	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	352.27	\$19,570.32	\$16,439.07	\$11,742.19
BEACON AVE-04	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	174.74	\$9,707.88	\$8,154.62	\$5,824.73
BEACON AVE-04	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	120.85	\$6,713.72	\$5,639.52	\$4,028.23
BEACON AVE-05	Odd	No	0	Concrete	Poor	Rehabilitation	4	228.84	\$12,713.33	\$10,679.20	\$7,628.00
BEACON AVE-03	Even	No	0	Concrete	Poor	Rehabilitation	4	332.94	\$18,496.56	\$15,537.11	\$11,097.94
BEACON AVE-04	Even	No	0	Concrete	Gap	Gap	4	252.91	\$14,050.70	\$0.00	\$0.00
BEACON AVE-04	Even	No	0	Concrete	Poor	Rehabilitation	4	129.81	\$7,211.72	\$6,057.85	\$4,327.03
BEACON AVE-05	Even	Yes	2	Concrete	Poor	Rehabilitation	4	125.28	\$6,960.02	\$5,846.42	\$4,176.01
Length:							1,717.64		\$95,424.25	\$68,353.78	\$48,824.13
BROMFIELD STREET											
BROMFIELD ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	82.77	\$4,598.26	\$3,862.54	\$2,758.96
BROMFIELD ST-02	Odd	No	0	Granite	Fair	Surface Treatment	6	199.80	\$16,649.80	\$13,985.83	\$9,989.88
BROMFIELD ST-04	Odd	No	0	Granite	Good	Routine Maintenance	6	64.73	\$1,294.66	\$1,294.66	\$1,294.66
BROMFIELD ST-01	Even	No	0	Granite	Fair	Surface Treatment	5	100.18	\$6,956.61	\$5,843.55	\$4,173.97
BROMFIELD ST-01	Even	Yes	2	Granite	Poor	Rehabilitation	4	63.91	\$3,550.54	\$2,982.46	\$2,130.33
BROMFIELD ST-01	Even	No	0	Granite	Poor	Rehabilitation	4	86.69	\$4,816.02	\$4,045.45	\$2,889.61
BROMFIELD ST-02	Even	No	0	Granite	Poor	Rehabilitation	6	172.92	\$14,409.73	\$12,104.17	\$8,645.84
Length:							770.99		\$52,275.63	\$44,118.67	\$31,883.24
CHARLES STREET											
CHARLES ST	Odd	No	0	Granite	Poor	Rehabilitation	4	363.92	\$20,217.95	\$16,983.08	\$12,130.77
CHARLES ST	Even	No	0	Granite	Poor	Rehabilitation	5	783.35	\$54,399.06	\$45,695.21	\$32,639.43
Length:							1,147.27		\$74,617.00	\$62,678.28	\$44,770.20
CHESTNUT STREET											
CHESTNUT ST-02	Odd	No	0	Asphalt	Fair	Surface Treatment	4	109.82	\$6,101.07	\$5,124.90	\$3,660.64
Length:							109.82		\$6,101.07	\$5,124.90	\$3,660.64
FRANKLIN STREET											
FRANKLIN ST-01	Even	No	0	Granite	Poor	Rehabilitation	4	119.44	\$6,635.61	\$5,573.91	\$3,981.37
FRANKLIN ST-01	Even	No	0	Concrete	Fair	Surface Treatment	4	29.63	\$1,646.26	\$1,382.86	\$987.76
Length:							149.07		\$8,281.87	\$6,956.77	\$4,969.12
GOODWINS AVENUE											
GOODWINS AVE	Even	No	0	Concrete	Poor	Rehabilitation	3	147.42	\$6,142.46	\$5,159.66	\$3,685.47

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
							Length:	147.42	\$6,142.46	\$5,159.66	\$3,685.47
GUILD STREET											
GUILD ST	Odd	Yes	2	Concrete	Fair	Surface Treatment	2	85.54	\$2,376.24	\$1,996.04	\$1,425.74
GUILD ST	Odd	Yes	2	Concrete	Gap	Gap	2	314.89	\$8,746.97	\$0.00	\$0.00
GUILD ST	Even	Yes	2	Concrete	Poor	Rehabilitation	3	367.95	\$15,331.42	\$12,878.39	\$9,198.85
							Length:	768.39	\$26,454.63	\$14,874.44	\$10,624.60
HANCOCK STREET											
HANCOCK ST-03	Odd	Yes	2	Granite	Fair	Surface Treatment	4	56.71	\$3,150.39	\$2,646.33	\$1,890.23
HANCOCK ST-02	Even	Yes	2	Granite	Poor	Rehabilitation	4	50.39	\$2,799.61	\$2,351.67	\$1,679.77
							Length:	107.10	\$5,950.00	\$4,998.00	\$3,570.00
HIGH STREET											
HIGH ST-44	Even	Yes	2	Granite	Fair	Surface Treatment	4	188.76	\$10,486.77	\$8,808.89	\$6,292.06
HIGH ST-45	Even	Yes	2	Granite	Fair	Surface Treatment	4	37.37	\$2,076.29	\$1,744.08	\$1,245.77
							Length:	226.14	\$12,563.06	\$10,552.97	\$7,537.84
LIME STREET											
LIME ST-04	Odd	No	0	Granite	Fair	Surface Treatment	4	118.22	\$6,568.02	\$5,517.14	\$3,940.81
LIME ST-08	Odd	No	0	Granite	Fair	Surface Treatment	4	120.60	\$6,699.76	\$5,627.80	\$4,019.86
LIME ST-08	Odd	No	0	Granite	Good	Routine Maintenance	4	79.05	\$1,053.97	\$1,053.97	\$1,053.97
LIME ST-08	Odd	No	0	Granite	Fair	Surface Treatment	4	65.41	\$3,633.68	\$3,052.29	\$2,180.21
LIME ST-08	Even	No	0	Granite	New	Defer Maintenance	4	89.93	\$0.00	\$0.00	\$0.00
							Length:	473.21	\$17,955.43	\$15,251.20	\$11,194.85
LINCOLN STREET											
LINCOLN ST	Even	No	0	Granite	Poor	Rehabilitation	4	175.64	\$9,757.79	\$8,196.55	\$5,854.68
							Length:	175.64	\$9,757.79	\$8,196.55	\$5,854.68
MADISON STREET											
MADISON ST-01	Odd	No	0	Concrete	Fair	Surface Treatment	4	75.23	\$4,179.22	\$3,510.55	\$2,507.53
MADISON ST-02	Even	No	0	Mix	Fair	Surface Treatment	4	225.77	\$12,542.88	\$10,536.02	\$7,525.73
MADISON ST-02	Even	No	0	Concrete	Poor	Rehabilitation	4	80.30	\$4,461.07	\$3,747.30	\$2,676.64
							Length:	381.30	\$21,183.17	\$17,793.86	\$12,709.90
MARLBORO STREET											
MARLBORO ST-05	Odd	Yes	2	Granite	Fair	Surface Treatment	4	86.65	\$4,813.90	\$4,043.67	\$2,888.34
MARLBORO ST-06	Odd	Yes	2	Granite	Fair	Surface Treatment	4	158.46	\$8,803.07	\$7,394.58	\$5,281.84
MARLBORO ST-07	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	169.18	\$9,399.05	\$7,895.20	\$5,639.43
MARLBORO ST-09	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	89.97	\$1,199.64	\$1,199.64	\$1,199.64
MARLBORO ST-05	Even	Yes	2	Granite	Poor	Rehabilitation	4	116.99	\$6,499.30	\$5,459.41	\$3,899.58
MARLBORO ST-08	Even	Yes	2	Concrete	Fair	Surface Treatment	4	61.62	\$3,423.36	\$2,875.63	\$2,054.02
MARLBORO ST-09	Even	Yes	2	Concrete	Fair	Surface Treatment	4	69.86	\$3,880.94	\$3,259.99	\$2,328.56
							Length:	752.73	\$38,019.26	\$32,128.12	\$23,291.41

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
MERRIMAC STREET											
MERRIMAC ST-32	Even	No	0	Granite	Fair	Surface Treatment	4	74.46	\$4,136.47	\$3,474.63	\$2,481.88
								Length: 74.46	\$4,136.47	\$3,474.63	\$2,481.88
NORTHERN BOULEVARD											
NORTHERN BLVD-03	Odd	No	0	Asphalt	Good	Routine Maintenance	4	328.82	\$4,384.32	\$4,384.32	\$4,384.32
NORTHERN BLVD-04	Odd	No	0	Asphalt	Good	Routine Maintenance	4	592.41	\$7,898.78	\$7,898.78	\$7,898.78
NORTHERN BLVD-04	Odd	No	0	Asphalt	Good	Routine Maintenance	4	120.42	\$1,605.57	\$1,605.57	\$1,605.57
NORTHERN BLVD-06	Odd	No	0	Asphalt	Good	Routine Maintenance	4	117.11	\$1,561.51	\$1,561.51	\$1,561.51
NORTHERN BLVD-07	Odd	No	0	Asphalt	Good	Routine Maintenance	4	129.46	\$1,726.10	\$1,726.10	\$1,726.10
NORTHERN BLVD-09	Odd	No	0	Asphalt	Good	Routine Maintenance	4	135.80	\$1,810.71	\$1,810.71	\$1,810.71
NORTHERN BLVD-11	Odd	No	0	Asphalt	Good	Routine Maintenance	4	76.81	\$1,024.14	\$1,024.14	\$1,024.14
NORTHERN BLVD-12	Odd	No	0	Asphalt	Good	Routine Maintenance	4	49.30	\$657.40	\$657.40	\$657.40
NORTHERN BLVD-12	Odd	No	0	Asphalt	Good	Routine Maintenance	4	82.40	\$1,098.72	\$1,098.72	\$1,098.72
NORTHERN BLVD-13	Odd	No	0	Asphalt	Good	Routine Maintenance	4	124.25	\$1,656.70	\$1,656.70	\$1,656.70
NORTHERN BLVD-14	Odd	No	0	Asphalt	Good	Routine Maintenance	4	169.38	\$2,258.42	\$2,258.42	\$2,258.42
NORTHERN BLVD-16	Odd	No	0	Asphalt	Good	Routine Maintenance	4	140.37	\$1,871.65	\$1,871.65	\$1,871.65
NORTHERN BLVD-18	Odd	No	0	Asphalt	Good	Routine Maintenance	4	91.91	\$1,225.46	\$1,225.46	\$1,225.46
NORTHERN BLVD-19	Odd	No	0	Asphalt	Good	Routine Maintenance	4	40.33	\$537.67	\$537.67	\$537.67
NORTHERN BLVD-20	Odd	No	0	Asphalt	Good	Routine Maintenance	4	154.48	\$2,059.71	\$2,059.71	\$2,059.71
NORTHERN BLVD-22	Odd	No	0	Asphalt	Good	Routine Maintenance	4	126.88	\$1,691.77	\$1,691.77	\$1,691.77
NORTHERN BLVD-24	Odd	No	0	Asphalt	Good	Routine Maintenance	4	103.47	\$1,379.63	\$1,379.63	\$1,379.63
								Length: 2,583.62	\$34,448.26	\$34,448.26	\$34,448.26
OAK STREET											
OAK ST-01	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	197.33	\$10,962.72	\$9,208.69	\$6,577.63
OAK ST-01	Odd	No	0	Concrete	Poor	Rehabilitation	5	158.54	\$11,009.67	\$9,248.12	\$6,605.80
OAK ST-03	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	114.84	\$6,380.15	\$5,359.33	\$3,828.09
OAK ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	63.51	\$3,528.20	\$2,963.69	\$2,116.92
OAK ST-02	Even	Yes	2	Concrete	Poor	Rehabilitation	3	236.11	\$9,837.73	\$8,263.69	\$5,902.64
OAK ST-03	Even	No	0	Concrete	Fair	Surface Treatment	4	198.00	\$11,000.04	\$9,240.04	\$6,600.03
								Length: 968.32	\$52,718.52	\$44,283.56	\$31,631.11
PINE STREET											
PINE ST	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	628.09	\$34,894.09	\$29,311.03	\$20,936.45
PINE ST	Even	No	0	Concrete	Fair	Surface Treatment	4	362.86	\$20,158.82	\$16,933.41	\$12,095.29
								Length: 990.95	\$55,052.91	\$46,244.44	\$33,031.74
PURCHASE STREET											
PURCHASE ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	165.44	\$2,205.83	\$2,205.83	\$2,205.83
PURCHASE ST-05	Odd	No	0	Granite	Fair	Surface Treatment	6	133.09	\$11,090.68	\$9,316.17	\$6,654.41
PURCHASE ST-07	Odd	No	0	Granite	Fair	Surface Treatment	4	264.95	\$14,719.67	\$12,364.52	\$8,831.80
PURCHASE ST-08	Odd	No	0	Granite	Poor	Rehabilitation	4	143.80	\$7,989.11	\$6,710.86	\$4,793.47

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
PURCHASE ST-04	Even	No	0	Granite	Fair	Surface Treatment	5	193.97	\$13,469.80	\$11,314.63	\$8,081.88
PURCHASE ST-05	Even	No	0	Granite	Fair	Surface Treatment	6	231.99	\$19,332.49	\$16,239.29	\$11,599.50
PURCHASE ST-07	Even	No	0	Granite	Fair	Surface Treatment	6	288.10	\$24,007.95	\$20,166.67	\$14,404.77
PURCHASE ST-08	Even	No	0	Granite	Poor	Rehabilitation	4	160.09	\$8,893.64	\$7,470.66	\$5,336.18
							Length:	1,581.42	\$101,709.16	\$85,788.63	\$61,907.83
REILLY AVENUE											
REILLY AVE-01	Even	Yes	2	None	Fair	Surface Treatment	4	309.80	\$17,211.13	\$14,457.35	\$10,326.68
REILLY AVE-01	Even	Yes	2	None	Gap	Gap	4	282.43	\$15,690.82	\$0.00	\$0.00
							Length:	592.24	\$32,901.95	\$14,457.35	\$10,326.68
SHANDEL DRIVE											
SHANDEL DR-01	Odd	No	0	CC Berm	Fair	Surface Treatment	4	776.27	\$43,126.28	\$36,226.08	\$25,875.77
SHANDEL DR-02	Odd	No	0	CC Berm	Poor	Rehabilitation	4	269.54	\$14,974.26	\$12,578.38	\$8,984.56
							Length:	1,045.81	\$58,100.55	\$48,804.46	\$34,860.33
SHIP STREET											
SHIP ST	Even	No	0	Granite	Fair	Surface Treatment	4	60.57	\$3,364.81	\$2,826.44	\$2,018.89
							Length:	60.57	\$3,364.81	\$2,826.44	\$2,018.89
SMITH'S STREET											
SMITH'S ST	Odd	No	0	None	Fair	Surface Treatment	4	58.44	\$3,246.50	\$2,727.06	\$1,947.90
							Length:	58.44	\$3,246.50	\$2,727.06	\$1,947.90
UNION STREET											
UNION ST-02	Odd	No	0	Concrete	Poor	Rehabilitation	4	57.64	\$3,202.38	\$2,690.00	\$1,921.43
UNION ST-02	Odd	No	0	Concrete	Fair	Surface Treatment	5	121.12	\$8,410.86	\$7,065.12	\$5,046.51
UNION ST-01	Even	No	0	Concrete	Poor	Rehabilitation	4	238.93	\$13,274.11	\$11,150.25	\$7,964.47
UNION ST-02	Even	No	0	Concrete	Fair	Surface Treatment	3	256.78	\$10,699.00	\$8,987.16	\$6,419.40
UNION ST-02	Even	No	0	Concrete	Poor	Rehabilitation	4	115.39	\$6,410.40	\$5,384.73	\$3,846.24
UNION ST-02	Even	No	0	Concrete	Gap	Gap	3	25.60	\$1,066.48	\$0.00	\$0.00
							Length:	815.45	\$43,063.23	\$35,277.27	\$25,198.05
WATER STREET											
WATER ST-04	Odd	No	0	Granite	Fair	Surface Treatment	4	57.25	\$3,180.49	\$2,671.61	\$1,908.30
WATER ST-05	Odd	No	0	Mix	Fair	Surface Treatment	4	124.53	\$6,918.31	\$5,811.38	\$4,150.99
WATER ST-07	Odd	No	0	Granite	Fair	Surface Treatment	4	158.20	\$8,788.65	\$7,382.47	\$5,273.19
WATER ST-07	Odd	No	0	Granite	Gap	Gap	4	33.16	\$1,842.10	\$0.00	\$0.00
WATER ST-09	Odd	No	0	Granite	Fair	Surface Treatment	4	343.58	\$19,087.75	\$16,033.71	\$11,452.65
WATER ST-09	Odd	No	0	Granite	Fair	Surface Treatment	4	82.11	\$4,561.94	\$3,832.03	\$2,737.16
WATER ST-10	Odd	No	0	Granite	Poor	Rehabilitation	5	235.09	\$16,325.67	\$13,713.57	\$9,795.40
WATER ST-11	Odd	No	0	Granite	Poor	Rehabilitation	4	151.22	\$8,401.27	\$7,057.06	\$5,040.76
WATER ST-12	Odd	No	0	Granite	Fair	Surface Treatment	4	38.18	\$2,120.93	\$1,781.58	\$1,272.56
WATER ST-04	Even	No	0	Mix	Fair	Surface Treatment	4	142.34	\$7,907.57	\$6,642.36	\$4,744.54
WATER ST-05	Even	No	0	Concrete	Fair	Surface Treatment	4	114.42	\$6,356.59	\$5,339.53	\$3,813.95

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
WATER ST-06	Even	No	0	Granite	Fair	Surface Treatment	4	419.29	\$23,293.63	\$19,566.65	\$13,976.18
								Length: 1,899.36	\$108,784.90	\$89,831.95	\$64,165.68

Ward: 2

ALLEN STREET

ALLEN ST	Odd	No	0	Granite	Fair	Surface Treatment	4	87.02	\$4,834.65	\$4,061.11	\$2,900.79
ALLEN ST	Odd	No	0	Granite	Fair	Surface Treatment	4	279.98	\$15,554.37	\$13,065.67	\$9,332.62
								Length: 367.00	\$20,389.03	\$17,126.78	\$12,233.42

ATWOOD STREET

ATWOOD ST	Odd	No	0	Granite	Fair	Surface Treatment	4	77.05	\$4,280.53	\$3,595.64	\$2,568.32
ATWOOD ST	Odd	No	0	Granite	Fair	Surface Treatment	4	66.56	\$3,697.57	\$3,105.96	\$2,218.54
								Length: 143.61	\$7,978.10	\$6,701.60	\$4,786.86

BRICHER PLACE

BRICHER PL-02	Odd	Yes	2	Concrete	Poor	Rehabilitation	2	56.24	\$1,562.23	\$1,312.27	\$937.34
BRICHER PL-02	Odd	Yes	2	Concrete	Good	Routine Maintenance	3	81.18	\$811.81	\$811.81	\$811.81
								Length: 137.42	\$2,374.04	\$2,124.08	\$1,749.15

BROMFIELD STREET

BROMFIELD ST-04	Even	No	0	Granite	Fair	Surface Treatment	6	254.34	\$21,194.87	\$17,803.69	\$12,716.92
BROMFIELD ST-06	Even	Yes	2	Granite	Fair	Surface Treatment	4	255.36	\$14,186.40	\$11,916.57	\$8,511.84
BROMFIELD ST-07	Even	Yes	2	Granite	Good	Routine Maintenance	4	174.65	\$2,328.65	\$2,328.65	\$2,328.65
								Length: 684.34	\$37,709.92	\$32,048.91	\$23,557.41

COFFIN'S COURT

COFFIN'S CT	Odd	Yes	2	Granite	Poor	Rehabilitation	4	106.54	\$5,918.97	\$4,971.93	\$3,551.38
COFFIN'S CT	Even	No	0	Mix	Fair	Surface Treatment	4	352.27	\$19,570.82	\$16,439.49	\$11,742.49
								Length: 458.82	\$25,489.79	\$21,411.42	\$15,293.87

FEDERAL STREET

FEDERAL ST-02	Odd	No	0	Granite	Fair	Surface Treatment	4	31.58	\$1,754.56	\$1,473.83	\$1,052.74
FEDERAL ST-03	Odd	No	0	Granite	Fair	Surface Treatment	4	115.83	\$6,435.26	\$5,405.62	\$3,861.16
FEDERAL ST-03	Odd	No	0	Granite	Fair	Surface Treatment	4	22.74	\$1,263.22	\$1,061.10	\$757.93
FEDERAL ST-05	Odd	Yes	2	Granite	Fair	Surface Treatment	4	25.54	\$1,419.03	\$1,191.99	\$851.42
FEDERAL ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	72.39	\$4,021.44	\$3,378.01	\$2,412.87
FEDERAL ST-02	Even	No	0	Granite	Poor	Rehabilitation	4	119.19	\$6,621.42	\$5,562.00	\$3,972.85
FEDERAL ST-03	Even	No	0	Granite	Fair	Surface Treatment	6	152.31	\$12,692.81	\$10,661.96	\$7,615.68
FEDERAL ST-04	Even	No	0	Granite	New	Defer Maintenance	4	43.38	\$0.00	\$0.00	\$0.00
FEDERAL ST-08	Even	No	0	Granite	Poor	Rehabilitation	6	64.07	\$5,339.53	\$4,485.21	\$3,203.72
FEDERAL ST-09	Even	No	0	Granite	Fair	Surface Treatment	4	49.34	\$2,740.85	\$2,302.32	\$1,644.51
FEDERAL ST-10	Even	No	0	Granite	New	Defer Maintenance	4	90.15	\$0.00	\$0.00	\$0.00
								Length: 786.52	\$42,288.13	\$35,522.03	\$25,372.88

HIGH STREET

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
HIGH ST-40	Odd	Yes	4	Granite	Fair	Surface Treatment	4	153.66	\$8,536.57	\$7,170.72	\$5,121.94
HIGH ST-40	Odd	Yes	4	Granite	Fair	Surface Treatment	4	292.22	\$16,234.30	\$13,636.81	\$9,740.58
HIGH ST-42	Odd	Yes	2	Granite	Fair	Surface Treatment	4	229.46	\$12,747.70	\$10,708.07	\$7,648.62
HIGH ST-43	Odd	No	0	Granite	Fair	Surface Treatment	6	140.77	\$11,730.61	\$9,853.71	\$7,038.37
HIGH ST-44	Odd	No	0	Granite	Fair	Surface Treatment	6	111.70	\$9,308.09	\$7,818.80	\$5,584.85
HIGH ST-40	Even	No	0	Granite	Poor	Rehabilitation	8	143.60	\$15,955.52	\$13,402.64	\$9,573.31
HIGH ST-43	Even	No	0	Granite	Fair	Surface Treatment	4	100.62	\$5,590.15	\$4,695.72	\$3,354.09
Length:								1,172.02	\$80,102.95	\$67,286.47	\$48,061.77
HILL STREET											
HILL ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	66.98	\$893.02	\$893.02	\$893.02
Length:								66.98	\$893.02	\$893.02	\$893.02
HORTON STREET											
HORTON ST-01	Odd	No	0	Granite	New	Defer Maintenance	4	81.57	\$0.00	\$0.00	\$0.00
HORTON ST-02	Odd	No	0	Granite	Fair	Surface Treatment	4	53.65	\$2,980.79	\$2,503.86	\$1,788.47
Length:								135.22	\$2,980.79	\$2,503.86	\$1,788.47
INDEPENDENT STREET											
INDEPENDENT ST-01	Even	No	0	Concrete	Fair	Surface Treatment	4	50.01	\$2,778.21	\$2,333.70	\$1,666.93
INDEPENDENT ST-01	Even	No	0	Granite	Poor	Rehabilitation	4	81.00	\$4,500.20	\$3,780.17	\$2,700.12
Length:								131.01	\$7,278.42	\$6,113.87	\$4,367.05
LIBERTY STREET											
LIBERTY ST-01	Odd	No	0	Mix	New	Defer Maintenance	4	360.08	\$0.00	\$0.00	\$0.00
LIBERTY ST-02	Odd	No	0	Granite	New	Defer Maintenance	4	61.15	\$0.00	\$0.00	\$0.00
LIBERTY ST-01	Even	No	0	Asphalt	Fair	Surface Treatment	4	352.82	\$19,601.31	\$16,465.10	\$11,760.79
LIBERTY ST-02	Even	No	0	Asphalt	Fair	Surface Treatment	4	138.59	\$7,699.45	\$6,467.54	\$4,619.67
Length:								912.65	\$27,300.77	\$22,932.65	\$16,380.46
LIME STREET											
LIME ST-03	Odd	No	0	Granite	Fair	Surface Treatment	4	160.00	\$8,888.95	\$7,466.72	\$5,333.37
LIME ST-01	Even	No	0	Granite	Fair	Surface Treatment	6	166.36	\$13,863.06	\$11,644.97	\$8,317.84
LIME ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	77.69	\$4,316.30	\$3,625.69	\$2,589.78
LIME ST-03	Even	No	0	Granite	Good	Routine Maintenance	4	37.56	\$500.80	\$500.80	\$500.80
LIME ST-03	Even	No	0	Granite	Fair	Surface Treatment	4	96.08	\$5,337.71	\$4,483.68	\$3,202.63
LIME ST-04	Even	No	0	Granite	Poor	Rehabilitation	4	79.07	\$4,392.68	\$3,689.86	\$2,635.61
LIME ST-06	Even	No	0	Granite	Fair	Surface Treatment	4	151.52	\$8,417.65	\$7,070.83	\$5,050.59
Length:								768.28	\$45,717.16	\$38,482.55	\$27,630.62
MIDDLE STREET											
MIDDLE ST-03	Odd	No	0	Granite	Fair	Surface Treatment	4	81.86	\$4,547.77	\$3,820.13	\$2,728.66
MIDDLE ST-04	Odd	No	0	Granite	Fair	Surface Treatment	4	205.25	\$11,402.95	\$9,578.48	\$6,841.77
MIDDLE ST-04	Odd	No	0	Granite	Fair	Surface Treatment	4	53.06	\$2,947.62	\$2,476.00	\$1,768.57
MIDDLE ST-03	Even	No	0	Granite	Poor	Rehabilitation	4	109.73	\$6,096.03	\$5,120.67	\$3,657.62

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
MIDDLE ST-04	Even	No	0	Granite	Fair	Surface Treatment	4	49.26	\$2,736.64	\$2,298.78	\$1,641.98
							Length:	499.16	\$27,731.01	\$23,294.05	\$16,638.61
MILK STREET											
MILK ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	54.63	\$3,034.74	\$2,549.18	\$1,820.84
MILK ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	116.71	\$6,483.93	\$5,446.50	\$3,890.36
MILK ST-01	Even	No	0	Granite	Fair	Surface Treatment	3	35.70	\$1,487.46	\$1,249.47	\$892.48
MILK ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	82.21	\$4,567.21	\$3,836.46	\$2,740.33
MILK ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	56.39	\$3,132.77	\$2,631.52	\$1,879.66
MILK ST-03	Even	No	0	Granite	Fair	Surface Treatment	4	91.75	\$5,097.08	\$4,281.55	\$3,058.25
							Length:	437.38	\$23,803.19	\$19,994.68	\$14,281.91
ORANGE STREET											
ORANGE ST	Odd	No	0	Granite	Poor	Rehabilitation	5	94.31	\$6,549.43	\$5,501.52	\$3,929.66
ORANGE ST	Even	No	0	Granite	Poor	Rehabilitation	6	190.85	\$15,903.94	\$13,359.31	\$9,542.37
							Length:	285.16	\$22,453.37	\$18,860.83	\$13,472.02
PARSONS STREET											
PARSONS ST	Odd	No	0	Granite	Poor	Rehabilitation	4	61.76	\$3,431.24	\$2,882.24	\$2,058.75
							Length:	61.76	\$3,431.24	\$2,882.24	\$2,058.75
PROSPECT STREET											
PROSPECT ST-03	Odd	No	0	Granite	Good	Routine Maintenance	5	105.59	\$1,759.91	\$1,759.91	\$1,759.91
PROSPECT ST-04	Odd	No	0	Granite	Good	Routine Maintenance	4	222.18	\$2,962.44	\$2,962.44	\$2,962.44
PROSPECT ST-06	Odd	No	0	Granite	Fair	Surface Treatment	4	20.80	\$1,155.60	\$970.71	\$693.36
PROSPECT ST-08	Odd	No	0	Granite	Poor	Rehabilitation	4	75.27	\$4,181.48	\$3,512.44	\$2,508.89
PROSPECT ST-03	Even	No	0	Granite	New	Defer Maintenance	4	214.78	\$0.00	\$0.00	\$0.00
PROSPECT ST-03	Even	No	0	Granite	Fair	Surface Treatment	4	41.88	\$2,326.72	\$1,954.45	\$1,396.03
PROSPECT ST-08	Even	No	0	Granite	Fair	Surface Treatment	4	152.49	\$8,471.71	\$7,116.24	\$5,083.03
							Length:	833.00	\$20,857.87	\$18,276.19	\$14,403.66
SCHOOL STREET											
SCHOOL ST	Even	No	0	Granite	Fair	Surface Treatment	4	49.31	\$2,739.42	\$2,301.11	\$1,643.65
							Length:	49.31	\$2,739.42	\$2,301.11	\$1,643.65
SPRING STREET											
SPRING ST	Odd	No	0	Granite	Fair	Surface Treatment	4	60.97	\$3,387.47	\$2,845.47	\$2,032.48
SPRING ST	Even	No	0	Granite	Fair	Surface Treatment	5	65.07	\$4,518.85	\$3,795.83	\$2,711.31
							Length:	126.05	\$7,906.31	\$6,641.30	\$4,743.79
STATE STREET											
STATE ST-12	Odd	Yes	4	Granite	Poor	Rehabilitation	2	237.12	\$6,586.72	\$5,532.84	\$3,952.03
STATE ST-13	Odd	Yes	4	Granite	Fair	Surface Treatment	3	394.77	\$16,448.82	\$13,817.00	\$9,869.29
STATE ST-13	Odd	Yes	4	Granite	Fair	Surface Treatment	4	141.96	\$7,886.63	\$6,624.77	\$4,731.98
STATE ST-11	Even	Yes	2	Granite	Good	Routine Maintenance	4	132.09	\$1,761.16	\$1,761.16	\$1,761.16

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
STATE ST-11	Even	Yes	2	Granite	Poor	Rehabilitation	4	122.89	\$6,827.01	\$5,734.69	\$4,096.21
STATE ST-13	Even	Yes	2	Granite	Fair	Surface Treatment	4	620.13	\$34,451.70	\$28,939.43	\$20,671.02
STATE ST-13	Even	Yes	2	Granite	Fair	Surface Treatment	4	396.39	\$22,021.74	\$18,498.26	\$13,213.05
STATE ST-13	Even	Yes	3	Concrete	Fair	Surface Treatment	4	120.10	\$6,672.48	\$5,604.88	\$4,003.49
Length:								2,165.45	\$102,656.26	\$86,513.04	\$62,298.22

TEMPLE STREET

TEMPLE ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	53.72	\$716.33	\$716.33	\$716.33
TEMPLE ST-02	Odd	No	0	Granite	Poor	Rehabilitation	4	193.33	\$10,740.38	\$9,021.92	\$6,444.23
TEMPLE ST-02	Odd	No	0	Granite	Poor	Rehabilitation	4	69.16	\$3,842.41	\$3,227.63	\$2,305.45
TEMPLE ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	77.55	\$1,033.96	\$1,033.96	\$1,033.96
TEMPLE ST-02	Odd	No	0	Granite	New	Defer Maintenance	4	37.01	\$0.00	\$0.00	\$0.00
TEMPLE ST-02	Odd	No	0	Granite	Poor	Rehabilitation	4	99.06	\$5,503.46	\$4,622.91	\$3,302.08
TEMPLE ST-02	Odd	No	0	Granite	Poor	Rehabilitation	3	147.77	\$6,157.24	\$5,172.08	\$3,694.35
Length:								677.60	\$27,993.79	\$23,794.83	\$17,496.39

TREMONT STREET

TREMONT ST	Odd	No	0	Granite	Fair	Surface Treatment	4	81.18	\$4,510.09	\$3,788.47	\$2,706.05
Length:								81.18	\$4,510.09	\$3,788.47	\$2,706.05

WATER STREET

WATER ST-16	Odd	No	0	Granite	Poor	Rehabilitation	5	111.86	\$7,767.98	\$6,525.10	\$4,660.79
WATER ST-18	Odd	No	0	Granite	Poor	Rehabilitation	4	48.04	\$2,669.07	\$2,242.02	\$1,601.44
WATER ST-18	Even	No	0	Granite	Poor	Rehabilitation	4	174.13	\$9,674.08	\$8,126.23	\$5,804.45
Length:								334.04	\$20,111.13	\$16,893.35	\$12,066.68

Ward: 3

ATKINSON STREET

ATKINSON ST	Odd	No	0	Granite	Fair	Surface Treatment	4	101.89	\$5,660.68	\$4,754.97	\$3,396.41
ATKINSON ST	Odd	No	0	Granite	Fair	Surface Treatment	4	156.10	\$8,672.32	\$7,284.75	\$5,203.39
ATKINSON ST	Even	No	0	Granite	Poor	Rehabilitation	4	66.78	\$3,709.80	\$3,116.23	\$2,225.88
ATKINSON ST	Even	No	0	Granite	Fair	Surface Treatment	4	92.23	\$5,123.82	\$4,304.01	\$3,074.29
Length:								417.00	\$23,166.63	\$19,459.97	\$13,899.98

AUBURN STREET

AUBURN ST-04	Odd	No	0	Granite	Poor	Rehabilitation	5	65.46	\$4,545.64	\$3,818.33	\$2,727.38
AUBURN ST-01	Even	No	0	Granite	Poor	Rehabilitation	6	80.16	\$6,680.17	\$5,611.35	\$4,008.10
AUBURN ST-02	Even	Yes	4	Granite	Fair	Surface Treatment	4	108.20	\$6,010.85	\$5,049.11	\$3,606.51
AUBURN ST-04	Even	Yes	4	Asphalt	Poor	Rehabilitation	2	408.20	\$11,338.83	\$9,524.62	\$6,803.30
Length:								662.01	\$28,575.49	\$24,003.41	\$17,145.29

BOARDMAN STREET

BOARDMAN ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	277.34	\$15,407.81	\$12,942.56	\$9,244.69
BOARDMAN ST-02	Odd	No	0	Granite	Poor	Rehabilitation	4	128.40	\$7,133.13	\$5,991.83	\$4,279.88

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
BOARDMAN ST-03	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	26.60	\$1,477.56	\$1,241.15	\$886.54
BOARDMAN ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	267.61	\$14,867.02	\$12,488.30	\$8,920.21
BOARDMAN ST-03	Even	Yes	2	Concrete	Fair	Surface Treatment	4	44.80	\$2,488.93	\$2,090.70	\$1,493.36
Length:								744.74	\$41,374.45	\$34,754.53	\$24,824.67
BRICHER PLACE											
BRICHER PL-01	Even	Yes	2	Concrete	Poor	Rehabilitation	2	167.06	\$4,640.63	\$3,898.13	\$2,784.38
Length:								167.06	\$4,640.63	\$3,898.13	\$2,784.38
BROAD STREET											
BROAD ST-01	Odd	Yes	4	Granite	Fair	Surface Treatment	3	178.69	\$7,445.40	\$6,254.14	\$4,467.24
BROAD ST-02	Odd	Yes	4	Granite	Fair	Surface Treatment	4	71.50	\$3,972.11	\$3,336.57	\$2,383.26
Length:								250.19	\$11,417.51	\$9,590.71	\$6,850.51
BUCK STREET											
BUCK ST-01	Odd	No	0	Granite	Poor	Rehabilitation	6	118.12	\$9,843.70	\$8,268.71	\$5,906.22
BUCK ST-01	Odd	No	0	Granite	Poor	Rehabilitation	6	76.04	\$6,336.74	\$5,322.86	\$3,802.05
BUCK ST-02	Odd	No	0	Granite	Fair	Surface Treatment	5	46.24	\$3,210.98	\$2,697.22	\$1,926.59
BUCK ST-02	Odd	Yes	2	Granite	Poor	Rehabilitation	4	53.09	\$2,949.18	\$2,477.31	\$1,769.51
BUCK ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	329.89	\$18,327.09	\$15,394.76	\$10,996.25
Length:								623.38	\$40,667.70	\$34,160.87	\$24,400.62
CAREY AVENUE											
CAREY AVE-01	Odd	No	0	Granite	New	Defer Maintenance	4	77.24	\$0.00	\$0.00	\$0.00
Length:								77.24	\$0.00	\$0.00	\$0.00
CARTER STREET											
CARTER ST-01	Odd	No	0	Granite	Poor	Rehabilitation	4	292.20	\$16,233.17	\$13,635.86	\$9,739.90
CARTER ST-02	Odd	No	0	Mix	Fair	Surface Treatment	4	109.49	\$6,082.79	\$5,109.54	\$3,649.67
CARTER ST-03	Even	Yes	2	Granite	Poor	Rehabilitation	4	139.11	\$7,728.49	\$6,491.93	\$4,637.09
Length:								540.80	\$30,044.44	\$25,237.33	\$18,026.67
CONGRESS STREET											
CONGRESS ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	27.58	\$367.80	\$367.80	\$367.80
Length:								27.58	\$367.80	\$367.80	\$367.80
EAGLE STREET											
EAGLE ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	74.24	\$4,124.35	\$3,464.45	\$2,474.61
EAGLE ST-02	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	102.79	\$1,370.55	\$1,370.55	\$1,370.55
EAGLE ST-01	Even	No	0	Concrete	Good	Routine Maintenance	4	72.95	\$972.65	\$972.65	\$972.65
Length:								249.98	\$6,467.54	\$5,807.65	\$4,817.80
HIGH STREET											
HIGH ST-19	Odd	No	0	Granite	Fair	Surface Treatment	6	69.73	\$5,810.52	\$4,880.83	\$3,486.31
HIGH ST-20	Odd	No	0	Granite	Fair	Surface Treatment	5	142.53	\$9,897.68	\$8,314.05	\$5,938.61
HIGH ST-20	Odd	Yes	2	Granite	Fair	Surface Treatment	4	220.61	\$12,255.96	\$10,295.00	\$7,353.57

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
HIGH ST-21	Odd	Yes	2	Granite	Fair	Surface Treatment	4	159.80	\$8,877.56	\$7,457.15	\$5,326.54
HIGH ST-21	Odd	Yes	2	Granite	Fair	Surface Treatment	4	49.12	\$2,729.00	\$2,292.36	\$1,637.40
HIGH ST-25	Odd	Yes	2	Granite	Fair	Surface Treatment	4	59.30	\$3,294.53	\$2,767.40	\$1,976.72
HIGH ST-25	Odd	No	0	Granite	Fair	Surface Treatment	8	161.71	\$17,968.24	\$15,093.32	\$10,780.94
HIGH ST-29	Odd	No	0	Granite	Fair	Surface Treatment	8	216.13	\$24,014.66	\$20,172.31	\$14,408.79
HIGH ST-19	Even	No	0	Granite	Fair	Surface Treatment	6	73.28	\$6,106.27	\$5,129.27	\$3,663.76
HIGH ST-20	Even	Yes	2	Granite	Fair	Surface Treatment	4	119.40	\$6,633.21	\$5,571.90	\$3,979.93
HIGH ST-21	Even	Yes	2	Granite	Fair	Surface Treatment	4	239.54	\$13,307.55	\$11,178.34	\$7,984.53
HIGH ST-22	Even	No	0	Granite	Fair	Surface Treatment	4	88.67	\$4,926.37	\$4,138.15	\$2,955.82
HIGH ST-23	Even	Yes	2	Granite	Fair	Surface Treatment	4	84.76	\$4,708.98	\$3,955.54	\$2,825.39
HIGH ST-32	Even	No	0	Granite	Fair	Surface Treatment	6	277.74	\$23,144.92	\$19,441.73	\$13,886.95
Length:								1,962.31	\$143,675.43	\$120,687.36	\$86,205.26
HILL STREET											
HILL ST-04	Odd	Yes	4	Concrete	Poor	Rehabilitation	4	56.42	\$3,134.30	\$2,632.81	\$1,880.58
HILL ST-04	Even	Yes	2	Concrete	Poor	Rehabilitation	3	143.62	\$5,984.12	\$5,026.66	\$3,590.47
Length:								200.04	\$9,118.42	\$7,659.47	\$5,471.05
JOHNSON STREET											
JOHNSON ST	Odd	No	0	Concrete	Fair	Surface Treatment	4	114.17	\$6,342.61	\$5,327.80	\$3,805.57
JOHNSON ST	Odd	No	0	Concrete	Poor	Rehabilitation	4	755.68	\$41,982.37	\$35,265.19	\$25,189.42
JOHNSON ST	Odd	No	0	Concrete	Gap	Gap	4	725.33	\$40,295.99	\$0.00	\$0.00
JOHNSON ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	67.11	\$3,728.43	\$3,131.88	\$2,237.06
JOHNSON ST	Even	No	0	Concrete	Fair	Surface Treatment	4	310.07	\$17,226.11	\$14,469.93	\$10,335.66
JOHNSON ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	55.56	\$3,086.46	\$2,592.63	\$1,851.88
Length:								2,027.92	\$112,661.98	\$60,787.43	\$43,419.59
KENT STREET											
KENT ST-01	Odd	Yes	2	Granite	Good	Routine Maintenance	4	218.03	\$2,907.01	\$2,907.01	\$2,907.01
KENT ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	276.76	\$3,690.16	\$3,690.16	\$3,690.16
KENT ST-05	Odd	No	0	Granite	Poor	Rehabilitation	6	94.30	\$7,858.75	\$6,601.35	\$4,715.25
KENT ST-06	Odd	No	0	Granite	Fair	Surface Treatment	6	99.34	\$8,278.73	\$6,954.14	\$4,967.24
KENT ST-07	Odd	No	0	Granite	Good	Routine Maintenance	4	137.35	\$1,831.28	\$1,831.28	\$1,831.28
KENT ST-07	Odd	No	0	Granite	Fair	Surface Treatment	5	49.19	\$3,415.77	\$2,869.24	\$2,049.46
KENT ST-01	Even	No	0	Granite	Good	Routine Maintenance	6	90.92	\$1,818.49	\$1,818.49	\$1,818.49
KENT ST-02	Even	No	0	Granite	Good	Routine Maintenance	6	60.02	\$1,200.30	\$1,200.30	\$1,200.30
KENT ST-05	Even	No	0	Granite	Fair	Surface Treatment	5	39.97	\$2,775.78	\$2,331.65	\$1,665.47
KENT ST-05	Even	No	0	Granite	Good	Routine Maintenance	5	90.14	\$1,502.30	\$1,502.30	\$1,502.30
KENT ST-06	Even	Yes	2	Granite	Good	Routine Maintenance	4	56.69	\$755.81	\$755.81	\$755.81
KENT ST-07	Even	Yes	2	Granite	Good	Routine Maintenance	4	340.04	\$4,533.92	\$4,533.92	\$4,533.92
Length:								1,552.75	\$40,568.28	\$36,995.64	\$31,636.67
LOW STREET											
LOW ST-11	Even	No	0	Granite	Fair	Surface Treatment	4	169.97	\$9,442.61	\$7,931.79	\$5,665.57

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
LOW ST-11	Even	No	0	Granite	Fair	Surface Treatment	6	354.23	\$29,519.05	\$24,796.00	\$17,711.43
LOW ST-11	Even	No	0	Granite	Poor	Rehabilitation	4	285.59	\$15,866.08	\$13,327.51	\$9,519.65
LOW ST-11	Even	No	0	Granite	Poor	Rehabilitation	6	494.50	\$41,208.39	\$34,615.05	\$24,725.03
LOW ST-12	Even	No	0	Granite	Fair	Surface Treatment	4	917.79	\$50,988.39	\$42,830.24	\$30,593.03
LOW ST-13	Even	No	0	Granite	Fair	Surface Treatment	4	771.14	\$42,841.19	\$35,986.60	\$25,704.71
							Length:	2,993.22	\$189,865.70	\$159,487.19	\$113,919.42
MARKET STREET											
MARKET ST-04	Odd	No	0	Granite	Poor	Rehabilitation	6	304.34	\$25,361.43	\$21,303.60	\$15,216.86
MARKET ST-01	Even	No	0	Granite	Poor	Rehabilitation	6	82.96	\$6,913.71	\$5,807.51	\$4,148.22
MARKET ST-02	Even	No	0	Granite	Poor	Rehabilitation	6	234.61	\$19,550.59	\$16,422.50	\$11,730.36
MARKET ST-03	Even	No	0	Granite	Fair	Surface Treatment	6	142.61	\$11,884.13	\$9,982.67	\$7,130.48
MARKET ST-04	Even	No	0	Granite	Poor	Rehabilitation	6	39.90	\$3,324.74	\$2,792.79	\$1,994.85
							Length:	804.42	\$67,034.60	\$56,309.07	\$40,220.76
MERRIMAC STREET											
MERRIMAC ST-20	Odd	No	0	Granite	Poor	Rehabilitation	5	194.17	\$13,484.19	\$11,326.72	\$8,090.51
MERRIMAC ST-21	Odd	No	0	Granite	Fair	Surface Treatment	6	171.47	\$14,289.08	\$12,002.83	\$8,573.45
MERRIMAC ST-23	Odd	No	0	Granite	Fair	Surface Treatment	5	123.66	\$8,587.80	\$7,213.75	\$5,152.68
MERRIMAC ST-25	Odd	No	0	Granite	Fair	Surface Treatment	4	55.38	\$3,076.51	\$2,584.27	\$1,845.90
MERRIMAC ST-27	Odd	No	0	Granite	Fair	Surface Treatment	5	93.78	\$6,512.29	\$5,470.32	\$3,907.37
MERRIMAC ST-30	Odd	No	0	Granite	Good	Routine Maintenance	5	71.29	\$1,188.18	\$1,188.18	\$1,188.18
MERRIMAC ST-21	Even	No	0	Granite	Poor	Rehabilitation	6	213.53	\$17,794.35	\$14,947.26	\$10,676.61
MERRIMAC ST-21	Even	No	0	Granite	Poor	Rehabilitation	5	118.41	\$8,223.04	\$6,907.35	\$4,933.82
MERRIMAC ST-22	Even	No	0	Granite	Fair	Surface Treatment	5	107.84	\$7,488.66	\$6,290.47	\$4,493.20
MERRIMAC ST-27	Even	No	0	Granite	Fair	Surface Treatment	4	42.89	\$2,382.68	\$2,001.45	\$1,429.61
MERRIMAC ST-31	Even	No	0	None	Fair	Surface Treatment	4	110.44	\$6,135.32	\$5,153.67	\$3,681.19
							Length:	1,302.86	\$89,162.09	\$75,086.26	\$53,972.53
MUNROE STREET											
MUNROE ST-03	Even	No	6	Granite	New	Defer Maintenance	4	68.51	\$0.00	\$0.00	\$0.00
							Length:	68.51	\$0.00	\$0.00	\$0.00
OLIVE STREET											
OLIVE ST-01	Odd	Yes	2	Granite	Poor	Rehabilitation	4	231.48	\$12,860.18	\$10,802.55	\$7,716.11
OLIVE ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	188.24	\$10,458.03	\$8,784.75	\$6,274.82
OLIVE ST-01	Odd	No	0	Granite	Fair	Surface Treatment	6	116.02	\$9,668.57	\$8,121.60	\$5,801.14
							Length:	535.75	\$32,986.78	\$27,708.90	\$19,792.07
STRONG STREET											
STRONG ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	52.09	\$2,893.80	\$2,430.79	\$1,736.28
STRONG ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	71.32	\$3,962.25	\$3,328.29	\$2,377.35
STRONG ST-02	Odd	No	0	None	Fair	Surface Treatment	4	59.62	\$3,312.32	\$2,782.35	\$1,987.39
STRONG ST-02	Odd	No	0	None	Fair	Surface Treatment	4	77.48	\$4,304.31	\$3,615.62	\$2,582.59

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
STRONG ST-01	Even	No	0	Granite	Poor	Rehabilitation	4	35.62	\$1,978.70	\$1,662.11	\$1,187.22
STRONG ST-02	Even	No	0	Granite	Fair	Surface Treatment	5	124.70	\$8,659.79	\$7,274.22	\$5,195.87
							Length:	420.83	\$25,111.16	\$21,093.38	\$15,066.70

SUMMIT PLACE

SUMMIT PL	Odd	No	0	Granite	Poor	Rehabilitation	4	325.56	\$18,086.73	\$15,192.85	\$10,852.04
SUMMIT PL	Odd	No	0	Granite	Poor	Rehabilitation	4	399.06	\$22,169.73	\$18,622.57	\$13,301.84
SUMMIT PL	Even	No	0	Granite	Poor	Rehabilitation	5	119.38	\$8,290.47	\$6,964.00	\$4,974.28
SUMMIT PL	Even	No	0	Granite	Poor	Rehabilitation	5	187.79	\$13,040.93	\$10,954.38	\$7,824.56
SUMMIT PL	Even	No	0	Granite	Good	Routine Maintenance	5	209.73	\$3,495.44	\$3,495.44	\$3,495.44
SUMMIT PL	Even	No	0	Granite	Fair	Surface Treatment	5	46.17	\$3,206.40	\$2,693.38	\$1,923.84
SUMMIT PL	Even	No	0	Granite	Poor	Rehabilitation	5	61.85	\$4,295.43	\$3,608.16	\$2,577.26
							Length:	1,349.54	\$72,585.14	\$61,530.78	\$44,949.26

VERNON STREET

VERNON ST-03	Odd	No	0	Granite	Fair	Surface Treatment	4	67.41	\$3,745.10	\$3,145.88	\$2,247.06
VERNON ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	78.81	\$4,378.43	\$3,677.88	\$2,627.06
							Length:	146.22	\$8,123.53	\$6,823.77	\$4,874.12

WARREN STREET

WARREN ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	31.55	\$1,752.90	\$1,472.44	\$1,051.74
WARREN ST-01	Odd	No	0	Concrete	Fair	Surface Treatment	4	51.79	\$2,877.14	\$2,416.80	\$1,726.28
WARREN ST-01	Odd	No	0	Concrete	Good	Routine Maintenance	4	34.65	\$462.02	\$462.02	\$462.02
WARREN ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	64.04	\$3,557.66	\$2,988.43	\$2,134.60
							Length:	182.03	\$8,649.72	\$7,339.69	\$5,374.64

WASHINGTON STREET

WASHINGTON ST-01	Odd	No	0	Granite	Poor	Rehabilitation	6	76.53	\$6,377.74	\$5,357.30	\$3,826.64
WASHINGTON ST-02	Odd	Yes	2	Granite	Fair	Surface Treatment	4	57.43	\$3,190.81	\$2,680.28	\$1,914.48
WASHINGTON ST-04	Odd	No	0	Granite	Poor	Rehabilitation	4	259.12	\$14,395.30	\$12,092.05	\$8,637.18
WASHINGTON ST-04	Odd	No	0	Granite	New	Defer Maintenance	4	52.72	\$0.00	\$0.00	\$0.00
WASHINGTON ST-05	Odd	No	0	Granite	New	Defer Maintenance	4	65.81	\$0.00	\$0.00	\$0.00
WASHINGTON ST-07	Odd	No	0	Granite	Poor	Rehabilitation	4	38.78	\$2,154.67	\$1,809.93	\$1,292.80
WASHINGTON ST-01	Even	No	0	Granite	Good	Routine Maintenance	6	64.87	\$1,297.49	\$1,297.49	\$1,297.49
WASHINGTON ST-01	Even	Yes	2	Granite	Poor	Rehabilitation	4	305.66	\$16,980.93	\$14,263.98	\$10,188.56
WASHINGTON ST-02	Even	No	0	Granite	Fair	Surface Treatment	6	288.64	\$24,053.61	\$20,205.03	\$14,432.16
WASHINGTON ST-07	Even	No	0	Granite	Fair	Surface Treatment	5	75.79	\$5,263.47	\$4,421.31	\$3,158.08
							Length:	1,285.36	\$73,714.00	\$62,127.36	\$44,747.40

Ward: 4

ADAMS STREET

ADAMS ST-02	Odd	Yes	4	None	Fair	Surface Treatment	2	85.72	\$2,381.07	\$2,000.10	\$1,428.64
ADAMS ST-01	Even	Yes	4	None	Poor	Rehabilitation	2	218.49	\$6,069.21	\$5,098.14	\$3,641.53

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
							Length:	304.21	\$8,450.28	\$7,098.23	\$5,070.17
ARLINGTON STREET											
ARLINGTON ST	Odd	No	0	Granite	Poor	Rehabilitation	5	73.62	\$5,112.24	\$4,294.28	\$3,067.35
							Length:	73.62	\$5,112.24	\$4,294.28	\$3,067.35
ASHLAND COURT											
ATKINSON CT	Odd	Yes	2	Granite	Poor	Rehabilitation	2	107.19	\$2,977.47	\$2,501.07	\$1,786.48
							Length:	107.19	\$2,977.47	\$2,501.07	\$1,786.48
ASHLAND STREET											
ASHLAND ST-01	Odd	Yes	2	Granite	Poor	Rehabilitation	6	188.85	\$15,737.51	\$13,219.51	\$9,442.50
ASHLAND ST-04	Odd	Yes	2	Granite	Fair	Surface Treatment	4	85.98	\$4,776.46	\$4,012.23	\$2,865.88
ASHLAND ST-04	Odd	No	0	Granite	Fair	Surface Treatment	4	89.36	\$4,964.38	\$4,170.08	\$2,978.63
ASHLAND ST-03	Even	Yes	2	Granite	Fair	Surface Treatment	4	288.16	\$16,008.66	\$13,447.27	\$9,605.20
ASHLAND ST-04	Even	Yes	2	Granite	Fair	Surface Treatment	4	115.56	\$6,420.12	\$5,392.90	\$3,852.07
							Length:	767.90	\$47,907.12	\$40,241.98	\$28,744.27
BEACON AVENUE											
BEACON ST	Even	Yes	2	None	Poor	Rehabilitation	2	133.94	\$3,720.59	\$3,125.30	\$2,232.36
BEACON ST	Even	Yes	2	None	Fair	Surface Treatment	2	100.08	\$2,779.97	\$2,335.18	\$1,667.98
							Length:	234.02	\$6,500.57	\$5,460.48	\$3,900.34
BROAD STREET											
BROAD ST-01	Even	Yes	6	Granite	Fair	Surface Treatment	4	99.26	\$5,514.35	\$4,632.05	\$3,308.61
BROAD ST-01	Even	Yes	5	Granite	Fair	Surface Treatment	4	119.67	\$6,648.22	\$5,584.51	\$3,988.93
BROAD ST-02	Even	No	0	Granite	Fair	Surface Treatment	8	76.98	\$8,553.46	\$7,184.90	\$5,132.07
							Length:	295.91	\$20,716.03	\$17,401.47	\$12,429.62
BUTLER STREET											
BUTLER ST	Odd	Yes	2	Granite	Fair	Surface Treatment	4	109.22	\$6,067.93	\$5,097.07	\$3,640.76
							Length:	109.22	\$6,067.93	\$5,097.07	\$3,640.76
CHAPEL STREET											
CHAPEL ST-01	Odd	No	0	Concrete	Fair	Surface Treatment	4	81.48	\$4,526.68	\$3,802.41	\$2,716.01
							Length:	81.48	\$4,526.68	\$3,802.41	\$2,716.01
CHRISTIE STREET											
CHRISTIE ST	Even	No	0	CC Berm	Fair	Surface Treatment	4	1,099.71	\$61,094.85	\$51,319.68	\$36,656.91
							Length:	1,099.71	\$61,094.85	\$51,319.68	\$36,656.91
COLLINS STREET											
COLLINS ST	Odd	No	0	Granite	Fair	Surface Treatment	4	86.27	\$4,792.59	\$4,025.78	\$2,875.56
COLLINS ST	Odd	No	0	Granite	Fair	Surface Treatment	4	95.63	\$5,312.67	\$4,462.64	\$3,187.60
							Length:	181.89	\$10,105.26	\$8,488.42	\$6,063.16
COLUMBUS AVENUE											

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
COLUMBUS AVE-02	Odd	Yes	2	None	Fair	Surface Treatment	4	276.39	\$15,354.94	\$12,898.15	\$9,212.96
COLUMBUS AVE-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	112.17	\$6,231.91	\$5,234.80	\$3,739.15
COLUMBUS AVE-02	Even	Yes	2	Concrete	Fair	Surface Treatment	4	117.88	\$6,548.80	\$5,500.99	\$3,929.28
COLUMBUS AVE-03	Even	Yes	2	None	Fair	Surface Treatment	4	205.94	\$11,441.29	\$9,610.68	\$6,864.77
Length:								712.38	\$39,576.94	\$33,244.63	\$23,746.16
COOLIDGE STREET											
COOLIDGE ST	Odd	Yes	2	Granite	Fair	Surface Treatment	2	235.51	\$6,542.04	\$5,495.31	\$3,925.22
Length:								235.51	\$6,542.04	\$5,495.31	\$3,925.22
DAWES STREET											
DAWES ST	Even	Yes	2	Concrete	Fair	Surface Treatment	4	101.33	\$5,629.42	\$4,728.71	\$3,377.65
Length:								101.33	\$5,629.42	\$4,728.71	\$3,377.65
FARRELL STREET											
FARRELL ST-01	Odd	No	0	Concrete	Poor	Rehabilitation	4	570.87	\$31,715.27	\$26,640.83	\$19,029.16
FARRELL ST-02	Odd	No	0	Granite	Poor	Rehabilitation	4	235.03	\$13,057.29	\$10,968.13	\$7,834.38
FARRELL ST-01	Even	No	0	Concrete	Poor	Rehabilitation	4	563.40	\$31,300.09	\$26,292.07	\$18,780.05
FARRELL ST-01	Even	No	0	Granite	Poor	Rehabilitation	4	75.94	\$4,219.02	\$3,543.98	\$2,531.41
FARRELL ST-02	Even	No	0	Granite	New	Defer Maintenance	4	72.10	\$0.00	\$0.00	\$0.00
Length:								1,517.35	\$80,291.67	\$67,445.00	\$48,175.00
FORRESTER STREET											
FORRESTER ST-01	Odd	No	0	None	Fair	Surface Treatment	4	157.57	\$8,754.09	\$7,353.43	\$5,252.45
FORRESTER ST-03	Odd	Yes	2	Granite	Fair	Surface Treatment	4	42.27	\$2,348.35	\$1,972.62	\$1,409.01
Length:								199.84	\$11,102.44	\$9,326.05	\$6,661.46
HIGH STREET											
HIGH ST-12	Odd	No	0	Granite	Fair	Surface Treatment	4	136.62	\$7,590.12	\$6,375.70	\$4,554.07
HIGH ST-12	Odd	No	0	Granite	New	Defer Maintenance	4	103.99	\$0.00	\$0.00	\$0.00
HIGH ST-12	Odd	No	0	Granite	Fair	Surface Treatment	4	25.72	\$1,429.03	\$1,200.38	\$857.42
HIGH ST-02	Even	Yes	2	Granite	Poor	Rehabilitation	4	248.75	\$13,819.42	\$11,608.31	\$8,291.65
HIGH ST-06	Even	No	0	Granite	Fair	Surface Treatment	6	64.26	\$5,354.87	\$4,498.09	\$3,212.92
HIGH ST-08	Even	No	0	Granite	Fair	Surface Treatment	6	93.23	\$7,769.12	\$6,526.06	\$4,661.47
HIGH ST-09	Even	Yes	2	Granite	Fair	Surface Treatment	4	165.59	\$9,199.72	\$7,727.76	\$5,519.83
HIGH ST-09	Even	Yes	2	Granite	Fair	Surface Treatment	4	13.31	\$739.72	\$621.37	\$443.83
HIGH ST-10	Even	Yes	2	Granite	Poor	Rehabilitation	4	165.22	\$9,179.14	\$7,710.48	\$5,507.48
HIGH ST-11	Even	Yes	2	Granite	Fair	Surface Treatment	4	217.76	\$12,097.74	\$10,162.11	\$7,258.65
HIGH ST-11	Even	No	0	Granite	Fair	Surface Treatment	6	146.51	\$12,209.55	\$10,256.02	\$7,325.73
HIGH ST-12	Even	Yes	2	Granite	Fair	Surface Treatment	4	96.69	\$5,371.45	\$4,512.02	\$3,222.87
Length:								1,477.67	\$84,759.88	\$71,198.30	\$50,855.93
HIGHLAND AVENUE											
HIGHLAND AVE-02	Even	No	0	Concrete	Poor	Rehabilitation	4	141.49	\$7,860.59	\$6,602.90	\$4,716.36

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
							Length:	141.49	\$7,860.59	\$6,602.90	\$4,716.36
HOWARD STREET											
HOWARD ST-01	Odd	Yes	2	Granite	Good	Routine Maintenance	3	107.32	\$1,073.21	\$1,073.21	\$1,073.21
HOWARD ST-01	Even	Yes	2	Granite	Fair	Surface Treatment	3	82.40	\$3,433.18	\$2,883.88	\$2,059.91
HOWARD ST-01	Even	Yes	2	Granite	Poor	Rehabilitation	3	74.16	\$3,090.02	\$2,595.61	\$1,854.01
							Length:	263.88	\$7,596.41	\$6,552.70	\$4,987.13
LAFAYETTE STREET											
LAFAYETTE ST	Odd	No	0	Concrete	Poor	Rehabilitation	4	36.81	\$2,044.79	\$1,717.63	\$1,226.88
							Length:	36.81	\$2,044.79	\$1,717.63	\$1,226.88
LOW STREET											
LOW ST-08	Even	No	0	Granite	Fair	Surface Treatment	4	661.79	\$36,766.16	\$30,883.58	\$22,059.70
LOW ST-09	Even	No	0	Granite	Fair	Surface Treatment	4	1,000.62	\$55,589.91	\$46,695.52	\$33,353.95
LOW ST-10	Even	No	0	Granite	Fair	Surface Treatment	4	158.89	\$8,827.15	\$7,414.81	\$5,296.29
							Length:	1,821.30	\$101,183.23	\$84,993.91	\$60,709.94
MAGNOLIA STREET											
MAGNOLIA ST	Odd	No	0	Granite	Fair	Surface Treatment	4	159.70	\$8,872.25	\$7,452.69	\$5,323.35
MAGNOLIA ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	114.72	\$6,373.18	\$5,353.47	\$3,823.91
MAGNOLIA ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	107.75	\$5,986.20	\$5,028.41	\$3,591.72
							Length:	382.17	\$21,231.63	\$17,834.57	\$12,738.98
MAPLE STREET											
MAPLE ST	Even	No	0	Granite	Fair	Surface Treatment	4	179.49	\$9,971.69	\$8,376.22	\$5,983.01
MAPLE ST	Even	Yes	2	Concrete	Fair	Surface Treatment	4	70.00	\$3,888.70	\$3,266.51	\$2,333.22
							Length:	249.49	\$13,860.39	\$11,642.73	\$8,316.23
MERRIMAC COURT											
MERRIMAC CT	Even	No	0	Concrete	Good	Routine Maintenance	3	42.01	\$420.10	\$420.10	\$420.10
							Length:	42.01	\$420.10	\$420.10	\$420.10
MERRIMAC STREET											
MERRIMAC ST-07	Odd	Yes	10	Mix	Fair	Surface Treatment	4	158.95	\$8,830.83	\$7,417.89	\$5,298.50
MERRIMAC ST-10	Odd	No	0	Granite	Poor	Rehabilitation	4	264.18	\$14,676.47	\$12,328.23	\$8,805.88
MERRIMAC ST-11	Odd	No	0	Granite	Poor	Rehabilitation	5	262.68	\$18,241.44	\$15,322.81	\$10,944.87
MERRIMAC ST-11	Odd	No	0	Granite	Poor	Rehabilitation	5	50.67	\$3,518.63	\$2,955.65	\$2,111.18
MERRIMAC ST-12	Odd	No	0	Granite	Poor	Rehabilitation	5	189.27	\$13,143.85	\$11,040.84	\$7,886.31
MERRIMAC ST-13	Odd	No	0	Granite	Fair	Surface Treatment	6	35.46	\$2,955.32	\$2,482.47	\$1,773.19
MERRIMAC ST-14	Odd	No	0	Granite	Poor	Rehabilitation	5	106.86	\$7,420.81	\$6,233.48	\$4,452.49
MERRIMAC ST-15	Odd	No	0	Granite	Poor	Rehabilitation	5	279.63	\$19,418.53	\$16,311.57	\$11,651.12
MERRIMAC ST-16	Odd	No	0	Granite	Poor	Rehabilitation	5	339.62	\$23,585.03	\$19,811.43	\$14,151.02
MERRIMAC ST-17	Odd	No	0	Granite	Poor	Rehabilitation	4	79.63	\$4,423.67	\$3,715.89	\$2,654.20
MERRIMAC ST-17	Odd	No	0	Granite	Fair	Surface Treatment	4	156.11	\$8,673.01	\$7,285.33	\$5,203.81

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
MERRIMAC ST-18	Odd	No	0	Granite	Fair	Surface Treatment	4	200.09	\$11,116.35	\$9,337.73	\$6,669.81
MERRIMAC ST-19	Odd	No	0	Granite	Fair	Surface Treatment	6	190.93	\$15,910.80	\$13,365.07	\$9,546.48
MERRIMAC ST-01	Even	Yes	2	Mix	Fair	Surface Treatment	3	224.47	\$9,353.02	\$7,856.54	\$5,611.81
MERRIMAC ST-02	Even	Yes	2	Granite	Good	Routine Maintenance	3	65.64	\$656.45	\$656.45	\$656.45
MERRIMAC ST-02	Even	Yes	2	None	Poor	Rehabilitation	2	280.59	\$7,794.15	\$6,547.09	\$4,676.49
MERRIMAC ST-04	Even	Yes	2	None	Poor	Rehabilitation	2	527.07	\$14,640.75	\$12,298.23	\$8,784.45
MERRIMAC ST-05	Even	Yes	2	None	Poor	Rehabilitation	2	301.67	\$8,379.81	\$7,039.04	\$5,027.89
MERRIMAC ST-06	Even	Yes	2	Concrete	Poor	Rehabilitation	2	845.98	\$23,499.52	\$19,739.60	\$14,099.71
MERRIMAC ST-07	Even	No	0	Concrete	Poor	Rehabilitation	4	377.68	\$20,982.43	\$17,625.24	\$12,589.46
MERRIMAC ST-07	Even	Yes	2	Concrete	Fair	Surface Treatment	2	95.84	\$2,662.21	\$2,236.26	\$1,597.33
MERRIMAC ST-08	Even	No	0	Granite	Fair	Surface Treatment	4	356.47	\$19,804.16	\$16,635.49	\$11,882.49
MERRIMAC ST-09	Even	Yes	2	Concrete	Fair	Surface Treatment	2	107.05	\$2,973.69	\$2,497.90	\$1,784.22
MERRIMAC ST-10	Even	Yes	2	Concrete	Poor	Rehabilitation	4	81.38	\$4,521.20	\$3,797.81	\$2,712.72
MERRIMAC ST-11	Even	Yes	2	Concrete	Poor	Rehabilitation	4	99.69	\$5,538.25	\$4,652.13	\$3,322.95
MERRIMAC ST-12	Even	Yes	2	Mix	Fair	Surface Treatment	4	285.66	\$15,869.86	\$13,330.69	\$9,521.92
MERRIMAC ST-15	Even	No	0	Granite	Fair	Surface Treatment	5	76.98	\$5,345.78	\$4,490.46	\$3,207.47
MERRIMAC ST-16	Even	Yes	2	Concrete	Poor	Rehabilitation	4	54.34	\$3,018.82	\$2,535.81	\$1,811.29
MERRIMAC ST-16	Even	Yes	2	Granite	Poor	Rehabilitation	4	91.14	\$5,063.23	\$4,253.12	\$3,037.94
MERRIMAC ST-17	Even	Yes	2	Granite	Poor	Rehabilitation	4	370.26	\$20,569.86	\$17,278.69	\$12,341.92
MERRIMAC ST-18	Even	Yes	2	Granite	Good	Routine Maintenance	4	77.22	\$1,029.61	\$1,029.61	\$1,029.61

Length: 6,633.23 \$323,617.56 \$272,108.52 \$194,844.96

MOSELEY AVENUE

MOSELEY AVE-07	Even	Yes	6	None	Fair	Surface Treatment	2	262.86	\$7,301.67	\$6,133.40	\$4,381.00
MOSELEY AVE-07	Even	Yes	6	None	Poor	Rehabilitation	2	268.37	\$7,454.62	\$6,261.88	\$4,472.77
MOSELEY AVE-08	Even	Yes	6	None	Fair	Surface Treatment	4	320.20	\$17,788.96	\$14,942.73	\$10,673.38
MOSELEY AVE-09	Even	Yes	6	None	Fair	Surface Treatment	4	155.43	\$8,634.90	\$7,253.31	\$5,180.94
MOULTON ST-01	Even	Yes	4	None	Fair	Surface Treatment	2	195.85	\$5,440.40	\$4,569.94	\$3,264.24

Length: 1,202.71 \$46,620.55 \$39,161.27 \$27,972.33

MUNROE STREET

MUNROE ST-06	Odd	Yes	4	Concrete	Poor	Rehabilitation	3	221.85	\$9,243.65	\$7,764.67	\$5,546.19
--------------	-----	-----	---	----------	------	----------------	---	--------	------------	------------	------------

Length: 221.85 \$9,243.65 \$7,764.67 \$5,546.19

NORTH ATKINSON STREET

NORTH ATKINSON ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	49.78	\$2,765.54	\$2,323.05	\$1,659.32
NORTH ATKINSON ST-01	Odd	No	0	Concrete	Fair	Surface Treatment	4	172.68	\$9,593.10	\$8,058.21	\$5,755.86
NORTH ATKINSON ST-02	Odd	No	0	Concrete	Fair	Surface Treatment	4	503.83	\$27,990.83	\$23,512.30	\$16,794.50

Length: 726.29 \$40,349.47 \$33,893.55 \$24,209.68

OAKLAND STREET

OAKLAND ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	61.17	\$3,398.34	\$2,854.60	\$2,039.00
OAKLAND ST-04	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	65.18	\$3,621.13	\$3,041.75	\$2,172.68

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
							Length:	126.35	\$7,019.47	\$5,896.35	\$4,211.68
PAYSON STREET											
PAYSON ST-02	Odd	Yes	2	Granite	New	Defer Maintenance	4	124.23	\$0.00	\$0.00	\$0.00
PAYSON ST-01	Even	No	0	Concrete	Poor	Rehabilitation	4	63.22	\$3,512.41	\$2,950.42	\$2,107.44
PAYSON ST-02	Even	Yes	2	Concrete	Good	Routine Maintenance	2	133.78	\$891.84	\$891.84	\$891.84
							Length:	321.23	\$4,404.25	\$3,842.26	\$2,999.29
PLUMMER AVENUE											
PLUMMER AVE-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	229.76	\$12,764.61	\$10,722.28	\$7,658.77
							Length:	229.76	\$12,764.61	\$10,722.28	\$7,658.77
RIVER STREET											
RIVER ST	Even	No	0	CC Berm	Fair	Surface Treatment	4	257.66	\$14,314.34	\$12,024.04	\$8,588.60
							Length:	257.66	\$14,314.34	\$12,024.04	\$8,588.60
TILTON STREET											
TILTON ST	Odd	No	0	Mix	Poor	Rehabilitation	4	476.03	\$26,446.35	\$22,214.93	\$15,867.81
TILTON ST	Even	No	0	Concrete	Poor	Rehabilitation	4	569.89	\$31,660.33	\$26,594.68	\$18,996.20
							Length:	1,045.92	\$58,106.68	\$48,809.61	\$34,864.01
TOPPAN'S LANE											
TOPPAN'S LN-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	86.05	\$4,780.71	\$4,015.80	\$2,868.43
TOPPAN'S LN-03	Even	No	0	Granite	Good	Routine Maintenance	4	29.31	\$390.77	\$390.77	\$390.77
							Length:	115.36	\$5,171.49	\$4,406.57	\$3,259.20
TRACY STREET											
TRACY ST	Even	No	0	None	Poor	Rehabilitation	4	485.44	\$26,968.88	\$22,653.86	\$16,181.33
							Length:	485.44	\$26,968.88	\$22,653.86	\$16,181.33
TYNG STREET											
TYNG ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	99.20	\$5,511.28	\$4,629.47	\$3,306.77
TYNG ST-01	Odd	No	0	Granite	Poor	Rehabilitation	6	197.05	\$16,421.19	\$13,793.80	\$9,852.71
TYNG ST-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	184.96	\$10,275.57	\$8,631.48	\$6,165.34
TYNG ST-02	Odd	Yes	4	Concrete	Fair	Surface Treatment	4	80.12	\$4,451.20	\$3,739.01	\$2,670.72
TYNG ST-01	Even	No	0	Granite	Fair	Surface Treatment	6	139.48	\$11,623.68	\$9,763.89	\$6,974.21
TYNG ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	132.12	\$7,339.80	\$6,165.43	\$4,403.88
							Length:	832.94	\$55,622.72	\$46,723.08	\$33,373.63
WILLOW AVENUE											
WILLOW AVE	Odd	No	0	Granite	Poor	Rehabilitation	4	135.68	\$7,537.91	\$6,331.84	\$4,522.75
WILLOW AVE	Odd	No	0	Granite	Gap	Gap	4	383.32	\$21,295.64	\$0.00	\$0.00
WILLOW AVE	Even	No	0	Granite	Poor	Rehabilitation	4	403.70	\$22,427.90	\$18,839.43	\$13,456.74
WILLOW AVE	Even	No	0	Granite	Gap	Gap	4	110.12	\$6,117.66	\$0.00	\$0.00
							Length:	1,032.82	\$57,379.11	\$25,171.28	\$17,979.48

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
WOODLAND STREET											
WOODLAND ST-02	Odd	Yes	2	Granite	Fair	Surface Treatment	4	30.89	\$1,715.86	\$1,441.32	\$1,029.52
WOODLAND ST-03	Odd	Yes	2	Granite	Fair	Surface Treatment	3	60.51	\$2,521.32	\$2,117.91	\$1,512.79
WOODLAND ST-06	Odd	Yes	4	Mix	Fair	Surface Treatment	3	300.57	\$12,523.66	\$10,519.87	\$7,514.20
WOODLAND ST-07	Odd	Yes	4	Granite	Poor	Rehabilitation	3	149.76	\$6,239.95	\$5,241.56	\$3,743.97
WOODLAND ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	32.16	\$1,786.50	\$1,500.66	\$1,071.90
WOODLAND ST-04	Even	Yes	2	Granite	Fair	Surface Treatment	4	82.06	\$4,558.98	\$3,829.54	\$2,735.39
WOODLAND ST-06	Even	Yes	2	Granite	Fair	Surface Treatment	3	238.65	\$9,943.76	\$8,352.76	\$5,966.26
WOODLAND ST-07	Even	Yes	2	Granite	Fair	Surface Treatment	4	209.87	\$11,659.65	\$9,794.10	\$6,995.79
WOODLAND ST-08	Even	Yes	2	Granite	Fair	Surface Treatment	4	246.23	\$13,679.47	\$11,490.76	\$8,207.68
Length:								1,350.70	\$64,629.15	\$54,288.49	\$38,777.49
ZABRISKIE DRIVE											
ZABRISKIE DR-01	Odd	No	0	Asphalt	Good	Routine Maintenance	4	42.79	\$570.54	\$570.54	\$570.54
ZABRISKIE DR-01	Odd	No	0	Granite	Gap	Gap	4	143.42	\$7,967.95	\$0.00	\$0.00
ZABRISKIE DR-01	Even	No	0	Mix	Fair	Surface Treatment	4	243.24	\$13,513.06	\$11,350.97	\$8,107.84
ZABRISKIE DR-02	Even	No	0	Asphalt	Good	Routine Maintenance	4	487.62	\$6,501.65	\$6,501.65	\$6,501.65
ZABRISKIE DR-02	Even	No	0	Asphalt	Good	Routine Maintenance	4	798.40	\$10,645.37	\$10,645.37	\$10,645.37
Length:								1,715.47	\$39,198.57	\$29,068.53	\$25,825.39
Ward: 5											
ANDERSON LANE											
ANDERSON LN	Odd	Yes	4	Asphalt	Poor	Rehabilitation	4	341.00	\$18,944.60	\$15,913.46	\$11,366.76
ANDERSON LN	Even	Yes	4	Asphalt	Poor	Rehabilitation	4	361.43	\$20,079.67	\$16,866.92	\$12,047.80
Length:								702.44	\$39,024.27	\$32,780.38	\$23,414.56
BARTLETT DRIVE											
BARTLETT DR-01	Even	No	0	CC Berm	Good	Routine Maintenance	4	351.18	\$4,682.39	\$4,682.39	\$4,682.39
BARTLETT DR-02	Even	No	0	CC Berm	Good	Routine Maintenance	4	517.70	\$6,902.64	\$6,902.64	\$6,902.64
Length:								868.88	\$11,585.03	\$11,585.03	\$11,585.03
BAYBERRY ROAD											
BAYBERRY RD-02	Odd	Yes	2	CC Berm	Poor	Rehabilitation	4	1,488.71	\$82,706.06	\$69,473.09	\$49,623.64
BAYBERRY RD-01	Even	Yes	2	CC Berm	Fair	Surface Treatment	4	243.54	\$13,530.12	\$11,365.30	\$8,118.07
Length:								1,732.25	\$96,236.18	\$80,838.39	\$57,741.71
BRADBURY LANE											
BRADBURY LN	Odd	Yes	2	CC Berm	Poor	Rehabilitation	4	457.09	\$25,393.69	\$21,330.70	\$15,236.22
BRADBURY LN	Even	Yes	2	CC Berm	Poor	Rehabilitation	4	203.56	\$11,309.10	\$9,499.64	\$6,785.46
BRADBURY LN	Even	Yes	2	CC Berm	Good	Routine Maintenance	4	320.41	\$4,272.16	\$4,272.16	\$4,272.16
BRADBURY LN	Even	Yes	2	CC Berm	Good	Routine Maintenance	4	836.10	\$11,148.06	\$11,148.06	\$11,148.06
Length:								1,817.17	\$52,123.02	\$46,250.57	\$37,441.90
CHARMANSKI DRIVE											

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
CHARMANSKI DR	Odd	Yes	2	None	Fair	Surface Treatment	4	256.61	\$14,256.27	\$11,975.26	\$8,553.76
							Length:	256.61	\$14,256.27	\$11,975.26	\$8,553.76
COLTIN DRIVE											
COLTIN DR-03	Odd	Yes	2	None	Fair	Surface Treatment	4	543.00	\$30,166.92	\$25,340.21	\$18,100.15
							Length:	543.00	\$30,166.92	\$25,340.21	\$18,100.15
DOE RUN DRIVE											
DOE RUN DR-01	Odd	Yes	2	None	Fair	Surface Treatment	4	481.61	\$26,756.19	\$22,475.20	\$16,053.72
DOE RUN DR-02	Odd	Yes	2	None	Fair	Surface Treatment	4	560.09	\$31,115.85	\$26,137.31	\$18,669.51
							Length:	1,041.70	\$57,872.04	\$48,612.52	\$34,723.23
FOX RUN ROAD											
FOX RUN RD-01	Even	Yes	2	Asphalt	Poor	Rehabilitation	4	463.07	\$25,726.18	\$21,610.00	\$15,435.71
FOX RUN RD-02	Even	Yes	2	Asphalt	Fair	Surface Treatment	4	660.57	\$36,698.40	\$30,826.66	\$22,019.04
							Length:	1,123.64	\$62,424.58	\$52,436.65	\$37,454.75
FRANCES DRIVE											
FRANCES DR	Even	Yes	2	CC Berm	Fair	Surface Treatment	4	2,844.31	\$158,017.46	\$132,734.67	\$94,810.48
							Length:	2,844.31	\$158,017.46	\$132,734.67	\$94,810.48
GOLDEN DRIVE											
GOLDEN DR	Odd	Yes	2	Granite	Fair	Surface Treatment	4	232.12	\$12,895.45	\$10,832.18	\$7,737.27
GOLDEN DR	Odd	Yes	2	Granite	Good	Routine Maintenance	4	299.01	\$3,986.78	\$3,986.78	\$3,986.78
GOLDEN DR	Odd	Yes	2	Granite	Good	Routine Maintenance	4	211.43	\$2,819.01	\$2,819.01	\$2,819.01
GOLDEN DR	Even	Yes	2	Granite	Good	Routine Maintenance	4	149.06	\$1,987.50	\$1,987.50	\$1,987.50
GOLDEN DR	Even	Yes	2	Granite	Good	Routine Maintenance	4	160.44	\$2,139.26	\$2,139.26	\$2,139.26
GOLDEN DR	Even	Yes	2	Granite	Good	Routine Maintenance	4	148.33	\$1,977.75	\$1,977.75	\$1,977.75
							Length:	1,200.39	\$25,805.74	\$23,742.47	\$20,647.56
GOLDSMITHS DRIVE											
GOLDSMITHS DR-01	Odd	Yes	6	CC Berm	Poor	Rehabilitation	4	265.90	\$14,772.12	\$12,408.58	\$8,863.27
GOLDSMITHS DR-02	Odd	Yes	6	CC Berm	Poor	Rehabilitation	4	324.24	\$18,013.39	\$15,131.25	\$10,808.04
GOLDSMITHS DR-03	Odd	Yes	6	CC Berm	Poor	Rehabilitation	4	300.68	\$16,704.19	\$14,031.52	\$10,022.51
GOLDSMITHS DR-04	Odd	Yes	3	CC Berm	Poor	Rehabilitation	4	628.66	\$34,925.68	\$29,337.57	\$20,955.41
GOLDSMITHS DR-03	Even	Yes	2	CC Berm	Poor	Rehabilitation	4	271.15	\$15,063.88	\$12,653.66	\$9,038.33
GOLDSMITHS DR-04	Even	Yes	2	CC Berm	Poor	Rehabilitation	4	264.66	\$14,703.12	\$12,350.62	\$8,821.87
GOLDSMITHS DR-04	Even	Yes	2	CC Berm	Fair	Surface Treatment	4	258.60	\$14,366.41	\$12,067.79	\$8,619.85
GOLDSMITHS DR-04	Even	Yes	2	CC Berm	Fair	Surface Treatment	4	248.98	\$13,831.95	\$11,618.84	\$8,299.17
GOLDSMITHS DR-05	Even	Yes	2	CC Berm	Poor	Rehabilitation	4	256.90	\$14,272.03	\$11,988.51	\$8,563.22
							Length:	2,819.75	\$156,652.79	\$131,588.34	\$93,991.67
HALE STREET											
HALE ST-01	Even	Yes	8	CC Berm	Fair	Surface Treatment	4	321.90	\$17,883.59	\$15,022.22	\$10,730.16
HALE ST-02	Even	No	0	CC Berm	Fair	Surface Treatment	4	388.65	\$21,591.68	\$18,137.01	\$12,955.01

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
HALE ST-02	Even	Yes	3	None	Fair	Surface Treatment	4	252.13	\$14,007.13	\$11,765.99	\$8,404.28
HALE ST-02	Even	Yes	6	None	Fair	Surface Treatment	4	220.99	\$12,277.07	\$10,312.73	\$7,366.24
HALE ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	783.13	\$43,506.96	\$36,545.85	\$26,104.18
HALE ST-04	Even	No	0	Granite	Poor	Rehabilitation	4	285.21	\$15,845.17	\$13,309.94	\$9,507.10
Length:								2,252.01	\$125,111.60	\$105,093.75	\$75,066.96
HIGH STREET											
HIGH ST-01	Odd	Yes	2	Granite	Good	Routine Maintenance	4	298.54	\$3,980.55	\$3,980.55	\$3,980.55
HIGH ST-02	Odd	Yes	2	Granite	Poor	Rehabilitation	4	89.93	\$4,996.35	\$4,196.94	\$2,997.81
HIGH ST-03	Odd	Yes	2	Granite	Fair	Surface Treatment	4	64.10	\$3,560.98	\$2,991.22	\$2,136.59
HIGH ST-05	Odd	Yes	2	Granite	Poor	Rehabilitation	4	90.93	\$5,051.90	\$4,243.59	\$3,031.14
HIGH ST-07	Odd	Yes	4	Granite	Fair	Surface Treatment	4	63.64	\$3,535.80	\$2,970.08	\$2,121.48
Length:								607.15	\$21,125.58	\$18,382.38	\$14,267.57
HUNTER DRIVE											
HUNTER DR	Odd	No	0	CC Berm	Fair	Surface Treatment	4	648.45	\$36,025.10	\$30,261.08	\$21,615.06
Length:								648.45	\$36,025.10	\$30,261.08	\$21,615.06
KNIGHTS LANE											
KNIGHTS LN-01	Even	No	0	CC Berm	Good	Routine Maintenance	4	312.05	\$4,160.68	\$4,160.68	\$4,160.68
KNIGHTS LN-02	Even	No	0	Mix	Good	Routine Maintenance	4	214.68	\$2,862.36	\$2,862.36	\$2,862.36
Length:								526.73	\$7,023.04	\$7,023.04	\$7,023.04
LAVALEE LANE											
LAVALEE LN-01	Odd	Yes	2	CC Berm	Fair	Surface Treatment	4	1,013.76	\$56,319.84	\$47,308.67	\$33,791.91
LAVALEE LN-01	Odd	Yes	2	CC Berm	Poor	Rehabilitation	4	125.63	\$6,979.67	\$5,862.92	\$4,187.80
LAVALEE LN-02	Odd	Yes	2	CC Berm	Fair	Surface Treatment	4	272.03	\$15,112.65	\$12,694.63	\$9,067.59
LAVALEE LN-03	Odd	Yes	2	CC Berm	Poor	Rehabilitation	4	261.77	\$14,542.68	\$12,215.85	\$8,725.61
LAVALEE LN-01	Even	Yes	2	CC Berm	Poor	Rehabilitation	4	158.48	\$8,804.32	\$7,395.63	\$5,282.59
Length:								1,831.66	\$101,759.16	\$85,477.70	\$61,055.50
LOIS STREET											
LOIS ST-02	Odd	No	0	CC Berm	Fair	Surface Treatment	4	245.36	\$13,630.99	\$11,450.04	\$8,178.60
Length:								245.36	\$13,630.99	\$11,450.04	\$8,178.60
LOW STREET											
LOW ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	484.27	\$26,903.82	\$22,599.21	\$16,142.29
LOW ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	458.78	\$25,487.83	\$21,409.78	\$15,292.70
LOW ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	181.96	\$2,426.11	\$2,426.11	\$2,426.11
LOW ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	203.76	\$2,716.85	\$2,716.85	\$2,716.85
LOW ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	233.92	\$12,995.72	\$10,916.41	\$7,797.43
LOW ST-03	Even	No	0	Granite	Fair	Surface Treatment	4	252.53	\$14,029.25	\$11,784.57	\$8,417.55
LOW ST-04	Even	No	0	Granite	Fair	Surface Treatment	4	236.29	\$13,127.16	\$11,026.82	\$7,876.30
LOW ST-05	Even	No	0	Granite	Fair	Surface Treatment	4	240.04	\$13,335.32	\$11,201.67	\$8,001.19
LOW ST-06	Even	No	0	Granite	Fair	Surface Treatment	4	765.22	\$42,512.45	\$35,710.46	\$25,507.47

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
LOW ST-07	Even	No	0	Granite	Fair	Surface Treatment	4	277.73	\$15,429.21	\$12,960.53	\$9,257.52
LOW ST-07	Even	No	0	Granite	Fair	Surface Treatment	4	241.38	\$13,410.22	\$11,264.59	\$8,046.13
LOW ST-07	Even	No	0	Granite	Fair	Surface Treatment	4	106.36	\$5,908.87	\$4,963.45	\$3,545.32
LOW ST-07	Even	No	0	Granite	Poor	Rehabilitation	4	310.35	\$17,241.52	\$14,482.88	\$10,344.91
							Length:	3,992.59	\$205,524.35	\$173,463.32	\$125,371.79
LT LEARY DRIVE											
LT LEARY DR	Even	No	0	CC Berm	Fair	Surface Treatment	4	635.66	\$35,314.25	\$29,663.97	\$21,188.55
							Length:	635.66	\$35,314.25	\$29,663.97	\$21,188.55
MURPHY AVENUE											
MURPHY AVE-01	Even	No	0	Granite	Gap	Gap	4	235.18	\$13,065.34	\$0.00	\$0.00
							Length:	235.18	\$13,065.34	\$0.00	\$0.00
MYRTLE AVENUE											
MYRTLE AVE-01	Odd	No	0	Concrete	Poor	Rehabilitation	4	411.21	\$22,844.86	\$19,189.68	\$13,706.91
							Length:	411.21	\$22,844.86	\$19,189.68	\$13,706.91
NORMAN AVENUE											
NORMAN AVE	Odd	Yes	5	Concrete	Poor	Rehabilitation	3	740.34	\$30,847.71	\$25,912.07	\$18,508.62
NORMAN AVE	Even	Yes	6	Concrete	Poor	Rehabilitation	2	747.86	\$20,773.94	\$17,450.11	\$12,464.37
							Length:	1,488.21	\$51,621.65	\$43,362.18	\$30,972.99
NORTH ATKINSON STREET											
NORTH ATKINSON ST-03	Odd	No	0	Concrete	Fair	Surface Treatment	4	398.78	\$22,154.29	\$18,609.60	\$13,292.57
NORTH ATKINSON ST-04	Odd	No	0	Granite	Gap	Gap	4	90.44	\$5,024.57	\$0.00	\$0.00
NORTH ATKINSON ST-04	Odd	No	0	Granite	Good	Routine Maintenance	4	136.86	\$1,824.74	\$1,824.74	\$1,824.74
NORTH ATKINSON ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	247.48	\$13,748.95	\$11,549.12	\$8,249.37
NORTH ATKINSON ST-03	Even	Yes	2	Concrete	Fair	Surface Treatment	2	88.55	\$2,459.84	\$2,066.27	\$1,475.91
NORTH ATKINSON ST-04	Even	No	0	Granite	Gap	Gap	4	165.75	\$9,208.26	\$0.00	\$0.00
NORTH ATKINSON ST-04	Even	No	0	Granite	Good	Routine Maintenance	4	90.31	\$1,204.17	\$1,204.17	\$1,204.17
							Length:	1,218.17	\$55,624.82	\$35,253.90	\$26,046.76
PHEASANT RUN DRIVE											
PHEASANT RUN DR	Odd	Yes	2	Asphalt	Poor	Rehabilitation	4	1,703.17	\$94,620.65	\$79,481.34	\$56,772.39
PHEASANT RUN DR	Even	Yes	2	Asphalt	Poor	Rehabilitation	4	334.93	\$18,607.31	\$15,630.14	\$11,164.39
							Length:	2,038.10	\$113,227.96	\$95,111.49	\$67,936.78
QUAIL RUN HOLLOW											
QUAIL RUN HOLLOW-01	Odd	Yes	2	None	Fair	Surface Treatment	4	343.10	\$19,060.85	\$16,011.12	\$11,436.51
QUAIL RUN HOLLOW-02	Odd	Yes	2	None	Fair	Surface Treatment	4	374.44	\$20,802.14	\$17,473.80	\$12,481.28
QUAIL RUN HOLLOW-03	Odd	Yes	2	None	Poor	Rehabilitation	4	216.48	\$12,026.94	\$10,102.63	\$7,216.16
							Length:	934.02	\$51,889.93	\$43,587.54	\$31,133.96
SIMMONS DRIVE											
SIMMONS DR-01	Odd	Yes	2	Granite	Good	Routine Maintenance	4	207.08	\$2,761.12	\$2,761.12	\$2,761.12

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
SIMMONS DR-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	192.98	\$2,573.04	\$2,573.04	\$2,573.04
							Length:	400.06	\$5,334.16	\$5,334.16	\$5,334.16
SQUIRES GLEN											
SQUIRES GLEN	Even	Yes	2	Asphalt	Fair	Surface Treatment	4	329.37	\$18,298.18	\$15,370.47	\$10,978.91
							Length:	329.37	\$18,298.18	\$15,370.47	\$10,978.91
STOREY BROOK ROAD											
STOREY BROOK RD-03	Odd	No	0	Granite	Fair	Surface Treatment	4	226.20	\$12,566.49	\$10,555.85	\$7,539.89
STOREY BROOK RD-04	Odd	Yes	2	Granite	Poor	Rehabilitation	4	55.64	\$3,090.86	\$2,596.32	\$1,854.51
STOREY BROOK RD-04	Even	Yes	2	Granite	Good	Routine Maintenance	4	32.09	\$427.91	\$427.91	\$427.91
							Length:	313.93	\$16,085.25	\$13,580.08	\$9,822.32
WANDOVER WAY											
WANDOVER WY	Odd	No	0	Asphalt	Fair	Surface Treatment	4	181.95	\$10,108.07	\$8,490.78	\$6,064.84
WANDOVER WY	Odd	No	0	Granite	Fair	Surface Treatment	4	160.96	\$8,942.10	\$7,511.36	\$5,365.26
							Length:	342.90	\$19,050.17	\$16,002.14	\$11,430.10
WILDWOOD DRIVE											
WILDWOOD DR-02	Odd	Yes	2	None	Fair	Surface Treatment	4	314.96	\$17,497.50	\$14,697.90	\$10,498.50
WILDWOOD DR-03	Odd	Yes	2	None	Fair	Surface Treatment	4	1,035.00	\$57,500.10	\$48,300.08	\$34,500.06
							Length:	1,349.96	\$74,997.60	\$62,997.99	\$44,998.56
WILKINSON DRIVE											
WILKINSON DR	Even	Yes	2	CC Berm	Good	Routine Maintenance	4	301.79	\$4,023.89	\$4,023.89	\$4,023.89
							Length:	301.79	\$4,023.89	\$4,023.89	\$4,023.89
Ward: 6											
AZALEA ROAD											
AZALEA RD	Odd	No	0	None	Poor	Rehabilitation	4	319.00	\$17,722.15	\$14,886.60	\$10,633.29
AZALEA RD	Even	No	0	None	Poor	Rehabilitation	4	337.59	\$18,755.28	\$15,754.43	\$11,253.17
							Length:	656.59	\$36,477.42	\$30,641.04	\$21,886.45
BOURBEAU TERRACE											
BOURBEAU TER	Even	Yes	2	CC Berm	Fair	Surface Treatment	4	1,838.98	\$102,165.81	\$85,819.28	\$61,299.49
BOURBEAU TER	Even	Yes	2	CC Berm	Gap	Gap	4	41.46	\$2,303.32	\$0.00	\$0.00
							Length:	1,880.44	\$104,469.13	\$85,819.28	\$61,299.49
BOYD DRIVE											
BOYD DR	Even	Yes	2	Asphalt	Fair	Surface Treatment	4	1,799.02	\$99,945.70	\$83,954.39	\$59,967.42
							Length:	1,799.02	\$99,945.70	\$83,954.39	\$59,967.42
CHAIN BRIDGE DRIVE											
CHAIN BRIDGE DR-01	Odd	No	0	None	Fair	Surface Treatment	4	315.52	\$17,528.77	\$14,724.17	\$10,517.26
CHAIN BRIDGE DR-02	Odd	No	0	None	Good	Routine Maintenance	4	223.02	\$2,973.58	\$2,973.58	\$2,973.58

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
							Length:	538.54	\$20,502.35	\$17,697.75	\$13,490.84
CHAISSON ROAD											
CHAISSON RD	Even	No	0	CC Berm	Fair	Surface Treatment	4	395.75	\$21,986.26	\$18,468.46	\$13,191.76
							Length:	395.75	\$21,986.26	\$18,468.46	\$13,191.76
COOMBS CIRCLE											
COOMBS CIRCLE	Odd	Yes	2	Asphalt	Fair	Surface Treatment	4	618.45	\$34,358.41	\$28,861.07	\$20,615.05
COOMBS CIRCLE	Even	Yes	2	Asphalt	Fair	Surface Treatment	4	690.84	\$38,379.95	\$32,239.16	\$23,027.97
							Length:	1,309.29	\$72,738.37	\$61,100.23	\$43,643.02
CUSHING AVENUE											
CUSHING AVE-03	Odd	Yes	6	None	Fair	Surface Treatment	4	109.34	\$6,074.41	\$5,102.51	\$3,644.65
							Length:	109.34	\$6,074.41	\$5,102.51	\$3,644.65
DENNETT DRIVE											
DENNETT DR-01	Odd	Yes	8	None	Poor	Rehabilitation	4	152.21	\$8,455.88	\$7,102.94	\$5,073.53
DENNETT DR-02	Odd	Yes	8	None	Poor	Rehabilitation	4	132.44	\$7,357.81	\$6,180.56	\$4,414.69
DENNETT DR-03	Odd	Yes	8	None	Gap	Gap	4	625.24	\$34,735.80	\$0.00	\$0.00
DENNETT DR-01	Even	Yes	6	None	Poor	Rehabilitation	4	154.32	\$8,573.12	\$7,201.42	\$5,143.87
DENNETT DR-04	Even	Yes	6	None	Poor	Rehabilitation	4	172.38	\$9,576.80	\$8,044.51	\$5,746.08
							Length:	1,236.59	\$68,699.42	\$28,529.44	\$20,378.17
DREW STREET											
DREW ST-01	Even	Yes	4	None	Poor	Rehabilitation	4	973.14	\$54,063.29	\$45,413.17	\$32,437.98
DREW ST-02	Even	Yes	4	None	Poor	Rehabilitation	4	289.07	\$16,059.44	\$13,489.93	\$9,635.66
							Length:	1,262.21	\$70,122.73	\$58,903.10	\$42,073.64
EVERETTE DRIVE											
EVERETTE DR-01	Even	Yes	2	CC Berm	Gap	Gap	4	155.55	\$8,641.65	\$0.00	\$0.00
							Length:	155.55	\$8,641.65	\$0.00	\$0.00
FERRY ROAD											
FERRY RD-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	145.94	\$8,107.93	\$6,810.66	\$4,864.76
FERRY RD-04	Odd	Yes	2	Concrete	Fair	Surface Treatment	2	140.07	\$3,890.89	\$3,268.34	\$2,334.53
FERRY RD-15	Odd	No	0	Granite	New	Defer Maintenance	4	789.21	\$0.00	\$0.00	\$0.00
FERRY RD-16	Odd	No	0	Granite	New	Defer Maintenance	4	353.96	\$0.00	\$0.00	\$0.00
FERRY RD-17	Odd	No	0	Granite	New	Defer Maintenance	4	196.98	\$0.00	\$0.00	\$0.00
FERRY RD-18	Odd	No	0	Granite	New	Defer Maintenance	4	352.05	\$0.00	\$0.00	\$0.00
FERRY RD-19	Odd	No	0	Granite	New	Defer Maintenance	4	329.33	\$0.00	\$0.00	\$0.00
FERRY RD-21	Odd	No	0	Granite	New	Defer Maintenance	4	116.53	\$0.00	\$0.00	\$0.00
FERRY RD-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	51.76	\$2,875.76	\$2,415.64	\$1,725.46
FERRY RD-02	Even	Yes	2	Concrete	Fair	Surface Treatment	2	229.98	\$6,388.47	\$5,366.31	\$3,833.08
FERRY RD-03	Even	Yes	2	Concrete	Fair	Surface Treatment	2	202.53	\$5,625.94	\$4,725.79	\$3,375.56
FERRY RD-04	Even	Yes	2	Concrete	Fair	Surface Treatment	2	141.84	\$3,940.02	\$3,309.61	\$2,364.01

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
FERRY RD-05	Even	Yes	2	Concrete	Fair	Surface Treatment	2	56.83	\$1,578.50	\$1,325.94	\$947.10
FERRY RD-18	Even	No	0	Granite	New	Defer Maintenance	4	80.05	\$0.00	\$0.00	\$0.00
FERRY RD-19	Even	No	0	Granite	New	Defer Maintenance	4	344.99	\$0.00	\$0.00	\$0.00
FERRY RD-21	Even	No	0	Granite	New	Defer Maintenance	4	81.89	\$0.00	\$0.00	\$0.00
FERRY RD-22	Even	No	0	Granite	New	Defer Maintenance	4	91.12	\$0.00	\$0.00	\$0.00
							Length:	3,705.08	\$32,407.50	\$27,222.30	\$19,444.50
MOSELEY AVENUE											
MOSELEY AVE-02	Even	Yes	2	None	Fair	Surface Treatment	6	121.11	\$10,092.13	\$8,477.39	\$6,055.28
MOSELEY AVE-03	Even	Yes	6	None	Poor	Rehabilitation	2	236.44	\$6,567.76	\$5,516.92	\$3,940.65
MOSELEY AVE-05	Even	Yes	6	None	Fair	Surface Treatment	2	277.45	\$7,706.83	\$6,473.74	\$4,624.10
							Length:	634.99	\$24,366.72	\$20,468.04	\$14,620.03
MOULTON STREET											
MOULTON ST-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	3	164.87	\$6,869.71	\$5,770.56	\$4,121.83
MOULTON ST-01	Even	Yes	2	Concrete	Poor	Rehabilitation	2	488.65	\$13,573.74	\$11,401.94	\$8,144.24
MOULTON ST-02	Even	Yes	2	Concrete	Fair	Surface Treatment	2	295.42	\$8,206.04	\$6,893.07	\$4,923.62
MOULTON ST-03	Even	Yes	2	Concrete	Fair	Surface Treatment	2	96.85	\$2,690.18	\$2,259.75	\$1,614.11
							Length:	1,045.79	\$31,339.67	\$26,325.32	\$18,803.80
PHILLIPS DRIVE											
PHILLIPS DR-01	Even	Yes	4	None	Poor	Rehabilitation	4	252.35	\$14,019.19	\$11,776.12	\$8,411.51
PHILLIPS DR-02	Even	Yes	4	None	Poor	Rehabilitation	4	203.04	\$11,279.98	\$9,475.18	\$6,767.99
PHILLIPS DR-03	Even	Yes	4	None	Poor	Rehabilitation	4	226.41	\$12,578.52	\$10,565.95	\$7,547.11
PHILLIPS DR-03	Even	Yes	3	None	Poor	Rehabilitation	4	274.26	\$15,236.49	\$12,798.65	\$9,141.90
PHILLIPS DR-04	Even	Yes	4	None	Poor	Rehabilitation	4	405.87	\$22,548.42	\$18,940.68	\$13,529.05
PHILLIPS DR-04	Even	Yes	4	None	Gap	Gap	4	191.77	\$10,654.15	\$0.00	\$0.00
PHILLIPS DR-05	Even	Yes	2	None	Gap	Gap	4	75.98	\$4,221.23	\$0.00	\$0.00
PHILLIPS DR-05	Even	Yes	4	None	Poor	Rehabilitation	4	277.85	\$15,436.23	\$12,966.43	\$9,261.74
PHILLIPS DR-06	Even	Yes	4	None	Gap	Gap	4	76.22	\$4,234.55	\$0.00	\$0.00
PHILLIPS DR-06	Even	Yes	4	None	Poor	Rehabilitation	4	131.81	\$7,322.92	\$6,151.25	\$4,393.75
							Length:	2,115.57	\$117,531.68	\$82,674.27	\$59,053.05
PINE HILL ROAD											
PINE HILL RD-01	Odd	No	0	Granite	New	Defer Maintenance	4	348.06	\$0.00	\$0.00	\$0.00
PINE HILL RD-01	Even	No	0	Asphalt	New	Defer Maintenance	4	329.67	\$0.00	\$0.00	\$0.00
							Length:	677.73	\$0.00	\$0.00	\$0.00
RYAN STREET											
RYAN ST	Odd	Yes	2	None	Poor	Rehabilitation	4	369.19	\$20,510.50	\$17,228.82	\$12,306.30
							Length:	369.19	\$20,510.50	\$17,228.82	\$12,306.30
SULLIVAN DRIVE											
SULLIVAN DR	Even	Yes	3	None	Gap	Gap	4	67.95	\$3,774.80	\$0.00	\$0.00
SULLIVAN DR	Even	Yes	3	None	Gap	Gap	4	48.97	\$2,720.76	\$0.00	\$0.00

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
SULLIVAN DR	Even	Yes	3	None	Poor	Rehabilitation	4	781.23	\$43,401.82	\$36,457.53	\$26,041.09
							Length:	898.15	\$49,897.38	\$36,457.53	\$26,041.09
TURKEY HILL ROAD											
TURKEY HILL RD-03	Even	Yes	2	CC Berm	Fair	Surface Treatment	4	286.88	\$15,937.62	\$13,387.60	\$9,562.57
TURKEY HILL RD-04	Even	Yes	2	CC Berm	Fair	Surface Treatment	4	326.51	\$18,139.20	\$15,236.93	\$10,883.52
TURKEY HILL RD-05	Even	Yes	2	CC Berm	Fair	Surface Treatment	4	472.80	\$26,266.87	\$22,064.17	\$15,760.12
TURKEY HILL RD-06	Even	Yes	2	CC Berm	Good	Routine Maintenance	4	601.55	\$8,020.62	\$8,020.62	\$8,020.62
TURKEY HILL RD-08	Even	Yes	2	CC Berm	Good	Routine Maintenance	4	337.68	\$4,502.37	\$4,502.37	\$4,502.37
TURKEY HILL RD-09	Even	Yes	2	CC Berm	Good	Routine Maintenance	4	252.64	\$3,368.56	\$3,368.56	\$3,368.56
TURKEY HILL RD-11	Even	Yes	2	CC Berm	Good	Routine Maintenance	4	179.15	\$2,388.70	\$2,388.70	\$2,388.70
TURKEY HILL RD-12	Even	Yes	2	CC Berm	Fair	Surface Treatment	4	75.93	\$4,218.32	\$3,543.39	\$2,530.99
TURKEY HILL RD-13	Even	Yes	2	CC Berm	Good	Routine Maintenance	4	272.97	\$3,639.57	\$3,639.57	\$3,639.57
TURKEY HILL RD-14	Even	Yes	2	CC Berm	Good	Routine Maintenance	4	210.50	\$2,806.67	\$2,806.67	\$2,806.67
TURKEY HILL RD-14	Even	Yes	5	CC Berm	Fair	Surface Treatment	4	848.66	\$47,147.60	\$39,603.98	\$28,288.56
TURKEY HILL RD-14	Even	Yes	2	Asphalt	Good	Routine Maintenance	4	190.16	\$2,535.42	\$2,535.42	\$2,535.42
							Length:	4,055.42	\$138,971.52	\$121,097.98	\$94,287.68
WINDWARD DRIVE											
WINDWARD DR	Even	Yes	2	Asphalt	Fair	Surface Treatment	4	1,767.72	\$98,206.69	\$82,493.62	\$58,924.02
WINDWARD DR	Even	Yes	2	Asphalt	Gap	Gap	4	38.74	\$2,152.39	\$0.00	\$0.00
WINDWARD DR	Even	Yes	2	Asphalt	Gap	Gap	4	39.11	\$2,172.51	\$0.00	\$0.00
							Length:	1,845.57	\$102,531.60	\$82,493.62	\$58,924.02
WOODMAN WAY											
WOODMAN WY-01	Even	Yes	4	CC Berm	Fair	Surface Treatment	4	101.92	\$5,661.98	\$4,756.06	\$3,397.19
WOODMAN WY-02	Even	Yes	4	CC Berm	Fair	Surface Treatment	4	624.06	\$34,669.96	\$29,122.77	\$20,801.98
							Length:	725.97	\$40,331.94	\$33,878.83	\$24,199.17

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Condition and Estimated Replacement Costs - Brick (Replace With Brick)

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Ward: 1											
BEACON AVENUE											
BEACON AVE-04	Odd	Yes	2	Granite	Good	Routine Maintenance	4	126.10	\$1,681.29	\$3,362.59	\$1,681.29
							Length:	126.10	\$1,681.29	\$3,362.59	\$1,681.29
BECK STREET											
BECK ST-01	Odd	No	0	Granite	Fair	Surface Treatment	5	246.86	\$26,743.50	\$18,514.73	\$18,514.73
BECK ST-02	Odd	No	0	Granite	Fair	Surface Treatment	4	65.74	\$5,697.75	\$3,944.59	\$3,944.59
BECK ST-03	Odd	No	0	Granite	Fair	Surface Treatment	4	160.48	\$13,908.30	\$9,628.82	\$9,628.82
							Length:	473.09	\$46,349.54	\$32,088.14	\$32,088.14
BROMFIELD STREET											
BROMFIELD ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	56.89	\$758.60	\$1,517.20	\$758.60
BROMFIELD ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	71.26	\$6,175.48	\$4,275.33	\$4,275.33
BROMFIELD ST-01	Even	No	0	Granite	Fair	Surface Treatment	6	247.11	\$32,124.48	\$22,240.03	\$22,240.03
BROMFIELD ST-02	Even	No	0	Granite	Fair	Surface Treatment	8	122.51	\$21,234.85	\$14,701.05	\$14,701.05
							Length:	497.77	\$60,293.41	\$42,733.61	\$41,975.01
FEDERAL STREET											
FEDERAL ST-09	Odd	No	0	Granite	Good	Routine Maintenance	6	159.19	\$3,183.83	\$6,367.67	\$3,183.83
FEDERAL ST-09	Odd	No	0	Granite	Good	Routine Maintenance	4	361.21	\$4,816.18	\$9,632.36	\$4,816.18
							Length:	520.41	\$8,000.01	\$16,000.03	\$8,000.01
FRANKLIN STREET											
FRANKLIN ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	68.83	\$917.70	\$1,835.41	\$917.70
							Length:	68.83	\$917.70	\$1,835.41	\$917.70
HANCOCK STREET											
HANCOCK ST-01	Odd	Yes	2	Mix	Good	Routine Maintenance	4	160.28	\$2,137.03	\$4,274.06	\$2,137.03
HANCOCK ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	51.88	\$691.80	\$1,383.60	\$691.80
							Length:	212.16	\$2,828.83	\$5,657.65	\$2,828.83
HIGH STREET											
HIGH ST-44	Even	Yes	2	Mix	Fair	Surface Treatment	4	96.32	\$8,348.09	\$5,779.44	\$5,779.44
HIGH ST-45	Even	No	0	Granite	Fair	Surface Treatment	8	164.90	\$28,582.38	\$19,787.80	\$19,787.80
							Length:	261.22	\$36,930.47	\$25,567.25	\$25,567.25
LIME STREET											
LIME ST-08	Even	No	0	Granite	Good	Routine Maintenance	4	32.89	\$438.48	\$876.95	\$438.48

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
							Length:	32.89	\$438.48	\$876.95	\$438.48
LUNT STREET											
LUNT ST	Even	No	0	Mix	Good	Routine Maintenance	4	209.13	\$2,788.40	\$5,576.79	\$2,788.40
							Length:	209.13	\$2,788.40	\$5,576.79	\$2,788.40
MADISON STREET											
MADISON ST-02	Odd	No	0	Granite	Fair	Surface Treatment	4	105.10	\$9,108.79	\$6,306.08	\$6,306.08
MADISON ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	66.19	\$882.55	\$1,765.09	\$882.55
							Length:	171.29	\$9,991.33	\$8,071.17	\$7,188.63
MARLBORO STREET											
MARLBORO ST-03	Odd	Yes	2	Granite	Fair	Surface Treatment	4	158.21	\$13,711.76	\$9,492.75	\$9,492.75
MARLBORO ST-04	Odd	No	0	Mix	Fair	Surface Treatment	4	154.46	\$13,386.39	\$9,267.50	\$9,267.50
MARLBORO ST-05	Odd	Yes	2	Granite	Good	Routine Maintenance	4	83.18	\$1,109.05	\$2,218.11	\$1,109.05
MARLBORO ST-09	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	80.69	\$6,993.55	\$4,841.69	\$4,841.69
MARLBORO ST-05	Even	Yes	2	Granite	Poor	Rehabilitation	4	62.75	\$5,438.75	\$4,880.93	\$3,765.29
							Length:	539.30	\$40,639.50	\$30,700.98	\$28,476.29
MERRIMAC STREET											
MERRIMAC ST-32	Even	No	0	Granite	Fair	Surface Treatment	5	92.08	\$9,974.87	\$6,905.68	\$6,905.68
							Length:	92.08	\$9,974.87	\$6,905.68	\$6,905.68
MILK STREET											
MILK ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	59.18	\$789.12	\$1,578.24	\$789.12
MILK ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	59.75	\$796.68	\$1,593.35	\$796.68
MILK ST-03	Odd	No	0	Granite	Good	Routine Maintenance	4	65.76	\$876.75	\$1,753.51	\$876.75
MILK ST-03	Odd	No	0	Granite	Good	Routine Maintenance	4	63.51	\$846.74	\$1,693.48	\$846.74
							Length:	248.20	\$3,309.29	\$6,618.57	\$3,309.29
NEPTUNE STREET											
NEPTUNE ST	Odd	No	0	Granite	Good	Routine Maintenance	4	69.07	\$920.89	\$1,841.79	\$920.89
NEPTUNE ST	Even	No	0	Granite	Good	Routine Maintenance	4	100.77	\$1,343.54	\$2,687.07	\$1,343.54
							Length:	169.83	\$2,264.43	\$4,528.86	\$2,264.43
OAK STREET											
OAK ST-02	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	40.32	\$537.57	\$1,075.15	\$537.57
OAK ST-03	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	72.53	\$967.01	\$1,934.01	\$967.01
OAK ST-01	Even	Yes	2	Granite	Good	Routine Maintenance	4	193.95	\$2,585.96	\$5,171.92	\$2,585.96
							Length:	306.79	\$4,090.54	\$8,181.09	\$4,090.54
PINE STREET											
PINE ST	Even	No	0	Mix	Good	Routine Maintenance	5	268.42	\$4,473.64	\$8,947.27	\$4,473.64
							Length:	268.42	\$4,473.64	\$8,947.27	\$4,473.64
PURCHASE STREET											

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
PURCHASE ST-04	Odd	No	0	Granite	Fair	Surface Treatment	5	55.60	\$6,023.05	\$4,169.81	\$4,169.81
PURCHASE ST-05	Odd	No	0	Granite	Fair	Surface Treatment	6	231.78	\$30,131.20	\$20,860.06	\$20,860.06
PURCHASE ST-06	Odd	No	0	Granite	Fair	Surface Treatment	6	73.16	\$9,510.49	\$6,584.18	\$6,584.18
PURCHASE ST-07	Odd	No	0	Granite	Fair	Surface Treatment	4	52.20	\$4,523.97	\$3,131.98	\$3,131.98
PURCHASE ST-01	Even	Yes	2	Granite	Fair	Surface Treatment	4	74.94	\$6,494.43	\$4,496.14	\$4,496.14
PURCHASE ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	245.50	\$21,276.26	\$14,729.72	\$14,729.72
PURCHASE ST-05	Even	Yes	2	Granite	Good	Routine Maintenance	4	47.94	\$639.26	\$1,278.51	\$639.26
Length:								781.11	\$78,598.66	\$55,250.41	\$54,611.15

SHANDEL DRIVE

SHANDEL DR-03	Odd	No	0	CC Berm	Good	Routine Maintenance	4	144.22	\$1,922.90	\$3,845.79	\$1,922.90
Length:								144.22	\$1,922.90	\$3,845.79	\$1,922.90

SHIP STREET

SHIP ST	Even	No	0	Granite	Good	Routine Maintenance	4	80.05	\$1,067.33	\$2,134.67	\$1,067.33
SHIP ST	Even	No	0	Granite	Fair	Surface Treatment	4	65.53	\$5,679.68	\$3,932.09	\$3,932.09
SHIP ST	Even	No	0	Mix	Good	Routine Maintenance	4	65.68	\$875.70	\$1,751.39	\$875.70
Length:								211.26	\$7,622.71	\$7,818.15	\$5,875.12

SMITH'S STREET

SMITH'S ST	Odd	No	0	Mix	Good	Routine Maintenance	4	313.67	\$4,182.26	\$8,364.51	\$4,182.26
SMITH'S ST	Odd	No	0	Granite	Good	Routine Maintenance	4	61.85	\$824.60	\$1,649.20	\$824.60
SMITH'S ST	Even	No	0	Granite	Gap	Gap	4	131.09	\$11,361.55	\$0.00	\$0.00
SMITH'S ST	Even	No	0	Granite	Good	Routine Maintenance	4	182.84	\$2,437.88	\$4,875.75	\$2,437.88
Length:								689.45	\$18,806.28	\$14,889.47	\$7,444.73

SOUTH POND STREET

SOUTH POND ST	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	59.26	\$790.15	\$1,580.31	\$790.15
Length:								59.26	\$790.15	\$1,580.31	\$790.15

UNION STREET

UNION ST-03	Odd	No	0	Granite	Good	Routine Maintenance	4	87.27	\$1,163.66	\$2,327.32	\$1,163.66
UNION ST-03	Odd	No	0	Granite	Good	Routine Maintenance	4	101.13	\$1,348.41	\$2,696.83	\$1,348.41
Length:								188.41	\$2,512.08	\$5,024.15	\$2,512.08

WATER STREET

WATER ST-06	Odd	No	0	Granite	New	Defer Maintenance	4	258.82	\$0.00	\$0.00	\$0.00
WATER ST-14	Odd	No	0	Granite	Good	Routine Maintenance	4	45.52	\$606.91	\$1,213.82	\$606.91
WATER ST-06	Even	No	0	Granite	Good	Routine Maintenance	4	218.68	\$2,915.79	\$5,831.58	\$2,915.79
WATER ST-07	Even	No	0	Mix	Good	Routine Maintenance	4	104.89	\$1,398.52	\$2,797.03	\$1,398.52
WATER ST-09	Even	No	0	Granite	Good	Routine Maintenance	4	142.77	\$1,903.59	\$3,807.17	\$1,903.59
Length:								770.68	\$6,824.80	\$13,649.60	\$6,824.80

Ward: 2

ALLEN STREET

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
ALLEN ST	Even	No	0	Granite	Fair	Surface Treatment	4	282.49	\$24,482.54	\$16,949.45	\$16,949.45
							Length:	282.49	\$24,482.54	\$16,949.45	\$16,949.45
ATWOOD STREET											
ATWOOD ST	Odd	No	0	Granite	Good	Routine Maintenance	4	217.60	\$2,901.39	\$5,802.78	\$2,901.39
ATWOOD ST	Even	No	0	Granite	Fair	Surface Treatment	4	131.35	\$11,383.54	\$7,880.91	\$7,880.91
ATWOOD ST	Even	No	0	Granite	Fair	Surface Treatment	4	219.19	\$18,996.42	\$13,151.37	\$13,151.37
							Length:	568.14	\$33,281.35	\$26,835.07	\$23,933.67
BECK STREET											
BECK ST-01	Even	No	0	Granite	Good	Routine Maintenance	5	244.69	\$4,078.20	\$8,156.39	\$4,078.20
BECK ST-02	Even	No	0	Granite	Good	Routine Maintenance	5	123.20	\$2,053.30	\$4,106.60	\$2,053.30
BECK ST-03	Even	No	0	Granite	Good	Routine Maintenance	4	179.69	\$2,395.91	\$4,791.82	\$2,395.91
							Length:	547.58	\$8,527.41	\$17,054.81	\$8,527.41
BROMFIELD STREET											
BROMFIELD ST-07	Even	Yes	2	Granite	Good	Routine Maintenance	4	87.72	\$1,169.64	\$2,339.28	\$1,169.64
							Length:	87.72	\$1,169.64	\$2,339.28	\$1,169.64
BROWN STREET											
BROWN ST	Odd	Yes	4	Granite	Good	Routine Maintenance	4	144.29	\$1,923.83	\$3,847.67	\$1,923.83
							Length:	144.29	\$1,923.83	\$3,847.67	\$1,923.83
FAIR STREET											
FAIR ST-02	Odd	No	0	Granite	New	Defer Maintenance	6	59.19	\$0.00	\$0.00	\$0.00
FAIR ST-03	Odd	No	0	Granite	Good	Routine Maintenance	4	40.53	\$540.38	\$1,080.76	\$540.38
FAIR ST-04	Odd	No	0	Granite	Good	Routine Maintenance	4	114.47	\$1,526.23	\$3,052.46	\$1,526.23
FAIR ST-05	Odd	No	0	Granite	Good	Routine Maintenance	4	99.84	\$1,331.26	\$2,662.52	\$1,331.26
FAIR ST-08	Odd	No	0	Granite	Good	Routine Maintenance	4	393.44	\$5,245.88	\$10,491.76	\$5,245.88
							Length:	707.47	\$8,643.75	\$17,287.51	\$8,643.75
FEDERAL STREET											
FEDERAL ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	353.40	\$30,627.69	\$21,203.79	\$21,203.79
FEDERAL ST-02	Odd	Yes	2	Granite	New	Defer Maintenance	4	52.24	\$0.00	\$0.00	\$0.00
FEDERAL ST-03	Odd	No	0	Granite	Fair	Surface Treatment	4	44.44	\$3,851.56	\$2,666.47	\$2,666.47
FEDERAL ST-04	Odd	No	0	Granite	Good	Routine Maintenance	4	59.72	\$796.30	\$1,592.60	\$796.30
FEDERAL ST-05	Odd	Yes	2	Granite	New	Defer Maintenance	4	45.28	\$0.00	\$0.00	\$0.00
FEDERAL ST-05	Odd	Yes	2	Granite	Good	Routine Maintenance	4	24.73	\$329.67	\$659.34	\$329.67
FEDERAL ST-06	Odd	No	0	Granite	New	Defer Maintenance	4	116.14	\$0.00	\$0.00	\$0.00
FEDERAL ST-07	Odd	No	0	Granite	New	Defer Maintenance	4	75.45	\$0.00	\$0.00	\$0.00
FEDERAL ST-08	Odd	No	0	Granite	Good	Routine Maintenance	6	78.73	\$1,574.53	\$3,149.07	\$1,574.53
FEDERAL ST-08	Odd	No	0	Granite	Good	Routine Maintenance	6	38.41	\$768.16	\$1,536.31	\$768.16
FEDERAL ST-02	Even	Yes	2	Granite	Good	Routine Maintenance	4	61.22	\$816.29	\$1,632.57	\$816.29
FEDERAL ST-02	Even	No	0	Granite	Poor	Rehabilitation	4	331.70	\$28,747.60	\$25,799.13	\$19,902.18
FEDERAL ST-04	Even	No	0	Granite	Poor	Rehabilitation	4	74.25	\$6,435.24	\$5,775.21	\$4,455.16

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
FEDERAL ST-06	Even	No	0	Granite	New	Defer Maintenance	4	127.20	\$0.00	\$0.00	\$0.00
FEDERAL ST-08	Even	No	0	Granite	New	Defer Maintenance	6	53.91	\$0.00	\$0.00	\$0.00
FEDERAL ST-10	Even	No	0	Granite	Good	Routine Maintenance	4	284.22	\$3,789.55	\$7,579.10	\$3,789.55
							Length:	1,821.04	\$77,736.59	\$71,593.59	\$56,302.10
FRUIT STREET											
FRUIT ST	Odd	No	0	Granite	Good	Routine Maintenance	4	526.36	\$7,018.13	\$14,036.26	\$7,018.13
FRUIT ST	Even	No	0	Granite	Good	Routine Maintenance	4	525.05	\$7,000.68	\$14,001.35	\$7,000.68
							Length:	1,051.41	\$14,018.81	\$28,037.61	\$14,018.81
GREENLEAF STREET											
GREENLEAF ST-02	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	113.49	\$9,836.00	\$8,827.18	\$6,809.54
GREENLEAF ST-04	Odd	No	0	Granite	Gap	Gap	7	62.46	\$9,472.82	\$0.00	\$0.00
							Length:	175.95	\$19,308.81	\$8,827.18	\$6,809.54
HIGH STREET											
HIGH ST-36	Odd	Yes	4	Granite	Good	Routine Maintenance	4	117.00	\$1,559.98	\$3,119.96	\$1,559.98
HIGH ST-38	Odd	Yes	4	Granite	Poor	Rehabilitation	4	120.42	\$10,436.20	\$9,365.82	\$7,225.06
HIGH ST-38	Odd	Yes	4	Granite	Poor	Rehabilitation	4	154.88	\$13,423.03	\$12,046.31	\$9,292.87
HIGH ST-39	Odd	Yes	4	Granite	Fair	Surface Treatment	4	405.61	\$35,152.49	\$24,336.34	\$24,336.34
HIGH ST-40	Odd	Yes	4	Granite	Fair	Surface Treatment	4	167.50	\$14,516.62	\$10,049.97	\$10,049.97
HIGH ST-41	Odd	Yes	3	Granite	Fair	Surface Treatment	5	189.60	\$20,539.56	\$14,219.70	\$14,219.70
HIGH ST-43	Odd	No	0	Granite	Good	Routine Maintenance	4	131.74	\$1,756.51	\$3,513.02	\$1,756.51
HIGH ST-44	Odd	Yes	2	Granite	Fair	Surface Treatment	4	174.06	\$15,085.41	\$10,443.74	\$10,443.74
HIGH ST-45	Odd	Yes	2	Granite	Good	Routine Maintenance	4	83.67	\$1,115.53	\$2,231.07	\$1,115.53
HIGH ST-38	Even	No	0	Granite	Fair	Surface Treatment	6	317.86	\$41,322.10	\$28,607.61	\$28,607.61
HIGH ST-39	Even	No	0	Granite	Fair	Surface Treatment	6	338.83	\$44,048.32	\$30,494.99	\$30,494.99
HIGH ST-40	Even	No	0	Granite	Fair	Surface Treatment	8	314.24	\$54,467.55	\$37,708.30	\$37,708.30
HIGH ST-40	Even	Yes	2	Granite	Good	Routine Maintenance	4	91.74	\$1,223.14	\$2,446.29	\$1,223.14
HIGH ST-41	Even	No	0	Granite	Fair	Surface Treatment	8	256.51	\$44,460.94	\$30,780.65	\$30,780.65
HIGH ST-42	Even	No	0	Granite	Fair	Surface Treatment	8	184.54	\$31,986.87	\$22,144.75	\$22,144.75
HIGH ST-43	Even	Yes	2	Granite	Good	Routine Maintenance	4	117.73	\$1,569.73	\$3,139.46	\$1,569.73
							Length:	3,165.91	\$332,663.99	\$244,647.98	\$232,528.88
HORTON STREET											
HORTON ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	103.03	\$1,373.73	\$2,747.46	\$1,373.73
HORTON ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	55.53	\$740.33	\$1,480.67	\$740.33
HORTON ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	50.31	\$670.86	\$1,341.72	\$670.86
							Length:	208.87	\$2,784.92	\$5,569.85	\$2,784.92
INDEPENDENT STREET											
INDEPENDENT ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	55.47	\$739.54	\$1,479.09	\$739.54
INDEPENDENT ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	45.36	\$3,930.94	\$2,721.42	\$2,721.42
							Length:	100.82	\$4,670.49	\$4,200.51	\$3,460.97

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
LIBERTY STREET											
LIBERTY ST-02	Odd	No	0	Granite	Fair	Surface Treatment	4	60.64	\$5,255.45	\$3,638.39	\$3,638.39
Length:								60.64	\$5,255.45	\$3,638.39	\$3,638.39
LIME STREET											
LIME ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	81.15	\$7,033.01	\$4,869.01	\$4,869.01
LIME ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	59.45	\$792.73	\$1,585.46	\$792.73
LIME ST-01	Even	Yes	3	Granite	Fair	Surface Treatment	6	233.45	\$30,347.98	\$21,010.14	\$21,010.14
LIME ST-07	Even	No	0	Granite	Good	Routine Maintenance	4	82.90	\$1,105.31	\$2,210.61	\$1,105.31
Length:								456.95	\$39,279.03	\$29,675.22	\$27,777.19
MIDDLE STREET											
MIDDLE ST-03	Odd	No	0	Granite	Good	Routine Maintenance	4	31.95	\$425.99	\$851.98	\$425.99
MIDDLE ST-04	Odd	No	0	Granite	Good	Routine Maintenance	4	79.04	\$1,053.81	\$2,107.62	\$1,053.81
MIDDLE ST-04	Even	No	0	Granite	New	Defer Maintenance	4	208.40	\$0.00	\$0.00	\$0.00
MIDDLE ST-04	Even	No	0	Granite	New	Defer Maintenance	4	131.79	\$0.00	\$0.00	\$0.00
Length:								451.18	\$1,479.80	\$2,959.60	\$1,479.80
MILK STREET											
MILK ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	135.56	\$1,807.41	\$3,614.81	\$1,807.41
MILK ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	82.47	\$1,099.55	\$2,199.09	\$1,099.55
MILK ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	59.88	\$798.43	\$1,596.85	\$798.43
MILK ST-03	Even	No	0	Granite	Good	Routine Maintenance	4	108.42	\$1,445.64	\$2,891.29	\$1,445.64
Length:								386.33	\$5,151.02	\$10,302.05	\$5,151.02
ORANGE STREET											
ORANGE ST	Odd	No	0	Granite	Poor	Rehabilitation	5	442.82	\$47,972.35	\$43,052.11	\$33,211.63
ORANGE ST	Even	No	0	Granite	Good	Routine Maintenance	6	70.15	\$1,403.09	\$2,806.18	\$1,403.09
Length:								512.98	\$49,375.44	\$45,858.29	\$34,614.72
PARSONS STREET											
PARSONS ST	Odd	Yes	2	Granite	Fair	Surface Treatment	4	272.38	\$23,605.90	\$16,342.55	\$16,342.55
PARSONS ST	Odd	Yes	2	Granite	Fair	Surface Treatment	4	270.13	\$23,411.01	\$16,207.62	\$16,207.62
PARSONS ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	191.37	\$16,585.56	\$11,482.31	\$11,482.31
PARSONS ST	Even	No	0	Granite	Fair	Surface Treatment	8	75.02	\$13,003.23	\$9,002.23	\$9,002.23
Length:								808.89	\$76,605.69	\$53,034.71	\$53,034.71
POND STREET											
POND ST-01	Odd	Yes	6	Granite	Fair	Surface Treatment	4	238.17	\$20,641.70	\$14,290.41	\$14,290.41
Length:								238.17	\$20,641.70	\$14,290.41	\$14,290.41
PROSPECT STREET											
PROSPECT ST-03	Odd	No	0	Granite	Good	Routine Maintenance	5	50.01	\$833.49	\$1,666.99	\$833.49
PROSPECT ST-05	Odd	No	0	Granite	Fair	Surface Treatment	4	240.66	\$20,857.25	\$14,439.63	\$14,439.63
PROSPECT ST-03	Even	No	0	Granite	Fair	Surface Treatment	4	34.20	\$2,963.81	\$2,051.87	\$2,051.87

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
PROSPECT ST-03	Even	No	0	Granite	Fair	Surface Treatment	4	50.91	\$4,411.96	\$3,054.44	\$3,054.44
PROSPECT ST-04	Even	No	0	Granite	Fair	Surface Treatment	4	40.78	\$3,534.34	\$2,446.85	\$2,446.85
PROSPECT ST-05	Even	No	0	Granite	Fair	Surface Treatment	4	67.18	\$5,822.00	\$4,030.61	\$4,030.61
Length:								483.73	\$38,422.85	\$27,690.39	\$26,856.89
SCHOOL STREET											
SCHOOL ST	Odd	No	0	Granite	Fair	Surface Treatment	5	547.24	\$59,284.62	\$41,043.20	\$41,043.20
Length:								547.24	\$59,284.62	\$41,043.20	\$41,043.20
SPRING STREET											
SPRING ST	Odd	No	0	Granite	Fair	Surface Treatment	4	136.01	\$11,787.40	\$8,160.51	\$8,160.51
SPRING ST	Odd	No	0	Granite	Poor	Rehabilitation	4	283.01	\$24,527.14	\$22,011.53	\$16,980.33
SPRING ST	Even	No	0	Granite	Good	Routine Maintenance	5	222.00	\$3,699.98	\$7,399.97	\$3,699.98
SPRING ST	Even	No	0	Granite	Good	Routine Maintenance	5	127.19	\$2,119.80	\$4,239.61	\$2,119.80
Length:								768.20	\$42,134.32	\$41,811.61	\$30,960.62
STATE STREET											
STATE ST-11	Odd	Yes	4	Granite	New	Defer Maintenance	4	38.40	\$0.00	\$0.00	\$0.00
STATE ST-12	Odd	No	0	Granite	Poor	Rehabilitation	6	86.54	\$11,250.30	\$10,096.42	\$7,788.67
STATE ST-13	Odd	Yes	4	Mix	Good	Routine Maintenance	4	78.11	\$1,041.44	\$2,082.88	\$1,041.44
STATE ST-11	Even	Yes	2	Granite	New	Defer Maintenance	5	152.90	\$0.00	\$0.00	\$0.00
STATE ST-11	Even	Yes	2	Granite	Poor	Rehabilitation	4	293.41	\$25,428.67	\$22,820.60	\$17,604.46
STATE ST-12	Even	No	0	Granite	Poor	Rehabilitation	7	365.38	\$55,416.06	\$49,732.36	\$38,364.96
STATE ST-13	Even	No	0	Granite	Poor	Rehabilitation	7	109.78	\$16,649.89	\$14,942.21	\$11,526.85
Length:								1,124.52	\$109,786.36	\$99,674.47	\$76,326.38
TEMPLE STREET											
TEMPLE ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	105.69	\$1,409.14	\$2,818.29	\$1,409.14
TEMPLE ST-02	Odd	No	0	Granite	Good	Routine Maintenance	3	91.59	\$915.92	\$1,831.85	\$915.92
TEMPLE ST-02	Odd	No	0	Granite	Fair	Surface Treatment	3	66.27	\$4,307.79	\$2,982.32	\$2,982.32
Length:								263.55	\$6,632.86	\$7,632.45	\$5,307.39
TREMONT STREET											
TREMONT ST	Odd	No	0	Granite	Fair	Surface Treatment	4	61.26	\$5,308.89	\$3,675.39	\$3,675.39
TREMONT ST	Odd	No	0	Granite	Fair	Surface Treatment	4	89.79	\$7,781.41	\$5,387.13	\$5,387.13
TREMONT ST	Even	No	0	Granite	Fair	Surface Treatment	6	338.93	\$44,060.39	\$30,503.34	\$30,503.34
Length:								489.97	\$57,150.69	\$39,565.86	\$39,565.86
WATER STREET											
WATER ST-17	Odd	No	0	Granite	Good	Routine Maintenance	4	46.28	\$617.02	\$1,234.03	\$617.02
WATER ST-17	Odd	No	0	Granite	Good	Routine Maintenance	4	164.70	\$2,195.98	\$4,391.96	\$2,195.98
WATER ST-17	Odd	No	0	Granite	Good	Routine Maintenance	4	59.61	\$794.74	\$1,589.47	\$794.74
WATER ST-18	Odd	No	0	Granite	Good	Routine Maintenance	4	68.95	\$919.28	\$1,838.56	\$919.28
WATER ST-18	Odd	No	0	Granite	Good	Routine Maintenance	6	119.28	\$2,385.67	\$4,771.34	\$2,385.67
WATER ST-17	Even	No	0	Granite	Good	Routine Maintenance	4	332.66	\$4,435.52	\$8,871.04	\$4,435.52

BETA Group, Inc.

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
							Length: 791.47	\$11,348.21	\$22,696.41	\$11,348.21

Ward: 3

ATKINSON STREET

ATKINSON ST	Odd	No	0	Granite	Fair	Surface Treatment	4	51.72	\$4,482.36	\$3,103.17	\$3,103.17
ATKINSON ST	Even	No	0	Granite	Fair	Surface Treatment	4	92.81	\$8,043.65	\$5,568.68	\$5,568.68
ATKINSON ST	Even	No	0	Granite	Fair	Surface Treatment	4	53.63	\$4,648.25	\$3,218.02	\$3,218.02
							Length: 198.16	\$17,174.26	\$11,889.87	\$11,889.87	

AUBURN STREET

AUBURN ST-01	Even	No	0	Granite	Fair	Surface Treatment	5	100.15	\$10,849.43	\$7,511.14	\$7,511.14
AUBURN ST-01	Even	No	0	Granite	Fair	Surface Treatment	6	25.99	\$3,378.88	\$2,339.23	\$2,339.23
AUBURN ST-02	Even	Yes	4	Granite	Fair	Surface Treatment	4	34.72	\$3,008.68	\$2,082.93	\$2,082.93
							Length: 160.86	\$17,236.99	\$11,933.30	\$11,933.30	

BOARDMAN STREET

BOARDMAN ST-01	Odd	No	0	Granite	Poor	Rehabilitation	4	107.65	\$9,329.88	\$8,372.97	\$6,459.15
BOARDMAN ST-02	Odd	Yes	2	Concrete	Good	Routine Maintenance	2	87.63	\$584.22	\$1,168.45	\$584.22
BOARDMAN ST-03	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	23.54	\$2,039.98	\$1,830.75	\$1,412.29
BOARDMAN ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	118.33	\$1,577.79	\$3,155.58	\$1,577.79
BOARDMAN ST-02	Even	No	0	Granite	Poor	Rehabilitation	4	105.12	\$9,110.20	\$8,175.82	\$6,307.06
BOARDMAN ST-03	Even	Yes	2	Granite	Good	Routine Maintenance	4	37.79	\$503.83	\$1,007.67	\$503.83
BOARDMAN ST-03	Even	Yes	2	Granite	Fair	Surface Treatment	4	112.39	\$9,740.46	\$6,743.40	\$6,743.40
BOARDMAN ST-03	Even	Yes	2	Granite	Good	Routine Maintenance	4	105.64	\$1,408.48	\$2,816.96	\$1,408.48
							Length: 698.09	\$34,294.85	\$33,271.60	\$24,996.23	

BROAD STREET

BROAD ST-01	Odd	No	4	Granite	Fair	Surface Treatment	8	125.54	\$21,759.60	\$15,064.34	\$15,064.34
BROAD ST-02	Odd	Yes	5	Granite	Good	Routine Maintenance	4	75.85	\$1,011.32	\$2,022.64	\$1,011.32
BROAD ST-02	Odd	Yes	5	Granite	Fair	Surface Treatment	4	163.11	\$14,136.59	\$9,786.87	\$9,786.87
							Length: 364.50	\$36,907.52	\$26,873.86	\$25,862.53	

BUCK STREET

BUCK ST-02	Odd	No	0	Granite	Fair	Surface Treatment	4	46.77	\$4,053.77	\$2,806.46	\$2,806.46
BUCK ST-02	Odd	No	0	Granite	Poor	Rehabilitation	5	65.52	\$7,097.98	\$6,369.98	\$4,913.99
BUCK ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	70.68	\$942.36	\$1,884.73	\$942.36
BUCK ST-02	Even	Yes	2	Granite	Good	Routine Maintenance	4	32.52	\$433.54	\$867.07	\$433.54
							Length: 215.49	\$12,527.65	\$11,928.24	\$9,096.34	

CARTER STREET

CARTER ST-05	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	34.35	\$2,977.14	\$2,671.80	\$2,061.10
CARTER ST-06	Odd	Yes	2	Mix	Fair	Surface Treatment	4	199.12	\$17,257.00	\$11,947.15	\$11,947.15
CARTER ST-02	Even	No	0	Granite	New	Defer Maintenance	5	27.27	\$0.00	\$0.00	\$0.00
							Length: 260.74	\$20,234.14	\$14,618.95	\$14,008.25	

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
CONGRESS STREET											
CONGRESS ST-01	Odd	No	0	Granite	Fair	Surface Treatment	5	177.28	\$19,205.35	\$13,296.01	\$13,296.01
								Length:	177.28	\$19,205.35	\$13,296.01
COURT STREET											
COURT ST	Odd	No	0	Granite	Poor	Rehabilitation	6	134.72	\$17,513.07	\$15,716.86	\$12,124.43
COURT ST	Even	No	0	Granite	Poor	Rehabilitation	5	408.15	\$44,216.64	\$39,681.60	\$30,611.52
								Length:	542.87	\$61,729.72	\$55,398.46
DOVE STREET											
DOVE ST	Odd	No	0	Concrete	Fair	Surface Treatment	4	206.79	\$17,922.11	\$12,407.61	\$12,407.61
DOVE ST	Even	No	0	Granite	New	Defer Maintenance	4	69.95	\$0.00	\$0.00	\$0.00
								Length:	276.74	\$17,922.11	\$12,407.61
EAGLE STREET											
EAGLE ST-02	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	67.88	\$905.02	\$1,810.03	\$905.02
EAGLE ST-02	Even	Yes	2	Granite	Good	Routine Maintenance	4	89.71	\$1,196.07	\$2,392.14	\$1,196.07
								Length:	157.58	\$2,101.09	\$4,202.18
GREEN STREET											
GREEN ST-01	Even	No	0	Granite	Good	Routine Maintenance	6	61.26	\$1,225.17	\$2,450.34	\$1,225.17
								Length:	61.26	\$1,225.17	\$2,450.34
HIGH STREET											
HIGH ST-20	Odd	No	0	Granite	Fair	Surface Treatment	5	83.83	\$9,081.21	\$6,286.99	\$6,286.99
HIGH ST-22	Odd	Yes	2	Granite	Fair	Surface Treatment	4	168.04	\$14,563.45	\$10,082.39	\$10,082.39
HIGH ST-25	Odd	No	0	Granite	Fair	Surface Treatment	6	207.89	\$27,026.27	\$18,710.50	\$18,710.50
HIGH ST-25	Odd	Yes	2	Granite	Fair	Surface Treatment	4	69.33	\$6,008.26	\$4,159.56	\$4,159.56
HIGH ST-29	Odd	No	0	Granite	Fair	Surface Treatment	8	33.22	\$5,758.00	\$3,986.31	\$3,986.31
HIGH ST-30	Odd	No	0	Granite	Fair	Surface Treatment	8	35.51	\$6,155.67	\$4,261.62	\$4,261.62
HIGH ST-18	Even	No	0	Granite	Poor	Rehabilitation	6	175.99	\$22,878.29	\$20,531.80	\$15,838.81
HIGH ST-19	Even	Yes	2	Granite	Fair	Surface Treatment	4	183.03	\$15,862.42	\$10,981.67	\$10,981.67
HIGH ST-20	Even	No	0	Granite	Fair	Surface Treatment	6	180.56	\$23,472.31	\$16,250.06	\$16,250.06
HIGH ST-22	Even	No	0	Granite	Fair	Surface Treatment	4	50.23	\$4,353.58	\$3,014.02	\$3,014.02
HIGH ST-23	Even	Yes	2	Granite	Fair	Surface Treatment	6	243.41	\$31,643.93	\$21,907.34	\$21,907.34
HIGH ST-24	Even	No	0	Granite	Fair	Surface Treatment	6	216.35	\$28,125.41	\$19,471.44	\$19,471.44
HIGH ST-25	Even	No	0	Granite	Fair	Surface Treatment	6	596.96	\$77,605.33	\$53,726.77	\$53,726.77
HIGH ST-26	Even	No	0	Granite	Fair	Surface Treatment	6	38.76	\$5,038.44	\$3,488.15	\$3,488.15
HIGH ST-29	Even	No	0	Granite	Poor	Rehabilitation	6	167.67	\$21,796.68	\$19,561.12	\$15,090.01
HIGH ST-30	Even	No	0	Granite	Fair	Surface Treatment	6	82.45	\$10,718.92	\$7,420.79	\$7,420.79
HIGH ST-31	Even	No	0	Granite	Poor	Rehabilitation	6	202.53	\$26,328.30	\$23,627.96	\$18,227.29
								Length:	2,735.75	\$336,416.47	\$247,468.48
JOHNSON STREET											

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
JOHNSON ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	33.16	\$2,874.08	\$1,989.75	\$1,989.75
							Length:	33.16	\$2,874.08	\$1,989.75	\$1,989.75
KENT STREET											
KENT ST-07	Odd	No	0	Granite	Good	Routine Maintenance	5	26.02	\$433.72	\$867.43	\$433.72
KENT ST-07	Odd	No	0	Granite	Good	Routine Maintenance	4	37.72	\$502.99	\$1,005.97	\$502.99
KENT ST-01	Even	No	0	Granite	Fair	Surface Treatment	6	106.61	\$13,859.25	\$9,594.87	\$9,594.87
KENT ST-05	Even	No	0	Granite	Poor	Rehabilitation	5	24.12	\$2,612.86	\$2,344.87	\$1,808.90
KENT ST-05	Even	Yes	2	Granite	Good	Routine Maintenance	4	138.26	\$1,843.52	\$3,687.04	\$1,843.52
KENT ST-06	Even	Yes	2	Granite	Good	Routine Maintenance	6	51.67	\$1,033.39	\$2,066.77	\$1,033.39
							Length:	384.41	\$20,285.72	\$19,566.96	\$15,217.38
MARKET STREET											
MARKET ST-04	Odd	No	0	Granite	Poor	Rehabilitation	6	102.62	\$13,340.83	\$11,972.54	\$9,235.96
MARKET ST-04	Even	No	0	Granite	Poor	Rehabilitation	6	315.73	\$41,044.87	\$36,835.14	\$28,415.68
MARKET ST-04	Even	No	0	Granite	Fair	Surface Treatment	5	51.77	\$5,608.65	\$3,882.91	\$3,882.91
							Length:	470.12	\$59,994.35	\$52,690.59	\$41,534.55
MERRILL STREET											
MERRILL ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	49.14	\$655.23	\$1,310.46	\$655.23
MERRILL ST-01	Even	No	0	Granite	New	Defer Maintenance	4	60.15	\$0.00	\$0.00	\$0.00
							Length:	109.29	\$655.23	\$1,310.46	\$655.23
MERRIMAC STREET											
MERRIMAC ST-28	Odd	No	0	Granite	Good	Routine Maintenance	6	203.16	\$4,063.17	\$8,126.34	\$4,063.17
MERRIMAC ST-28	Even	No	0	Granite	Fair	Surface Treatment	5	330.12	\$35,762.74	\$24,758.82	\$24,758.82
MERRIMAC ST-31	Even	No	0	Granite	Good	Routine Maintenance	4	119.08	\$1,587.78	\$3,175.57	\$1,587.78
MERRIMAC ST-32	Even	No	0	Granite	Good	Routine Maintenance	4	57.35	\$764.61	\$1,529.22	\$764.61
							Length:	709.71	\$42,178.30	\$37,589.94	\$31,174.38
MUNROE STREET											
MUNROE ST-03	Even	No	6	Granite	New	Defer Maintenance	4	118.83	\$0.00	\$0.00	\$0.00
MUNROE ST-04	Even	Yes	2	Granite	Good	Routine Maintenance	4	48.31	\$644.11	\$1,288.22	\$644.11
							Length:	167.13	\$644.11	\$1,288.22	\$644.11
OLIVE STREET											
OLIVE ST-01	Odd	No	0	Granite	Poor	Rehabilitation	6	39.96	\$5,195.36	\$4,662.50	\$3,596.79
OLIVE ST-02	Odd	No	0	Granite	Fair	Surface Treatment	4	112.37	\$9,738.46	\$6,742.01	\$6,742.01
							Length:	152.33	\$14,933.82	\$11,404.51	\$10,338.80
RUSSIA STREET											
RUSSIA ST-01	Odd	No	0	Granite	New	Defer Maintenance	4	74.12	\$0.00	\$0.00	\$0.00
RUSSIA ST-01	Odd	No	0	Granite	Gap	Gap	4	87.06	\$7,545.25	\$0.00	\$0.00
RUSSIA ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	39.10	\$521.37	\$1,042.73	\$521.37
							Length:	200.29	\$8,066.62	\$1,042.73	\$521.37

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
STRONG STREET											
STRONG ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	32.29	\$2,798.20	\$1,937.21	\$1,937.21
STRONG ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	47.07	\$627.61	\$1,255.23	\$627.61
							Length:	79.36	\$3,425.81	\$3,192.44	\$2,564.83
SUMMIT PLACE											
SUMMIT PL	Even	No	0	Granite	Fair	Surface Treatment	5	60.80	\$6,586.75	\$4,560.06	\$4,560.06
							Length:	60.80	\$6,586.75	\$4,560.06	\$4,560.06
VERNON STREET											
VERNON ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	286.90	\$3,825.35	\$7,650.71	\$3,825.35
VERNON ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	153.89	\$13,337.07	\$9,233.36	\$9,233.36
VERNON ST-03	Even	No	0	Concrete	Fair	Surface Treatment	4	19.16	\$1,660.71	\$1,149.72	\$1,149.72
							Length:	459.95	\$18,823.14	\$18,033.79	\$14,208.44
WARREN STREET											
WARREN ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	59.53	\$793.76	\$1,587.53	\$793.76
WARREN ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	78.83	\$1,051.05	\$2,102.10	\$1,051.05
WARREN ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	71.70	\$955.95	\$1,911.89	\$955.95
WARREN ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	94.23	\$1,256.43	\$2,512.86	\$1,256.43
WARREN ST-03	Even	No	0	Granite	Good	Routine Maintenance	4	113.61	\$1,514.83	\$3,029.67	\$1,514.83
							Length:	417.90	\$5,572.03	\$11,144.05	\$5,572.03
WASHINGTON STREET											
WASHINGTON ST-03	Odd	No	0	Granite	Good	Routine Maintenance	6	64.42	\$1,288.47	\$2,576.93	\$1,288.47
WASHINGTON ST-05	Odd	No	0	Granite	Poor	Rehabilitation	4	47.43	\$4,110.46	\$3,688.87	\$2,845.70
WASHINGTON ST-07	Odd	No	0	Granite	Fair	Surface Treatment	4	25.63	\$2,220.88	\$1,537.53	\$1,537.53
WASHINGTON ST-03	Even	No	0	Granite	Poor	Rehabilitation	6	200.25	\$26,032.60	\$23,362.59	\$18,022.57
WASHINGTON ST-04	Even	No	0	Granite	Fair	Surface Treatment	6	47.79	\$6,212.80	\$4,301.17	\$4,301.17
							Length:	385.52	\$39,865.21	\$35,467.10	\$27,995.44
WHITES COURT											
WHITES CT	Odd	No	0	Granite	Fair	Surface Treatment	4	110.44	\$9,571.12	\$6,626.16	\$6,626.16
WHITES CT	Even	No	0	Granite	New	Defer Maintenance	4	125.92	\$0.00	\$0.00	\$0.00
							Length:	236.35	\$9,571.12	\$6,626.16	\$6,626.16
Ward: 4											
ADAMS STREET											
ADAMS ST-02	Even	Yes	4	None	Good	Routine Maintenance	2	17.78	\$118.55	\$237.10	\$118.55
							Length:	17.78	\$118.55	\$237.10	\$118.55
ARLINGTON STREET											
ARLINGTON ST	Odd	No	0	Granite	Poor	Rehabilitation	5	267.53	\$28,982.09	\$26,009.56	\$20,064.52
ARLINGTON ST	Odd	No	0	Granite	Poor	Rehabilitation	5	499.82	\$54,147.21	\$48,593.65	\$37,486.53

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
ARLINGTON ST	Even	No	0	Granite	Poor	Rehabilitation	5	858.75	\$93,031.20	\$83,489.54	\$64,406.22
							Length:	1,626.10	\$176,160.50	\$158,092.76	\$121,957.27
ASHLAND STREET											
ASHLAND ST-01	Odd	Yes	2	Granite	Good	Routine Maintenance	4	127.88	\$1,705.05	\$3,410.11	\$1,705.05
ASHLAND ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	80.36	\$6,964.75	\$4,821.75	\$4,821.75
ASHLAND ST-03	Odd	Yes	2	Granite	New	Defer Maintenance	4	53.53	\$0.00	\$0.00	\$0.00
							Length:	261.77	\$8,669.80	\$8,231.86	\$6,526.80
BROAD STREET											
BROAD ST-01	Even	No	0	Granite	Poor	Rehabilitation	8	324.21	\$56,196.37	\$50,432.64	\$38,905.18
BROAD ST-01	Even	Yes	6	Granite	Good	Routine Maintenance	4	51.85	\$691.37	\$1,382.74	\$691.37
BROAD ST-02	Even	Yes	5	Granite	Good	Routine Maintenance	4	90.62	\$1,208.28	\$2,416.57	\$1,208.28
BROAD ST-02	Even	Yes	4	Granite	Good	Routine Maintenance	4	103.99	\$1,386.54	\$2,773.08	\$1,386.54
							Length:	570.67	\$59,482.56	\$57,005.02	\$42,191.37
COLUMBUS AVENUE											
COLUMBUS AVE-02	Odd	No	0	Granite	Good	Routine Maintenance	5	162.36	\$2,706.08	\$5,412.17	\$2,706.08
							Length:	162.36	\$2,706.08	\$5,412.17	\$2,706.08
DAWES STREET											
DAWES ST	Odd	Yes	2	Granite	Good	Routine Maintenance	2	68.74	\$458.24	\$916.47	\$458.24
							Length:	68.74	\$458.24	\$916.47	\$458.24
HIGH STREET											
HIGH ST-10	Odd	Yes	4	Granite	New	Defer Maintenance	4	178.33	\$0.00	\$0.00	\$0.00
HIGH ST-10	Odd	Yes	4	Granite	Poor	Rehabilitation	4	160.09	\$13,874.44	\$12,451.42	\$9,605.38
HIGH ST-15	Odd	No	0	Granite	Fair	Surface Treatment	4	225.03	\$19,502.62	\$13,501.82	\$13,501.82
HIGH ST-16	Odd	Yes	2	Granite	Fair	Surface Treatment	4	49.67	\$4,304.56	\$2,980.08	\$2,980.08
HIGH ST-01	Even	Yes	2	Granite	Fair	Surface Treatment	4	111.26	\$9,642.16	\$6,675.34	\$6,675.34
HIGH ST-05	Even	No	0	Granite	Fair	Surface Treatment	6	513.98	\$66,816.94	\$46,257.88	\$46,257.88
HIGH ST-11	Even	Yes	2	Granite	Good	Routine Maintenance	4	140.81	\$1,877.46	\$3,754.93	\$1,877.46
HIGH ST-12	Even	Yes	2	Granite	Good	Routine Maintenance	4	272.38	\$3,631.73	\$7,263.47	\$3,631.73
HIGH ST-13	Even	Yes	2	Granite	New	Defer Maintenance	4	78.66	\$0.00	\$0.00	\$0.00
HIGH ST-13	Even	No	0	Granite	Fair	Surface Treatment	6	107.29	\$13,947.41	\$9,655.90	\$9,655.90
HIGH ST-14	Even	No	0	Granite	Fair	Surface Treatment	6	132.17	\$17,182.69	\$11,895.71	\$11,895.71
HIGH ST-15	Even	No	0	Granite	Fair	Surface Treatment	6	221.43	\$28,785.66	\$19,928.53	\$19,928.53
HIGH ST-16	Even	No	0	Granite	Fair	Surface Treatment	6	204.20	\$26,546.39	\$18,378.27	\$18,378.27
HIGH ST-17	Even	No	0	Granite	Good	Routine Maintenance	6	49.14	\$982.88	\$1,965.77	\$982.88
							Length:	2,444.44	\$207,094.96	\$154,709.12	\$145,371.00
HOWARD STREET											
HOWARD ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	54.25	\$723.34	\$1,446.68	\$723.34
HOWARD ST-03	Even	No	0	Granite	Gap	Gap	4	175.15	\$15,179.40	\$0.00	\$0.00
HOWARD ST-03	Even	No	0	Granite	New	Defer Maintenance	4	74.63	\$0.00	\$0.00	\$0.00

BETA Group, Inc.

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
							Length:	304.02	\$15,902.74	\$1,446.68	\$723.34
MAGNOLIA STREET											
MAGNOLIA ST	Even	No	0	Granite	Good	Routine Maintenance	4	62.73	\$836.44	\$1,672.87	\$836.44
							Length:	62.73	\$836.44	\$1,672.87	\$836.44
MERRIMAC STREET											
MERRIMAC ST-11	Odd	No	0	Granite	Good	Routine Maintenance	5	94.87	\$1,581.18	\$3,162.37	\$1,581.18
MERRIMAC ST-17	Odd	No	0	Granite	Good	Routine Maintenance	4	75.22	\$1,002.93	\$2,005.85	\$1,002.93
MERRIMAC ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	3	60.32	\$3,920.61	\$2,714.27	\$2,714.27
MERRIMAC ST-11	Even	Yes	2	Concrete	New	Defer Maintenance	4	105.54	\$0.00	\$0.00	\$0.00
MERRIMAC ST-11	Even	Yes	2	Concrete	New	Defer Maintenance	4	44.85	\$0.00	\$0.00	\$0.00
MERRIMAC ST-14	Even	Yes	2	Concrete	Good	Routine Maintenance	4	106.96	\$1,426.08	\$2,852.17	\$1,426.08
MERRIMAC ST-19	Even	Yes	2	Granite	Good	Routine Maintenance	4	358.42	\$4,778.88	\$9,557.76	\$4,778.88
MERRIMAC ST-21	Even	Yes	2	Granite	New	Defer Maintenance	4	87.47	\$0.00	\$0.00	\$0.00
							Length:	933.64	\$12,709.69	\$20,292.42	\$11,503.35
OAKLAND STREET											
OAKLAND ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	253.93	\$22,007.18	\$15,235.74	\$15,235.74
OAKLAND ST-05	Even	Yes	2	Mix	Good	Routine Maintenance	4	208.10	\$2,774.72	\$5,549.44	\$2,774.72
							Length:	462.03	\$24,781.90	\$20,785.18	\$18,010.46
PLUMMER AVENUE											
PLUMMER AVE-03	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	201.92	\$2,692.25	\$5,384.49	\$2,692.25
PLUMMER AVE-03	Even	Yes	2	Concrete	Good	Routine Maintenance	4	191.71	\$2,556.14	\$5,112.28	\$2,556.14
							Length:	393.63	\$5,248.38	\$10,496.77	\$5,248.38
TOPPAN'S LANE											
TOPPAN'S LN-01	Even	Yes	6	Granite	Fair	Surface Treatment	4	150.21	\$13,017.83	\$9,012.35	\$9,012.35
							Length:	150.21	\$13,017.83	\$9,012.35	\$9,012.35
TYNG STREET											
TYNG ST-01	Odd	Yes	2	Concrete	New	Defer Maintenance	4	44.12	\$0.00	\$0.00	\$0.00
TYNG ST-02	Odd	Yes	2	Concrete	New	Defer Maintenance	4	75.33	\$0.00	\$0.00	\$0.00
TYNG ST-02	Odd	Yes	2	Granite	Poor	Rehabilitation	4	111.31	\$9,647.18	\$8,657.73	\$6,678.82
TYNG ST-01	Even	Yes	2	Granite	Poor	Rehabilitation	4	622.61	\$53,959.19	\$48,424.91	\$37,356.36
TYNG ST-01	Even	No	0	Granite	Fair	Surface Treatment	6	93.73	\$12,185.10	\$8,435.84	\$8,435.84
TYNG ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	50.08	\$4,339.93	\$3,004.57	\$3,004.57
TYNG ST-02	Even	Yes	2	Granite	Poor	Rehabilitation	6	438.87	\$57,052.98	\$51,201.39	\$39,498.22
							Length:	1,436.05	\$137,184.38	\$119,724.44	\$94,973.80
WALNUT STREET											
WALNUT ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	73.08	\$6,333.26	\$4,384.57	\$4,384.57
WALNUT ST-02	Even	No	0	None	Good	Routine Maintenance	4	43.48	\$579.70	\$1,159.40	\$579.70
							Length:	116.55	\$6,912.96	\$5,543.97	\$4,964.27

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
WOODLAND STREET												
	WOODLAND ST-08	Odd	Yes	2	Granite	Good	Routine Maintenance	4	50.64	\$675.23	\$1,350.47	\$675.23
	WOODLAND ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	75.25	\$1,003.38	\$2,006.75	\$1,003.38
								Length:	125.90	\$1,678.61	\$3,357.22	\$1,678.61

Ward: 5

HENDERSON CIRCLE

	HENDERSON CIRCLE	Odd	No	0	Granite	Good	Routine Maintenance	4	248.98	\$3,319.79	\$6,639.58	\$3,319.79
								Length:	248.98	\$3,319.79	\$6,639.58	\$3,319.79

HIGH STREET

	HIGH ST-03	Odd	Yes	2	Granite	Good	Routine Maintenance	4	27.50	\$366.68	\$733.36	\$366.68
	HIGH ST-03	Odd	Yes	2	Granite	Good	Routine Maintenance	4	105.90	\$1,412.00	\$2,824.00	\$1,412.00
	HIGH ST-05	Odd	Yes	2	Granite	Good	Routine Maintenance	4	40.51	\$540.07	\$1,080.14	\$540.07
								Length:	173.91	\$2,318.75	\$4,637.50	\$2,318.75

LOW STREET

	LOW ST-01	Odd	No	0	Granite	New	Defer Maintenance	4	280.02	\$0.00	\$0.00	\$0.00
								Length:	280.02	\$0.00	\$0.00	\$0.00

Ward: 6

MOSELEY AVENUE

	MOSELEY AVE-02	Even	Yes	6	None	Good	Routine Maintenance	4	98.62	\$1,314.87	\$2,629.74	\$1,314.87
								Length:	98.62	\$1,314.87	\$2,629.74	\$1,314.87

MOULTON STREET

	MOULTON ST-02	Odd	Yes	2	None	Good	Routine Maintenance	4	55.05	\$733.99	\$1,467.98	\$733.99
								Length:	55.05	\$733.99	\$1,467.98	\$733.99

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Condition and Estimated Replacement Costs - Concrete (Replace With Concrete)

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Ward: 1											
ALTER COURT											
ALTER CT	Odd	No	0	Mix	Good	Routine Maintenance	4	159.57	\$2,127.60	\$2,127.60	\$2,127.60
							Length:	159.57	\$2,127.60	\$2,127.60	\$2,127.60
BARTON COURT											
BARTON CT	Odd	Yes	2	None	Poor	Rehabilitation	4	132.91	\$7,383.86	\$6,202.44	\$4,430.31
							Length:	132.91	\$7,383.86	\$6,202.44	\$4,430.31
BARTON STREET											
BARTON ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	367.11	\$20,394.82	\$17,131.65	\$12,236.89
BARTON ST-02	Odd	Yes	2	Granite	Fair	Surface Treatment	4	251.01	\$13,944.88	\$11,713.70	\$8,366.93
BARTON ST-03	Odd	Yes	2	Granite	Fair	Surface Treatment	4	245.20	\$13,622.44	\$11,442.85	\$8,173.47
BARTON ST-01	Even	Yes	2	Granite	Fair	Surface Treatment	4	329.24	\$18,291.18	\$15,364.59	\$10,974.71
BARTON ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	211.51	\$11,750.62	\$9,870.52	\$7,050.37
BARTON ST-03	Even	Yes	2	Granite	Fair	Surface Treatment	4	229.58	\$12,754.48	\$10,713.76	\$7,652.69
							Length:	1,633.65	\$90,758.42	\$76,237.08	\$54,455.05
BEACON AVENUE											
BEACON AVE-05	Even	Yes	2	Concrete	Fair	Surface Treatment	4	170.39	\$9,465.91	\$7,951.36	\$5,679.55
							Length:	170.39	\$9,465.91	\$7,951.36	\$5,679.55
BROMFIELD COURT											
BROMFIELD CT	Odd	No	0	Granite	New	Defer Maintenance	4	89.27	\$0.00	\$0.00	\$0.00
BROMFIELD CT	Even	No	0	None	Poor	Rehabilitation	4	93.21	\$5,178.39	\$4,349.84	\$3,107.03
							Length:	182.48	\$5,178.39	\$4,349.84	\$3,107.03
BROMFIELD STREET											
BROMFIELD ST-02	Odd	No	0	Granite	Fair	Surface Treatment	5	52.53	\$3,648.04	\$3,064.35	\$2,188.82
BROMFIELD ST-02	Odd	No	0	Granite	New	Defer Maintenance	4	74.53	\$0.00	\$0.00	\$0.00
BROMFIELD ST-04	Odd	No	0	Granite	Good	Routine Maintenance	6	112.65	\$2,253.04	\$2,253.04	\$2,253.04
BROMFIELD ST-06	Odd	No	0	Granite	Fair	Surface Treatment	6	140.80	\$11,733.38	\$9,856.04	\$7,040.03
BROMFIELD ST-06	Odd	Yes	2	Granite	Fair	Surface Treatment	4	133.87	\$7,437.04	\$6,247.11	\$4,462.22
BROMFIELD ST-07	Odd	Yes	2	Granite	Fair	Surface Treatment	4	329.91	\$18,328.21	\$15,395.70	\$10,996.93
BROMFIELD ST-01	Even	Yes	2	Mix	Fair	Surface Treatment	4	141.44	\$7,857.94	\$6,600.67	\$4,714.76
							Length:	985.73	\$51,257.65	\$43,416.91	\$31,655.81
CHESTNUT STREET											

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
CHESTNUT ST-01	Odd	Yes	2	Mix	Poor	Rehabilitation	4	251.03	\$13,945.94	\$11,714.59	\$8,367.56
CHESTNUT ST-02	Odd	No	0	Mix	Fair	Surface Treatment	5	619.38	\$43,012.41	\$36,130.42	\$25,807.45
CHESTNUT ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	220.43	\$12,246.26	\$10,286.86	\$7,347.76
CHESTNUT ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	690.40	\$38,355.81	\$32,218.88	\$23,013.49
Length:								1,781.24	\$107,560.42	\$90,350.75	\$64,536.25

FRANKLIN STREET

FRANKLIN ST-01	Odd	No	0	Granite	Fair	Surface Treatment	5	219.72	\$15,258.60	\$12,817.22	\$9,155.16
FRANKLIN ST-01	Even	No	0	Granite	New	Defer Maintenance	4	69.96	\$0.00	\$0.00	\$0.00
FRANKLIN ST-01	Even	No	0	Concrete	Fair	Surface Treatment	4	75.33	\$4,185.24	\$3,515.60	\$2,511.15
Length:								365.02	\$19,443.84	\$16,332.83	\$11,666.31

HANCOCK STREET

HANCOCK ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	64.91	\$865.42	\$865.42	\$865.42
HANCOCK ST-01	Odd	Yes	2	Granite	Good	Routine Maintenance	4	76.60	\$1,021.27	\$1,021.27	\$1,021.27
HANCOCK ST-02	Odd	No	0	Granite	Poor	Rehabilitation	4	515.27	\$28,626.38	\$24,046.16	\$17,175.83
HANCOCK ST-03	Odd	Yes	2	Mix	Good	Routine Maintenance	4	120.92	\$1,612.23	\$1,612.23	\$1,612.23
HANCOCK ST-01	Even	No	0	Mix	Good	Routine Maintenance	4	189.70	\$2,529.40	\$2,529.40	\$2,529.40
HANCOCK ST-02	Even	Yes	2	Mix	Fair	Surface Treatment	4	200.07	\$11,114.85	\$9,336.47	\$6,668.91
HANCOCK ST-02	Even	Yes	2	Mix	Fair	Surface Treatment	4	290.31	\$16,128.37	\$13,547.83	\$9,677.02
HANCOCK ST-03	Even	No	0	Concrete	Fair	Surface Treatment	4	178.31	\$9,906.19	\$8,321.20	\$5,943.72
Length:								1,636.09	\$71,804.11	\$61,279.99	\$45,493.79

HARRISON STREET

HARRISON ST	Odd	No	0	Granite	Good	Routine Maintenance	4	245.73	\$3,276.39	\$3,276.39	\$3,276.39
HARRISON ST	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	362.41	\$20,133.74	\$16,912.34	\$12,080.24
HARRISON ST	Odd	Yes	2	Concrete	Gap	Gap	4	54.07	\$3,003.71	\$0.00	\$0.00
HARRISON ST	Even	No	0	Concrete	Fair	Surface Treatment	4	317.20	\$17,622.42	\$14,802.84	\$10,573.45
HARRISON ST	Even	No	0	Concrete	Gap	Gap	4	340.63	\$18,923.92	\$0.00	\$0.00
Length:								1,320.04	\$62,960.18	\$34,991.56	\$25,930.08

LIME STREET

LIME ST-07	Odd	No	0	Granite	Fair	Surface Treatment	4	175.58	\$9,754.27	\$8,193.59	\$5,852.56
LIME ST-08	Odd	No	0	Granite	Good	Routine Maintenance	4	98.67	\$1,315.65	\$1,315.65	\$1,315.65
LIME ST-08	Odd	No	0	Granite	Fair	Surface Treatment	4	75.39	\$4,188.40	\$3,518.25	\$2,513.04
LIME ST-08	Odd	No	0	Granite	Good	Routine Maintenance	4	68.14	\$908.60	\$908.60	\$908.60
LIME ST-08	Odd	No	0	Granite	Fair	Surface Treatment	4	39.93	\$2,218.33	\$1,863.40	\$1,331.00
LIME ST-08	Even	No	0	Granite	Fair	Surface Treatment	4	406.65	\$22,591.72	\$18,977.04	\$13,555.03
Length:								864.37	\$40,976.97	\$34,776.54	\$25,475.88

LINCOLN STREET

LINCOLN ST	Odd	Yes	2	Mix	Poor	Rehabilitation	4	622.35	\$34,574.94	\$29,042.95	\$20,744.96
Length:								622.35	\$34,574.94	\$29,042.95	\$20,744.96

LUNT STREET

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
LUNT ST	Odd	No	0	Concrete	Fair	Surface Treatment	4	340.45	\$18,914.06	\$15,887.81	\$11,348.44
LUNT ST	Even	No	0	Concrete	Fair	Surface Treatment	4	68.62	\$3,812.07	\$3,202.14	\$2,287.24
LUNT ST	Even	No	0	Granite	New	Defer Maintenance	4	60.15	\$0.00	\$0.00	\$0.00
							Length:	469.22	\$22,726.13	\$19,089.95	\$13,635.68

MADISON STREET

MADISON ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	278.78	\$15,487.66	\$13,009.63	\$9,292.59
MADISON ST-02	Odd	No	0	Granite	New	Defer Maintenance	4	30.07	\$0.00	\$0.00	\$0.00
MADISON ST-01	Even	Yes	2	Mix	Fair	Surface Treatment	4	348.08	\$19,337.66	\$16,243.63	\$11,602.59
MADISON ST-02	Even	No	0	Concrete	Fair	Surface Treatment	4	62.43	\$3,468.15	\$2,913.24	\$2,080.89
MADISON ST-02	Even	No	0	Concrete	Fair	Surface Treatment	4	114.32	\$6,350.84	\$5,334.71	\$3,810.51
							Length:	833.67	\$44,644.30	\$37,501.22	\$26,786.58

MARLBORO STREET

MARLBORO ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	126.86	\$7,047.75	\$5,920.11	\$4,228.65
MARLBORO ST-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	165.24	\$9,179.95	\$7,711.16	\$5,507.97
MARLBORO ST-04	Odd	No	0	Concrete	Poor	Rehabilitation	4	28.24	\$1,568.82	\$1,317.81	\$941.29
MARLBORO ST-08	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	336.14	\$18,674.42	\$15,686.51	\$11,204.65
MARLBORO ST-09	Odd	Yes	2	Mix	Poor	Rehabilitation	4	132.83	\$7,379.42	\$6,198.71	\$4,427.65
MARLBORO ST-09	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	72.95	\$972.67	\$972.67	\$972.67
MARLBORO ST-01	Even	No	0	Granite	Fair	Surface Treatment	5	133.38	\$9,262.48	\$7,780.48	\$5,557.49
MARLBORO ST-03	Even	Yes	2	Granite	Poor	Rehabilitation	4	215.63	\$11,979.36	\$10,062.66	\$7,187.61
MARLBORO ST-04	Even	Yes	2	Granite	Fair	Surface Treatment	4	164.53	\$9,140.63	\$7,678.13	\$5,484.38
MARLBORO ST-06	Even	Yes	2	Concrete	Poor	Rehabilitation	4	162.33	\$9,018.53	\$7,575.57	\$5,411.12
MARLBORO ST-07	Even	Yes	2	Concrete	Fair	Surface Treatment	4	317.88	\$17,660.04	\$14,834.44	\$10,596.03
MARLBORO ST-08	Even	Yes	2	Concrete	Good	Routine Maintenance	4	76.72	\$1,022.91	\$1,022.91	\$1,022.91
MARLBORO ST-09	Even	Yes	2	Concrete	Poor	Rehabilitation	4	279.03	\$15,501.69	\$13,021.42	\$9,301.01
							Length:	2,211.76	\$118,408.66	\$99,782.56	\$71,843.42

MILK STREET

MILK ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	49.74	\$663.15	\$663.15	\$663.15
MILK ST-02	Odd	Yes	2	Granite	Poor	Rehabilitation	4	208.83	\$11,601.69	\$9,745.42	\$6,961.01
MILK ST-02	Odd	Yes	2	Granite	Poor	Rehabilitation	4	90.78	\$5,043.28	\$4,236.36	\$3,025.97
MILK ST-03	Odd	No	0	Granite	Poor	Rehabilitation	4	82.30	\$4,571.95	\$3,840.44	\$2,743.17
							Length:	431.64	\$21,880.07	\$18,485.36	\$13,393.30

NEPTUNE STREET

NEPTUNE ST	Odd	No	0	Concrete	Fair	Surface Treatment	4	523.66	\$29,092.22	\$24,437.47	\$17,455.33
NEPTUNE ST	Even	No	0	Mix	Poor	Rehabilitation	4	318.32	\$17,684.46	\$14,854.95	\$10,610.68
NEPTUNE ST	Even	No	0	Concrete	Fair	Surface Treatment	4	178.80	\$9,933.39	\$8,344.05	\$5,960.03
							Length:	1,020.78	\$56,710.08	\$47,636.46	\$34,026.05

OAK STREET

OAK ST-01	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	279.21	\$15,511.46	\$13,029.63	\$9,306.88
-----------	-----	-----	---	----------	------	----------------	---	--------	-------------	-------------	------------

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
OAK ST-02	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	192.41	\$10,689.36	\$8,979.06	\$6,413.62
OAK ST-03	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	57.63	\$3,201.86	\$2,689.56	\$1,921.11
OAK ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	157.91	\$8,772.55	\$7,368.94	\$5,263.53
							Length:	687.15	\$38,175.23	\$32,067.19	\$22,905.14

PURCHASE STREET

PURCHASE ST-01	Odd	No	0	Granite	New	Defer Maintenance	4	146.05	\$0.00	\$0.00	\$0.00
PURCHASE ST-09	Odd	No	0	Granite	Fair	Surface Treatment	5	313.09	\$21,742.21	\$18,263.46	\$13,045.33
PURCHASE ST-01	Even	No	0	Granite	New	Defer Maintenance	4	85.71	\$0.00	\$0.00	\$0.00
PURCHASE ST-03	Even	No	0	Granite	New	Defer Maintenance	5	71.14	\$0.00	\$0.00	\$0.00
PURCHASE ST-05	Even	No	0	Granite	Fair	Surface Treatment	6	62.73	\$5,227.27	\$4,390.90	\$3,136.36
PURCHASE ST-06	Even	No	0	Granite	Fair	Surface Treatment	4	73.01	\$4,055.97	\$3,407.02	\$2,433.58
PURCHASE ST-07	Even	No	0	Granite	Fair	Surface Treatment	6	63.21	\$5,267.83	\$4,424.97	\$3,160.70
PURCHASE ST-09	Even	Yes	2	Granite	Fair	Surface Treatment	4	294.24	\$16,346.94	\$13,731.43	\$9,808.17
							Length:	1,109.18	\$52,640.22	\$44,217.78	\$31,584.13

SALEM STREET

SALEM ST	Odd	No	0	Granite	Good	Routine Maintenance	4	732.28	\$9,763.77	\$9,763.77	\$9,763.77
SALEM ST	Even	No	0	Granite	Gap	Gap	4	265.28	\$14,738.04	\$0.00	\$0.00
SALEM ST	Even	No	0	Granite	Good	Routine Maintenance	4	398.21	\$5,309.40	\$5,309.40	\$5,309.40
							Length:	1,395.77	\$29,811.21	\$15,073.17	\$15,073.17

SHIP STREET

SHIP ST	Even	No	0	Granite	Good	Routine Maintenance	4	56.11	\$748.15	\$748.15	\$748.15
SHIP ST	Even	No	0	Mix	Fair	Surface Treatment	4	199.96	\$11,108.97	\$9,331.53	\$6,665.38
							Length:	256.07	\$11,857.12	\$10,079.68	\$7,413.53

SMITH'S STREET

SMITH'S ST	Odd	No	0	Concrete	Fair	Surface Treatment	4	45.74	\$2,541.05	\$2,134.48	\$1,524.63
SMITH'S ST	Odd	No	0	Concrete	Fair	Surface Treatment	4	54.05	\$3,003.02	\$2,522.54	\$1,801.81
SMITH'S ST	Even	No	0	Concrete	Fair	Surface Treatment	4	221.09	\$12,282.98	\$10,317.70	\$7,369.79
							Length:	320.89	\$17,827.05	\$14,974.72	\$10,696.23

SOUTH POND STREET

SOUTH POND ST	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	152.07	\$8,448.49	\$7,096.73	\$5,069.09
SOUTH POND ST	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	257.97	\$14,331.56	\$12,038.51	\$8,598.93
							Length:	410.04	\$22,780.05	\$19,135.24	\$13,668.03

UNION STREET

UNION ST-01	Odd	No	0	Concrete	Fair	Surface Treatment	4	202.43	\$11,246.12	\$9,446.74	\$6,747.67
UNION ST-01	Odd	No	0	Granite	New	Defer Maintenance	4	30.34	\$0.00	\$0.00	\$0.00
UNION ST-02	Odd	No	0	Concrete	Poor	Rehabilitation	4	204.61	\$11,367.19	\$9,548.44	\$6,820.31
UNION ST-03	Odd	No	0	Concrete	Fair	Surface Treatment	4	120.76	\$6,708.62	\$5,635.24	\$4,025.17
UNION ST-03	Even	No	0	Concrete	Good	Routine Maintenance	4	71.60	\$954.66	\$954.66	\$954.66

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
							Length: 629.73	\$30,276.59	\$25,585.08	\$18,547.82
WATER STREET										
WATER ST-04	Odd	No	0	Mix	Poor	Rehabilitation	4	295.23	\$16,401.52	\$13,777.28
WATER ST-05	Odd	No	0	Concrete	Poor	Rehabilitation	4	148.52	\$8,250.92	\$6,930.77
WATER ST-06	Odd	No	0	Concrete	Poor	Rehabilitation	4	77.88	\$4,326.92	\$3,634.62
WATER ST-06	Odd	No	0	Granite	New	Defer Maintenance	4	80.15	\$0.00	\$0.00
WATER ST-09	Odd	No	0	Granite	Good	Routine Maintenance	4	123.56	\$1,647.52	\$1,647.52
WATER ST-12	Odd	No	0	Granite	Poor	Rehabilitation	4	138.39	\$7,688.59	\$6,458.42
WATER ST-13	Odd	No	0	Granite	Fair	Surface Treatment	4	232.01	\$12,889.70	\$10,827.35
WATER ST-14	Odd	No	0	Granite	Good	Routine Maintenance	4	122.39	\$1,631.91	\$1,631.91
WATER ST-14	Odd	No	0	Granite	Good	Routine Maintenance	4	47.84	\$637.93	\$637.93
WATER ST-15	Odd	No	0	Granite	Good	Routine Maintenance	4	122.77	\$1,636.92	\$1,636.92
WATER ST-04	Even	No	0	Concrete	Poor	Rehabilitation	4	243.11	\$13,505.97	\$11,345.02
WATER ST-05	Even	No	0	Concrete	Poor	Rehabilitation	4	124.98	\$6,943.28	\$5,832.35
WATER ST-06	Even	No	0	Granite	New	Defer Maintenance	4	221.59	\$0.00	\$0.00
WATER ST-08	Even	No	0	Concrete	Poor	Rehabilitation	4	53.40	\$2,966.68	\$2,492.01
WATER ST-08	Even	No	0	Granite	Good	Routine Maintenance	4	331.84	\$4,424.51	\$4,424.51
WATER ST-09	Even	No	0	Granite	Good	Routine Maintenance	4	371.86	\$4,958.14	\$4,958.14
WATER ST-10	Even	No	0	Granite	Good	Routine Maintenance	4	170.83	\$2,277.68	\$2,277.68
WATER ST-11	Even	No	0	Granite	Good	Routine Maintenance	4	114.03	\$1,520.40	\$1,520.40
WATER ST-12	Even	No	0	Granite	Good	Routine Maintenance	4	196.65	\$2,621.96	\$2,621.96
WATER ST-13	Even	No	0	Granite	Good	Routine Maintenance	4	184.54	\$2,460.55	\$2,460.55
WATER ST-14	Even	No	0	Granite	Good	Routine Maintenance	4	170.67	\$2,275.66	\$2,275.66
WATER ST-15	Even	No	0	Granite	Good	Routine Maintenance	4	94.50	\$1,260.04	\$1,260.04
WATER ST-16	Even	No	0	Granite	Good	Routine Maintenance	4	211.58	\$2,821.01	\$2,821.01
							Length: 3,878.34	\$103,147.81	\$91,472.04	\$73,958.38
Ward: 2										
ALLEN STREET										
ALLEN ST	Odd	No	0	Granite	Fair	Surface Treatment	4	126.02	\$7,001.27	\$5,881.07
ALLEN ST	Odd	No	0	Granite	Good	Routine Maintenance	4	110.15	\$1,468.69	\$1,468.69
ALLEN ST	Even	No	0	Granite	Fair	Surface Treatment	4	319.45	\$17,747.18	\$14,907.63
							Length: 555.62	\$26,217.14	\$22,257.38	\$16,317.76
ATWOOD STREET										
ATWOOD ST	Odd	No	0	Granite	Fair	Surface Treatment	4	103.74	\$5,763.48	\$4,841.32
ATWOOD ST	Even	No	0	Granite	Fair	Surface Treatment	4	48.46	\$2,692.40	\$2,261.62
ATWOOD ST	Even	No	0	Granite	Fair	Surface Treatment	4	150.98	\$8,387.51	\$7,045.50
							Length: 303.18	\$16,843.39	\$14,148.45	\$10,106.03
BRICHER PLACE										
BRICHER PL-02	Odd	Yes	2	Concrete	New	Defer Maintenance	4	39.58	\$0.00	\$0.00

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
BRICHER PL-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	3	139.77	\$5,823.70	\$4,891.91	\$3,494.22
							Length:	179.35	\$5,823.70	\$4,891.91	\$3,494.22
BROMFIELD STREET											
BROMFIELD ST-07	Even	Yes	2	Granite	Fair	Surface Treatment	4	72.76	\$4,042.45	\$3,395.66	\$2,425.47
							Length:	72.76	\$4,042.45	\$3,395.66	\$2,425.47
COFFIN'S COURT											
COFFIN'S CT	Odd	Yes	2	Mix	Fair	Surface Treatment	3	206.42	\$8,600.64	\$7,224.54	\$5,160.39
							Length:	206.42	\$8,600.64	\$7,224.54	\$5,160.39
DALTON STREET											
DALTON ST	Odd	Yes	2	Granite	Good	Routine Maintenance	4	406.71	\$5,422.78	\$5,422.78	\$5,422.78
DALTON ST	Even	Yes	2	Granite	Good	Routine Maintenance	4	384.10	\$5,121.37	\$5,121.37	\$5,121.37
							Length:	790.81	\$10,544.15	\$10,544.15	\$10,544.15
FAIR STREET											
FAIR ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	133.73	\$1,783.04	\$1,783.04	\$1,783.04
FAIR ST-02	Odd	No	0	Granite	Fair	Surface Treatment	4	74.06	\$4,114.35	\$3,456.05	\$2,468.61
FAIR ST-06	Odd	No	0	Granite	Good	Routine Maintenance	4	115.58	\$1,541.01	\$1,541.01	\$1,541.01
FAIR ST-07	Odd	No	0	Granite	New	Defer Maintenance	4	139.20	\$0.00	\$0.00	\$0.00
FAIR ST-08	Odd	No	0	Granite	Good	Routine Maintenance	4	100.85	\$1,344.60	\$1,344.60	\$1,344.60
							Length:	563.41	\$8,783.00	\$8,124.70	\$7,137.26
FEDERAL STREET											
FEDERAL ST-02	Odd	Yes	2	Granite	New	Defer Maintenance	4	126.42	\$0.00	\$0.00	\$0.00
FEDERAL ST-03	Odd	No	0	Granite	Fair	Surface Treatment	4	17.98	\$998.98	\$839.15	\$599.39
FEDERAL ST-08	Odd	No	0	Granite	Fair	Surface Treatment	6	27.99	\$2,332.55	\$1,959.34	\$1,399.53
FEDERAL ST-04	Even	Yes	2	Granite	Good	Routine Maintenance	4	35.67	\$475.54	\$475.54	\$475.54
FEDERAL ST-05	Even	Yes	2	Granite	New	Defer Maintenance	4	28.50	\$0.00	\$0.00	\$0.00
FEDERAL ST-07	Even	Yes	2	Granite	Fair	Surface Treatment	4	72.79	\$4,044.09	\$3,397.03	\$2,426.45
							Length:	309.35	\$7,851.16	\$6,671.06	\$4,900.91
GREENLEAF STREET											
GREENLEAF ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	47.53	\$633.80	\$633.80	\$633.80
GREENLEAF ST-02	Odd	Yes	2	Mix	Good	Routine Maintenance	4	84.72	\$1,129.59	\$1,129.59	\$1,129.59
GREENLEAF ST-03	Odd	Yes	2	Granite	Fair	Surface Treatment	4	126.39	\$7,021.80	\$5,898.31	\$4,213.08
GREENLEAF ST-04	Odd	No	0	Granite	Good	Routine Maintenance	4	67.75	\$903.30	\$903.30	\$903.30
GREENLEAF ST-04	Odd	No	0	Granite	Good	Routine Maintenance	4	213.49	\$2,846.50	\$2,846.50	\$2,846.50
GREENLEAF ST-04	Even	No	0	Granite	Fair	Surface Treatment	4	133.88	\$7,437.61	\$6,247.59	\$4,462.57
GREENLEAF ST-04	Even	Yes	2	Granite	New	Defer Maintenance	4	95.98	\$0.00	\$0.00	\$0.00
							Length:	769.74	\$19,972.60	\$17,659.09	\$14,188.84
HIGH STREET											
HIGH ST-37	Odd	Yes	2	Granite	Good	Routine Maintenance	4	30.24	\$403.16	\$403.16	\$403.16

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
HIGH ST-37	Odd	Yes	2	Granite	Good	Routine Maintenance	4	437.00	\$5,826.67	\$5,826.67	\$5,826.67
HIGH ST-41	Odd	Yes	2	Granite	Fair	Surface Treatment	4	100.86	\$5,603.21	\$4,706.70	\$3,361.93
HIGH ST-45	Odd	Yes	2	Granite	Good	Routine Maintenance	4	112.99	\$1,506.50	\$1,506.50	\$1,506.50
HIGH ST-45	Odd	Yes	2	Granite	Good	Routine Maintenance	4	59.86	\$798.14	\$798.14	\$798.14
Length:								740.94	\$14,137.68	\$13,241.16	\$11,896.39
HILL STREET											
HILL ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	149.59	\$1,994.54	\$1,994.54	\$1,994.54
HILL ST-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	544.04	\$30,224.56	\$25,388.63	\$18,134.74
HILL ST-03	Odd	Yes	3	Granite	Fair	Surface Treatment	4	286.70	\$15,927.50	\$13,379.10	\$9,556.50
Length:								980.33	\$48,146.60	\$40,762.27	\$29,685.78
HORTON STREET											
HORTON ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	62.30	\$3,460.99	\$2,907.23	\$2,076.59
HORTON ST-02	Odd	Yes	2	Granite	Fair	Surface Treatment	4	185.12	\$10,284.43	\$8,638.92	\$6,170.66
HORTON ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	180.08	\$10,004.65	\$8,403.91	\$6,002.79
HORTON ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	61.30	\$3,405.75	\$2,860.83	\$2,043.45
Length:								488.80	\$27,155.83	\$22,810.89	\$16,293.50
INDEPENDENT STREET											
INDEPENDENT ST-01	Even	No	0	Concrete	Fair	Surface Treatment	4	141.81	\$7,878.10	\$6,617.60	\$4,726.86
INDEPENDENT ST-01	Even	No	0	Concrete	Fair	Surface Treatment	4	39.86	\$2,214.49	\$1,860.17	\$1,328.69
INDEPENDENT ST-01	Even	No	0	Concrete	Gap	Gap	4	107.92	\$5,995.71	\$0.00	\$0.00
Length:								289.59	\$16,088.30	\$8,477.77	\$6,055.55
LIME STREET											
LIME ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	109.20	\$6,066.63	\$5,095.97	\$3,639.98
LIME ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	182.69	\$10,149.36	\$8,525.46	\$6,089.62
LIME ST-03	Odd	No	0	Granite	Poor	Rehabilitation	4	94.73	\$5,262.59	\$4,420.58	\$3,157.56
LIME ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	60.43	\$3,357.29	\$2,820.13	\$2,014.38
LIME ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	44.19	\$2,454.96	\$2,062.17	\$1,472.98
LIME ST-03	Even	No	0	Granite	Fair	Surface Treatment	4	88.91	\$4,939.32	\$4,149.03	\$2,963.59
LIME ST-03	Even	No	0	Granite	Good	Routine Maintenance	4	41.82	\$557.63	\$557.63	\$557.63
LIME ST-04	Even	No	0	Granite	Good	Routine Maintenance	4	89.31	\$1,190.74	\$1,190.74	\$1,190.74
LIME ST-07	Even	No	0	Granite	Fair	Surface Treatment	4	64.78	\$3,598.93	\$3,023.10	\$2,159.36
Length:								776.05	\$37,577.47	\$31,844.81	\$23,245.83
MIDDLE STREET											
MIDDLE ST-04	Odd	No	0	Granite	Fair	Surface Treatment	4	27.52	\$1,528.70	\$1,284.11	\$917.22
MIDDLE ST-03	Even	No	0	Granite	Good	Routine Maintenance	4	64.77	\$863.66	\$863.66	\$863.66
Length:								92.29	\$2,392.36	\$2,147.77	\$1,780.88
MILK STREET											
MILK ST-01	Odd	No	0	Granite	Poor	Rehabilitation	4	229.56	\$12,753.56	\$10,712.99	\$7,652.14
MILK ST-01	Odd	No	0	Granite	New	Defer Maintenance	4	18.41	\$0.00	\$0.00	\$0.00

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
MILK ST-01	Even	No	0	Granite	Good	Routine Maintenance	5	55.12	\$918.75	\$918.75	\$918.75
MILK ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	136.97	\$7,609.60	\$6,392.06	\$4,565.76
MILK ST-02	Even	No	0	Granite	New	Defer Maintenance	4	263.54	\$0.00	\$0.00	\$0.00
MILK ST-03	Even	No	0	Granite	Good	Routine Maintenance	4	56.02	\$746.98	\$746.98	\$746.98
							Length:	759.64	\$22,028.89	\$18,770.78	\$13,883.62
ORANGE STREET											
ORANGE ST	Odd	No	0	Granite	Good	Routine Maintenance	4	10.36	\$138.08	\$138.08	\$138.08
ORANGE ST	Odd	No	0	Granite	Good	Routine Maintenance	4	21.18	\$282.33	\$282.33	\$282.33
ORANGE ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	306.68	\$17,038.01	\$14,311.92	\$10,222.80
							Length:	338.22	\$17,458.42	\$14,732.34	\$10,643.22
PARSONS STREET											
PARSONS ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	138.13	\$7,674.05	\$6,446.20	\$4,604.43
PARSONS ST	Even	Yes	2	Granite	Good	Routine Maintenance	4	146.54	\$1,953.80	\$1,953.80	\$1,953.80
PARSONS ST	Even	No	0	Granite	Fair	Surface Treatment	4	61.92	\$3,440.02	\$2,889.62	\$2,064.01
							Length:	346.59	\$13,067.88	\$11,289.62	\$8,622.25
POND STREET											
POND ST-03	Odd	No	0	Granite	New	Defer Maintenance	4	274.17	\$0.00	\$0.00	\$0.00
							Length:	274.17	\$0.00	\$0.00	\$0.00
PROSPECT STREET											
PROSPECT ST-03	Odd	No	0	Granite	Good	Routine Maintenance	5	212.10	\$3,535.08	\$3,535.08	\$3,535.08
PROSPECT ST-05	Odd	No	0	Granite	Fair	Surface Treatment	4	223.68	\$12,426.83	\$10,438.53	\$7,456.10
PROSPECT ST-05	Odd	No	0	Granite	Good	Routine Maintenance	4	90.97	\$1,212.94	\$1,212.94	\$1,212.94
PROSPECT ST-06	Odd	No	0	Granite	Good	Routine Maintenance	4	227.88	\$3,038.44	\$3,038.44	\$3,038.44
PROSPECT ST-06	Odd	No	0	Granite	Poor	Rehabilitation	4	25.28	\$1,404.32	\$1,179.63	\$842.59
PROSPECT ST-07	Odd	No	0	Granite	Poor	Rehabilitation	4	246.18	\$13,676.45	\$11,488.22	\$8,205.87
PROSPECT ST-08	Odd	No	0	Granite	Fair	Surface Treatment	4	137.08	\$7,615.62	\$6,397.12	\$4,569.37
PROSPECT ST-04	Even	No	0	Granite	Good	Routine Maintenance	4	161.70	\$2,156.04	\$2,156.04	\$2,156.04
PROSPECT ST-05	Even	No	0	Granite	Good	Routine Maintenance	4	188.32	\$2,510.87	\$2,510.87	\$2,510.87
PROSPECT ST-05	Even	Yes	2	Granite	Good	Routine Maintenance	4	299.77	\$3,996.96	\$3,996.96	\$3,996.96
PROSPECT ST-06	Even	Yes	2	Granite	Fair	Surface Treatment	4	246.69	\$13,704.73	\$11,511.97	\$8,222.84
PROSPECT ST-07	Even	No	0	Granite	New	Defer Maintenance	4	186.31	\$0.00	\$0.00	\$0.00
PROSPECT ST-08	Even	No	0	Granite	Good	Routine Maintenance	4	44.54	\$593.89	\$593.89	\$593.89
							Length:	2,290.50	\$65,872.16	\$58,059.69	\$46,340.98
SCHOOL STREET											
SCHOOL ST	Even	No	0	Granite	Fair	Surface Treatment	4	506.40	\$28,133.12	\$23,631.82	\$16,879.87
							Length:	506.40	\$28,133.12	\$23,631.82	\$16,879.87
SPRING STREET											
SPRING ST	Odd	No	0	Granite	Fair	Surface Treatment	4	78.74	\$4,374.26	\$3,674.38	\$2,624.56
SPRING ST	Even	No	0	Granite	Fair	Surface Treatment	5	77.93	\$5,411.99	\$4,546.07	\$3,247.19

BETA Group, Inc.

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
							Length:	156.67	\$9,786.25	\$8,220.45	\$5,871.75
STATE STREET											
STATE ST-11	Odd	Yes	4	Granite	Fair	Surface Treatment	4	264.21	\$14,678.41	\$12,329.86	\$8,807.05
STATE ST-12	Odd	Yes	4	Granite	New	Defer Maintenance	4	449.83	\$0.00	\$0.00	\$0.00
STATE ST-13	Odd	Yes	5	Concrete	Fair	Surface Treatment	3	297.03	\$12,376.09	\$10,395.92	\$7,425.66
STATE ST-13	Even	Yes	2	Granite	New	Defer Maintenance	4	117.26	\$0.00	\$0.00	\$0.00
STATE ST-13	Even	Yes	2	Granite	Poor	Rehabilitation	4	93.91	\$5,217.08	\$4,382.35	\$3,130.25
STATE ST-13	Even	Yes	2	Granite	Good	Routine Maintenance	4	230.58	\$3,074.40	\$3,074.40	\$3,074.40
							Length:	1,452.82	\$35,345.98	\$30,182.53	\$22,437.35
TEMPLE STREET											
TEMPLE ST-02	Odd	No	0	Granite	Fair	Surface Treatment	4	57.19	\$3,177.25	\$2,668.89	\$1,906.35
TEMPLE ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	82.41	\$1,098.84	\$1,098.84	\$1,098.84
							Length:	139.60	\$4,276.09	\$3,767.73	\$3,005.19
TREMONT STREET											
TREMONT ST	Odd	No	0	Granite	New	Defer Maintenance	6	166.76	\$0.00	\$0.00	\$0.00
TREMONT ST	Odd	No	0	Granite	Fair	Surface Treatment	4	148.56	\$8,253.39	\$6,932.84	\$4,952.03
TREMONT ST	Even	Yes	2	Granite	New	Defer Maintenance	4	119.68	\$0.00	\$0.00	\$0.00
TREMONT ST	Even	No	0	Granite	New	Defer Maintenance	6	87.57	\$0.00	\$0.00	\$0.00
							Length:	522.57	\$8,253.39	\$6,932.84	\$4,952.03
WATER STREET											
WATER ST-16	Odd	No	0	Granite	Poor	Rehabilitation	5	145.36	\$10,094.17	\$8,479.10	\$6,056.50
							Length:	145.36	\$10,094.17	\$8,479.10	\$6,056.50
Ward: 3											
AUBURN STREET											
AUBURN ST-04	Odd	No	0	Granite	Good	Routine Maintenance	5	48.91	\$815.12	\$815.12	\$815.12
AUBURN ST-04	Even	Yes	4	Granite	Fair	Surface Treatment	2	224.36	\$6,232.14	\$5,235.00	\$3,739.29
							Length:	273.26	\$7,047.26	\$6,050.12	\$4,554.41
BOARDMAN STREET											
BOARDMAN ST-02	Odd	Yes	2	Concrete	Good	Routine Maintenance	2	66.58	\$443.84	\$443.84	\$443.84
BOARDMAN ST-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	2	26.99	\$749.59	\$629.65	\$449.75
BOARDMAN ST-03	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	109.42	\$6,078.73	\$5,106.13	\$3,647.24
BOARDMAN ST-03	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	281.60	\$15,644.35	\$13,141.26	\$9,386.61
BOARDMAN ST-03	Odd	Yes	2	Concrete	Fair	Surface Treatment	3	81.12	\$3,379.92	\$2,839.13	\$2,027.95
BOARDMAN ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	222.02	\$12,334.19	\$10,360.72	\$7,400.52
BOARDMAN ST-03	Even	Yes	2	Granite	Good	Routine Maintenance	4	50.98	\$679.79	\$679.79	\$679.79
BOARDMAN ST-03	Even	Yes	2	Concrete	Poor	Rehabilitation	4	67.74	\$3,763.17	\$3,161.06	\$2,257.90
							Length:	906.43	\$43,073.58	\$36,361.58	\$26,293.60
BRICHER PLACE											

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
BRICHER PL-02	Even	Yes	2	Concrete	Fair	Surface Treatment	2	85.51	\$2,375.22	\$1,995.19	\$1,425.13
							Length:	85.51	\$2,375.22	\$1,995.19	\$1,425.13
BROAD STREET											
BROAD ST-01	Odd	Yes	4	Granite	Fair	Surface Treatment	3	116.19	\$4,841.06	\$4,066.49	\$2,904.64
BROAD ST-01	Odd	Yes	4	Granite	Fair	Surface Treatment	4	297.87	\$16,548.47	\$13,900.71	\$9,929.08
BROAD ST-02	Odd	Yes	5	Granite	Good	Routine Maintenance	4	188.36	\$2,511.53	\$2,511.53	\$2,511.53
BROAD ST-02	Odd	Yes	5	Granite	Good	Routine Maintenance	4	66.77	\$890.22	\$890.22	\$890.22
BROAD ST-02	Odd	Yes	5	Granite	Fair	Surface Treatment	4	219.73	\$12,207.11	\$10,253.97	\$7,324.27
							Length:	888.92	\$36,998.40	\$31,622.93	\$23,559.74
BUCK STREET											
BUCK ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	43.08	\$2,393.53	\$2,010.57	\$1,436.12
BUCK ST-02	Odd	Yes	2	Granite	Fair	Surface Treatment	4	130.09	\$7,227.20	\$6,070.85	\$4,336.32
BUCK ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	277.32	\$15,406.55	\$12,941.50	\$9,243.93
BUCK ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	57.61	\$3,200.70	\$2,688.59	\$1,920.42
							Length:	508.10	\$28,227.98	\$23,711.50	\$16,936.79
CAREY AVENUE											
CAREY AVE-01	Odd	No	0	Granite	Fair	Surface Treatment	4	95.22	\$5,289.73	\$4,443.37	\$3,173.84
							Length:	95.22	\$5,289.73	\$4,443.37	\$3,173.84
CARTER STREET											
CARTER ST-01	Odd	No	0	Granite	Poor	Rehabilitation	4	95.00	\$5,278.03	\$4,433.55	\$3,166.82
CARTER ST-02	Odd	No	0	Concrete	Poor	Rehabilitation	4	107.25	\$5,958.16	\$5,004.85	\$3,574.90
CARTER ST-03	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	123.34	\$6,852.44	\$5,756.05	\$4,111.46
CARTER ST-04	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	196.40	\$10,911.31	\$9,165.50	\$6,546.78
CARTER ST-05	Odd	Yes	2	Concrete	Gap	Gap	4	28.73	\$1,596.30	\$0.00	\$0.00
CARTER ST-05	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	50.73	\$2,818.33	\$2,367.39	\$1,691.00
CARTER ST-05	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	130.95	\$7,274.99	\$6,111.00	\$4,365.00
CARTER ST-01	Even	Yes	2	Mix	Fair	Surface Treatment	4	382.61	\$21,256.26	\$17,855.26	\$12,753.76
CARTER ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	28.97	\$1,609.64	\$1,352.10	\$965.78
CARTER ST-02	Even	Yes	2	Concrete	Fair	Surface Treatment	4	158.52	\$8,806.91	\$7,397.81	\$5,284.15
CARTER ST-04	Even	Yes	2	Concrete	Good	Routine Maintenance	4	79.14	\$1,055.18	\$1,055.18	\$1,055.18
CARTER ST-04	Even	Yes	2	Concrete	Good	Routine Maintenance	4	97.60	\$1,301.30	\$1,301.30	\$1,301.30
CARTER ST-05	Even	Yes	2	Concrete	Fair	Surface Treatment	4	122.61	\$6,811.76	\$5,721.88	\$4,087.05
CARTER ST-06	Even	Yes	2	Mix	New	Defer Maintenance	4	210.16	\$0.00	\$0.00	\$0.00
							Length:	1,812.03	\$81,530.61	\$67,521.85	\$48,903.17
CONGRESS STREET											
CONGRESS ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	130.02	\$7,223.36	\$6,067.62	\$4,334.01
CONGRESS ST-03	Odd	Yes	2	Granite	New	Defer Maintenance	4	160.46	\$0.00	\$0.00	\$0.00
CONGRESS ST-03	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	109.11	\$6,061.71	\$5,091.84	\$3,637.03
CONGRESS ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	235.89	\$13,104.78	\$11,008.01	\$7,862.87

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
CONGRESS ST-01	Even	Yes	2	Granite	New	Defer Maintenance	4	53.84	\$0.00	\$0.00	\$0.00
CONGRESS ST-03	Even	Yes	2	Granite	Fair	Surface Treatment	4	274.75	\$15,264.10	\$12,821.84	\$9,158.46
CONGRESS ST-03	Even	Yes	2	Granite	Good	Routine Maintenance	4	47.48	\$633.02	\$633.02	\$633.02
Length:								1,011.54	\$42,286.96	\$35,622.33	\$25,625.38
COURT STREET											
COURT ST	Odd	No	0	Granite	Fair	Surface Treatment	6	270.47	\$22,539.12	\$18,932.86	\$13,523.47
Length:								270.47	\$22,539.12	\$18,932.86	\$13,523.47
DOVE STREET											
DOVE ST	Odd	No	0	Mix	Fair	Surface Treatment	4	286.85	\$15,936.30	\$13,386.49	\$9,561.78
DOVE ST	Odd	No	0	Concrete	Fair	Surface Treatment	4	138.53	\$7,696.26	\$6,464.86	\$4,617.76
DOVE ST	Odd	No	0	Concrete	Fair	Surface Treatment	4	87.57	\$4,864.97	\$4,086.57	\$2,918.98
DOVE ST	Even	No	0	Granite	New	Defer Maintenance	4	145.41	\$0.00	\$0.00	\$0.00
DOVE ST	Even	No	0	Granite	New	Defer Maintenance	4	108.26	\$0.00	\$0.00	\$0.00
DOVE ST	Even	No	0	Granite	Fair	Surface Treatment	4	152.70	\$8,483.22	\$7,125.90	\$5,089.93
DOVE ST	Even	No	0	Concrete	Poor	Rehabilitation	4	138.92	\$7,717.51	\$6,482.71	\$4,630.51
DOVE ST	Even	No	0	Concrete	Fair	Surface Treatment	4	158.57	\$8,809.21	\$7,399.74	\$5,285.53
Length:								1,216.81	\$53,507.47	\$44,946.28	\$32,104.48
EAGLE STREET											
EAGLE ST-01	Odd	Yes	2	Mix	Fair	Surface Treatment	4	251.16	\$13,953.17	\$11,720.67	\$8,371.90
EAGLE ST-01	Odd	Yes	2	Mix	Fair	Surface Treatment	4	131.13	\$7,284.95	\$6,119.36	\$4,370.97
EAGLE ST-02	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	78.03	\$1,040.39	\$1,040.39	\$1,040.39
EAGLE ST-01	Even	No	0	Concrete	Fair	Surface Treatment	4	253.21	\$14,067.12	\$11,816.38	\$8,440.27
EAGLE ST-01	Even	No	0	Concrete	Fair	Surface Treatment	4	106.50	\$5,916.69	\$4,970.02	\$3,550.01
EAGLE ST-02	Even	Yes	2	Concrete	Fair	Surface Treatment	4	93.04	\$5,168.66	\$4,341.68	\$3,101.20
EAGLE ST-02	Even	Yes	2	Concrete	Good	Routine Maintenance	4	40.60	\$541.36	\$541.36	\$541.36
Length:								953.66	\$47,972.36	\$40,549.86	\$29,416.12
ELM STREET											
ELM ST	Even	No	0	Concrete	Fair	Surface Treatment	4	293.82	\$16,323.20	\$13,711.49	\$9,793.92
Length:								293.82	\$16,323.20	\$13,711.49	\$9,793.92
GREEN STREET											
GREEN ST-01	Even	No	0	Granite	New	Defer Maintenance	6	351.25	\$0.00	\$0.00	\$0.00
Length:								351.25	\$0.00	\$0.00	\$0.00
HIGH STREET											
HIGH ST-18	Odd	No	0	Granite	Fair	Surface Treatment	6	291.24	\$24,270.12	\$20,386.90	\$14,562.07
HIGH ST-19	Odd	No	0	Granite	Good	Routine Maintenance	6	214.84	\$4,296.86	\$4,296.86	\$4,296.86
HIGH ST-21	Odd	Yes	2	Granite	Good	Routine Maintenance	4	25.38	\$338.41	\$338.41	\$338.41
HIGH ST-21	Odd	Yes	2	Granite	Fair	Surface Treatment	4	91.35	\$5,075.20	\$4,263.17	\$3,045.12
HIGH ST-23	Odd	Yes	2	Granite	Fair	Surface Treatment	4	347.85	\$19,325.08	\$16,233.06	\$11,595.05
HIGH ST-24	Odd	Yes	2	Granite	Fair	Surface Treatment	4	278.28	\$15,459.96	\$12,986.37	\$9,275.98

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
HIGH ST-25	Odd	Yes	2	Granite	Fair	Surface Treatment	4	64.50	\$3,583.43	\$3,010.08	\$2,150.06
HIGH ST-26	Odd	No	0	Granite	Good	Routine Maintenance	8	20.64	\$550.31	\$550.31	\$550.31
HIGH ST-20	Even	No	0	Granite	Fair	Surface Treatment	6	156.98	\$13,081.57	\$10,988.52	\$7,848.94
HIGH ST-21	Even	Yes	2	Granite	Good	Routine Maintenance	4	39.99	\$533.18	\$533.18	\$533.18
HIGH ST-21	Even	Yes	2	Granite	Good	Routine Maintenance	4	20.48	\$273.05	\$273.05	\$273.05
Length:								1,551.53	\$86,787.16	\$73,859.90	\$54,469.01
HILL STREET											
HILL ST-04	Odd	Yes	4	Concrete	Fair	Surface Treatment	4	544.78	\$30,265.48	\$25,423.00	\$18,159.29
HILL ST-04	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	212.61	\$11,811.89	\$9,921.99	\$7,087.14
Length:								757.39	\$42,077.37	\$35,344.99	\$25,246.42
HILLSIDE AVENUE											
HILLSIDE AVE	Odd	No	0	None	Fair	Surface Treatment	3	250.78	\$10,449.00	\$8,777.16	\$6,269.40
Length:								250.78	\$10,449.00	\$8,777.16	\$6,269.40
JOHNSON STREET											
JOHNSON ST	Even	Yes	2	Mix	Fair	Surface Treatment	4	1,027.97	\$57,109.32	\$47,971.83	\$34,265.59
JOHNSON ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	90.89	\$5,049.36	\$4,241.46	\$3,029.61
Length:								1,118.86	\$62,158.68	\$52,213.29	\$37,295.21
KENT STREET											
KENT ST-03	Odd	Yes	2	Granite	Poor	Rehabilitation	4	214.30	\$11,905.41	\$10,000.54	\$7,143.25
KENT ST-04	Odd	Yes	2	Granite	Poor	Rehabilitation	4	86.51	\$4,805.85	\$4,036.91	\$2,883.51
KENT ST-05	Odd	Yes	4	Granite	Fair	Surface Treatment	4	50.08	\$2,782.02	\$2,336.90	\$1,669.21
KENT ST-07	Odd	No	0	Granite	Fair	Surface Treatment	4	108.36	\$6,020.16	\$5,056.93	\$3,612.09
KENT ST-07	Odd	No	0	Granite	Poor	Rehabilitation	5	59.12	\$4,105.89	\$3,448.95	\$2,463.53
KENT ST-02	Even	Yes	4	Granite	Fair	Surface Treatment	4	195.33	\$10,851.68	\$9,115.41	\$6,511.01
KENT ST-03	Even	No	0	Granite	Good	Routine Maintenance	4	205.43	\$2,739.08	\$2,739.08	\$2,739.08
KENT ST-07	Even	No	0	Granite	Fair	Surface Treatment	6	55.76	\$4,646.48	\$3,903.04	\$2,787.89
Length:								974.89	\$47,856.56	\$40,637.77	\$29,809.57
LOW STREET											
LOW ST-13	Even	No	0	Granite	Good	Routine Maintenance	4	166.81	\$2,224.13	\$2,224.13	\$2,224.13
Length:								166.81	\$2,224.13	\$2,224.13	\$2,224.13
MARKET STREET											
MARKET ST-01	Even	No	0	Granite	Fair	Surface Treatment	5	51.83	\$3,599.12	\$3,023.26	\$2,159.47
MARKET ST-01	Even	No	0	Granite	Fair	Surface Treatment	6	60.74	\$5,061.69	\$4,251.82	\$3,037.01
Length:								112.57	\$8,660.81	\$7,275.08	\$5,196.48
MERRILL STREET											
MERRILL ST-01	Odd	No	0	Granite	New	Defer Maintenance	4	581.09	\$0.00	\$0.00	\$0.00
MERRILL ST-02	Odd	No	0	Granite	New	Defer Maintenance	4	132.73	\$0.00	\$0.00	\$0.00
MERRILL ST-01	Even	No	0	Granite	New	Defer Maintenance	4	266.66	\$0.00	\$0.00	\$0.00

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
MERRILL ST-01	Even	No	0	Granite	New	Defer Maintenance	4	62.74	\$0.00	\$0.00	\$0.00
MERRILL ST-01	Even	No	0	Granite	New	Defer Maintenance	4	149.51	\$0.00	\$0.00	\$0.00
MERRILL ST-02	Even	No	0	Granite	New	Defer Maintenance	4	128.39	\$0.00	\$0.00	\$0.00
Length: 1,321.12									\$0.00	\$0.00	\$0.00

MERRIMAC STREET

MERRIMAC ST-22	Odd	No	0	Granite	Fair	Surface Treatment	4	137.83	\$7,657.27	\$6,432.11	\$4,594.36
MERRIMAC ST-23	Odd	No	0	Granite	Fair	Surface Treatment	6	47.51	\$3,959.51	\$3,325.99	\$2,375.71
MERRIMAC ST-25	Odd	No	0	Granite	Fair	Surface Treatment	4	76.13	\$4,229.49	\$3,552.77	\$2,537.69
MERRIMAC ST-26	Odd	No	0	Granite	Fair	Surface Treatment	4	101.44	\$5,635.36	\$4,733.71	\$3,381.22
MERRIMAC ST-27	Odd	No	0	Granite	Fair	Surface Treatment	5	48.43	\$3,363.27	\$2,825.15	\$2,017.96
MERRIMAC ST-28	Odd	No	0	Granite	Good	Routine Maintenance	4	162.74	\$2,169.92	\$2,169.92	\$2,169.92
MERRIMAC ST-29	Odd	No	0	Granite	Fair	Surface Treatment	5	133.16	\$9,247.23	\$7,767.67	\$5,548.34
MERRIMAC ST-22	Even	No	0	Granite	Fair	Surface Treatment	5	49.46	\$3,434.67	\$2,885.13	\$2,060.80
MERRIMAC ST-23	Even	No	0	Granite	Poor	Rehabilitation	4	58.84	\$3,269.12	\$2,746.06	\$1,961.47
MERRIMAC ST-24	Even	No	0	Granite	Poor	Rehabilitation	4	137.60	\$7,644.58	\$6,421.45	\$4,586.75
MERRIMAC ST-25	Even	No	0	Granite	New	Defer Maintenance	5	130.60	\$0.00	\$0.00	\$0.00
MERRIMAC ST-25	Even	No	0	Granite	Good	Routine Maintenance	4	33.75	\$450.04	\$450.04	\$450.04
MERRIMAC ST-26	Even	No	0	Granite	Good	Routine Maintenance	4	97.80	\$1,304.06	\$1,304.06	\$1,304.06
MERRIMAC ST-27	Even	No	0	Granite	Fair	Surface Treatment	4	104.23	\$5,790.53	\$4,864.05	\$3,474.32
MERRIMAC ST-28	Even	No	0	Granite	Good	Routine Maintenance	5	73.04	\$1,217.34	\$1,217.34	\$1,217.34
MERRIMAC ST-29	Even	No	0	Granite	Fair	Surface Treatment	5	163.22	\$11,334.63	\$9,521.09	\$6,800.78
MERRIMAC ST-30	Even	No	0	Granite	Fair	Surface Treatment	4	93.42	\$5,190.01	\$4,359.61	\$3,114.01
MERRIMAC ST-31	Even	No	0	Granite	Fair	Surface Treatment	5	103.08	\$7,158.62	\$6,013.24	\$4,295.17
Length: 1,752.31									\$83,055.66	\$70,589.37	\$51,889.94

MUNROE STREET

MUNROE ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	240.79	\$3,210.50	\$3,210.50	\$3,210.50
MUNROE ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	192.41	\$2,565.50	\$2,565.50	\$2,565.50
MUNROE ST-03	Odd	No	0	Granite	Fair	Surface Treatment	5	186.57	\$12,956.33	\$10,883.32	\$7,773.80
MUNROE ST-04	Odd	Yes	2	Granite	Fair	Surface Treatment	4	86.12	\$4,784.37	\$4,018.87	\$2,870.62
MUNROE ST-04	Odd	No	0	Granite	Fair	Surface Treatment	6	43.89	\$3,657.74	\$3,072.50	\$2,194.64
MUNROE ST-01	Even	No	0	Granite	New	Defer Maintenance	6	220.14	\$0.00	\$0.00	\$0.00
MUNROE ST-02	Even	No	0	Granite	New	Defer Maintenance	4	170.77	\$0.00	\$0.00	\$0.00
MUNROE ST-04	Even	Yes	2	Granite	Fair	Surface Treatment	4	83.62	\$4,645.32	\$3,902.07	\$2,787.19
MUNROE ST-04	Even	Yes	2	Granite	New	Defer Maintenance	4	44.45	\$0.00	\$0.00	\$0.00
Length: 1,268.76									\$31,819.76	\$27,652.76	\$21,402.26

OCEAN AVENUE

OCEAN ST	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	106.70	\$5,928.04	\$4,979.56	\$3,556.83
OCEAN ST	Odd	Yes	2	Granite	Fair	Surface Treatment	4	78.60	\$4,366.64	\$3,667.98	\$2,619.99
Length: 185.30									\$10,294.69	\$8,647.54	\$6,176.81

OCEAN STREET

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
OCEAN ST	Even	Yes	2	Mix	Fair	Surface Treatment	4	203.13	\$11,285.06	\$9,479.45	\$6,771.03
							Length:	203.13	\$11,285.06	\$9,479.45	\$6,771.03
OLIVE STREET											
OLIVE ST-01	Odd	No	0	Granite	Fair	Surface Treatment	8	170.36	\$18,928.53	\$15,899.97	\$11,357.12
OLIVE ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	52.89	\$2,938.16	\$2,468.06	\$1,762.90
OLIVE ST-02	Odd	No	0	Concrete	Fair	Surface Treatment	5	68.33	\$4,744.90	\$3,985.72	\$2,846.94
OLIVE ST-03	Odd	Yes	2	Mix	Fair	Surface Treatment	4	177.46	\$9,858.96	\$8,281.53	\$5,915.38
OLIVE ST-04	Odd	No	0	Mix	Poor	Rehabilitation	4	256.13	\$14,229.31	\$11,952.62	\$8,537.58
OLIVE ST-05	Odd	No	0	Mix	Fair	Surface Treatment	4	295.72	\$16,429.16	\$13,800.49	\$9,857.49
OLIVE ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	203.48	\$11,304.53	\$9,495.81	\$6,782.72
OLIVE ST-03	Even	Yes	2	Concrete	Fair	Surface Treatment	4	113.49	\$6,305.21	\$5,296.38	\$3,783.13
OLIVE ST-04	Even	Yes	2	Concrete	Fair	Surface Treatment	4	225.21	\$12,511.46	\$10,509.62	\$7,506.87
OLIVE ST-05	Even	No	0	Mix	Fair	Surface Treatment	4	304.26	\$16,903.12	\$14,198.62	\$10,141.87
							Length:	1,867.32	\$114,153.35	\$95,888.81	\$68,492.01
PLEASANT STREET											
PLEASANT ST-05	Odd	No	0	Granite	Fair	Surface Treatment	4	111.99	\$6,221.69	\$5,226.22	\$3,733.01
PLEASANT ST-05	Even	No	0	Granite	Fair	Surface Treatment	4	117.27	\$6,514.98	\$5,472.58	\$3,908.99
							Length:	229.26	\$12,736.67	\$10,698.80	\$7,642.00
POND STREET											
POND ST-04	Odd	Yes	4	Granite	Good	Routine Maintenance	4	190.66	\$2,542.10	\$2,542.10	\$2,542.10
POND ST-05	Odd	Yes	2	Granite	New	Defer Maintenance	4	203.64	\$0.00	\$0.00	\$0.00
POND ST-06	Odd	No	0	Granite	Good	Routine Maintenance	4	81.80	\$1,090.68	\$1,090.68	\$1,090.68
POND ST-03	Even	Yes	2	Granite	Good	Routine Maintenance	4	305.91	\$4,078.79	\$4,078.79	\$4,078.79
POND ST-04	Even	Yes	2	Granite	Good	Routine Maintenance	5	215.53	\$3,592.17	\$3,592.17	\$3,592.17
POND ST-05	Even	Yes	2	Granite	Good	Routine Maintenance	5	212.50	\$3,541.75	\$3,541.75	\$3,541.75
POND ST-06	Even	No	0	Granite	Fair	Surface Treatment	4	95.04	\$5,279.77	\$4,435.00	\$3,167.86
							Length:	1,305.07	\$20,125.26	\$19,280.50	\$18,013.35
R.R. STREET											
R.R. ST	Odd	Yes	2	Granite	Poor	Rehabilitation	4	203.95	\$11,330.69	\$9,517.78	\$6,798.42
							Length:	203.95	\$11,330.69	\$9,517.78	\$6,798.42
RUSSIA STREET											
RUSSIA ST-01	Odd	No	0	Granite	New	Defer Maintenance	4	75.89	\$0.00	\$0.00	\$0.00
RUSSIA ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	55.33	\$3,073.79	\$2,581.98	\$1,844.27
RUSSIA ST-01	Even	No	0	Granite	New	Defer Maintenance	4	60.10	\$0.00	\$0.00	\$0.00
RUSSIA ST-01	Even	No	0	None	Poor	Rehabilitation	4	157.52	\$8,750.94	\$7,350.79	\$5,250.57
RUSSIA ST-01	Even	No	0	Granite	New	Defer Maintenance	4	39.73	\$0.00	\$0.00	\$0.00
RUSSIA ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	300.89	\$4,011.80	\$4,011.80	\$4,011.80
							Length:	689.45	\$15,836.54	\$13,944.58	\$11,106.64
STRONG STREET											

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
STRONG ST-01	Odd	No	0	Granite	Fair	Surface Treatment	4	158.76	\$8,819.81	\$7,408.64	\$5,291.88
STRONG ST-01	Odd	No	0	Mix	Good	Routine Maintenance	4	165.83	\$2,211.06	\$2,211.06	\$2,211.06
STRONG ST-02	Odd	No	0	Concrete	Fair	Surface Treatment	4	58.65	\$3,258.26	\$2,736.94	\$1,954.96
STRONG ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	89.60	\$1,194.70	\$1,194.70	\$1,194.70
STRONG ST-01	Even	No	0	Granite	Poor	Rehabilitation	4	38.30	\$2,128.02	\$1,787.54	\$1,276.81
STRONG ST-01	Even	No	0	None	Good	Routine Maintenance	5	151.23	\$2,520.45	\$2,520.45	\$2,520.45
STRONG ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	127.26	\$7,069.92	\$5,938.73	\$4,241.95
Length:								789.63	\$27,202.21	\$23,798.05	\$18,691.80

SUMMER STREET

SUMMER ST-01	Odd	No	0	Granite	Fair	Surface Treatment	5	404.61	\$28,097.87	\$23,602.21	\$16,858.72
SUMMER ST-02	Odd	No	0	Granite	Poor	Rehabilitation	5	116.78	\$8,109.55	\$6,812.02	\$4,865.73
SUMMER ST-03	Odd	No	0	Granite	Poor	Rehabilitation	4	220.11	\$12,228.56	\$10,271.99	\$7,337.13
SUMMER ST-04	Odd	No	0	Granite	Fair	Surface Treatment	4	225.97	\$12,554.01	\$10,545.37	\$7,532.41
Length:								967.47	\$60,989.99	\$51,231.59	\$36,593.99

SUMMIT PLACE

SUMMIT PL	Even	No	0	Granite	Poor	Rehabilitation	5	127.01	\$8,819.97	\$7,408.77	\$5,291.98
Length:								127.01	\$8,819.97	\$7,408.77	\$5,291.98

TOPPAN'S LANE

TOPPAN'S LN-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	389.59	\$21,644.16	\$18,181.10	\$12,986.50
TOPPAN'S LN-02	Odd	No	0	Granite	Fair	Surface Treatment	4	135.45	\$7,524.96	\$6,320.96	\$4,514.97
TOPPAN'S LN-02	Odd	No	0	None	Fair	Surface Treatment	4	328.39	\$18,243.75	\$15,324.75	\$10,946.25
TOPPAN'S LN-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	548.42	\$30,467.99	\$25,593.11	\$18,280.79
TOPPAN'S LN-03	Odd	No	0	Granite	Fair	Surface Treatment	4	730.83	\$40,601.61	\$34,105.35	\$24,360.97
Length:								2,132.68	\$118,482.46	\$99,525.27	\$71,089.48

VERNON STREET

VERNON ST-01	Even	No	0	Granite	Poor	Rehabilitation	4	43.14	\$2,396.41	\$2,012.98	\$1,437.84
VERNON ST-03	Even	No	0	Granite	Fair	Surface Treatment	4	55.46	\$3,081.21	\$2,588.22	\$1,848.73
Length:								98.60	\$5,477.62	\$4,601.20	\$3,286.57

WARREN STREET

WARREN ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	56.82	\$757.66	\$757.66	\$757.66
WARREN ST-01	Odd	No	0	Granite	New	Defer Maintenance	4	140.17	\$0.00	\$0.00	\$0.00
WARREN ST-02	Odd	No	0	Concrete	Good	Routine Maintenance	4	70.22	\$936.29	\$936.29	\$936.29
WARREN ST-03	Odd	No	0	Concrete	Fair	Surface Treatment	4	124.87	\$6,936.96	\$5,827.05	\$4,162.18
WARREN ST-04	Odd	Yes	2	Granite	Good	Routine Maintenance	4	99.73	\$1,329.69	\$1,329.69	\$1,329.69
WARREN ST-05	Odd	Yes	2	Granite	Good	Routine Maintenance	4	131.20	\$1,749.28	\$1,749.28	\$1,749.28
WARREN ST-06	Odd	Yes	2	Mix	Fair	Surface Treatment	4	123.27	\$6,848.14	\$5,752.44	\$4,108.89
WARREN ST-06	Odd	Yes	2	Granite	Good	Routine Maintenance	4	108.30	\$1,443.93	\$1,443.93	\$1,443.93
WARREN ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	19.19	\$1,066.37	\$895.75	\$639.82
WARREN ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	203.95	\$11,330.33	\$9,517.48	\$6,798.20

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
WARREN ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	107.06	\$5,947.75	\$4,996.11	\$3,568.65
WARREN ST-04	Even	No	0	Granite	Good	Routine Maintenance	4	81.15	\$1,081.95	\$1,081.95	\$1,081.95
WARREN ST-05	Even	No	0	Concrete	Fair	Surface Treatment	4	91.20	\$5,066.54	\$4,255.89	\$3,039.92
WARREN ST-06	Even	Yes	2	Concrete	Poor	Rehabilitation	4	243.31	\$13,517.42	\$11,354.63	\$8,110.45
Length: 1,600.42									\$58,012.32	\$49,898.16	\$37,726.92

WASHINGTON STREET

WASHINGTON ST-01	Odd	No	0	Granite	Poor	Rehabilitation	6	300.90	\$25,074.87	\$21,062.89	\$15,044.92
WASHINGTON ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	128.44	\$1,712.50	\$1,712.50	\$1,712.50
WASHINGTON ST-02	Odd	Yes	2	Granite	Fair	Surface Treatment	4	109.04	\$6,057.98	\$5,088.70	\$3,634.79
WASHINGTON ST-03	Odd	No	0	Granite	Fair	Surface Treatment	6	134.87	\$11,239.54	\$9,441.21	\$6,743.72
WASHINGTON ST-05	Odd	No	0	Granite	New	Defer Maintenance	5	113.49	\$0.00	\$0.00	\$0.00
WASHINGTON ST-05	Odd	No	0	Granite	Fair	Surface Treatment	5	71.19	\$4,944.04	\$4,152.99	\$2,966.42
WASHINGTON ST-07	Odd	No	0	Granite	Fair	Surface Treatment	4	77.71	\$4,317.24	\$3,626.48	\$2,590.34
WASHINGTON ST-08	Odd	No	0	Granite	Fair	Surface Treatment	6	295.72	\$24,642.95	\$20,700.08	\$14,785.77
WASHINGTON ST-10	Odd	No	0	Granite	New	Defer Maintenance	8	160.96	\$0.00	\$0.00	\$0.00
WASHINGTON ST-10	Odd	No	0	Granite	Fair	Surface Treatment	6	114.05	\$9,503.78	\$7,983.18	\$5,702.27
WASHINGTON ST-04	Even	No	0	Granite	Fair	Surface Treatment	6	177.51	\$14,792.67	\$12,425.84	\$8,875.60
WASHINGTON ST-04	Even	No	0	Granite	Poor	Rehabilitation	6	90.04	\$7,503.03	\$6,302.54	\$4,501.82
WASHINGTON ST-05	Even	Yes	2	Granite	New	Defer Maintenance	4	69.86	\$0.00	\$0.00	\$0.00
WASHINGTON ST-05	Even	No	0	Granite	Fair	Surface Treatment	5	186.85	\$12,975.72	\$10,899.60	\$7,785.43
WASHINGTON ST-07	Even	No	0	Granite	Fair	Surface Treatment	5	61.25	\$4,253.66	\$3,573.07	\$2,552.19
Length: 2,091.88									\$127,017.96	\$106,969.09	\$76,895.78

WINTER STREET

WINTER ST-02	Even	No	0	Granite	Good	Routine Maintenance	5	673.71	\$11,228.50	\$11,228.50	\$11,228.50
WINTER ST-03	Even	No	0	Granite	Fair	Surface Treatment	5	377.22	\$26,195.97	\$22,004.62	\$15,717.58
Length: 1,050.93									\$37,424.47	\$33,233.12	\$26,946.09

Ward: 4

ADAMS STREET

ADAMS ST-01	Even	Yes	4	None	Fair	Surface Treatment	2	183.54	\$5,098.39	\$4,282.65	\$3,059.03
ADAMS ST-01	Even	Yes	4	Concrete	New	Defer Maintenance	4	266.52	\$0.00	\$0.00	\$0.00
ADAMS ST-02	Even	Yes	4	None	Poor	Rehabilitation	2	85.36	\$2,370.97	\$1,991.62	\$1,422.58
Length: 535.42									\$7,469.36	\$6,274.26	\$4,481.62

ASHLAND COURT

ATKINSON CT	Odd	Yes	2	Granite	Fair	Surface Treatment	4	164.66	\$9,147.52	\$7,683.92	\$5,488.51
Length: 164.66									\$9,147.52	\$7,683.92	\$5,488.51

ASHLAND STREET

ASHLAND ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	322.80	\$17,933.59	\$15,064.22	\$10,760.16
ASHLAND ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	45.94	\$2,552.42	\$2,144.03	\$1,531.45
ASHLAND ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	93.27	\$5,181.86	\$4,352.76	\$3,109.11

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
ASHLAND ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	66.18	\$882.41	\$882.41	\$882.41
ASHLAND ST-03	Odd	Yes	2	Granite	Fair	Surface Treatment	4	226.10	\$12,561.35	\$10,551.53	\$7,536.81
ASHLAND ST-03	Odd	Yes	2	Granite	Good	Routine Maintenance	4	41.92	\$558.91	\$558.91	\$558.91
ASHLAND ST-04	Odd	Yes	2	Granite	Fair	Surface Treatment	4	60.57	\$3,364.84	\$2,826.46	\$2,018.90
ASHLAND ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	436.74	\$24,263.47	\$20,381.32	\$14,558.08
ASHLAND ST-01	Even	No	0	Mix	Fair	Surface Treatment	4	88.21	\$4,900.49	\$4,116.41	\$2,940.30
ASHLAND ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	81.77	\$4,542.92	\$3,816.05	\$2,725.75
ASHLAND ST-04	Even	Yes	2	Granite	Fair	Surface Treatment	4	98.83	\$5,490.39	\$4,611.92	\$3,294.23
Length:								1,562.34	\$82,232.64	\$69,306.03	\$49,916.11

BEACON AVENUE

BEACON ST	Even	Yes	2	None	Fair	Surface Treatment	3	54.19	\$2,258.12	\$1,896.82	\$1,354.87
Length:								54.19	\$2,258.12	\$1,896.82	\$1,354.87

BEACON STREET

BEACON ST	Odd	Yes	2	None	Gap	Gap	2	80.91	\$2,247.45	\$0.00	\$0.00
BEACON ST	Odd	Yes	2	None	Fair	Surface Treatment	2	160.98	\$4,471.69	\$3,756.22	\$2,683.02
Length:								241.89	\$6,719.15	\$3,756.22	\$2,683.02

BROAD STREET

BROAD ST-01	Even	Yes	4	Granite	Fair	Surface Treatment	4	117.53	\$6,529.31	\$5,484.62	\$3,917.58
BROAD ST-02	Even	Yes	5	Granite	Fair	Surface Treatment	4	123.33	\$6,851.40	\$5,755.18	\$4,110.84
BROAD ST-02	Even	Yes	6	Granite	Fair	Surface Treatment	4	241.02	\$13,390.22	\$11,247.78	\$8,034.13
BROAD ST-02	Even	Yes	4	Granite	Fair	Surface Treatment	4	159.95	\$8,886.25	\$7,464.45	\$5,331.75
Length:								641.83	\$35,657.18	\$29,952.03	\$21,394.31

BUTLER STREET

BUTLER ST	Odd	Yes	2	Mix	Fair	Surface Treatment	4	184.19	\$10,232.61	\$8,595.39	\$6,139.57
BUTLER ST	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	149.99	\$8,332.69	\$6,999.46	\$4,999.61
BUTLER ST	Even	Yes	2	Concrete	Good	Routine Maintenance	4	446.68	\$5,955.77	\$5,955.77	\$5,955.77
Length:								780.86	\$24,521.07	\$21,550.63	\$17,094.95

CALIFORNIA STREET

CALIFORNIA ST	Odd	Yes	4	Granite	Fair	Surface Treatment	4	270.41	\$15,022.62	\$12,619.00	\$9,013.57
CALIFORNIA ST	Even	Yes	4	Granite	Fair	Surface Treatment	3	271.95	\$11,331.05	\$9,518.08	\$6,798.63
Length:								542.35	\$26,353.67	\$22,137.08	\$15,812.20

CHAPEL STREET

CHAPEL ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	459.98	\$25,554.58	\$21,465.84	\$15,332.75
CHAPEL ST-02	Odd	Yes	2	Granite	New	Defer Maintenance	4	69.66	\$0.00	\$0.00	\$0.00
CHAPEL ST-02	Odd	Yes	2	Mix	Fair	Surface Treatment	4	140.51	\$7,805.83	\$6,556.90	\$4,683.50
CHAPEL ST-03	Odd	Yes	2	Granite	Fair	Surface Treatment	4	248.72	\$13,817.93	\$11,607.06	\$8,290.76
CHAPEL ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	462.22	\$25,678.75	\$21,570.15	\$15,407.25
CHAPEL ST-01	Even	Yes	2	Concrete	Gap	Gap	4	87.08	\$4,837.89	\$0.00	\$0.00
CHAPEL ST-02	Even	Yes	2	Mix	Fair	Surface Treatment	4	247.98	\$13,776.76	\$11,572.48	\$8,266.06

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
CHAPEL ST-02	Even	Yes	2	Granite	Good	Routine Maintenance	4	278.47	\$3,712.99	\$3,712.99	\$3,712.99
							Length:	1,994.62	\$95,184.73	\$76,485.43	\$55,693.30
COLLINS STREET											
COLLINS ST	Odd	No	0	Granite	New	Defer Maintenance	4	93.09	\$0.00	\$0.00	\$0.00
COLLINS ST	Odd	No	0	Granite	Fair	Surface Treatment	4	450.21	\$25,011.48	\$21,009.64	\$15,006.89
COLLINS ST	Odd	No	0	Granite	Gap	Gap	4	181.19	\$10,066.26	\$0.00	\$0.00
COLLINS ST	Odd	No	0	Granite	Fair	Surface Treatment	4	171.41	\$9,522.51	\$7,998.91	\$5,713.51
COLLINS ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	491.24	\$27,290.92	\$22,924.37	\$16,374.55
COLLINS ST	Even	Yes	2	Granite	New	Defer Maintenance	4	80.11	\$0.00	\$0.00	\$0.00
							Length:	1,467.24	\$71,891.16	\$51,932.92	\$37,094.94
COLUMBUS AVENUE											
COLUMBUS AVE-02	Odd	Yes	2	Granite	Fair	Surface Treatment	4	116.41	\$6,467.11	\$5,432.37	\$3,880.27
COLUMBUS AVE-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	257.01	\$14,278.12	\$11,993.62	\$8,566.87
COLUMBUS AVE-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	407.05	\$22,613.72	\$18,995.52	\$13,568.23
							Length:	780.46	\$43,358.95	\$36,421.52	\$26,015.37
DAWES STREET											
DAWES ST	Odd	Yes	2	Mix	Good	Routine Maintenance	4	211.03	\$2,813.74	\$2,813.74	\$2,813.74
DAWES ST	Odd	Yes	2	Concrete	Good	Routine Maintenance	2	170.59	\$1,137.27	\$1,137.27	\$1,137.27
DAWES ST	Odd	Yes	2	Concrete	Good	Routine Maintenance	2	44.30	\$295.30	\$295.30	\$295.30
DAWES ST	Even	Yes	2	None	Good	Routine Maintenance	4	100.12	\$1,334.97	\$1,334.97	\$1,334.97
							Length:	526.04	\$5,581.29	\$5,581.29	\$5,581.29
DEXTER LANE											
DEXTER ST	Odd	No	0	Mix	Fair	Surface Treatment	4	234.23	\$13,012.72	\$10,930.69	\$7,807.63
							Length:	234.23	\$13,012.72	\$10,930.69	\$7,807.63
DEXTER STREET											
DEXTER ST	Odd	No	0	Mix	Gap	Gap	4	139.00	\$7,722.06	\$0.00	\$0.00
DEXTER ST	Even	Yes	2	Granite	Fair	Surface Treatment	3	425.17	\$17,715.52	\$14,881.04	\$10,629.31
							Length:	564.17	\$25,437.58	\$14,881.04	\$10,629.31
DONER DRIVE											
DONER DR	Even	No	0	Granite	New	Defer Maintenance	4	111.91	\$0.00	\$0.00	\$0.00
							Length:	111.91	\$0.00	\$0.00	\$0.00
DOROTHY LUCY DRIVE											
DOROTHY LUCY DR-01	Odd	No	0	Granite	New	Defer Maintenance	4	1,312.94	\$0.00	\$0.00	\$0.00
DOROTHY LUCY DR-02	Odd	No	0	Granite	New	Defer Maintenance	4	376.88	\$0.00	\$0.00	\$0.00
DOROTHY LUCY DR-03	Odd	No	0	Granite	New	Defer Maintenance	4	129.68	\$0.00	\$0.00	\$0.00
DOROTHY LUCY DR-02	Even	No	0	Granite	New	Defer Maintenance	4	30.58	\$0.00	\$0.00	\$0.00
							Length:	1,850.08	\$0.00	\$0.00	\$0.00
FARRELL STREET											

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
FARRELL ST-01	Even	Yes	2	Granite	Fair	Surface Treatment	4	87.20	\$4,844.49	\$4,069.38	\$2,906.70
							Length:	87.20	\$4,844.49	\$4,069.38	\$2,906.70
FORRESTER STREET											
FORRESTER ST-01	Odd	Yes	2	Granite	Fair	Surface Treatment	4	341.40	\$18,966.44	\$15,931.81	\$11,379.86
FORRESTER ST-02	Odd	No	0	Concrete	Fair	Surface Treatment	6	84.09	\$7,007.52	\$5,886.31	\$4,204.51
FORRESTER ST-03	Odd	No	0	Granite	Good	Routine Maintenance	6	391.69	\$7,833.87	\$7,833.87	\$7,833.87
FORRESTER ST-03	Odd	Yes	2	Granite	Good	Routine Maintenance	4	34.12	\$454.89	\$454.89	\$454.89
FORRESTER ST-04	Odd	Yes	2	Granite	Fair	Surface Treatment	4	330.19	\$18,344.15	\$15,409.09	\$11,006.49
FORRESTER ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	521.19	\$28,955.10	\$24,322.29	\$17,373.06
FORRESTER ST-02	Even	Yes	2	Concrete	Fair	Surface Treatment	4	88.64	\$4,924.53	\$4,136.60	\$2,954.72
FORRESTER ST-03	Even	Yes	2	Concrete	Fair	Surface Treatment	4	544.01	\$30,222.98	\$25,387.30	\$18,133.79
FORRESTER ST-04	Even	Yes	2	Mix	Fair	Surface Treatment	4	339.67	\$18,870.80	\$15,851.47	\$11,322.48
							Length:	2,675.01	\$135,580.28	\$115,213.64	\$84,663.67
GOVE DRIVE											
GOVE DR	Odd	No	0	Granite	New	Defer Maintenance	4	410.42	\$0.00	\$0.00	\$0.00
							Length:	410.42	\$0.00	\$0.00	\$0.00
HIGH STREET											
HIGH ST-08	Odd	Yes	4	Granite	Fair	Surface Treatment	4	307.51	\$17,083.71	\$14,350.32	\$10,250.23
HIGH ST-09	Odd	Yes	4	Granite	New	Defer Maintenance	4	246.40	\$0.00	\$0.00	\$0.00
HIGH ST-10	Odd	Yes	4	Granite	Fair	Surface Treatment	4	224.64	\$12,480.25	\$10,483.41	\$7,488.15
HIGH ST-10	Odd	Yes	4	Granite	Poor	Rehabilitation	4	191.61	\$10,644.85	\$8,941.68	\$6,386.91
HIGH ST-12	Odd	No	0	Granite	Good	Routine Maintenance	4	69.83	\$931.01	\$931.01	\$931.01
HIGH ST-12	Odd	No	0	Granite	Good	Routine Maintenance	4	34.89	\$465.22	\$465.22	\$465.22
HIGH ST-13	Odd	Yes	2	Granite	Fair	Surface Treatment	4	149.04	\$8,280.24	\$6,955.40	\$4,968.15
HIGH ST-14	Odd	Yes	2	Granite	Good	Routine Maintenance	4	166.26	\$2,216.80	\$2,216.80	\$2,216.80
HIGH ST-15	Odd	Yes	2	Granite	Good	Routine Maintenance	4	61.07	\$814.24	\$814.24	\$814.24
HIGH ST-16	Odd	Yes	2	Granite	Good	Routine Maintenance	4	152.59	\$2,034.58	\$2,034.58	\$2,034.58
HIGH ST-01	Even	Yes	2	Granite	Good	Routine Maintenance	4	300.25	\$4,003.35	\$4,003.35	\$4,003.35
HIGH ST-03	Even	Yes	2	Granite	Fair	Surface Treatment	4	293.09	\$16,282.77	\$13,677.53	\$9,769.66
HIGH ST-04	Even	Yes	2	Granite	Fair	Surface Treatment	4	141.72	\$7,873.16	\$6,613.45	\$4,723.90
HIGH ST-05	Even	Yes	2	Granite	Good	Routine Maintenance	4	105.37	\$1,404.96	\$1,404.96	\$1,404.96
HIGH ST-07	Even	Yes	2	Granite	Fair	Surface Treatment	4	130.35	\$7,241.71	\$6,083.04	\$4,345.03
HIGH ST-08	Even	Yes	2	Granite	Good	Routine Maintenance	4	224.60	\$2,994.61	\$2,994.61	\$2,994.61
HIGH ST-09	Even	Yes	2	Granite	Good	Routine Maintenance	4	33.83	\$451.06	\$451.06	\$451.06
HIGH ST-11	Even	Yes	2	Granite	New	Defer Maintenance	4	51.89	\$0.00	\$0.00	\$0.00
							Length:	2,884.93	\$95,202.53	\$82,420.66	\$63,247.85
HIGHLAND AVENUE											
HIGHLAND AVE-01	Odd	No	0	Concrete	Good	Routine Maintenance	4	271.97	\$3,626.23	\$3,626.23	\$3,626.23
HIGHLAND AVE-02	Odd	No	0	Granite	Poor	Rehabilitation	4	132.56	\$7,364.37	\$6,186.07	\$4,418.62
HIGHLAND AVE-03	Even	Yes	2	None	Good	Routine Maintenance	4	233.68	\$3,115.78	\$3,115.78	\$3,115.78

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
HIGHLAND AVE-03	Even	Yes	2	Granite	Good	Routine Maintenance	4	606.86	\$8,091.50	\$8,091.50	\$8,091.50	
								Length:	1,245.07	\$22,197.87	\$21,019.58	\$19,252.13
HOWARD STREET												
HOWARD ST-01	Odd	Yes	2	Granite	Good	Routine Maintenance	3	110.83	\$1,108.30	\$1,108.30	\$1,108.30	
HOWARD ST-01	Odd	No	0	Mix	Fair	Surface Treatment	4	134.57	\$7,476.18	\$6,279.99	\$4,485.71	
HOWARD ST-02	Odd	Yes	2	Granite	Gap	Gap	4	119.87	\$6,659.21	\$0.00	\$0.00	
HOWARD ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	117.51	\$1,566.85	\$1,566.85	\$1,566.85	
HOWARD ST-01	Even	Yes	2	Granite	Good	Routine Maintenance	4	51.59	\$687.87	\$687.87	\$687.87	
HOWARD ST-01	Even	No	0	Granite	Gap	Gap	4	60.41	\$3,355.89	\$0.00	\$0.00	
HOWARD ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	127.61	\$7,089.34	\$5,955.05	\$4,253.61	
								Length:	722.38	\$27,943.64	\$15,598.06	\$12,102.33
JACKSON STREET												
JACKSON ST-01	Odd	No	0	Granite	New	Defer Maintenance	4	260.69	\$0.00	\$0.00	\$0.00	
JACKSON ST-02	Odd	No	0	Granite	New	Defer Maintenance	4	146.41	\$0.00	\$0.00	\$0.00	
JACKSON ST-03	Odd	Yes	2	Granite	New	Defer Maintenance	4	203.91	\$0.00	\$0.00	\$0.00	
JACKSON ST-01	Even	Yes	2	Granite	New	Defer Maintenance	4	280.12	\$0.00	\$0.00	\$0.00	
JACKSON ST-02	Even	Yes	2	Granite	New	Defer Maintenance	4	186.72	\$0.00	\$0.00	\$0.00	
JACKSON ST-03	Even	Yes	2	Granite	New	Defer Maintenance	4	212.45	\$0.00	\$0.00	\$0.00	
								Length:	1,290.30	\$0.00	\$0.00	\$0.00
JEFFERSON STREET												
JEFFERSON ST-04	Odd	Yes	5	Asphalt	New	Defer Maintenance	3	583.08	\$0.00	\$0.00	\$0.00	
JEFFERSON ST-01	Even	Yes	4	Concrete	Good	Routine Maintenance	3	400.68	\$4,006.81	\$4,006.81	\$4,006.81	
JEFFERSON ST-02	Even	Yes	2	Concrete	Good	Routine Maintenance	3	226.49	\$2,264.93	\$2,264.93	\$2,264.93	
JEFFERSON ST-03	Even	Yes	2	Mix	New	Defer Maintenance	4	227.26	\$0.00	\$0.00	\$0.00	
JEFFERSON ST-04	Even	Yes	2	Asphalt	Good	Routine Maintenance	4	513.51	\$6,846.76	\$6,846.76	\$6,846.76	
								Length:	1,951.02	\$13,118.50	\$13,118.50	\$13,118.50
LAFAYETTE STREET												
LAFAYETTE ST	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	761.12	\$42,284.72	\$35,519.17	\$25,370.83	
LAFAYETTE ST	Odd	No	0	Concrete	Poor	Rehabilitation	4	104.07	\$5,781.78	\$4,856.70	\$3,469.07	
LAFAYETTE ST	Even	Yes	2	Concrete	Fair	Surface Treatment	4	916.82	\$50,934.22	\$42,784.75	\$30,560.53	
								Length:	1,782.01	\$99,000.73	\$83,160.61	\$59,400.44
LOW STREET												
LOW ST-10	Even	No	0	Granite	Good	Routine Maintenance	4	58.97	\$786.31	\$786.31	\$786.31	
								Length:	58.97	\$786.31	\$786.31	\$786.31
MAGNOLIA STREET												
MAGNOLIA ST	Odd	Yes	2	None	Gap	Gap	2	325.50	\$9,041.80	\$0.00	\$0.00	
MAGNOLIA ST	Odd	Yes	2	None	Fair	Surface Treatment	2	80.62	\$2,239.52	\$1,881.20	\$1,343.71	
MAGNOLIA ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	235.66	\$13,092.24	\$10,997.49	\$7,855.35	
MAGNOLIA ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	50.61	\$2,811.74	\$2,361.86	\$1,687.05	

BETA Group, Inc.

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
							Length:	692.40	\$27,185.31	\$15,240.55	\$10,886.11
MAPLE STREET											
MAPLE ST	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	190.93	\$10,607.35	\$8,910.18	\$6,364.41
MAPLE ST	Even	Yes	2	Concrete	Good	Routine Maintenance	4	161.07	\$2,147.61	\$2,147.61	\$2,147.61
MAPLE ST	Even	No	0	Concrete	Fair	Surface Treatment	4	207.02	\$11,501.26	\$9,661.06	\$6,900.76
							Length:	559.03	\$24,256.22	\$20,718.85	\$15,412.78
MERRIMAC COURT											
MERRIMAC CT	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	68.28	\$910.45	\$910.45	\$910.45
MERRIMAC CT	Even	Yes	2	Concrete	Good	Routine Maintenance	3	185.60	\$1,856.00	\$1,856.00	\$1,856.00
							Length:	253.88	\$2,766.45	\$2,766.45	\$2,766.45
MERRIMAC STREET											
MERRIMAC ST-07	Odd	Yes	6	Mix	Fair	Surface Treatment	4	437.63	\$24,312.95	\$20,422.88	\$14,587.77
MERRIMAC ST-12	Odd	No	0	Granite	Fair	Surface Treatment	6	183.54	\$15,295.09	\$12,847.87	\$9,177.05
MERRIMAC ST-19	Odd	No	0	Granite	Fair	Surface Treatment	5	99.80	\$6,930.74	\$5,821.82	\$4,158.44
MERRIMAC ST-01	Even	Yes	2	Granite	New	Defer Maintenance	3	127.56	\$0.00	\$0.00	\$0.00
MERRIMAC ST-01	Even	Yes	2	Granite	New	Defer Maintenance	3	240.66	\$0.00	\$0.00	\$0.00
MERRIMAC ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	3	82.11	\$3,421.09	\$2,873.71	\$2,052.65
MERRIMAC ST-02	Even	Yes	2	Granite	Good	Routine Maintenance	3	46.61	\$466.08	\$466.08	\$466.08
MERRIMAC ST-06	Even	Yes	2	Concrete	Fair	Surface Treatment	4	152.31	\$8,461.75	\$7,107.87	\$5,077.05
MERRIMAC ST-07	Even	Yes	2	Concrete	Fair	Surface Treatment	4	147.49	\$8,193.74	\$6,882.74	\$4,916.24
MERRIMAC ST-09	Even	Yes	2	Concrete	Fair	Surface Treatment	4	917.38	\$50,965.41	\$42,810.94	\$30,579.25
MERRIMAC ST-10	Even	Yes	2	Concrete	Poor	Rehabilitation	4	262.56	\$14,586.49	\$12,252.65	\$8,751.89
MERRIMAC ST-11	Even	Yes	2	Concrete	Fair	Surface Treatment	4	53.07	\$2,948.24	\$2,476.52	\$1,768.94
MERRIMAC ST-11	Even	Yes	2	Concrete	New	Defer Maintenance	4	58.08	\$0.00	\$0.00	\$0.00
MERRIMAC ST-13	Even	Yes	2	Concrete	Good	Routine Maintenance	4	57.21	\$762.85	\$762.85	\$762.85
MERRIMAC ST-15	Even	No	0	Granite	Fair	Surface Treatment	4	211.15	\$11,730.63	\$9,853.73	\$7,038.38
MERRIMAC ST-16	Even	Yes	2	Granite	Fair	Surface Treatment	4	59.34	\$3,296.71	\$2,769.23	\$1,978.02
MERRIMAC ST-16	Even	Yes	2	Concrete	Fair	Surface Treatment	4	168.33	\$9,351.69	\$7,855.42	\$5,611.01
MERRIMAC ST-18	Even	Yes	2	Granite	Poor	Rehabilitation	4	117.19	\$6,510.62	\$5,468.92	\$3,906.37
							Length:	3,422.02	\$167,234.07	\$140,673.25	\$100,832.02
MOSELEY AVENUE											
MOSELEY AVE-11	Even	No	0	Granite	New	Defer Maintenance	4	261.21	\$0.00	\$0.00	\$0.00
MOULTON ST-01	Even	Yes	2	Granite	Good	Routine Maintenance	4	211.41	\$2,818.83	\$2,818.83	\$2,818.83
							Length:	472.62	\$2,818.83	\$2,818.83	\$2,818.83
MUNROE STREET											
MUNROE ST-05	Odd	Yes	4	Granite	Fair	Surface Treatment	4	256.66	\$14,259.02	\$11,977.57	\$8,555.41
MUNROE ST-05	Even	Yes	2	Mix	Fair	Surface Treatment	4	261.90	\$14,550.02	\$12,222.02	\$8,730.01
MUNROE ST-06	Even	Yes	2	Concrete	Fair	Surface Treatment	4	221.67	\$12,314.99	\$10,344.59	\$7,388.99
							Length:	740.23	\$41,124.03	\$34,544.18	\$24,674.42

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
NORTH ATKINSON STREET												
	NORTH ATKINSON ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	148.17	\$8,231.93	\$6,914.82	\$4,939.16
	NORTH ATKINSON ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	112.64	\$6,257.50	\$5,256.30	\$3,754.50
	NORTH ATKINSON ST-01	Odd	No	0	Concrete	Fair	Surface Treatment	4	250.15	\$13,897.24	\$11,673.68	\$8,338.34
	Length:							510.96	\$28,386.67	\$23,844.80	\$17,032.00	
OAKLAND STREET												
	OAKLAND ST-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	295.22	\$16,401.06	\$13,776.89	\$9,840.64
	OAKLAND ST-03	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	173.56	\$9,642.45	\$8,099.66	\$5,785.47
	OAKLAND ST-04	Odd	Yes	2	Mix	Fair	Surface Treatment	4	372.37	\$20,687.39	\$17,377.41	\$12,412.43
	OAKLAND ST-05	Odd	Yes	2	Mix	Good	Routine Maintenance	4	284.93	\$3,799.06	\$3,799.06	\$3,799.06
	OAKLAND ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	311.98	\$17,332.41	\$14,559.22	\$10,399.44
	OAKLAND ST-02	Even	Yes	2	Mix	Fair	Surface Treatment	4	282.78	\$15,709.81	\$13,196.24	\$9,425.88
	OAKLAND ST-03	Even	Yes	2	Concrete	Fair	Surface Treatment	4	227.62	\$12,645.31	\$10,622.06	\$7,587.18
	OAKLAND ST-04	Even	Yes	2	Mix	Good	Routine Maintenance	4	358.10	\$4,774.63	\$4,774.63	\$4,774.63
	OAKLAND ST-05	Even	Yes	2	Concrete	Good	Routine Maintenance	4	49.52	\$660.25	\$660.25	\$660.25
	Length:							2,356.08	\$101,652.37	\$86,865.42	\$64,685.00	
PAYSON STREET												
	PAYSON ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	222.01	\$12,334.16	\$10,360.70	\$7,400.50
	PAYSON ST-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	245.61	\$13,645.01	\$11,461.81	\$8,187.01
	PAYSON ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	130.69	\$7,260.58	\$6,098.89	\$4,356.35
	PAYSON ST-02	Even	Yes	2	Concrete	Fair	Surface Treatment	2	71.17	\$1,976.82	\$1,660.53	\$1,186.09
	PAYSON ST-02	Even	Yes	2	Concrete	Fair	Surface Treatment	2	156.63	\$4,350.86	\$3,654.73	\$2,610.52
	Length:							826.11	\$39,567.44	\$33,236.65	\$23,740.46	
PLUMMER AVENUE												
	PLUMMER AVE-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	553.28	\$30,737.67	\$25,819.64	\$18,442.60
	PLUMMER AVE-02	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	90.96	\$1,212.77	\$1,212.77	\$1,212.77
	PLUMMER AVE-03	Odd	Yes	2	Granite	New	Defer Maintenance	4	25.61	\$0.00	\$0.00	\$0.00
	PLUMMER AVE-03	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	571.56	\$31,753.39	\$26,672.84	\$19,052.03
	PLUMMER AVE-01	Even	Yes	2	Mix	Fair	Surface Treatment	4	331.60	\$18,422.10	\$15,474.56	\$11,053.26
	PLUMMER AVE-02	Even	Yes	2	Mix	Fair	Surface Treatment	4	104.55	\$5,808.24	\$4,878.92	\$3,484.94
	PLUMMER AVE-03	Even	Yes	2	Mix	Fair	Surface Treatment	4	589.67	\$32,759.24	\$27,517.76	\$19,655.54
	Length:							2,267.22	\$120,693.40	\$101,576.50	\$72,901.15	
RAWSON AVENUE												
	RAWSON AVE-01	Even	Yes	4	Concrete	New	Defer Maintenance	2	238.37	\$0.00	\$0.00	\$0.00
	Length:							238.37	\$0.00	\$0.00	\$0.00	
STANLEY STREET												
	STANLEY ST	Odd	Yes	2	Mix	New	Defer Maintenance	2	380.81	\$0.00	\$0.00	\$0.00
	Length:							380.81	\$0.00	\$0.00	\$0.00	

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
TOPPAN'S LANE											
TOPPAN'S LN-01	Even	Yes	2	Concrete	Poor	Rehabilitation	4	86.24	\$4,790.98	\$4,024.42	\$2,874.59
TOPPAN'S LN-01	Even	Yes	2	Granite	Fair	Surface Treatment	4	78.77	\$4,375.98	\$3,675.82	\$2,625.59
Length:								165.01	\$9,166.96	\$7,700.24	\$5,500.17
TYNG STREET											
TYNG ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	97.39	\$5,410.53	\$4,544.84	\$3,246.32
TYNG ST-01	Odd	Yes	2	Mix	Fair	Surface Treatment	4	271.21	\$15,067.36	\$12,656.58	\$9,040.42
TYNG ST-01	Odd	No	0	Granite	Good	Routine Maintenance	6	98.76	\$1,975.14	\$1,975.14	\$1,975.14
TYNG ST-01	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	39.08	\$2,171.03	\$1,823.67	\$1,302.62
TYNG ST-02	Odd	Yes	4	Concrete	New	Defer Maintenance	4	66.38	\$0.00	\$0.00	\$0.00
TYNG ST-02	Odd	Yes	4	Concrete	Fair	Surface Treatment	4	158.68	\$8,815.37	\$7,404.91	\$5,289.22
TYNG ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	50.55	\$2,808.26	\$2,358.93	\$1,684.95
Length:								782.04	\$36,247.69	\$30,764.08	\$22,538.67
WALNUT STREET											
WALNUT ST-01	Odd	Yes	4	Concrete	Fair	Surface Treatment	4	358.28	\$19,904.62	\$16,719.88	\$11,942.77
WALNUT ST-02	Odd	Yes	4	Concrete	Good	Routine Maintenance	4	321.71	\$4,289.47	\$4,289.47	\$4,289.47
WALNUT ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	98.46	\$5,470.12	\$4,594.90	\$3,282.07
WALNUT ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	161.24	\$8,957.63	\$7,524.41	\$5,374.58
WALNUT ST-02	Even	Yes	2	Concrete	Fair	Surface Treatment	4	185.17	\$10,287.48	\$8,641.48	\$6,172.49
WALNUT ST-02	Even	Yes	2	Concrete	Fair	Surface Treatment	4	75.80	\$4,211.00	\$3,537.24	\$2,526.60
Length:								1,200.67	\$53,120.32	\$45,307.38	\$33,587.98
WILLIAM BASHAW JR WAY											
WILLIAM BASHAW JR WY	Even	No	0	Granite	Good	Routine Maintenance	4	204.78	\$2,730.34	\$2,730.34	\$2,730.34
Length:								204.78	\$2,730.34	\$2,730.34	\$2,730.34
WOODLAND STREET											
WOODLAND ST-01	Odd	No	0	Mix	Fair	Surface Treatment	4	194.74	\$10,818.82	\$9,087.81	\$6,491.29
WOODLAND ST-02	Odd	Yes	2	Granite	Poor	Rehabilitation	4	235.32	\$13,073.42	\$10,981.67	\$7,844.05
WOODLAND ST-03	Odd	Yes	2	Granite	Good	Routine Maintenance	3	102.25	\$1,022.51	\$1,022.51	\$1,022.51
WOODLAND ST-04	Odd	Yes	2	Granite	Fair	Surface Treatment	3	161.16	\$6,715.14	\$5,640.72	\$4,029.09
WOODLAND ST-07	Odd	Yes	4	Granite	Good	Routine Maintenance	3	100.93	\$1,009.27	\$1,009.27	\$1,009.27
WOODLAND ST-08	Odd	Yes	2	Granite	Good	Routine Maintenance	4	25.15	\$335.31	\$335.31	\$335.31
WOODLAND ST-08	Odd	Yes	4	Granite	Good	Routine Maintenance	4	188.61	\$2,514.77	\$2,514.77	\$2,514.77
WOODLAND ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	48.61	\$2,700.52	\$2,268.44	\$1,620.31
WOODLAND ST-03	Even	Yes	2	Granite	Fair	Surface Treatment	4	172.10	\$9,561.34	\$8,031.53	\$5,736.81
WOODLAND ST-04	Even	Yes	2	Granite	Good	Routine Maintenance	4	120.31	\$1,604.17	\$1,604.17	\$1,604.17
Length:								1,349.19	\$49,355.29	\$42,496.21	\$32,207.59
Ward: 5											
BROOKS COURT											

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
BROOKS CT	Odd	No	0	Granite	New	Defer Maintenance	4	51.15	\$0.00	\$0.00	\$0.00
BROOKS CT	Odd	No	0	Granite	Gap	Gap	4	215.10	\$11,950.18	\$0.00	\$0.00
BROOKS CT	Even	No	0	Granite	New	Defer Maintenance	5	273.16	\$0.00	\$0.00	\$0.00
Length:								539.41	\$11,950.18	\$0.00	\$0.00

HALE STREET

HALE ST-08	Even	No	0	Granite	Good	Routine Maintenance	4	322.47	\$4,299.63	\$4,299.63	\$4,299.63
HALE ST-08	Even	No	0	Granite	Good	Routine Maintenance	4	112.90	\$1,505.27	\$1,505.27	\$1,505.27
HALE ST-08	Even	No	0	Granite	Fair	Surface Treatment	4	824.11	\$45,783.96	\$38,458.53	\$27,470.38
Length:								1,259.48	\$51,588.86	\$44,263.43	\$33,275.28

HENDERSON CIRCLE

HENDERSON CIRCLE	Even	No	0	Granite	Good	Routine Maintenance	4	717.59	\$9,567.89	\$9,567.89	\$9,567.89
Length:								717.59	\$9,567.89	\$9,567.89	\$9,567.89

HIGH STREET

HIGH ST-01	Odd	Yes	2	Granite	Good	Routine Maintenance	4	79.58	\$1,061.02	\$1,061.02	\$1,061.02
HIGH ST-02	Odd	Yes	2	Granite	Poor	Rehabilitation	4	137.43	\$7,635.25	\$6,413.61	\$4,581.15
HIGH ST-03	Odd	Yes	2	Granite	Good	Routine Maintenance	4	30.26	\$403.47	\$403.47	\$403.47
HIGH ST-04	Odd	Yes	2	Granite	Fair	Surface Treatment	4	140.22	\$7,790.24	\$6,543.80	\$4,674.14
HIGH ST-05	Odd	Yes	2	Granite	New	Defer Maintenance	4	28.23	\$0.00	\$0.00	\$0.00
HIGH ST-05	Odd	Yes	2	Granite	New	Defer Maintenance	4	182.04	\$0.00	\$0.00	\$0.00
HIGH ST-05	Odd	Yes	2	Granite	Fair	Surface Treatment	4	49.13	\$2,729.40	\$2,292.69	\$1,637.64
HIGH ST-05	Odd	Yes	2	Granite	Fair	Surface Treatment	4	85.78	\$4,765.40	\$4,002.93	\$2,859.24
HIGH ST-05	Odd	Yes	2	Granite	Good	Routine Maintenance	4	55.64	\$741.80	\$741.80	\$741.80
HIGH ST-06	Odd	Yes	4	Granite	Good	Routine Maintenance	4	68.69	\$915.93	\$915.93	\$915.93
HIGH ST-07	Odd	Yes	4	Granite	Good	Routine Maintenance	4	76.08	\$1,014.39	\$1,014.39	\$1,014.39
Length:								933.07	\$27,056.88	\$23,389.64	\$17,888.77

LOW STREET

LOW ST-01	Odd	Yes	4	Granite	Good	Routine Maintenance	4	159.02	\$2,120.30	\$2,120.30	\$2,120.30
LOW ST-10	Odd	No	0	Granite	Good	Routine Maintenance	4	42.93	\$572.40	\$572.40	\$572.40
LOW ST-01	Even	No	0	Granite	Poor	Rehabilitation	4	102.34	\$5,685.47	\$4,775.79	\$3,411.28
Length:								304.29	\$8,378.17	\$7,468.49	\$6,103.98

MELVIN COURT

MELVIN CT	Odd	No	0	Granite	Good	Routine Maintenance	4	403.63	\$5,381.76	\$5,381.76	\$5,381.76
Length:								403.63	\$5,381.76	\$5,381.76	\$5,381.76

NORTH ATKINSON STREET

NORTH ATKINSON ST-01	Even	Yes	2	Mix	Good	Routine Maintenance	4	488.54	\$6,513.85	\$6,513.85	\$6,513.85
NORTH ATKINSON ST-02	Even	No	0	Granite	New	Defer Maintenance	4	209.52	\$0.00	\$0.00	\$0.00
Length:								698.06	\$6,513.85	\$6,513.85	\$6,513.85

Ward: 6

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
ARTHUR WELCH DRIVE											
ARTHUR WELCH DR	Odd	Yes	2	Granite	Good	Routine Maintenance	4	681.46	\$9,086.19	\$9,086.19	\$9,086.19
								Length: 681.46	\$9,086.19	\$9,086.19	\$9,086.19
CLIPPER WAY											
CLIPPER WY-01	Even	No	0	Concrete	Good	Routine Maintenance	4	318.57	\$4,247.60	\$4,247.60	\$4,247.60
CLIPPER WY-04	Even	No	0	Concrete	Good	Routine Maintenance	4	187.50	\$2,499.96	\$2,499.96	\$2,499.96
								Length: 506.07	\$6,747.56	\$6,747.56	\$6,747.56
DANIEL LUCY WAY											
DANIEL LUCY WY-01	Odd	Yes	2	Granite	Good	Routine Maintenance	4	1,244.28	\$16,590.45	\$16,590.45	\$16,590.45
DANIEL LUCY WY-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	104.91	\$1,398.80	\$1,398.80	\$1,398.80
DANIEL LUCY WY-03	Odd	Yes	2	Granite	Good	Routine Maintenance	4	1,506.53	\$20,087.01	\$20,087.01	\$20,087.01
								Length: 2,855.72	\$38,076.26	\$38,076.26	\$38,076.26
FERRY ROAD											
FERRY RD-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	244.33	\$13,574.15	\$11,402.29	\$8,144.49
FERRY RD-03	Odd	Yes	2	Concrete	Fair	Surface Treatment	2	181.86	\$5,051.59	\$4,243.34	\$3,030.96
FERRY RD-09	Odd	Yes	2	Asphalt	New	Defer Maintenance	4	114.02	\$0.00	\$0.00	\$0.00
FERRY RD-01	Even	Yes	4	Concrete	Fair	Surface Treatment	4	233.25	\$12,958.32	\$10,884.99	\$7,774.99
FERRY RD-02	Even	Yes	4	Concrete	Good	Routine Maintenance	4	107.18	\$1,429.03	\$1,429.03	\$1,429.03
								Length: 880.64	\$33,013.09	\$27,959.64	\$20,379.47
MOSELEY AVENUE											
MOSELEY AVE-05	Odd	Yes	8	None	Good	Routine Maintenance	4	196.45	\$2,619.39	\$2,619.39	\$2,619.39
MOSELEY AVE-02	Even	Yes	3	None	Fair	Surface Treatment	6	260.03	\$21,668.99	\$18,201.95	\$13,001.39
								Length: 456.48	\$24,288.39	\$20,821.35	\$15,620.79
MOULTON STREET											
MOULTON ST-02	Odd	Yes	2	Concrete	Fair	Surface Treatment	3	61.99	\$2,582.75	\$2,169.51	\$1,549.65
								Length: 61.99	\$2,582.75	\$2,169.51	\$1,549.65
NOBLE STREET											
NOBLE ST-01	Even	Yes	2	Asphalt	Good	Routine Maintenance	4	205.93	\$2,745.69	\$2,745.69	\$2,745.69
								Length: 205.93	\$2,745.69	\$2,745.69	\$2,745.69
TURKEY HILL ROAD											
TURKEY HILL RD-08	Even	Yes	2	CC Berm	Fair	Surface Treatment	4	370.04	\$20,557.51	\$17,268.31	\$12,334.50
								Length: 370.04	\$20,557.51	\$17,268.31	\$12,334.50
WILLIAM HALL DRIVE											
WILLIAM HALL DR	Odd	Yes	2	Granite	Good	Routine Maintenance	4	523.60	\$6,981.30	\$6,981.30	\$6,981.30
								Length: 523.60	\$6,981.30	\$6,981.30	\$6,981.30
WOODMAN WAY											
WOODMAN WY-01	Even	No	0	Granite	Good	Routine Maintenance	4	129.86	\$1,731.41	\$1,731.41	\$1,731.41

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
WOODMAN WY-01	Even	Yes	4	Granite	Good	Routine Maintenance	4	422.32	\$5,630.95	\$5,630.95	\$5,630.95
WOODMAN WY-02	Even	No	0	Concrete	Good	Routine Maintenance	4	104.91	\$1,398.81	\$1,398.81	\$1,398.81
							Length:	657.09	\$8,761.17	\$8,761.17	\$8,761.17

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Condition and Estimated Replacement Costs - Mix Materials (Replace With Concrete)

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Ward: 1											
BEACON AVENUE											
BEACON AVE-05	Odd	No	0	Concrete	Poor	Rehabilitation	4	93.11	\$5,172.92	\$4,345.25	\$3,103.75
							Length:	93.11	\$5,172.92	\$4,345.25	\$3,103.75
BROMFIELD STREET											
BROMFIELD ST-01	Odd	Yes	2	Granite	Poor	Rehabilitation	4	564.30	\$31,350.12	\$26,334.10	\$18,810.07
							Length:	564.30	\$31,350.12	\$26,334.10	\$18,810.07
FRANKLIN STREET											
FRANKLIN ST-02	Odd	No	0	Concrete	Poor	Rehabilitation	4	719.69	\$39,983.02	\$33,585.73	\$23,989.81
FRANKLIN ST-02	Even	No	0	Mix	Poor	Rehabilitation	4	717.38	\$39,854.54	\$33,477.81	\$23,912.72
							Length:	1,437.08	\$79,837.56	\$67,063.55	\$47,902.53
LIME STREET											
LIME ST-04	Odd	No	0	Granite	Good	Routine Maintenance	4	119.81	\$1,597.52	\$1,597.52	\$1,597.52
LIME ST-06	Odd	No	0	Granite	Good	Routine Maintenance	4	99.65	\$1,328.70	\$1,328.70	\$1,328.70
							Length:	219.47	\$2,926.22	\$2,926.22	\$2,926.22
LINCOLN STREET											
LINCOLN ST	Even	Yes	2	Granite	Fair	Surface Treatment	4	448.21	\$24,900.31	\$20,916.26	\$14,940.19
							Length:	448.21	\$24,900.31	\$20,916.26	\$14,940.19
MADISON STREET											
MADISON ST-02	Odd	No	0	Mix	Poor	Rehabilitation	4	267.52	\$14,862.30	\$12,484.33	\$8,917.38
MADISON ST-02	Odd	No	0	Concrete	Fair	Surface Treatment	4	132.77	\$7,375.94	\$6,195.79	\$4,425.57
							Length:	400.29	\$22,238.25	\$18,680.13	\$13,342.95
MARLBORO STREET											
MARLBORO ST-03	Odd	Yes	2	Granite	Fair	Surface Treatment	4	47.81	\$2,656.12	\$2,231.14	\$1,593.67
MARLBORO ST-07	Odd	Yes	2	Concrete	Poor	Rehabilitation	4	180.93	\$10,051.89	\$8,443.58	\$6,031.13
MARLBORO ST-02	Even	Yes	2	Granite	Fair	Surface Treatment	4	189.73	\$10,540.37	\$8,853.91	\$6,324.22
MARLBORO ST-08	Even	Yes	2	Concrete	Fair	Surface Treatment	4	228.85	\$12,713.69	\$10,679.50	\$7,628.21
							Length:	647.32	\$35,962.07	\$30,208.14	\$21,577.24
OAK STREET											
OAK ST-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	227.75	\$12,652.75	\$10,628.31	\$7,591.65
							Length:	227.75	\$12,652.75	\$10,628.31	\$7,591.65

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
PURCHASE STREET											
PURCHASE ST-04	Odd	No	0	Granite	Fair	Surface Treatment	5	133.27	\$9,254.91	\$7,774.12	\$5,552.95
PURCHASE ST-04	Odd	No	0	Granite	Fair	Surface Treatment	5	89.35	\$6,204.87	\$5,212.09	\$3,722.92
								Length:	222.62	\$15,459.78	\$12,986.22
										\$9,275.87	
WATER STREET											
WATER ST-07	Even	No	0	Concrete	Fair	Surface Treatment	4	44.29	\$2,460.40	\$2,066.73	\$1,476.24
								Length:	44.29	\$2,460.40	\$2,066.73
										\$1,476.24	
Ward: 2											
FEDERAL STREET											
FEDERAL ST-09	Even	No	0	Granite	Good	Routine Maintenance	4	124.64	\$1,661.83	\$1,661.83	\$1,661.83
								Length:	124.64	\$1,661.83	\$1,661.83
HORTON STREET											
HORTON ST-01	Even	No	0	Granite	Fair	Surface Treatment	4	221.92	\$12,328.62	\$10,356.04	\$7,397.17
								Length:	221.92	\$12,328.62	\$10,356.04
										\$7,397.17	
LIME STREET											
LIME ST-02	Odd	No	0	Granite	Fair	Surface Treatment	4	197.43	\$10,968.18	\$9,213.27	\$6,580.91
								Length:	197.43	\$10,968.18	\$9,213.27
										\$6,580.91	
MILK STREET											
MILK ST-01	Even	No	0	Granite	Fair	Surface Treatment	5	249.31	\$17,313.44	\$14,543.29	\$10,388.06
								Length:	249.31	\$17,313.44	\$14,543.29
										\$10,388.06	
SPRING STREET											
SPRING ST	Even	No	0	Granite	Good	Routine Maintenance	5	67.28	\$1,121.41	\$1,121.41	\$1,121.41
								Length:	67.28	\$1,121.41	\$1,121.41
TEMPLE STREET											
TEMPLE ST-02	Odd	No	0	Granite	Fair	Surface Treatment	3	80.39	\$3,349.50	\$2,813.58	\$2,009.70
								Length:	80.39	\$3,349.50	\$2,813.58
										\$2,009.70	
Ward: 3											
CARTER STREET											
CARTER ST-05	Even	Yes	2	Concrete	Fair	Surface Treatment	4	181.49	\$10,082.93	\$8,469.66	\$6,049.76
								Length:	181.49	\$10,082.93	\$8,469.66
										\$6,049.76	
HILL STREET											
HILL ST-04	Odd	Yes	2	Concrete	Fair	Surface Treatment	3	211.02	\$8,792.69	\$7,385.86	\$5,275.62
								Length:	211.02	\$8,792.69	\$7,385.86
										\$5,275.62	
STRONG STREET											
STRONG ST-02	Even	No	0	Granite	Fair	Surface Treatment	5	149.25	\$10,364.62	\$8,706.28	\$6,218.77

BETA Group, Inc.

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
							Length:	149.25	\$10,364.62	\$8,706.28	\$6,218.77
SUMMIT PLACE											
SUMMIT PL	Odd	No	0	Granite	Fair	Surface Treatment	4	236.27	\$13,126.19	\$11,026.00	\$7,875.71
SUMMIT PL	Even	No	0	Granite	Good	Routine Maintenance	5	99.36	\$1,655.98	\$1,655.98	\$1,655.98
SUMMIT PL	Even	No	0	Granite	Good	Routine Maintenance	5	53.57	\$892.76	\$892.76	\$892.76
							Length:	389.20	\$15,674.93	\$13,574.74	\$10,424.46
WARREN STREET											
WARREN ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	45.72	\$609.57	\$609.57	\$609.57
							Length:	45.72	\$609.57	\$609.57	\$609.57
Ward: 4											
COLUMBUS AVENUE											
COLUMBUS AVE-01	Even	Yes	2	Concrete	Fair	Surface Treatment	4	161.07	\$8,948.37	\$7,516.63	\$5,369.02
							Length:	161.07	\$8,948.37	\$7,516.63	\$5,369.02
MERRIMAC STREET											
MERRIMAC ST-01	Even	Yes	2	Concrete	Good	Routine Maintenance	3	101.38	\$1,013.76	\$1,013.76	\$1,013.76
							Length:	101.38	\$1,013.76	\$1,013.76	\$1,013.76
TILTON STREET											
TILTON ST	Odd	Yes	2	Concrete	Fair	Surface Treatment	4	54.66	\$3,036.58	\$2,550.73	\$1,821.95
							Length:	54.66	\$3,036.58	\$2,550.73	\$1,821.95
WOODLAND STREET											
WOODLAND ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	129.39	\$1,725.24	\$1,725.24	\$1,725.24
							Length:	129.39	\$1,725.24	\$1,725.24	\$1,725.24
Ward: 5											
HIGH STREET											
HIGH ST-03	Odd	No	0	Granite	Good	Routine Maintenance	6	61.33	\$1,226.61	\$1,226.61	\$1,226.61
							Length:	61.33	\$1,226.61	\$1,226.61	\$1,226.61

City of Newburyport, Massachusetts

Sidewalk Management Program

Sidewalk Condition and Estimated Replacement Costs - Pavers (Replace With Brick)

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Ward: 1											
HANCOCK STREET											
HANCOCK ST-02	Even	Yes	2	Granite	Good	Routine Maintenance	4	59.58	\$794.46	\$1,588.92	\$794.46
							Length:	59.58	\$794.46	\$1,588.92	\$794.46
WATER STREET											
WATER ST-06	Odd	No	0	Concrete	Good	Routine Maintenance	4	61.04	\$813.86	\$1,627.73	\$813.86
WATER ST-12	Odd	No	0	Granite	Good	Routine Maintenance	4	36.79	\$490.52	\$981.05	\$490.52
							Length:	97.83	\$1,304.39	\$2,608.77	\$1,304.39
Ward: 2											
BRICHER PLACE											
BRICHER PL-02	Odd	Yes	2	Concrete	Good	Routine Maintenance	4	48.11	\$641.49	\$1,282.99	\$641.49
							Length:	48.11	\$641.49	\$1,282.99	\$641.49
STATE STREET											
STATE ST-13	Odd	Yes	2	Granite	Good	Routine Maintenance	4	52.29	\$697.21	\$1,394.43	\$697.21
							Length:	52.29	\$697.21	\$1,394.43	\$697.21
Ward: 3											
BOARDMAN STREET											
BOARDMAN ST-03	Even	Yes	2	Granite	Fair	Surface Treatment	4	77.60	\$6,725.36	\$4,656.02	\$4,656.02
							Length:	77.60	\$6,725.36	\$4,656.02	\$4,656.02
BUCK STREET											
BUCK ST-01	Odd	No	0	Granite	Good	Routine Maintenance	6	34.84	\$696.87	\$1,393.74	\$696.87
							Length:	34.84	\$696.87	\$1,393.74	\$696.87
CARTER STREET											
CARTER ST-02	Even	Yes	2	Granite	Good	Routine Maintenance	4	24.62	\$328.26	\$656.52	\$328.26
CARTER ST-04	Even	Yes	2	Concrete	Good	Routine Maintenance	4	36.68	\$489.09	\$978.18	\$489.09
							Length:	61.30	\$817.35	\$1,634.71	\$817.35
DOVE STREET											
DOVE ST	Odd	No	0	Granite	Good	Routine Maintenance	4	57.29	\$763.93	\$1,527.85	\$763.93
							Length:	57.29	\$763.93	\$1,527.85	\$763.93
MERRIMAC STREET											

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
MERRIMAC ST-26	Even	No	0	Granite	Good	Routine Maintenance	4	33.45	\$446.04	\$892.07	\$446.04
							Length:	33.45	\$446.04	\$892.07	\$446.04
MUNROE STREET											
MUNROE ST-04	Odd	Yes	2	Granite	Good	Routine Maintenance	4	50.83	\$677.79	\$1,355.59	\$677.79
							Length:	50.83	\$677.79	\$1,355.59	\$677.79
WARREN STREET											
WARREN ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	55.64	\$741.92	\$1,483.85	\$741.92
							Length:	55.64	\$741.92	\$1,483.85	\$741.92
Ward: 4											
FORRESTER STREET											
FORRESTER ST-03	Odd	Yes	2	Granite	Good	Routine Maintenance	4	79.65	\$1,062.04	\$2,124.09	\$1,062.04
							Length:	79.65	\$1,062.04	\$2,124.09	\$1,062.04
MERRIMAC STREET											
MERRIMAC ST-02	Even	Yes	2	Granite	Good	Routine Maintenance	3	304.24	\$3,042.36	\$6,084.73	\$3,042.36
							Length:	304.24	\$3,042.36	\$6,084.73	\$3,042.36

City of Newburyport, Massachusetts

Sidewalk Management Program

Downtown Overlay District Sidewalk Condition and Estimated Replacement Costs - Brick (Replace With Brick)

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
Ward: 1											
MERRIMAC STREET											
MERRIMAC ST-32	Even	No	0	Granite	Good	Routine Maintenance	6	38.49	\$769.80	\$1,539.59	\$769.80
Length:								38.49	\$769.80	\$1,539.59	\$769.80
Ward: 2											
CENTER STREET											
CENTER ST-01	Odd	No	0	Granite	Fair	Surface Treatment	2	39.34	\$1,704.66	\$1,180.15	\$1,180.15
CENTER ST-02	Odd	No	0	Granite	Poor	Rehabilitation	2	73.81	\$3,198.32	\$2,870.29	\$2,214.22
CENTER ST-02	Odd	No	0	Granite	Poor	Rehabilitation	4	112.30	\$9,732.77	\$8,734.53	\$6,738.07
CENTER ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	102.98	\$1,373.03	\$2,746.07	\$1,373.03
CENTER ST-02	Even	No	0	Granite	New	Defer Maintenance	4	28.86	\$0.00	\$0.00	\$0.00
CENTER ST-02	Even	No	0	Granite	Poor	Rehabilitation	4	146.17	\$12,668.38	\$11,369.06	\$8,770.41
CENTER ST-02	Even	No	0	Concrete	Poor	Rehabilitation	4	52.79	\$4,575.06	\$4,105.83	\$3,167.35
CENTER ST-02	Even	No	0	Concrete	Fair	Surface Treatment	4	58.35	\$5,056.84	\$3,500.89	\$3,500.89
Length:								614.59	\$38,309.06	\$34,506.81	\$26,944.13
CHARTER STREET											
CHARTER ST	Odd	No	0	Granite	Good	Routine Maintenance	5	568.53	\$9,475.53	\$18,951.06	\$9,475.53
CHARTER ST	Even	No	0	Granite	Good	Routine Maintenance	4	577.88	\$7,705.02	\$15,410.04	\$7,705.02
Length:								1,146.41	\$17,180.55	\$34,361.10	\$17,180.55
ESSEX STREET											
ESSEX ST	Odd	No	0	Granite	Good	Routine Maintenance	5	352.12	\$5,868.70	\$11,737.41	\$5,868.70
ESSEX ST	Odd	No	0	Granite	Good	Routine Maintenance	5	220.82	\$3,680.41	\$7,360.83	\$3,680.41
ESSEX ST	Even	No	0	Granite	Good	Routine Maintenance	4	119.63	\$1,595.05	\$3,190.10	\$1,595.05
ESSEX ST	Even	No	0	Granite	Good	Routine Maintenance	4	61.13	\$815.09	\$1,630.19	\$815.09
ESSEX ST	Even	No	0	Granite	Fair	Surface Treatment	5	74.95	\$8,119.88	\$5,621.46	\$5,621.46
ESSEX ST	Even	No	0	Granite	Poor	Rehabilitation	5	214.39	\$23,226.05	\$20,843.89	\$16,079.58
ESSEX ST	Even	No	0	Granite	Good	Routine Maintenance	5	99.23	\$1,653.88	\$3,307.76	\$1,653.88
Length:								1,142.29	\$44,959.08	\$53,691.63	\$35,314.17
FAIR STREET											
FAIR ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	123.95	\$1,652.69	\$3,305.39	\$1,652.69
FAIR ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	149.60	\$1,994.70	\$3,989.41	\$1,994.70
FAIR ST-03	Even	No	0	Granite	Good	Routine Maintenance	4	47.59	\$634.52	\$1,269.05	\$634.52
FAIR ST-04	Even	No	0	Granite	Good	Routine Maintenance	4	120.53	\$1,607.05	\$3,214.09	\$1,607.05

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
FAIR ST-05	Even	No	0	Granite	Good	Routine Maintenance	4	67.51	\$900.10	\$1,800.20	\$900.10
FAIR ST-06	Even	No	0	Granite	Good	Routine Maintenance	4	55.97	\$746.32	\$1,492.64	\$746.32
FAIR ST-06	Even	No	0	Granite	Good	Routine Maintenance	4	80.43	\$1,072.45	\$2,144.89	\$1,072.45
FAIR ST-07	Even	No	0	Granite	Good	Routine Maintenance	4	143.38	\$1,911.77	\$3,823.54	\$1,911.77
FAIR ST-08	Even	No	0	Granite	Good	Routine Maintenance	4	462.83	\$6,171.05	\$12,342.10	\$6,171.05
Length:								1,251.80	\$16,690.66	\$33,381.32	\$16,690.66
GARDEN STREET											
GARDEN ST	Odd	No	0	Granite	Poor	Rehabilitation	4	290.55	\$25,180.61	\$22,597.98	\$17,432.73
GARDEN ST	Even	No	0	Granite	Fair	Surface Treatment	4	94.91	\$8,225.96	\$5,694.90	\$5,694.90
GARDEN ST	Even	No	0	Granite	Poor	Rehabilitation	4	118.83	\$10,298.76	\$9,242.47	\$7,129.91
GARDEN ST	Even	No	0	Granite	Fair	Surface Treatment	4	64.62	\$5,600.54	\$3,877.30	\$3,877.30
Length:								568.91	\$49,305.87	\$41,412.65	\$34,134.83
GREEN STREET											
GREEN ST-01	Odd	No	0	Granite	New	Defer Maintenance	6	377.36	\$0.00	\$0.00	\$0.00
GREEN ST-03	Odd	No	0	Granite	New	Defer Maintenance	6	512.02	\$0.00	\$0.00	\$0.00
GREEN ST-04	Odd	No	0	Granite	Fair	Surface Treatment	5	159.07	\$17,232.85	\$11,930.43	\$11,930.43
GREEN ST-04	Odd	No	0	Granite	Fair	Surface Treatment	6	169.90	\$22,087.10	\$15,291.07	\$15,291.07
GREEN ST-03	Even	No	0	Granite	New	Defer Maintenance	6	459.86	\$0.00	\$0.00	\$0.00
GREEN ST-04	Even	No	0	Granite	Good	Routine Maintenance	6	316.07	\$6,321.48	\$12,642.95	\$6,321.48
Length:								1,994.28	\$45,641.43	\$39,864.46	\$33,542.98
GREENLEAF STREET											
GREENLEAF ST-04	Even	No	0	Mix	Poor	Rehabilitation	4	322.01	\$27,907.43	\$25,045.13	\$19,320.53
GREENLEAF ST-04	Even	Yes	2	Concrete	Fair	Surface Treatment	4	153.38	\$13,293.07	\$9,202.89	\$9,202.89
GREENLEAF ST-04	Even	No	0	Concrete	Poor	Rehabilitation	4	123.06	\$10,665.48	\$9,571.58	\$7,383.79
Length:								598.45	\$51,865.97	\$43,819.60	\$35,907.21
HALE STREET											
HALE'S CT	Odd	No	0	Granite	Fair	Surface Treatment	3	39.28	\$2,553.08	\$1,767.52	\$1,767.52
HALE'S CT	Odd	No	0	Granite	Fair	Surface Treatment	4	216.70	\$18,781.01	\$13,002.24	\$13,002.24
Length:								255.98	\$21,334.09	\$14,769.75	\$14,769.75
HALE'S COURT											
HALE'S CT	Even	No	0	None	Fair	Surface Treatment	4	88.81	\$7,696.67	\$5,328.47	\$5,328.47
Length:								88.81	\$7,696.67	\$5,328.47	\$5,328.47
HIGH STREET											
HIGH ST-33	Even	No	0	Granite	Good	Routine Maintenance	4	229.52	\$3,060.26	\$6,120.51	\$3,060.26
HIGH ST-34	Even	No	0	Granite	Fair	Surface Treatment	8	41.05	\$7,115.03	\$4,925.79	\$4,925.79
HIGH ST-35	Even	No	0	Granite	Fair	Surface Treatment	8	125.47	\$21,748.67	\$15,056.77	\$15,056.77
HIGH ST-36	Even	No	0	Granite	Fair	Surface Treatment	6	121.53	\$15,799.45	\$10,938.08	\$10,938.08
HIGH ST-36	Even	No	0	Granite	Good	Routine Maintenance	6	65.81	\$1,316.21	\$2,632.42	\$1,316.21
HIGH ST-37	Even	No	0	Granite	Fair	Surface Treatment	6	450.31	\$58,539.67	\$40,527.46	\$40,527.46

BETA Group, Inc.

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
							Length: 1,033.69	\$107,579.29	\$80,201.05	\$75,824.58
LIBERTY STREET										
LIBERTY ST-03	Odd	No	0	Granite	Fair	Surface Treatment	4	112.97	\$9,791.05	\$6,778.42
LIBERTY ST-04	Odd	Yes	2	Granite	Fair	Surface Treatment	4	143.12	\$12,403.63	\$8,587.13
LIBERTY ST-05	Odd	No	0	Granite	Good	Routine Maintenance	4	174.49	\$2,326.57	\$4,653.15
LIBERTY ST-05	Odd	No	0	Granite	Good	Routine Maintenance	4	58.37	\$778.26	\$1,556.52
LIBERTY ST-05	Odd	No	0	Granite	Fair	Surface Treatment	4	93.53	\$8,105.74	\$5,611.66
LIBERTY ST-03	Even	No	0	Granite	Good	Routine Maintenance	4	75.61	\$1,008.10	\$2,016.20
LIBERTY ST-03	Even	No	0	Granite	Fair	Surface Treatment	4	90.98	\$7,884.61	\$5,458.57
LIBERTY ST-04	Even	No	0	Granite	Good	Routine Maintenance	4	117.55	\$1,567.39	\$3,134.77
LIBERTY ST-05	Even	No	0	Granite	Good	Routine Maintenance	4	90.75	\$1,209.95	\$2,419.91
LIBERTY ST-05	Even	No	0	Granite	Fair	Surface Treatment	6	155.95	\$20,273.75	\$14,035.67
LIBERTY ST-05	Even	No	0	Granite	Good	Routine Maintenance	6	65.88	\$1,317.54	\$2,635.08
							Length: 1,179.20	\$66,666.59	\$56,887.09	\$48,679.27
MARKET STREET										
MARKET ST-01	Odd	No	0	Granite	Fair	Surface Treatment	6	50.07	\$6,509.12	\$4,506.31
MARKET ST-01	Odd	No	0	Granite	Fair	Surface Treatment	6	65.64	\$8,533.20	\$5,907.60
MARKET ST-01	Odd	No	0	Granite	Fair	Surface Treatment	6	44.83	\$5,827.63	\$4,034.51
MARKET ST-01	Odd	No	0	Granite	Good	Routine Maintenance	6	44.02	\$880.50	\$1,760.99
MARKET ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	139.71	\$1,862.79	\$3,725.57
MARKET ST-02	Odd	No	0	Granite	Good	Routine Maintenance	8	98.93	\$2,638.11	\$5,276.22
MARKET ST-03	Odd	No	0	Granite	Good	Routine Maintenance	4	119.33	\$1,591.04	\$3,182.08
MARKET ST-03	Odd	No	0	Granite	Fair	Surface Treatment	4	43.28	\$3,750.60	\$2,596.57
							Length: 605.80	\$31,592.97	\$30,989.85	\$24,017.42
MERRIMAC STREET										
MERRIMAC ST-31	Odd	No	0	Granite	Fair	Surface Treatment	6	107.21	\$13,937.89	\$9,649.31
MERRIMAC ST-31	Odd	No	0	Granite	Poor	Rehabilitation	6	171.02	\$22,232.24	\$19,952.01
MERRIMAC ST-32	Odd	No	0	Granite	Poor	Rehabilitation	4	221.11	\$19,163.06	\$17,197.62
MERRIMAC ST-32	Odd	No	0	Granite	Good	Routine Maintenance	6	52.65	\$1,052.98	\$2,105.96
MERRIMAC ST-33	Even	No	0	Granite	Fair	Surface Treatment	8	696.26	\$120,684.53	\$83,550.83
MERRIMAC ST-33	Even	No	0	Granite	Fair	Surface Treatment	4	148.72	\$12,889.43	\$8,923.45
MERRIMAC ST-33	Even	No	0	Granite	Good	Routine Maintenance	4	40.10	\$534.64	\$1,069.29
MERRIMAC ST-33	Even	No	0	Granite	Fair	Surface Treatment	6	457.47	\$59,470.68	\$41,172.01
							Length: 1,894.54	\$249,965.46	\$183,620.48	\$173,541.51
MIDDLE STREET										
MIDDLE ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	271.22	\$3,616.32	\$7,232.65
MIDDLE ST-02	Odd	No	0	Granite	New	Defer Maintenance	4	81.93	\$0.00	\$0.00
MIDDLE ST-02	Odd	No	0	Granite	Poor	Rehabilitation	4	49.44	\$4,285.11	\$3,845.61
MIDDLE ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	163.61	\$2,181.51	\$4,363.02
MIDDLE ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	291.65	\$3,888.66	\$7,777.32

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
MIDDLE ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	73.06	\$974.12	\$1,948.24	\$974.12
MIDDLE ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	122.47	\$10,614.31	\$7,348.37	\$7,348.37
MIDDLE ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	48.21	\$642.76	\$1,285.52	\$642.76
MIDDLE ST-02	Even	No	0	Granite	New	Defer Maintenance	4	69.41	\$0.00	\$0.00	\$0.00
Length:								1,171.01	\$26,202.80	\$33,800.74	\$21,618.36

OTIS PLACE

OTIS PL-01	Odd	No	0	Granite	Good	Routine Maintenance	4	74.84	\$997.87	\$1,995.74	\$997.87
OTIS PL-01	Odd	No	0	Granite	Fair	Surface Treatment	4	41.49	\$3,595.44	\$2,489.15	\$2,489.15
OTIS PL-01	Odd	No	0	Granite	Good	Routine Maintenance	4	110.11	\$1,468.09	\$2,936.17	\$1,468.09
OTIS PL-02	Odd	No	0	Granite	Fair	Surface Treatment	4	147.05	\$12,744.38	\$8,823.03	\$8,823.03
OTIS PL-01	Even	No	0	Granite	Fair	Surface Treatment	5	24.49	\$2,653.49	\$1,837.03	\$1,837.03
OTIS PL-01	Even	No	0	Granite	Fair	Surface Treatment	4	128.81	\$11,163.29	\$7,728.43	\$7,728.43
OTIS PL-02	Even	No	0	Granite	Good	Routine Maintenance	4	26.18	\$349.08	\$698.17	\$349.08
OTIS PL-02	Even	No	0	Granite	Fair	Surface Treatment	4	92.35	\$8,003.61	\$5,540.96	\$5,540.96
OTIS PL-02	Even	No	0	Granite	Poor	Rehabilitation	4	45.38	\$3,933.28	\$3,529.86	\$2,723.04
Length:								690.70	\$44,908.54	\$35,578.56	\$31,956.69

PLEASANT STREET

PLEASANT ST-01	Odd	No	0	Granite	Good	Routine Maintenance	6	353.51	\$7,070.10	\$14,140.21	\$7,070.10
PLEASANT ST-02	Odd	No	0	Granite	Good	Routine Maintenance	7	272.09	\$6,348.67	\$12,697.34	\$6,348.67
PLEASANT ST-03	Odd	No	0	Granite	Good	Routine Maintenance	5	289.47	\$4,824.54	\$9,649.07	\$4,824.54
PLEASANT ST-04	Odd	No	0	Granite	Fair	Surface Treatment	5	293.97	\$31,846.68	\$22,047.70	\$22,047.70
PLEASANT ST-01	Even	No	0	Granite	Good	Routine Maintenance	7	349.23	\$8,148.74	\$16,297.48	\$8,148.74
PLEASANT ST-02	Even	No	0	Granite	Fair	Surface Treatment	6	133.56	\$17,362.52	\$12,020.20	\$12,020.20
PLEASANT ST-02	Even	No	0	Granite	Good	Routine Maintenance	6	146.88	\$2,937.65	\$5,875.29	\$2,937.65
PLEASANT ST-03	Even	No	0	Granite	Good	Routine Maintenance	6	277.39	\$5,547.82	\$11,095.63	\$5,547.82
PLEASANT ST-04	Even	No	0	Granite	Good	Routine Maintenance	4	139.66	\$1,862.07	\$3,724.14	\$1,862.07
PLEASANT ST-04	Even	No	0	Granite	Good	Routine Maintenance	4	34.25	\$456.66	\$913.32	\$456.66
PLEASANT ST-04	Even	No	0	Granite	Fair	Surface Treatment	4	82.04	\$7,110.46	\$4,922.63	\$4,922.63
PLEASANT ST-04	Even	No	0	Granite	Fair	Surface Treatment	4	45.48	\$3,941.56	\$2,728.77	\$2,728.77
Length:								2,417.52	\$97,457.45	\$116,111.78	\$78,915.54

POND STREET

POND ST-02	Odd	Yes	2	Granite	Good	Routine Maintenance	4	442.23	\$5,896.46	\$11,792.93	\$5,896.46
Length:								442.23	\$5,896.46	\$11,792.93	\$5,896.46

PRINCE PLACE

PRINCE PL	Odd	No	0	Granite	Good	Routine Maintenance	4	170.98	\$2,279.73	\$4,559.46	\$2,279.73
PRINCE PL	Odd	No	0	Granite	Poor	Rehabilitation	4	206.11	\$17,862.45	\$16,030.41	\$12,366.31
PRINCE PL	Even	No	0	Granite	Fair	Surface Treatment	4	67.68	\$5,865.40	\$4,060.66	\$4,060.66
PRINCE PL	Even	No	0	Granite	Poor	Rehabilitation	3	158.02	\$10,271.62	\$9,218.12	\$7,111.12
PRINCE PL	Even	No	0	Mix	Poor	Rehabilitation	4	122.91	\$10,651.81	\$9,559.32	\$7,374.33

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
							Length: 725.69	\$46,931.02	\$43,427.97	\$33,192.16
PROSPECT STREET										
PROSPECT ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	96.49	\$1,286.57	\$1,286.57
PROSPECT ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	44.31	\$590.83	\$590.83
PROSPECT ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	109.14	\$1,455.14	\$1,455.14
PROSPECT ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	116.26	\$1,550.20	\$1,550.20
PROSPECT ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	64.94	\$865.89	\$865.89
PROSPECT ST-02	Odd	No	0	Granite	Good	Routine Maintenance	4	100.21	\$1,336.17	\$1,336.17
PROSPECT ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	192.47	\$2,566.22	\$2,566.22
PROSPECT ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	150.97	\$2,012.91	\$2,012.91
PROSPECT ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	67.87	\$904.94	\$904.94
PROSPECT ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	31.90	\$425.33	\$425.33
PROSPECT ST-02	Even	No	0	Granite	Good	Routine Maintenance	4	74.50	\$993.32	\$993.32
							Length: 1,049.06	\$13,987.51	\$27,975.03	\$13,987.51
STATE STREET										
STATE ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	37.08	\$494.39	\$494.39
STATE ST-01	Odd	No	0	Granite	Good	Routine Maintenance	8	75.94	\$2,025.07	\$2,025.07
STATE ST-02	Odd	No	0	Granite	Good	Routine Maintenance	7	116.18	\$2,710.80	\$2,710.80
STATE ST-03	Odd	No	0	Granite	Fair	Surface Treatment	8	219.48	\$38,043.22	\$26,337.61
STATE ST-04	Odd	No	0	Granite	Fair	Surface Treatment	8	79.43	\$13,767.45	\$9,531.31
STATE ST-05	Odd	No	0	Granite	Fair	Surface Treatment	8	99.02	\$17,163.51	\$11,882.43
STATE ST-06	Odd	No	0	Granite	Fair	Surface Treatment	7	147.82	\$22,419.48	\$15,521.18
STATE ST-07	Odd	No	0	Granite	Fair	Surface Treatment	7	125.36	\$19,012.63	\$13,162.59
STATE ST-08	Odd	No	0	Granite	Good	Routine Maintenance	8	52.37	\$1,396.51	\$1,396.51
STATE ST-09	Odd	No	0	Granite	Good	Routine Maintenance	8	184.64	\$4,923.85	\$4,923.85
STATE ST-10	Odd	No	0	Granite	Poor	Rehabilitation	8	249.97	\$43,328.45	\$38,884.51
STATE ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	30.58	\$407.68	\$407.68
STATE ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	58.31	\$777.52	\$1,555.03
STATE ST-02	Even	No	0	Granite	Good	Routine Maintenance	8	160.52	\$4,280.46	\$8,560.92
STATE ST-03	Even	No	0	Granite	Good	Routine Maintenance	8	259.06	\$6,908.31	\$13,816.62
STATE ST-04	Even	No	0	Granite	Good	Routine Maintenance	8	109.32	\$2,915.19	\$5,830.38
STATE ST-05	Even	No	0	Granite	Good	Routine Maintenance	8	80.25	\$2,140.07	\$4,280.14
STATE ST-06	Even	No	0	Granite	Good	Routine Maintenance	8	191.81	\$5,115.04	\$10,230.07
STATE ST-07	Even	No	0	Granite	Good	Routine Maintenance	8	137.99	\$3,679.61	\$7,359.23
STATE ST-08	Even	No	0	Granite	Good	Routine Maintenance	8	39.34	\$1,049.16	\$2,098.32
STATE ST-09	Even	No	0	Granite	Fair	Surface Treatment	8	187.74	\$32,541.32	\$22,528.61
STATE ST-10	Even	No	0	Granite	Fair	Surface Treatment	8	254.42	\$44,099.22	\$30,530.23
							Length: 2,896.63	\$269,198.92	\$246,025.75	\$198,314.22
TEMPLE STREET										
TEMPLE ST-01	Odd	No	0	Granite	Good	Routine Maintenance	5	419.28	\$6,987.99	\$13,975.98

BETA Group, Inc.

	Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC
TEMPLE ST-01	Odd	No	0	Granite	Good	Routine Maintenance	5	143.53	\$2,392.24	\$4,784.48	\$2,392.24
TEMPLE ST-01	Even	No	0	Granite	New	Defer Maintenance	4	86.84	\$0.00	\$0.00	\$0.00
TEMPLE ST-01	Even	No	0	Granite	Good	Routine Maintenance	4	468.58	\$6,247.70	\$12,495.41	\$6,247.70
Length: 1,118.23									\$15,627.93	\$31,255.86	\$15,627.93

TITCOMB STREET

TITCOMB ST-01	Odd	No	0	Granite	Good	Routine Maintenance	4	59.77	\$796.94	\$1,593.88	\$796.94
TITCOMB ST-01	Odd	No	0	Granite	Poor	Rehabilitation	4	199.38	\$17,279.73	\$15,507.45	\$11,962.89
TITCOMB ST-02	Odd	No	0	Granite	Good	Routine Maintenance	6	100.57	\$2,011.40	\$4,022.80	\$2,011.40
TITCOMB ST-02	Odd	No	0	Granite	Fair	Surface Treatment	6	170.98	\$22,227.55	\$15,388.30	\$15,388.30
TITCOMB ST-02	Odd	No	0	Granite	Good	Routine Maintenance	5	59.17	\$986.10	\$1,972.21	\$986.10
TITCOMB ST-02	Odd	No	0	Granite	Poor	Rehabilitation	4	79.18	\$6,862.40	\$6,158.56	\$4,750.89
TITCOMB ST-01	Even	No	0	Granite	Fair	Surface Treatment	5	239.32	\$25,926.14	\$17,948.86	\$17,948.86
TITCOMB ST-02	Even	No	0	Granite	Good	Routine Maintenance	5	97.11	\$1,618.50	\$3,237.01	\$1,618.50
TITCOMB ST-02	Even	No	0	Granite	Poor	Rehabilitation	5	217.79	\$23,593.78	\$21,173.91	\$16,334.16
TITCOMB ST-02	Even	No	0	Granite	Fair	Surface Treatment	4	81.96	\$7,102.87	\$4,917.37	\$4,917.37
Length: 1,305.22									\$108,405.41	\$91,920.35	\$76,715.42

WASHINGTON STREET

WASHINGTON ST-08	Even	No	0	Granite	Fair	Surface Treatment	6	258.12	\$33,555.57	\$23,230.78	\$23,230.78
WASHINGTON ST-10	Even	No	0	Granite	Good	Routine Maintenance	6	76.10	\$1,521.93	\$3,043.85	\$1,521.93
WASHINGTON ST-10	Even	No	0	Granite	New	Defer Maintenance	6	114.77	\$0.00	\$0.00	\$0.00
WASHINGTON ST-10	Even	No	0	Granite	Fair	Surface Treatment	6	67.79	\$8,812.80	\$6,101.17	\$6,101.17
WASHINGTON ST-10	Even	Yes	2	Granite	Good	Routine Maintenance	4	66.23	\$883.04	\$1,766.09	\$883.04
Length: 583.01									\$44,773.34	\$34,141.88	\$31,736.92

WATER STREET

WATER ST-19	Odd	No	0	Granite	Good	Routine Maintenance	6	64.57	\$1,291.31	\$2,582.62	\$1,291.31
WATER ST-19	Odd	No	0	Granite	Good	Routine Maintenance	6	72.81	\$1,456.11	\$2,912.21	\$1,456.11
WATER ST-20	Odd	No	0	Granite	Good	Routine Maintenance	6	65.43	\$1,308.59	\$2,617.18	\$1,308.59
WATER ST-21	Odd	No	0	Granite	Fair	Surface Treatment	10	152.64	\$33,072.65	\$22,896.45	\$22,896.45
WATER ST-21	Odd	No	0	Granite	Fair	Surface Treatment	7	212.81	\$32,276.52	\$22,345.29	\$22,345.29
WATER ST-21	Odd	No	0	Granite	Good	Routine Maintenance	6	144.26	\$2,885.23	\$5,770.45	\$2,885.23
WATER ST-19	Even	No	0	Granite	Good	Routine Maintenance	4	105.35	\$1,404.69	\$2,809.38	\$1,404.69
WATER ST-20	Even	No	0	Granite	Good	Routine Maintenance	4	102.54	\$1,367.27	\$2,734.53	\$1,367.27
WATER ST-21	Even	No	0	Granite	Fair	Surface Treatment	4	302.01	\$26,174.44	\$18,120.77	\$18,120.77
WATER ST-21	Even	No	0	Granite	Fair	Surface Treatment	4	150.42	\$13,036.61	\$9,025.34	\$9,025.34
Length: 1,372.85									\$114,273.42	\$91,814.23	\$82,101.04

Ward: 3

AUBURN STREET

AUBURN ST-01	Odd	Yes	4	Granite	Poor	Rehabilitation	4	113.41	\$9,828.76	\$8,820.68	\$6,804.53
AUBURN ST-01	Odd	No	4	Granite	Fair	Surface Treatment	4	122.77	\$10,639.77	\$7,365.99	\$7,365.99

BETA Group, Inc.

Location	GS	GS Width	Curb Type	Condition	Repair	Width	Length	Est. Cost New GC	Est. Cost Adjust GC	Est. Cost No GC	
							Length:	236.18	\$20,468.53	\$16,186.68	\$14,170.52
GREENLEAF STREET											
GREENLEAF ST-01	Even	Yes	4	Granite	Poor	Rehabilitation	4	612.44	\$53,078.10	\$47,634.19	\$36,746.38
							Length:	612.44	\$53,078.10	\$47,634.19	\$36,746.38
HIGH STREET											
HIGH ST-31	Odd	No	0	Granite	Good	Routine Maintenance	4	165.85	\$2,211.32	\$4,422.65	\$2,211.32
							Length:	165.85	\$2,211.32	\$4,422.65	\$2,211.32
POND STREET											
POND ST-02	Even	Yes	6	Granite	Fair	Surface Treatment	3	417.23	\$27,120.22	\$18,775.54	\$18,775.54
							Length:	417.23	\$27,120.22	\$18,775.54	\$18,775.54

City of Newburyport, Massachusetts

Ramp Totals By Street

Street	Number of Ramps
ALLEN STREET	3
ASHLAND STREET	3
AUBURN STREET	4
AZALEA ROAD	2
BARTLETT DRIVE	2
BARTON STREET	5
BEACON AVENUE	2
BECK STREET	2
BRICHER PLACE	2
BROMFIELD STREET	13
CARTER STREET	13
CHAPEL STREET	3
CLIPPER WAY	1
COFFIN'S COURT	2
COLTIN DRIVE	1
COLUMBUS AVENUE	3
CONGRESS STREET	4
COOLIDGE STREET	1
CROW LANE	1
CUSHING AVENUE	1
DANIEL LUCY WAY	5
DENNETT DRIVE	2
DOROTHY LUCY DRIVE	4
FAIR STREET	24
FEDERAL STREET	18
FERRY ROAD	16
FORRESTER STREET	4
FRANCES DRIVE	2
FRUIT STREET	3
GOLDEN DRIVE	6
GOLDSMITHS DRIVE	2
GREENLEAF STREET	3
HALE STREET	2
HANCOCK STREET	3
HARNCHS WAY	2

Street	Number of Ramps
HIGH STREET	129
HIGHLAND AVENUE	4
HILL STREET	8
HOYTS LANE	1
HUNTER DRIVE	1
JACKSON STREET	4
JEFFERSON STREET	4
KENT STREET	5
KNIGHTS LANE	2
LAVALEE LANE	2
LIBERTY STREET	2
LIME STREET	19
LONGFELLOW DRIVE	1
LOW STREET	32
MARLBORO STREET	5
MERRIMAC STREET	114
MIDDLE STREET	3
MILK STREET	1
MOSELEY AVENUE	11
MOULTON STREET	1
MUNROE STREET	2
MURPHY AVENUE	4
NOBLE STREET	2
NORTH ATKINSON STREET	6
NORTHERN BOULEVARD	24
OAKLAND STREET	2
OLIVE STREET	4
PARSONS STREET	2
PHEASANT RUN DRIVE	1
PHILLIPS DRIVE	5
PLEASANT STREET	13
PLUMMER AVENUE	2
POND STREET	14
PRINCE PLACE	1
PROSPECT STREET	5
PURCHASE STREET	13
QUAIL RUN HOLLOW	4

Street	Number of Ramps
RAWSON AVENUE	1
RUSSIA STREET	4
SAVORY STREET	2
SIMMONS DRIVE	4
SOUTH POND STREET	1
SPOFFORD STREET	12
SQUIRES GLEN	2
STATE STREET	38
STOREY AVENUE	4
STOREY BROOK ROAD	2
TILTON STREET	2
TOPPAN'S LANE	6
TURKEY HILL ROAD	21
TYNG STREET	8
UNION STREET	2
UPLAND ROAD	2
VIRGINIA LANE	1
WARREN STREET	13
WASHINGTON STREET	11
WATER STREET	33
WHITES COURT	2
WILDWOOD DRIVE	1
WOODLAND STREET	8
WOODMAN WAY	1
Total:	798.00

City of Newburyport, Massachusetts

Ramp Totals By Street With Inspection Data

Det. Warning Panel		Det. Warning Panel Obstruction		Ramp Condition	Ramp Material	Obstruction	Obstruction Type
Ward: 1							
BARTON STREET		5 Ramps					
At ALTER COURT		2 Ramps					
15-18-1	No	No		Poor	Concrete	Yes	Curbing
15-18-2	No	No		Poor	Asphalt	Yes	Curbing
At BARTON COURT		1 Ramps					
15-21-1	No	No		Poor	Concrete	Yes	Curbing
At HIGH STREET		2 Ramps					
15-14-1	No	No		Good	Concrete	No	None
15-14-2	No	No		Good	Concrete	No	None
BEACON AVENUE		2 Ramps					
At OAK STREET		2 Ramps					
15-11-1	No	No		Poor	Asphalt	No	None
15-11-2	No	No		Poor	Asphalt	No	None
BECK STREET		2 Ramps					
At SMITH'S STREET		2 Ramps					
15-89-1	No	No		Good	Brick	No	None
15-89-2	No	No		Good	Brick	No	None
BROMFIELD STREET		10 Ramps					
At BROMFIELD COURT		2 Ramps					
15-32-1	No	No		Poor	Concrete	No	None
15-32-2	No	No		Poor	Concrete	No	None
At HANCOCK STREET		2 Ramps					
15-50-1	Yes	Yes		Good	Concrete	No	None
15-50-2	Yes	Yes		Good	Concrete	No	None
At HIGH STREET		1 Ramps					
15-19-1	No	No		Fair	Brick	No	None
At MILK STREET		2 Ramps					
15-52-1	Yes	Yes		Good	Concrete	No	None
15-52-4	Yes	Yes		Good	Concrete	No	None
At WATER STREET		3 Ramps					
15-86-1	No	No		Good	Concrete	No	None
15-86-2	No	No		Good	Concrete	No	None
15-86-3	No	No		Poor	Asphalt	No	None
FEDERAL STREET		1 Ramps					
At BECK STREET		1 Ramps					
9-9-1	No	No		Fair	Brick	Yes	Curbing

BETA Group, Inc.

Det. Warning Panel	Det. Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
HANCOCK STREET		3 Ramps				
At	LUNT STREET	2 Ramps				
15-42-1	Yes	Yes	Good	Concrete	No	None
15-42-2	Yes	Yes	Good	Concrete	No	None
At	MADISON STREET	1 Ramps				
15-33-1	No	No	Poor	Concrete	Yes	Curbing
HIGH STREET		2 Ramps				
At	MARLBORO STREET	2 Ramps				
15-10-1	No	No	Good	Brick	No	None
15-10-2	No	No	Good	Brick	Yes	Curbing
LIME STREET		4 Ramps				
At	MILK STREET	2 Ramps				
15-64-5	Yes	Yes	Good	Concrete	No	None
15-64-6	Yes	Yes	Good	Concrete	No	None
At	PURCHASE STREET	2 Ramps				
15-74-1	Yes	Yes	Good	Concrete	Yes	Curbing
15-74-2	Yes	Yes	Good	Concrete	No	None
MARLBORO STREET		5 Ramps				
At	PINE STREET	1 Ramps				
15-31-1	No	No	Good	Brick	No	None
At	REILLY AVENUE	2 Ramps				
15-16-1	No	No	Poor	Asphalt	No	None
15-16-2	No	No	Fair	Asphalt	No	None
At	WATER STREET	2 Ramps				
15-49-1	No	No	Fair	Asphalt	No	None
15-49-2	Yes	Yes	Good	Concrete	No	None
MILK STREET		1 Ramps				
At	FRANKLIN STREET	1 Ramps				
15-58-1	No	No	Good	Brick	No	None
NORTHERN BOULEVARD		24 Ramps				
At	56TH STREET	2 Ramps				
11-14-1	No	No	Good	Asphalt	No	None
11-14-2	No	No	Good	Asphalt	No	None
At	58TH STREET	2 Ramps				
11-18-1	No	No	Good	Asphalt	No	None
11-18-2	No	No	Good	Asphalt	No	None
At	60TH STREET	2 Ramps				
11-23-1	No	No	Good	Asphalt	No	None
11-23-2	No	No	Good	Asphalt	No	None

Det. Warning Panel	Det. Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At 62ND STREET		2 Ramps				
11-28-1	No	No	Good	Asphalt	No	None
11-28-2	No	No	Good	Asphalt	No	None
At 64TH STREET		2 Ramps				
11-31-1	No	No	Good	Asphalt	No	None
11-31-2	No	No	Good	Asphalt	No	None
At 66TH STREET		2 Ramps				
11-35-1	No	No	Good	Asphalt	No	None
11-35-2	No	No	Good	Asphalt	No	None
At 68TH STREET		2 Ramps				
11-39-1	No	No	Good	Asphalt	No	None
11-39-2	No	No	Good	Asphalt	No	None
At 70TH STREET		2 Ramps				
11-42-1	No	No	Good	Asphalt	No	None
11-42-2	No	No	Good	Asphalt	No	None
At 72ND STREET		2 Ramps				
11-47-1	No	No	Good	Asphalt	No	None
11-47-2	No	No	Good	Asphalt	No	None
At 74TH STREET		2 Ramps				
11-53-1	No	No	Good	Asphalt	No	None
11-53-2	No	No	Good	Asphalt	No	None
At 76TH STREET		2 Ramps				
11-55-1	No	No	Good	Asphalt	No	None
11-55-2	No	No	Good	Asphalt	No	None
At 78TH STREET		2 Ramps				
11-65-1	No	No	Good	Asphalt	No	None
11-65-2	No	No	Good	Asphalt	No	None
PURCHASE STREET		13 Ramps				
At CHARLES STREET		2 Ramps				
15-69-1	Yes	Yes	Good	Concrete	No	None
15-69-2	Yes	Yes	Good	Concrete	No	None
At FRANKLIN STREET		4 Ramps				
15-65-1	Yes	Yes	Good	Concrete	No	None
15-65-2	Yes	Yes	Good	Concrete	No	None
15-65-3	Yes	Yes	Good	Concrete	No	None
15-65-4	Yes	Yes	Good	Concrete	No	None
At HARRISON STREET		2 Ramps				
15-53-1	No	No	Good	Brick	No	None
15-53-2	No	No	Fair	Asphalt	No	None

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At LUNT STREET		2 Ramps						
15-55-1	No	No		Fair	Brick	Yes	Curbing	
15-55-2	No	No		Fair	Concrete	Yes	Curbing	
At NEPTUNE STREET		1 Ramps						
15-47-1	No	No		Good	Brick	No	None	
At SALEM STREET		2 Ramps						
15-67-1	Yes	Yes		Good	Concrete	No	None	
15-67-2	Yes	Yes		Good	Concrete	Yes	Curbing	
SOUTH POND STREET		1 Ramps						
At BEACON AVENUE		1 Ramps						
15-6-1	No	No		Poor	Asphalt	No	None	
UNION STREET		2 Ramps						
At WATER STREET		1 Ramps						
15-17-1	No	No		Fair	Asphalt	No	None	
At WOODWELLS AVENUE		1 Ramps						
15-37-1	Yes	Yes		Good	Concrete	No	None	
WATER STREET		19 Ramps						
At FEDERAL STREET		1 Ramps						
9-30-1	No	No		Good	Concrete	No	None	
At FRANKLIN STREET		2 Ramps						
9-1-1	Yes	Yes		Good	Concrete	No	None	
9-1-2	Yes	Yes		Good	Concrete	No	None	
At HARRISON STREET		4 Ramps						
15-73-1	Yes	Yes		Good	Concrete	No	None	
15-73-2	Yes	Yes		Good	Concrete	No	None	
15-73-3	Yes	Yes		Good	Concrete	No	None	
15-73-4	No	No		Good	Concrete	No	None	
At LIME STREET		6 Ramps						
9-18-1	Yes	Yes		Good	Concrete	No	None	
9-18-2	Yes	Yes		Good	Concrete	No	None	
9-18-3	Yes	Yes		Good	Concrete	No	None	
9-18-4	Yes	Yes		Good	Concrete	No	None	
9-18-5	Yes	Yes		Good	Concrete	No	None	
9-18-6	Yes	Yes		Good	Concrete	No	None	
At MADISON STREET		2 Ramps						
15-60-1	No	No		Good	Brick	No	None	
15-60-2	Yes	Yes		Good	Concrete	No	None	
At SHIP STREET		2 Ramps						
9-24-1	No	No		Fair	Concrete	No	None	

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
9-24-2	No	No	Poor	Concrete	No	None
At WOODWELLS AVENUE 2 Ramps						
15-41-1	No	No	Fair	Asphalt	No	None
15-41-2	No	No	Fair	Asphalt	No	None
Ward: 2						
ALLEN STREET 3 Ramps						
At HIGH STREET 2 Ramps						
15-23-1	No	No	Good	Concrete	No	None
15-23-2	No	No	Fair	Brick	No	None
At PROSPECT STREET 1 Ramps						
15-44-1	Yes	Yes	Good	Concrete	No	None
BROMFIELD STREET 3 Ramps						
At HIGH STREET 1 Ramps						
15-19-2	No	No	Fair	Concrete	No	None
At MILK STREET 2 Ramps						
15-52-2	Yes	Yes	Good	Concrete	No	None
15-52-3	Yes	Yes	Good	Concrete	No	None
COFFIN'S COURT 2 Ramps						
At HIGH STREET 2 Ramps						
15-26-1	No	No	Fair	Concrete	No	None
15-26-2	No	No	Good	Concrete	No	None
FAIR STREET 24 Ramps						
At CHARTER STREET 2 Ramps						
9-7-1	Yes	Yes	Good	Concrete	No	None
9-7-2	No	No	Good	Concrete	No	None
At LIBERTY STREET 4 Ramps						
9-26-1	No	No	Good	Concrete	No	None
9-26-2	No	No	Good	Concrete	No	None
9-26-3	No	No	Good	Concrete	No	None
9-26-4	No	No	Good	Concrete	No	None
At MIDDLE STREET 5 Ramps						
9-20-1	No	No	Fair	Concrete	Yes	Catch Basin
9-20-2	No	No	Fair	Concrete	Yes	Catch Basin
9-20-3	No	No	Fair	Concrete	No	None
9-20-4	No	No	Fair	Concrete	Yes	Curbing
9-20-5	No	No	Fair	Concrete	Yes	Curbing
At ORANGE STREET 2 Ramps						
9-4-1	No	No	Good	Brick	No	None
9-4-2	No	No	Good	Concrete	No	None

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At PROSPECT STREET		1 Ramps						
15-80-1	Yes	Yes		Good	Concrete	No	None	
At SPRING STREET		2 Ramps						
9-11-1	No	No		Fair	Concrete	Yes	Catch Basin	
9-11-2	No	No		Good	Brick	No	None	
At TEMPLE STREET		6 Ramps						
15-87-1	No	No		Fair	Concrete	Yes	Catch Basin	
15-87-2	No	No		Fair	Concrete	Yes	Curbing	
15-87-3	Yes	Yes		Good	Concrete	No	None	
15-87-4	Yes	Yes		Good	Concrete	No	None	
15-87-5	Yes	Yes		Good	Concrete	No	None	
15-87-6	Yes	Yes		Good	Concrete	No	None	
At WATER STREET		2 Ramps						
9-39-1	No	No		Good	Concrete	Yes	Curbing	
9-39-2	No	No		Good	Concrete	No	None	
FEDERAL STREET		17 Ramps						
At ATWOOD STREET		1 Ramps						
15-82-1	No	No		Fair	Brick	No	None	
At BECK STREET		2 Ramps						
9-9-2	No	No		Fair	Brick	Yes	Curbing	
9-9-3	No	No		Good	Brick	Yes	Curbing	
At LIBERTY STREET		1 Ramps						
9-15-1	No	No		Fair	Asphalt	No	None	
At MIDDLE STREET		1 Ramps						
9-8-1	No	No		Good	Brick	Yes	Curbing	
At MILK STREET		3 Ramps						
15-75-1	Yes	Yes		Good	Concrete	No	None	
15-75-2	Yes	Yes		Good	Concrete	No	None	
15-75-3	Yes	Yes		Good	Concrete	No	None	
At ORANGE STREET		2 Ramps						
15-77-1	Yes	Yes		Good	Concrete	No	None	
15-77-2	Yes	Yes		Good	Concrete	No	None	
At PROSPECT STREET		6 Ramps						
15-66-1	No	No		Good	Concrete	No	None	
15-66-2	No	No		Good	Concrete	No	None	
15-66-3	No	No		Good	Concrete	No	None	
15-66-4	No	No		Good	Concrete	No	None	
15-66-5	No	No		Fair	Concrete	Yes	Curbing	
15-66-6	No	No		Good	Concrete	No	None	

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At	SCHOOL STREET				1 Ramps			
15-90-1	No		No		Good	Brick	No	None
FRUIT STREET					3 Ramps			
At	PROSPECT STREET				3 Ramps			
15-79-1	No		No		Fair	Concrete	No	None
15-79-2	No		No		Good	Concrete	No	None
15-79-3	No		No		Good	Concrete	No	None
GREENLEAF STREET					3 Ramps			
At	DALTON STREET				2 Ramps			
14-23-1	No		No		Good	Concrete	No	None
14-23-2	No		No		Good	Concrete	No	None
At	FULTON STREET				1 Ramps			
14-22-1	No		No		Good	Concrete	No	None
HIGH STREET					24 Ramps			
At	0				2 Ramps			
15-A-1	No		No		Good	Brick	No	None
15-A-2	No		No		Good	Brick	Yes	Curbing
At	FEDERAL STREET				4 Ramps			
15-46-1	No		No		Fair	Brick	No	None
15-46-2	No		No		Fair	Brick	Yes	Man Hole
15-46-3	No		No		Fair	Brick	No	None
15-46-4	No		No		Fair	Brick	No	None
At	FRUIT STREET				2 Ramps			
15-62-1	No		No		Fair	Brick	Yes	Curbing
15-62-2	No		No		Fair	Brick	Yes	Curbing
At	GREEN STREET				2 Ramps			
14-45-2	No		No		Fair	Brick	Yes	Curbing
14-45-3	No		No		Fair	Brick	Yes	Curbing
At	PARK STREET				2 Ramps			
14-42-1	No		No		Fair	Brick	Yes	Curbing
14-42-2	No		No		Fair	Brick	Yes	Curbing
At	ROBERTS LANE				2 Ramps			
15-12-1	No		No		Good	Concrete	No	None
15-12-2	No		No		Good	Concrete	Yes	Man Hole
At	STATE STREET				8 Ramps			
14-34-1	No		No		Good	Brick	No	None
14-34-2	No		No		Good	Brick	No	None
14-34-3	No		No		Good	Brick	No	None
14-34-4	Yes		Yes		Good	Brick	No	None

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
14-34-5	Yes	Yes	Good	Brick	No	None
14-34-6	No	No	Good	Brick	No	None
14-34-7	No	No	Good	Brick	Yes	Curbing
14-34-8	No	No	Good	Brick	Yes	Curbing
At TREMONT STREET		2 Ramps				
15-56-1	No	No	Fair	Brick	Yes	Curbing
15-56-2	No	No	Fair	Brick	Yes	Curbing
HILL STREET		5 Ramps				
At BOYLSTON STREET		2 Ramps				
14-10-1	No	No	Fair	Concrete	No	None
14-10-2	No	No	Fair	Concrete	No	None
At BRICHER PLACE		1 Ramps				
14-14-1	No	No	Fair	Asphalt	No	None
At DALTON STREET		2 Ramps				
14-21-1	No	No	Good	Concrete	No	None
14-21-2	No	No	Good	Concrete	No	None
LIBERTY STREET		2 Ramps				
At INDEPENDENT STREET		1 Ramps				
9-22-1	No	No	Good	Asphalt	No	None
At PIKE STREET		1 Ramps				
9-31-1	No	No	Fair	Concrete	No	None
LIME STREET		15 Ramps				
At HIGH STREET		4 Ramps				
15-34-1	No	No	Good	Brick	No	None
15-34-2	No	No	Good	Brick	No	None
15-34-3	No	No	Good	Brick	No	None
15-34-4	No	No	Good	Brick	No	None
At MILK STREET		6 Ramps				
15-64-1	Yes	Yes	Good	Concrete	No	None
15-64-2	Yes	Yes	Good	Concrete	No	None
15-64-3	Yes	Yes	Good	Concrete	No	None
15-64-4	Yes	Yes	Good	Concrete	No	None
15-64-7	Yes	Yes	Good	Concrete	No	None
15-64-8	Yes	Yes	Good	Concrete	No	None
At PROSPECT STREET		5 Ramps				
15-57-1	No	No	Good	Concrete	No	None
15-57-2	No	No	Good	Concrete	No	None
15-57-3	No	No	Good	Concrete	No	None
15-57-4	Yes	Yes	Good	Concrete	No	None

Det. Warning Panel	Det. Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
15-57-5	Yes	Yes	Good	Concrete	No	None
MERRIMAC STREET		15 Ramps				
At 0		6 Ramps				
9-B-1	No	No	Good	Brick	No	None
9-B-2	No	No	Fair	Brick	No	None
9-C-1	No	No	Good	Brick	No	None
9-C-2	No	No	Good	Brick	No	None
9-C-3	No	No	Good	Brick	No	None
9-C-4	No	No	Good	Brick	No	None
At GREEN STREET		5 Ramps				
8-44-1	No	No	Good	Brick	No	None
8-44-2	No	No	Good	Asphalt	No	None
8-44-3	No	No	Good	Asphalt	Yes	Signal
8-44-4	No	No	Fair	Brick	No	None
8-44-5	No	No	Fair	Brick	Yes	Curbing
At MARKET STREET		1 Ramps				
8-50-1	No	No	Good	Concrete	No	None
At TITCOMB STREET		3 Ramps				
8-47-2	No	No	Good	Concrete	No	None
8-47-3	No	No	Good	Concrete	No	None
8-47-4	No	No	Fair	Asphalt	No	None
MIDDLE STREET		3 Ramps				
At CENTER STREET		1 Ramps				
9-28-1	No	No	Good	Concrete	No	None
At PARKING LOT		2 Ramps				
9-33-1	No	No	Good	Asphalt	No	None
9-33-2	No	No	Fair	Asphalt	Yes	Curbing
PARSONS STREET		2 Ramps				
At HIGH STREET		2 Ramps				
15-25-1	No	No	Good	Brick	No	None
15-25-2	No	No	Good	Brick	No	None
PLEASANT STREET		9 Ramps				
At HALE'S COURT		2 Ramps				
9-32-1	No	No	Good	Brick	No	None
9-32-2	No	No	Good	Brick	No	None
At MARKET STREET		3 Ramps				
8-42-1	Yes	Yes	Good	Concrete	No	None
8-42-2	Yes	Yes	Good	Concrete	No	None
8-42-7	No	No	Fair	Brick	No	None

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At TITCOMB STREET								
2 Ramps								
8-36-1	No	No		Fair	Concrete	Yes	Curbing	
8-36-2	Yes	Yes		Good	Brick	Yes	Curbing	
At TRACY PLACE								
2 Ramps								
9-25-1	No	No		Good	Brick	No	None	
9-25-2	No	No		Good	Brick	No	None	
POND STREET								
5 Ramps								
At GREENLEAF STREET								
2 Ramps								
14-32-1	Yes	Yes		Good	Concrete	No	None	
14-32-5	Yes	Yes		Good	Concrete	No	None	
At HIGH STREET								
2 Ramps								
14-37-1	No	No		Good	Brick	No	None	
14-37-2	No	No		Good	Brick	No	None	
At HILL STREET								
1 Ramps								
14-31-2	Yes	Yes		Good	Concrete	No	None	
PRINCE PLACE								
1 Ramps								
At HALE'S COURT								
1 Ramps								
8-16-1	No	No		Poor	Asphalt	Yes	Curbing	
PROSPECT STREET								
5 Ramps								
At ORANGE STREET								
2 Ramps								
15-85-1	No	No		Good	Concrete	No	None	
15-85-2	No	No		Good	Concrete	No	None	
At PARSONS STREET								
3 Ramps								
15-51-1	Yes	Yes		Good	Concrete	No	None	
15-51-2	Yes	Yes		Good	Concrete	No	None	
15-51-3	Yes	Yes		Good	Concrete	No	None	
STATE STREET								
38 Ramps								
At BOYLSTON STREET								
2 Ramps								
14-15-1	No	No		Poor	Brick	Yes	Curbing	
14-15-2	No	No		Fair	Brick	Yes	Curbing	
At BROWN STREET								
2 Ramps								
14-19-1	No	No		Good	Concrete	No	None	
14-19-2	No	No		Good	Concrete	No	None	
At CENTRAL PLACE								
2 Ramps								
14-24-1	No	No		Good	Concrete	No	None	
14-24-2	No	No		Good	Concrete	No	None	
At CHARTER STREET								
2 Ramps								
9-19-1	No	No		Good	Brick	No	None	
9-19-2	No	No		Good	Brick	No	None	

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At	ESSEX STREET				2 Ramps			
9-27-1	No		No		Good	Brick	No	None
9-27-2	No		No		Good	Brick	No	None
At	GREENLEAF STREET				2 Ramps			
14-19-1	No		No		Fair	Brick	Yes	Curbing
14-19-2	No		No		Good	Brick	No	None
At	HARRIS STREET				3 Ramps			
9-3-1	No		No		Good	Brick	No	None
9-3-2	No		No		Good	Brick	No	None
9-3-3	No		No		Good	Brick	No	None
At	LIBERTY STREET				4 Ramps			
9-38-1	No		No		Good	Brick	No	None
9-38-2	No		No		Good	Brick	No	None
9-38-3	No		No		Good	Brick	No	None
9-38-4	No		No		Good	Brick	No	None
At	MIDDLE STREET				4 Ramps			
9-35-1	No		No		Good	Brick	No	None
9-35-2	No		No		Good	Brick	No	None
9-35-3	No		No		Good	Brick	No	None
9-35-4	No		No		Good	Brick	No	None
At	PARKER STREET				1 Ramps			
14-3-1	No		No		Good	Concrete	No	None
At	PLEASANT STREET				5 Ramps			
9-23-1	No		No		Good	Brick	No	None
9-23-2	No		No		Good	Brick	No	None
9-23-3	No		No		Good	Brick	No	None
9-23-4	No		No		Good	Brick	Yes	Curbing
9-23-5	No		No		Good	Brick	Yes	Curbing
At	PRINCE PLACE				2 Ramps			
9-12-1	No		No		Good	Brick	No	None
9-12-2	No		No		Good	Brick	No	None
At	PROSPECT STREET				3 Ramps			
9-6-1	No		No		Fair	Brick	No	None
9-6-2	Yes		Yes		Fair	Brick	No	None
9-6-3	Yes		Yes		Fair	Brick	No	None
At	TEMPLE STREET				4 Ramps			
9-13-1	No		No		Good	Brick	Yes	Curbing
9-13-2	No		No		Good	Brick	No	None
9-13-3	No		No		Good	Brick	No	None

BETA Group, Inc.

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
9-13-4	No	No	Good	Brick	No	None
WATER STREET 14 Ramps						
At 0	2 Ramps					
9-A-1	No	No	Good	Concrete	Yes	Utility Access
9-A-2	No	No	Good	Concrete	No	None
At CENTER STREET	2 Ramps					
9-43-1	No	No	Fair	Asphalt	No	None
9-43-2	No	No	Good	Asphalt	No	None
At FEDERAL STREET	1 Ramps					
9-30-2	No	No	Fair	Brick	No	None
At FERRY WHARF	2 Ramps					
9-42-1	No	No	Fair	Brick	Yes	Curbing
9-42-2	No	No	Fair	Brick	No	None
At INDEPENDENT STREET	3 Ramps					
9-37-1	No	No	Fair	Brick	No	None
9-37-2	No	No	Fair	Brick	No	None
9-37-3	No	No	Fair	Asphalt	Yes	Curbing
At PARKING LOT	2 Ramps					
9-44-1	No	No	Fair	Brick	No	None
9-44-2	No	No	Fair	Brick	Yes	Curbing
At PIKE STREET	2 Ramps					
9-41-1	No	No	Fair	Asphalt	No	None
9-41-2	No	No	Good	Asphalt	No	None

Ward: 3

AUBURN STREET 4 Ramps						
At HIGH STREET	2 Ramps					
8-9-1	No	No	Good	Brick	No	None
8-9-2	No	No	Good	Brick	No	None
At POND STREET	2 Ramps					
14-28-1	No	No	Poor	Concrete	No	None
14-28-2	No	No	Poor	Concrete	No	None
BRICHER PLACE 2 Ramps						
At QUILL STREET	2 Ramps					
14-13-1	No	No	Fair	Asphalt	No	None
14-13-2	No	No	Fair	Asphalt	No	None
CARTER STREET 13 Ramps						
At CUTTERS COURT	1 Ramps					
8-110-1	No	No	Poor	Concrete	No	None
At EAGLE STREET	1 Ramps					

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
8-79-1	No	No	Fair	Brick	Yes	Curbing
At GRIFFINS COURT 1 Ramps						
8-118-1	No	No	Fair	Brick	Yes	Curbing
At MERRIMAC STREET 2 Ramps						
8-128-1	No	No	Fair	Asphalt	No	None
8-128-2	No	No	Fair	Asphalt	No	None
At MUNROE STREET 8 Ramps						
8-106-1	Yes	Yes	Good	Concrete	No	None
8-106-2	Yes	Yes	Good	Concrete	No	None
8-106-3	Yes	Yes	Good	Concrete	No	None
8-106-4	Yes	Yes	Good	Concrete	No	None
8-106-5	Yes	Yes	Good	Concrete	No	None
8-106-6	Yes	Yes	Good	Concrete	No	None
8-106-7	Yes	Yes	Good	Concrete	No	None
8-106-8	Yes	Yes	Good	Concrete	No	None
CONGRESS STREET 4 Ramps						
At MERRILL STREET 4 Ramps						
8-65-1	Yes	Yes	Good	Concrete	No	None
8-65-2	Yes	Yes	Good	Concrete	No	None
8-65-3	Yes	Yes	Good	Concrete	No	None
8-65-4	Yes	Yes	Good	Concrete	No	None
HIGH STREET 46 Ramps						
At BOARDMAN STREET 3 Ramps						
8-26-1	No	No	Fair	Brick	No	None
8-26-2	No	No	Fair	Brick	No	None
8-26-3	No	No	Fair	Concrete	No	None
At BROAD STREET 3 Ramps						
8-81-2	No	No	Fair	Brick	No	None
8-81-3	No	No	Fair	Brick	No	None
8-81-4	No	No	Good	Concrete	No	None
At BUCK STREET 2 Ramps						
8-38-1	No	No	Fair	Brick	No	None
8-38-2	No	No	Good	Concrete	No	None
At CAREY AVENUE 2 Ramps						
8-19-1	No	No	Good	Concrete	No	None
8-19-2	No	No	Good	Concrete	No	None
At CARTER STREET 2 Ramps						
8-73-1	No	No	Fair	Brick	No	None
8-73-2	No	No	Fair	Brick	No	None

BETA Group, Inc.

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At COURT STREET		2 Ramps						
8-5-1	No	No		Fair	Brick	Yes	Curbing	
8-5-2	No	No		Fair	Brick	Yes	Curbing	
At EPPA WAY		2 Ramps						
14-41-1	No	No		Good	Brick	No	None	
14-41-2	No	No		Good	Brick	No	None	
At GREEN STREET		2 Ramps						
14-45-1	No	No		Fair	Brick	Yes	Curbing	
14-45-4	No	No		Good	Brick	No	None	
At JOHNSON STREET		4 Ramps						
8-40-1	No	No		Fair	Concrete	No	None	
8-40-2	No	No		Fair	Concrete	No	None	
8-40-3	No	No		Fair	Concrete	No	None	
8-40-4	No	No		Fair	Brick	No	None	
At KENT STREET		4 Ramps						
8-48-1	No	No		Fair	Concrete	No	None	
8-48-2	No	No		Fair	Concrete	No	None	
8-48-3	No	No		Good	Concrete	No	None	
8-48-4	No	No		Fair	Brick	No	None	
At MARKET STREET		4 Ramps						
8-10-1	No	No		Fair	Brick	No	None	
8-10-2	No	No		Poor	Brick	Yes	Curbing	
8-10-3	No	No		Poor	Brick	Yes	Curbing	
8-10-4	No	No		Fair	Asphalt	Yes	Curbing	
At OLIVE STREET		4 Ramps						
8-31-1	No	No		Fair	Brick	No	None	
8-31-2	No	No		Good	Brick	No	None	
8-31-3	No	No		Fair	Asphalt	No	None	
8-31-4	No	No		Fair	Asphalt	No	None	
At PARK STREET		1 Ramps						
14-42-3	No	No		Good	Brick	No	None	
At SUMMER STREET		4 Ramps						
8-17-1	No	No		Fair	Brick	No	None	
8-17-2	No	No		Good	Concrete	No	None	
8-17-3	No	No		Fair	Brick	Yes	Curbing	
8-17-4	No	No		Fair	Brick	Yes	Curbing	
At SUMMIT PLACE		2 Ramps						
8-60-1	No	No		Good	Concrete	No	None	
8-60-2	No	No		Good	Concrete	No	None	

BETA Group, Inc.

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At TOPPAN'S LANE		1 Ramps						
8-87-1	No	No			Good	Concrete	No	None
At WINTER STREET		4 Ramps						
8-18-1	No	No			Good	Brick	No	None
8-18-2	No	No			Good	Concrete	No	None
8-18-3	No	No			Good	Concrete	No	None
8-18-4	No	No			Good	Concrete	No	None
HILL STREET		3 Ramps						
At BRICHER PLACE		1 Ramps						
14-14-2	No	No			Poor	Asphalt	No	None
At ROUTE 1		2 Ramps						
14-8-1	Yes	Yes			Good	Concrete	No	None
14-8-2	Yes	Yes			Good	Concrete	No	None
KENT STREET		5 Ramps						
At CURRIERS COURT		2 Ramps						
8-91-1	No	No			Fair	Asphalt	No	None
8-91-2	No	No			Fair	Asphalt	No	None
At MUNROE STREET		3 Ramps						
8-74-1	No	No			Good	Concrete	No	None
8-74-2	No	No			Good	Concrete	No	None
8-74-3	Yes	Yes			Good	Concrete	No	None
LOW STREET		7 Ramps						
At 0		4 Ramps						
14-A-1	Yes	Yes			Good	Concrete	No	None
14-A-2	Yes	Yes			Good	Concrete	No	None
14-B-1	Yes	Yes			Fair	Concrete	No	None
14-B-2	Yes	Yes			Fair	Concrete	No	None
At JOHNSON STREET		2 Ramps						
14-40-1	No	No			Good	Asphalt	No	None
14-40-2	No	No			Fair	Asphalt	No	None
At TOPPAN'S LANE		1 Ramps						
8-8-1	Yes	Yes			Good	Concrete	No	None
MERRIMAC STREET		40 Ramps						
At BOARDMAN STREET		2 Ramps						
8-76-1	No	No			Fair	Concrete	No	None
8-76-2	No	No			Good	Concrete	No	None
At BROAD STREET		1 Ramps						
8-132-2	No	No			Fair	Asphalt	Yes	Man Hole
At BROWNS WHARF		2 Ramps						

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
8-49-1	No	No	Fair	Asphalt	No	None
8-49-2	No	No	Good	Brick	No	None
At DOVE STREET		2 Ramps				
8-117-1	No	No	Good	Asphalt	No	None
8-117-2	No	No	Poor	Concrete	No	None
At ELM STREET		2 Ramps				
8-89-1	No	No	Fair	Concrete	No	None
8-89-2	No	No	Fair	Concrete	No	None
At KENT STREET		1 Ramps				
8-112-1	No	No	Fair	Concrete	No	None
At MARKET STREET		1 Ramps				
8-50-2	No	No	Fair	Asphalt	No	None
At MECHANICS COURT		4 Ramps				
8-67-1	No	No	Good	Brick	No	None
8-67-2	No	No	Fair	Brick	Yes	Curbing
8-67-3	No	No	Fair	Brick	Yes	Curbing
8-72-1	No	No	Fair	Brick	Yes	Curbing
At MERRILL STREET		2 Ramps				
8-97-1	Yes	Yes	Good	Concrete	No	None
8-97-2	Yes	Yes	Good	Concrete	No	None
At OLIVE STREET		2 Ramps				
8-83-1	No	No	Good	Concrete	No	None
8-83-2	No	No	Good	Concrete	No	None
At POP CROWLEY WAY		4 Ramps				
8-104-1	Yes	Yes	Good	Concrete	No	None
8-104-2	No	No	Good	Concrete	No	None
8-77-1	No	No	Fair	Concrete	No	None
8-77-2	No	No	Good	Asphalt	No	None
At STRONG STREET		2 Ramps				
8-62-1	No	No	Good	Concrete	No	None
8-62-2	No	No	Fair	Brick	No	None
At SUMMER STREET		5 Ramps				
8-54-1	No	No	Fair	Concrete	No	None
8-54-2	No	No	Fair	Concrete	No	None
8-54-3	No	No	Fair	Concrete	No	None
8-54-4	No	No	Fair	Concrete	Yes	Sign
8-54-5	No	No	Fair	Concrete	No	None
At TITCOMB STREET		1 Ramps				
8-47-1	No	No	Good	Brick	No	None

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At WARREN STREET 3 Ramps								
8-122-1	No	No	Fair	Asphalt	Yes	Curbing		
8-122-2	No	No	Fair	Asphalt	No	None		
8-122-3	No	No	Fair	Concrete	No	None		
At WHITES COURT 2 Ramps								
8-92-1	No	No	Good	Asphalt	No	None		
8-92-2	Yes	Yes	Good	Concrete	No	None		
At WINTER STREET 4 Ramps								
8-58-1	No	No	Fair	Concrete	No	None		
8-58-2	No	No	Fair	Concrete	No	None		
8-58-3	No	No	Good	Concrete	No	None		
8-58-4	No	No	Good	Concrete	No	None		
MUNROE STREET 2 Ramps								
At DOVE STREET 2 Ramps								
8-85-1	Yes	Yes	Good	Concrete	No	None		
8-85-2	Yes	Yes	Good	Concrete	No	None		
OLIVE STREET 4 Ramps								
At CONGRESS STREET 2 Ramps								
8-53-1	Yes	Yes	Good	Concrete	No	None		
8-53-2	Yes	Yes	Good	Concrete	No	None		
At RUSSIA STREET 2 Ramps								
8-59-1	No	No	Good	Concrete	No	None		
8-59-2	No	No	Fair	Concrete	No	None		
PLEASANT STREET 4 Ramps								
At MARKET STREET 4 Ramps								
8-42-3	Yes	Yes	Good	Concrete	No	None		
8-42-4	Yes	Yes	Good	Concrete	No	None		
8-42-5	Yes	Yes	Good	Concrete	No	None		
8-42-6	Yes	Yes	Good	Concrete	No	None		
POND STREET 9 Ramps								
At COTTAGE COURT 2 Ramps								
14-27-1	Yes	Yes	Good	Concrete	No	None		
14-27-2	No	No	Good	Concrete	No	None		
At EPPA WAY 1 Ramps								
14-36-1	No	No	Good	Asphalt	No	None		
At GREENLEAF STREET 3 Ramps								
14-32-2	Yes	Yes	Good	Concrete	No	None		
14-32-3	Yes	Yes	Good	Concrete	No	None		
14-32-4	Yes	Yes	Good	Concrete	No	None		

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At HILL STREET		1 Ramps						
14-31-1	Yes	Yes			Good	Concrete	No	None
At HILLSIDE AVENUE		2 Ramps						
14-26-1	Yes	Yes			Good	Concrete	No	None
14-26-2	Yes	Yes			Good	Concrete	No	None
RUSSIA STREET		4 Ramps						
At MERRILL STREET		4 Ramps						
8-70-1	Yes	Yes			Good	Concrete	No	None
8-70-2	Yes	Yes			Good	Concrete	No	None
8-70-3	Yes	Yes			Good	Concrete	No	None
8-70-4	Yes	Yes			Good	Concrete	No	None
TOPPAN'S LANE		3 Ramps						
At HIGHLAND AVENUE		1 Ramps						
8-66-1	Yes	Yes			Good	Concrete	No	None
At SUMMIT PLACE		2 Ramps						
8-27-1	No	No			Poor	Concrete	Yes	Gate
8-27-2	No	No			Good	Concrete	No	None
WARREN STREET		13 Ramps						
At CUTTERS COURT		2 Ramps						
8-100-1	No	No			Fair	Concrete	No	None
8-100-2	Yes	Yes			Good	Concrete	No	None
At GRIFFINS COURT		2 Ramps						
8-108-1	No	No			Fair	Concrete	No	None
8-108-2	No	No			Good	Brick	No	None
At LAFAYETTE COURT		2 Ramps						
8-88-1	No	No			Good	Asphalt	No	None
8-88-2	No	No			Good	Asphalt	No	None
At MUNROE STREET		5 Ramps						
8-93-1	Yes	Yes			Good	Concrete	No	None
8-93-2	Yes	Yes			Good	Concrete	No	None
8-93-3	Yes	Yes			Good	Concrete	No	None
8-93-4	Yes	Yes			Good	Concrete	No	None
8-93-5	No	No			Fair	Concrete	Yes	Catch Basin
At OCEAN STREET		2 Ramps						
8-80-1	No	No			Good	Concrete	Yes	Curbing
8-80-2	No	No			Good	Concrete	No	None
WASHINGTON STREET		11 Ramps						
At 0		2 Ramps						
8-B-1	Yes	Yes			Good	Concrete	No	None

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
8-B-2	Yes	Yes	Good	Concrete	No	None
At COURT STREET 2 Ramps						
8-20-1	No	No	Good	Concrete	No	None
8-20-2	No	No	Good	Concrete	No	None
At OLIVE STREET 1 Ramps						
8-45-1	Yes	Yes	Good	Concrete	Yes	Curbing
At STRONG STREET 1 Ramps						
8-35-1	No	No	Fair	Concrete	Yes	Curbing
At SUMMER STREET 3 Ramps						
8-28-1	No	No	Good	Concrete	No	None
8-28-2	No	No	Fair	Concrete	No	None
8-28-3	No	No	Fair	Concrete	No	None
At WINTER STREET 2 Ramps						
8-32-1	No	No	Fair	Concrete	No	None
8-32-2	No	No	Fair	Concrete	No	None
WHITES COURT 2 Ramps						
At POP CROWLEY WAY 2 Ramps						
8-105-1	No	No	Good	Brick	No	None
8-105-2	No	No	Good	Brick	No	None
Ward: 4						
ASHLAND STREET 3 Ramps						
At COOLIDGE STREET 1 Ramps						
5-17-1	No	No	Poor	Asphalt	No	None
At STANLEY STREET 2 Ramps						
5-19-1	Yes	Yes	Good	Concrete	No	None
5-19-2	Yes	Yes	Good	Concrete	No	None
CHAPEL STREET 3 Ramps						
At MAGNOLIA STREET 1 Ramps						
8-155-1	No	No	Fair	Asphalt	Yes	Curbing
At PAYSON STREET 2 Ramps						
8-162-1	Yes	Yes	Good	Concrete	No	None
8-162-2	Yes	Yes	Good	Concrete	No	None
COLUMBUS AVENUE 3 Ramps						
At FARRELL STREET 1 Ramps						
8-137-1	No	No	Poor	Asphalt	No	None
At TRACY PLACE 2 Ramps						
8-138-1	No	No	Fair	Asphalt	No	None
8-138-2	No	No	Fair	Asphalt	Yes	Curbing
COOLIDGE STREET 1 Ramps						

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At DAWES STREET		1 Ramps						
5-23-1	No	No		Fair	Concrete	No	None	
DOROTHY LUCY DRIVE		4 Ramps						
At DONER DRIVE		2 Ramps						
4-81-1	No	No		Good	Concrete	No	None	
4-81-2	No	No		Good	Concrete	No	None	
At GOVE DRIVE		2 Ramps						
4-59-1	No	No		Good	Concrete	No	None	
4-59-2	No	No		Good	Concrete	No	None	
FORRESTER STREET		4 Ramps						
At MERRIMAC STREET		2 Ramps						
5-26-1	No	No		Fair	Asphalt	No	None	
5-26-2	No	No		Fair	Asphalt	No	None	
At STANLEY STREET		2 Ramps						
5-12-1	Yes	Yes		Good	Concrete	No	None	
5-12-2	Yes	Yes		Good	Concrete	No	None	
HIGH STREET		42 Ramps						
At 0		3 Ramps						
5-A-4	No	No		Fair	Brick	No	None	
8-A-1	No	No		Good	Concrete	No	None	
8-A-2	No	No		Good	Brick	No	None	
At ARLINGTON STREET		2 Ramps						
8-121-1	No	No		Fair	Brick	No	None	
8-121-2	No	No		Fair	Brick	No	None	
At ASHLAND STREET		3 Ramps						
5-7-1	No	No		Good	Concrete	No	None	
5-7-2	No	No		Good	Concrete	No	None	
5-7-3	No	No		Good	Concrete	No	None	
At BROAD STREET		1 Ramps						
8-81-1	No	No		Fair	Brick	No	None	
At CHAPEL STREET		4 Ramps						
8-148-1	No	No		Good	Concrete	No	None	
8-148-2	No	No		Good	Concrete	No	None	
8-148-3	No	No		Good	Concrete	No	None	
8-148-4	No	No		Good	Concrete	No	None	
At COLUMBUS AVENUE		2 Ramps						
8-153-1	No	No		Good	Concrete	No	None	
8-153-2	No	No		Good	Brick	No	None	
At FORRESTER STREET		2 Ramps						

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
8-159-1	No	No	Good	Concrete	No	None
8-159-2	No	No	Good	Concrete	No	None
At JEFFERSON STREET		2 Ramps				
5-18-1	No	No	Good	Concrete	No	None
5-18-2	No	No	Good	Concrete	No	None
At LAFAYETTE STREET		2 Ramps				
8-129-1	No	No	Good	Concrete	No	None
8-129-2	No	No	Good	Concrete	No	None
At NORTH ATKINSON STREET		1 Ramps				
5-4-2	No	No	Good	Concrete	No	None
At OAKLAND STREET		4 Ramps				
8-114-1	No	No	Good	Brick	No	None
8-114-2	No	No	Good	Brick	No	None
8-114-3	No	No	Fair	Brick	No	None
8-114-4	No	No	Good	Concrete	No	None
At PLUMMER AVENUE		3 Ramps				
4-19-1	No	No	Good	Concrete	No	None
4-19-2	No	No	Good	Concrete	No	None
4-19-3	No	No	Fair	Concrete	Yes	Man Hole
At RAWSON AVENUE		2 Ramps				
8-135-1	No	No	Good	Concrete	No	None
8-135-2	No	No	Good	Concrete	No	None
At TOPPAN'S LANE		3 Ramps				
8-87-2	No	No	Good	Concrete	No	None
8-87-3	No	No	Fair	Concrete	No	None
8-87-4	No	No	Fair	Brick	Yes	Curbing
At TYNG STREET		2 Ramps				
8-98-1	No	No	Good	Brick	No	None
8-98-2	No	No	Good	Brick	No	None
At UPLAND ROAD		2 Ramps				
4-17-1	No	No	Poor	Asphalt	No	None
4-17-2	No	No	Poor	Concrete	No	None
At WILLOW AVENUE		4 Ramps				
8-154-1	No	No	Poor	Asphalt	No	None
8-154-2	No	No	Fair	Asphalt	No	None
8-154-3	No	No	Good	Concrete	No	None
8-154-4	No	No	Good	Concrete	No	None
HIGHLAND AVENUE		4 Ramps				
At ARLINGTON STREET		1 Ramps				

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
8-90-1	No	No	Fair	Concrete	No	None
At LAFAYETTE STREET 2 Ramps						
8-99-1	No	No	Poor	Asphalt	No	None
8-99-2	No	No	Fair	Asphalt	No	None
At RAWSON AVENUE 1 Ramps						
8-109-1	No	No	Fair	Concrete	No	None
JACKSON STREET 4 Ramps						
At CARLTON DRIVE 2 Ramps						
8-145-1	Yes	Yes	Good	Concrete	No	None
8-145-2	Yes	Yes	Good	Concrete	No	None
At COLLINS STREET 2 Ramps						
8-142-1	Yes	Yes	Good	Concrete	No	None
8-142-2	Yes	Yes	Good	Concrete	No	None
JEFFERSON STREET 4 Ramps						
At ADAMS STREET 2 Ramps						
5-31-1	Yes	Yes	Good	Concrete	No	None
5-31-2	Yes	Yes	Good	Concrete	No	None
At CHRISTOPHER STREET 2 Ramps						
5-33-1	Yes	Yes	Good	Concrete	No	None
5-33-2	Yes	Yes	Good	Concrete	No	None
LOW STREET 8 Ramps						
At COLTIN DRIVE 1 Ramps						
8-37-2	Yes	Yes	Good	Concrete	No	None
At HUNTER DRIVE 1 Ramps						
8-61-1	No	No	Fair	Asphalt	No	None
At TOPPAN'S LANE 2 Ramps						
8-8-2	Yes	Yes	Good	Concrete	No	None
8-8-3	Yes	Yes	Good	Concrete	No	None
At WILLIAM BASHAW JR WAY 2 Ramps						
8-39-1	Yes	Yes	Good	Concrete	No	None
8-39-2	No	No	Fair	Asphalt	No	None
At ZABRISKIE DRIVE 2 Ramps						
8-15-1	No	No	Fair	Asphalt	No	None
8-15-2	No	No	Poor	Asphalt	No	None
MERRIMAC STREET 55 Ramps						
At 0 3 Ramps						
4-D-1	No	No	Good	Asphalt	No	None
5-B-1	No	No	Good	Concrete	No	None
5-C-1	No	No	Fair	Concrete	No	None

Det.	Warning Panel	Det.	Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At	ASHLAND STREET				3 Ramps			
5-30-1	No		No		Fair	Asphalt	No	None
5-30-2	No		No		Fair	Asphalt	No	None
5-30-3	No		No		Poor	Asphalt	No	None
At	BAYNE LANE				2 Ramps			
4-82-1	No		No		Good	Asphalt	No	None
4-82-2	No		No		Fair	Asphalt	No	None
At	BROAD STREET				2 Ramps			
8-132-1	No		No		Fair	Asphalt	No	None
8-132-3	No		No		Poor	Concrete	No	None
At	BUTLER STREET				4 Ramps			
5-14-1	No		No		Good	Concrete	No	None
5-14-2	No		No		Good	Asphalt	No	None
5-14-3	No		No		Fair	Asphalt	No	None
5-14-4	No		No		Good	Asphalt	No	None
At	CALIFORNIA STREET				2 Ramps			
8-158-1	No		No		Good	Asphalt	No	None
8-158-2	No		No		Good	Asphalt	No	None
At	CHRISTIE STREET				1 Ramps			
4-75-1	No		No		Fair	Asphalt	No	None
At	CLARK STREET				2 Ramps			
2-1-1	No		No		Good	Asphalt	No	None
2-1-2	No		No		Good	Concrete	No	None
At	DONER DRIVE				2 Ramps			
4-83-1	No		No		Good	Concrete	No	None
4-83-2	No		No		Good	Brick	No	None
At	JEFFERSON STREET				5 Ramps			
5-37-1	Yes		Yes		Good	Concrete	No	None
5-37-2	Yes		Yes		Good	Concrete	No	None
5-37-3	Yes		Yes		Good	Concrete	No	None
5-38-1	Yes		Yes		Good	Concrete	No	None
5-38-2	No		No		Fair	Asphalt	No	None
At	MANSON AVENUE				2 Ramps			
8-143-1	No		No		Good	Asphalt	No	None
8-143-2	No		No		Poor	Concrete	No	None
At	MERRIMAC COURT				1 Ramps			
5-16-1	No		No		Good	Concrete	No	None
At	MOSELEY AVENUE				6 Ramps			
2-2-1	Yes		Yes		Good	Concrete	No	None

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
2-2-2	Yes	Yes	Good	Concrete	No	None
2-2-3	Yes	Yes	Good	Concrete	No	None
2-2-4	Yes	Yes	Good	Concrete	No	None
2-2-5	Yes	Yes	Good	Concrete	No	None
2-2-6	Yes	Yes	Good	Concrete	No	None
At MOULTON STREET		2 Ramps				
4-62-1	No	No	Fair	Asphalt	No	None
4-62-2	No	No	Fair	Asphalt	No	None
At OAKLAND STREET		3 Ramps				
8-146-1	No	No	Good	Asphalt	No	None
8-146-2	No	No	Good	Asphalt	No	None
8-146-3	No	No	Good	Brick	No	None
At PLUMMER AVENUE		3 Ramps				
5-41-1	No	No	Good	Asphalt	No	None
5-41-2	No	No	Good	Concrete	No	None
5-41-3	No	No	Good	Asphalt	No	None
At SAVORY STREET		2 Ramps				
5-10-1	No	No	Fair	Asphalt	No	None
5-10-2	No	No	Fair	Asphalt	No	None
At TYNG STREET		4 Ramps				
8-139-1	No	No	Fair	Concrete	No	None
8-139-2	No	No	Fair	Concrete	No	None
8-139-3	No	No	Fair	Concrete	No	None
8-139-4	No	No	Fair	Asphalt	No	None
At UNION PLACE		2 Ramps				
5-20-1	No	No	Poor	Concrete	No	None
5-20-2	No	No	Fair	Concrete	No	None
At WOODLAND STREET		4 Ramps				
5-2-1	No	No	Fair	Asphalt	No	None
5-2-2	No	No	Fair	Asphalt	No	None
5-2-3	No	No	Fair	Concrete	Yes	Curbing
5-2-4	No	No	Fair	Asphalt	Yes	Curbing
MOSELEY AVENUE		4 Ramps				
At CHASE STREET		1 Ramps				
4-29-1	No	No	Good	Asphalt	No	None
At DOROTHY LUCY DRIVE		2 Ramps				
4-56-1	No	No	Fair	Asphalt	No	None
4-56-2	No	No	Good	Concrete	No	None
At NEW STREET		1 Ramps				

Det.	Warning Panel	Det.	Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
4-52-2	No	No		Fair	Asphalt	No	None
NORTH ATKINSON STREET		2 Ramps					
At	CHARRON DRIVE	1 Ramps					
8-136-1	No	No		Poor	Asphalt	No	None
At	TRACY STREET	1 Ramps					
8-147-1	No	No		Good	Asphalt	Yes	Catch Basin
OAKLAND STREET		2 Ramps					
At	JACKSON STREET	2 Ramps					
8-133-1	Yes	Yes		Good	Concrete	No	None
8-133-2	Yes	Yes		Good	Concrete	No	None
PLUMMER AVENUE		2 Ramps					
At	CHRISTOPHER STREET	2 Ramps					
5-36-1	No	No		Poor	Asphalt	No	None
5-36-2	No	No		Poor	Asphalt	No	None
RAWSON AVENUE		1 Ramps					
At	FARRELL STREET	1 Ramps					
8-116-1	No	No		Poor	Asphalt	No	None
SAVORY STREET		2 Ramps					
At	RIVER STREET	2 Ramps					
5-15-1	No	No		Poor	Asphalt	No	None
5-15-2	No	No		Poor	Asphalt	No	None
SPOFFORD STREET		3 Ramps					
At	CLARK STREET	2 Ramps					
2-4-1	No	No		Good	Asphalt	No	None
2-4-2	No	No		Good	Asphalt	No	None
At	MOSELEY AVENUE	1 Ramps					
2-3-10	Yes	Yes		Good	Concrete	No	None
TILTON STREET		2 Ramps					
At	MCCLINTOCK AVENUE	1 Ramps					
8-126-1	No	No		Good	Asphalt	No	None
At	RAWSON AVENUE	1 Ramps					
8-107-1	No	No		Poor	Asphalt	No	None
TOPPAN'S LANE		3 Ramps					
At	HIGHLAND AVENUE	3 Ramps					
8-66-2	Yes	Yes		Good	Concrete	No	None
8-66-3	Yes	Yes		Good	Concrete	No	None
8-66-4	Yes	Yes		Good	Concrete	No	None
TYNG STREET		8 Ramps					
At	MUNROE STREET	8 Ramps					

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
8-124-1	No	No	Good	Concrete	No	None
8-124-2	No	No	Good	Concrete	No	None
8-124-3	No	No	Good	Concrete	No	None
8-124-4	No	No	Good	Concrete	Yes	Catch Basin
8-124-5	No	No	Good	Brick	No	None
8-124-6	No	No	Good	Brick	No	None
8-124-7	No	No	Good	Concrete	No	None
8-124-8	No	No	Good	Concrete	No	None
UPLAND ROAD 2 Ramps						
At ADAMS STREET 2 Ramps						
5-32-1	No	No	Poor	Asphalt	No	None
5-32-2	No	No	Good	Asphalt	No	None
WOODLAND STREET 8 Ramps						
At CARLTON DRIVE 2 Ramps						
8-140-1	Yes	Yes	Good	Concrete	No	None
8-140-2	Yes	Yes	Good	Concrete	No	None
At DEXTER STREET 2 Ramps						
8-150-1	Yes	Yes	Good	Concrete	No	None
8-150-2	Yes	Yes	Good	Concrete	No	None
At HIGH STREET 2 Ramps						
8-134-1	No	No	Good	Concrete	No	None
8-134-2	No	No	Good	Concrete	No	None
At JACKSON STREET 2 Ramps						
8-152-1	Yes	Yes	Good	Concrete	No	None
8-152-2	Yes	Yes	Good	Concrete	No	None
Ward: 5						
BARTLETT DRIVE 2 Ramps						
At WANDOVER WAY 2 Ramps						
6-1-1	No	No	Poor	Asphalt	No	None
6-1-2	No	No	Poor	Asphalt	No	None
COLTIN DRIVE 1 Ramps						
At COLTIN DRIVE 1 Ramps						
8-12-1	No	No	Fair	Asphalt	No	None
CROW LANE 1 Ramps						
At KINGHTS LANE 1 Ramps						
13-9-1	No	No	Fair	Asphalt	No	None
FRANCES DRIVE 2 Ramps						
At LAVALEE LANE 2 Ramps						
12-5-1	No	No	Good	Asphalt	No	None

Det. Warning Panel	Det. Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
12-5-2	No	No	Fair	Asphalt	No	None
GOLDEN DRIVE		6 Ramps				
At 0		6 Ramps				
8-D-1	Yes	Yes	Good	Concrete	No	None
8-E-1	No	No	Good	Concrete	No	None
8-F-1	No	No	Good	Concrete	No	None
8-F-2	No	No	Good	Concrete	No	None
8-G-1	Yes	Yes	Good	Concrete	No	None
8-G-2	Yes	Yes	Good	Concrete	No	None
GOLDSMITHS DRIVE		2 Ramps				
At BERRY DRIVE		2 Ramps				
13-6-1	No	No	Fair	Asphalt	No	None
13-6-2	No	No	Fair	Asphalt	No	None
HALE STREET		2 Ramps				
At LAVALEE LANE		2 Ramps				
12-3-1	No	No	Fair	Concrete	No	None
12-3-2	No	No	Fair	Concrete	No	None
HIGH STREET		15 Ramps				
At 0		3 Ramps				
5-A-1	No	No	Good	Concrete	No	None
5-A-2	No	No	Good	Concrete	No	None
5-A-3	No	No	Good	Concrete	No	None
At ASHLAND STREET		1 Ramps				
5-7-4	No	No	Good	Concrete	No	None
At BROOKS COURT		2 Ramps				
5-9-1	No	No	Good	Concrete	No	None
5-9-2	No	No	Fair	Concrete	No	None
At CUTTING DRIVE		2 Ramps				
4-18-1	No	No	Good	Concrete	No	None
4-18-2	No	No	Fair	Asphalt	No	None
At JEFFERSON STREET		2 Ramps				
5-18-3	No	No	Fair	Concrete	No	None
5-18-4	No	No	Good	Concrete	No	None
At MYRTLE AVENUE		3 Ramps				
5-21-1	No	No	Fair	Asphalt	No	None
5-21-2	No	No	Poor	Concrete	No	None
5-21-3	No	No	Good	Concrete	No	None
At NORTH ATKINSON STREET		1 Ramps				
5-4-1	No	No	Good	Concrete	No	None

Det. Warning Panel	Det. Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At PLUMMER AVENUE	1 Ramps					
4-19-4	No	No	Fair	Concrete	Yes	Curbing
HUNTER DRIVE	1 Ramps					
At LOIS STREET	1 Ramps					
8-82-1	No	No	Fair	Asphalt	No	None
KNIGHTS LANE	2 Ramps					
At BARTLETT DRIVE	2 Ramps					
7-1-1	No	No	Good	Asphalt	No	None
7-1-2	No	No	Good	Asphalt	No	None
LAVALEE LANE	2 Ramps					
At BRADBURY LANE	2 Ramps					
12-9-1	No	No	Good	Asphalt	No	None
12-9-2	No	No	Good	Asphalt	No	None
LOW STREET	17 Ramps					
At AVON STREET	2 Ramps					
7-18-1	No	No	Good	Asphalt	No	None
7-18-2	No	No	Good	Asphalt	No	None
At BRISSETTE AVENUE	2 Ramps					
7-19-1	No	No	Good	Asphalt	No	None
7-19-2	No	No	Good	Asphalt	No	None
At COLTIN DRIVE	1 Ramps					
8-37-1	Yes	Yes	Good	Concrete	No	None
At COURTS FARM LANE	2 Ramps					
8-68-1	No	No	Poor	Asphalt	No	None
8-68-2	No	No	Poor	Asphalt	No	None
At HUNTER DRIVE	1 Ramps					
8-61-2	No	No	Fair	Asphalt	No	None
At MURPHY AVENUE	2 Ramps					
7-17-1	No	No	Fair	Asphalt	No	None
7-17-2	No	No	Good	Asphalt	No	None
At NORTH ATKINSON STREET	2 Ramps					
7-13-1	No	No	Fair	Asphalt	No	None
7-13-2	No	No	Good	Asphalt	No	None
At STICKNEY AVENUE	2 Ramps					
7-21-1	No	No	Good	Asphalt	No	None
7-21-2	No	No	Good	Asphalt	No	None
At TOPPAN'S LANE	1 Ramps					
8-8-4	No	No	Fair	Concrete	No	None
At WILLIAMSON AVENUE	2 Ramps					

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
7-22-1	No	No	Fair	Asphalt	Yes	Man Hole
7-22-2	No	No	Good	Asphalt	No	None
MURPHY AVENUE		4 Ramps				
At NORMAN AVENUE		4 Ramps				
7-20-1	Yes	Yes	Good	Concrete	No	None
7-20-2	Yes	Yes	Good	Concrete	No	None
7-20-3	Yes	Yes	Good	Concrete	No	None
7-20-4	Yes	Yes	Good	Concrete	No	None
NORTH ATKINSON STREET		4 Ramps				
At 0		2 Ramps				
8-C-1	Yes	Yes	Good	Concrete	No	None
8-C-2	Yes	Yes	Good	Concrete	No	None
At CHARRON DRIVE		1 Ramps				
8-136-2	No	No	Poor	Asphalt	No	None
At SIMMONS DRIVE		1 Ramps				
7-15-1	No	No	Good	Concrete	No	None
PHEASANT RUN DRIVE		1 Ramps				
At QUAIL RUN HOLLOW		1 Ramps				
7-2-1	No	No	Fair	Asphalt	No	None
QUAIL RUN HOLLOW		4 Ramps				
At DOE RUN DRIVE		1 Ramps				
13-7-1	No	No	Poor	Asphalt	No	None
At FOX RUN ROAD		1 Ramps				
13-11-1	No	No	Fair	Asphalt	No	None
At WILDWOOD DRIVE		2 Ramps				
7-3-1	No	No	Fair	Asphalt	No	None
7-3-2	No	No	Fair	Asphalt	No	None
SIMMONS DRIVE		4 Ramps				
At GOLDEN DRIVE		4 Ramps				
8-111-1	No	No	Good	Concrete	Yes	Curbing
8-111-2	Yes	Yes	Fair	Concrete	Yes	Curbing
8-120-1	No	No	Good	Concrete	No	None
8-120-2	No	No	Good	Concrete	No	None
SQUIRES GLEN		2 Ramps				
At HALE STREET		2 Ramps				
14-38-1	No	No	Fair	Concrete	No	None
14-38-2	No	No	Fair	Asphalt	No	None
STOREY AVENUE		2 Ramps				
At DANIEL LUCY WAY		2 Ramps				

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
7-12-3	Yes	Yes	Good	Concrete	No	None
7-12-4	Yes	Yes	Good	Concrete	No	None
STOREY BROOK ROAD		2 Ramps				
At LT LEARY DRIVE		1 Ramps				
7-10-1	No	No	Good	Asphalt	No	None
At VIRGINIA LANE		1 Ramps				
7-11-1	No	No	Good	Asphalt	No	None
TURKEY HILL ROAD		4 Ramps				
At BARTLETT DRIVE		2 Ramps				
12-29-1	No	No	Fair	Asphalt	No	None
12-29-2	No	No	Fair	Asphalt	No	None
At HALE STREET		1 Ramps				
12-2-2	No	No	Good	Concrete	No	None
At HENDERSON CIRCLE		1 Ramps				
6-12-1	Yes	Yes	Good	Concrete	No	None
VIRGINIA LANE		1 Ramps				
At MELVIN COURT		1 Ramps				
7-7-1	No	No	Good	Concrete	No	None
WILDWOOD DRIVE		1 Ramps				
At CHARMANSKI DRIVE		1 Ramps				
7-4-1	No	No	Fair	Asphalt	No	None
Ward: 6						
AZALEA ROAD		2 Ramps				
At FENDERS AVENUE		2 Ramps				
4-61-1	No	No	Poor	Asphalt	No	None
4-61-2	No	No	Poor	Asphalt	No	None
CLIPPER WAY		1 Ramps				
At CLARK STREET		1 Ramps				
4-2-1	No	No	Good	Concrete	No	None
CUSHING AVENUE		1 Ramps				
At HARDY STREET		1 Ramps				
4-54-1	No	No	Fair	Asphalt	No	None
DANIEL LUCY WAY		5 Ramps				
At ARTHUR WELCH DRIVE		2 Ramps				
4-7-1	No	No	Good	Concrete	No	None
4-7-2	No	No	Good	Concrete	No	None
At CURZON'S MILL ROAD		1 Ramps				
3-1-1	No	No	Good	Concrete	No	None
At WILLIAM HALL DRIVE		2 Ramps				

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
4-4-1	No	No	Good	Concrete	No	None
4-4-2	No	No	Good	Concrete	No	None
DENNETT DRIVE 2 Ramps						
At FINNEGAN WAY 1 Ramps						
6-15-1	No	No	Fair	Asphalt	Yes	Catch Basin
At STOREY AVENUE 1 Ramps						
6-18-1	No	No	Fair	Asphalt	No	None
FERRY ROAD 16 Ramps						
At AZALEA ROAD 2 Ramps						
4-70-1	Yes	Yes	Good	Concrete	No	None
4-70-2	Yes	Yes	Good	Concrete	No	None
At BOYD DRIVE 2 Ramps						
4-49-1	Yes	Yes	Good	Concrete	No	None
4-49-2	Yes	Yes	Good	Concrete	No	None
At BRIGGS AVENUE 2 Ramps						
4-68-1	Yes	Yes	Good	Concrete	No	None
4-68-2	Yes	Yes	Good	Concrete	No	None
At CHAISSON ROAD 2 Ramps						
4-26-1	No	No	Fair	Concrete	No	None
4-26-2	No	No	Fair	Asphalt	Yes	Catch Basin
At HARDY STREET 1 Ramps						
4-31-1	No	No	Poor	Asphalt	No	None
At HARNCHS WAY 2 Ramps						
4-25-1	No	No	Fair	Asphalt	No	None
4-25-2	No	No	Fair	Concrete	No	None
At LAUREL STREET 4 Ramps						
4-72-1	Yes	Yes	Good	Concrete	No	None
4-72-2	Yes	Yes	Good	Concrete	No	None
4-72-3	Yes	Yes	Good	Concrete	No	None
4-72-4	No	No	Good	Asphalt	No	None
At LAWTON DRIVE 1 Ramps						
4-30-1	No	No	Fair	Asphalt	No	None
HARNCHS WAY 2 Ramps						
At STOREY AVENUE 2 Ramps						
4-21-1	No	No	Poor	Asphalt	No	None
4-21-2	No	No	Fair	Asphalt	No	None
HOYTS LANE 1 Ramps						
At DREW STREET 1 Ramps						
6-24-1	No	No	Fair	Asphalt	No	None

Det. Warning Panel	Det. Warning Panel	Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
LONGFELLOW DRIVE		1 Ramps				
At	TURKEY HILL ROAD	1 Ramps				
12-20-1	No	No	Fair	Asphalt	No	None
MERRIMAC STREET		4 Ramps				
At	MOSELEY AVENUE	4 Ramps				
2-2-10	Yes	Yes	Good	Concrete	No	None
2-2-7	Yes	Yes	Good	Concrete	No	None
2-2-8	Yes	Yes	Good	Concrete	No	None
2-2-9	Yes	Yes	Good	Concrete	No	None
MOSELEY AVENUE		7 Ramps				
At	CHASE STREET	1 Ramps				
4-29-2	No	No	Fair	Asphalt	No	None
At	HARDY STREET	3 Ramps				
4-44-1	No	No	Fair	Asphalt	No	None
4-45-1	No	No	Good	Asphalt	No	None
4-45-2	No	No	Good	Asphalt	No	None
At	MOULTON STREET	2 Ramps				
4-39-1	Yes	Yes	Good	Brick	No	None
4-39-2	No	No	Poor	Asphalt	Yes	Curbing
At	NEW STREET	1 Ramps				
4-52-1	No	No	Fair	Asphalt	No	None
MOULTON STREET		1 Ramps				
At	GARNET STREET	1 Ramps				
4-48-1	No	No	Fair	Asphalt	No	None
NOBLE STREET		2 Ramps				
At	COOMBS CIRCLE	2 Ramps				
4-32-1	No	No	Good	Asphalt	No	None
4-32-2	No	No	Fair	Asphalt	No	None
PHILLIPS DRIVE		5 Ramps				
At	DREW STREET	3 Ramps				
6-25-1	No	No	Poor	Asphalt	No	None
6-26-1	No	No	Good	Asphalt	No	None
6-26-2	No	No	Good	Asphalt	No	None
At	SULLIVAN DRIVE	2 Ramps				
6-22-1	No	No	Poor	Asphalt	No	None
6-23-1	No	No	Fair	Asphalt	No	None
SPOFFORD STREET		9 Ramps				
At	MOSELEY AVENUE	9 Ramps				
2-3-1	Yes	Yes	Good	Concrete	No	None

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
2-3-2	Yes	Yes	Good	Concrete	No	None
2-3-3	Yes	Yes	Good	Concrete	No	None
2-3-4	Yes	Yes	Good	Concrete	No	None
2-3-5	Yes	Yes	Good	Concrete	No	None
2-3-6	Yes	Yes	Good	Concrete	No	None
2-3-7	Yes	Yes	Good	Concrete	No	None
2-3-8	Yes	Yes	Good	Concrete	No	None
2-3-9	Yes	Yes	Good	Concrete	No	None
STOREY AVENUE						
2 Ramps						
At DANIEL LUCY WAY						
2 Ramps						
7-12-1	No	No	Good	Concrete	No	None
7-12-2	No	No	Good	Concrete	No	None
TURKEY HILL ROAD						
17 Ramps						
At BARTLETT DRIVE						
2 Ramps						
12-29-3	No	No	Fair	Concrete	Yes	Curbing
12-29-4	No	No	Fair	Concrete	Yes	Curbing
At BOURBEAU TERRACE						
4 Ramps						
6-2-1	No	No	Fair	Concrete	Yes	Curbing
6-2-2	No	No	Fair	Concrete	Yes	Curbing
6-5-1	No	No	Fair	Concrete	Yes	Curbing
6-5-2	No	No	Fair	Concrete	Yes	Curbing
At EVERETTE DRIVE						
2 Ramps						
6-10-1	No	No	Fair	Concrete	No	None
6-10-2	No	No	Fair	Concrete	No	None
At HALE STREET						
1 Ramps						
12-2-1	No	No	Good	Concrete	No	None
At LONGFELLOW DRIVE						
2 Ramps						
12-4-1	No	No	Good	Concrete	No	None
12-4-2	No	No	Fair	Concrete	No	None
At MARQUAND ROAD						
2 Ramps						
12-8-1	No	No	Fair	Concrete	No	None
12-8-2	No	No	Fair	Concrete	No	None
At NEWHALL LANE						
2 Ramps						
12-15-1	No	No	Fair	Concrete	No	None
12-15-2	No	No	Fair	Concrete	No	None
At WINDWARD DRIVE						
2 Ramps						
12-28-1	No	No	Good	Concrete	No	None
12-28-2	No	No	Good	Concrete	No	None
WOODMAN WAY						
1 Ramps						

	Det. Warning Panel	Det. Warning Panel Obstruction	Ramp Condition	Ramp Material	Obstruction	Obstruction Type
At CLIPPER WAY	1 Ramps					
4-11-1	No	No	Good	Asphalt	No	None

City of Newburyport, Massachusetts

Intersections With Sidewalks and No Ramps

		Proposed Number of Ramps	Cost
Ward: 1			
BEACON AVENUE	2	Locations	
At LINCOLN STREET			
15-20		4	\$14,000.00
At PINE STREET			
15-15		2	\$7,000.00
Estimated Street Total Cost:			\$21,000.00
BECK STREET	1	Locations	
At SHIP STREET			
9-2		2	\$7,000.00
Estimated Street Total Cost:			\$7,000.00
BROMFIELD STREET	1	Locations	
At PURCHASE STREET			
15-61		6	\$21,000.00
Estimated Street Total Cost:			\$21,000.00
CHESTNUT STREET	1	Locations	
At BARTON STREET			
15-28		2	\$7,000.00
Estimated Street Total Cost:			\$7,000.00
GOODWINS AVENUE	1	Locations	
At WATER STREET			
15-35		1	\$3,500.00
Estimated Street Total Cost:			\$3,500.00
LIME STREET	1	Locations	
At BECK STREET			
15-84		2	\$7,000.00
Estimated Street Total Cost:			\$7,000.00
MARLBORO STREET	7	Locations	
At CHESTNUT STREET			
15-22		2	\$7,000.00
At HANCOCK STREET			
15-27		2	\$7,000.00
At LINCOLN STREET			
15-38		2	\$7,000.00
At OAK STREET			
15-24		2	\$7,000.00
At PURCHASE STREET			
15-36		2	\$7,000.00

BETA Group, Inc.

	Proposed Number of Ramps	Cost
At SOUTH POND STREET		
15-13	2	\$7,000.00
At UNION STREET		
15-45	2	\$7,000.00
Estimated Street Total Cost:		\$49,000.00
OAK STREET	1 Locations	
At GUILD STREET		
15-7	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
PURCHASE STREET	1 Locations	
At MADISON STREET		
15-43	4	\$14,000.00
Estimated Street Total Cost:		\$14,000.00
UNION STREET	2 Locations	
At BEACON AVENUE		
15-29	2	\$7,000.00
At GOODWINS AVENUE		
15-30	2	\$7,000.00
Estimated Street Total Cost:		\$14,000.00
Ward: 2		
BROMFIELD STREET	2 Locations	
At CHESTNUT STREET		
15-40	2	\$7,000.00
At PROSPECT STREET		
15-39	4	\$14,000.00
Estimated Street Total Cost:		\$21,000.00
FAIR STREET	1 Locations	
At ESSEX STREET		
9-14	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
FEDERAL STREET	2 Locations	
At HORTN STREET		
15-59	2	\$7,000.00
At SPRING STREET		
15-88	2	\$7,000.00
Estimated Street Total Cost:		\$14,000.00
FEDERAL STREETT	1 Locations	
At TEMPLE STREET		
15-72	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
HORTON STREET	1 Locations	

	Proposed Number of Ramps	Cost
At FOSTER COURT		
15-54	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
LIBERTY STREET 1 Locations		
At CENTER STREET		
9-34	4	\$14,000.00
Estimated Street Total Cost:		\$14,000.00
LIME STREET 2 Locations		
At HORTON STREET		
15-48	2	\$7,000.00
At SCHOOL STREET		
15-76	2	\$7,000.00
Estimated Street Total Cost:		\$14,000.00
MIDDLE STREET 1 Locations		
At INDEPENDENT STREET		
9-17	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
OTIS PLACE 1 Locations		
At GARDEN STREET		
15-78	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
PROSPECT STREET 1 Locations		
At TREMONT STREET		
15-71	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
STATE STREET 1 Locations		
At GARDEN STREET		
15-83	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
WASHINGTON STREET 2 Locations		
At MARKET STREET		
8-25	8	\$28,000.00
At TITCOMB STREET		
8-21	2	\$7,000.00
Estimated Street Total Cost:		\$35,000.00
Ward: 3		
AUBURN STREET 2 Locations		
At R.R. STREET		
14-43	2	\$7,000.00
At VERNON STREET		
8-4	2	\$7,000.00

Proposed Number of Ramps		Cost
Estimated Street Total Cost:		\$14,000.00
BOARDMAN STREET	1 Locations	
At ATKINSON STREET		
8-52	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
BROAD STREET	1 Locations	
At MUNROE STREET		
8-115	8	\$28,000.00
Estimated Street Total Cost:		\$28,000.00
CAREY AVENUE	1 Locations	
At VERNON STREET		
8-11	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
CARTER STREET	1 Locations	
At OCEAN STREET		
8-94	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
CONGRESS STREET	1 Locations	
At BUCK STREET		
8-63	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
KENT STREET	4 Locations	
At CONGRESS STREET		
8-78	2	\$7,000.00
At EAGLE STREET		
8-55	2	\$7,000.00
At RUSSIA STREET		
8-86	2	\$7,000.00
At WASHINGTON STREET		
8-64	2	\$7,000.00
Estimated Street Total Cost:		\$28,000.00
MARKET STREET	1 Locations	
At BIRCH STREET		
8-33	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
MERRIMAC STREET	1 Locations	
At CALDWELLS COURT		
8-102	3	\$10,500.00
Estimated Street Total Cost:		\$10,500.00
OLIVE STREET	1 Locations	
At PLUM STREET		

	Proposed Number of Ramps	Cost
8-69	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
PLEASANT STREET	1 Locations	
At SUMMER STREET		
8-43	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
R.R. STREET	1 Locations	
At ROUTE 1		
8-2	1	\$3,500.00
Estimated Street Total Cost:		\$3,500.00
STRONG STREET	1 Locations	
At ATKINSN STREET		
8-46	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
SUMMER STREET	1 Locations	
At BIRCH STREET		
8-34	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
WARREN STREET	1 Locations	
At EAGLE STREET		
8-71	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
WASHINGTON STREET	2 Locations	
At BOARDMAN STREET		
8-41	8	\$28,000.00
At BUCK STREET		
8-51	8	\$28,000.00
Estimated Street Total Cost:		\$56,000.00
Ward: 4		
ASHLAND STREET	2 Locations	
At ASHLAND COURT		
5-25	2	\$7,000.00
At DAWES STREET		
5-13	2	\$7,000.00
Estimated Street Total Cost:		\$14,000.00
FARRELL STREET	1 Locations	
At MCCLINTOCK AVENUE		
8-131	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
FORRESTER STREET	2 Locations	
At HOWARD STREET		

	Proposed Number of Ramps	Cost
5-22	2	\$7,000.00
At MAPLE STREET		
5-8	2	\$7,000.00
Estimated Street Total Cost:		\$14,000.00
HIGH STREET	2 Locations	
At STOREY AVENUE		
4-22	4	\$14,000.00
4-23	4	\$14,000.00
Estimated Street Total Cost:		\$28,000.00
HOWARD STREET	1 Locations	
At BUTLER STREET		
5-5	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
MAPLE STREET	1 Locations	
At WILLOW AVENUE		
5-3	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
MERRIMAC STREET	1 Locations	
At CHRISTIE STREET		
4-66	1	\$3,500.00
Estimated Street Total Cost:		\$3,500.00
MOSELEY AVENUE	1 Locations	
At CHAIN BRIDGE DRIVE		
4-80	1	\$3,500.00
Estimated Street Total Cost:		\$3,500.00
OAKLAND STREET	2 Locations	
At COLLINS STREET		
8-125	2	\$7,000.00
At MUNROE STREET		
8-130	2	\$7,000.00
Estimated Street Total Cost:		\$14,000.00
PAYSON STREET	1 Locations	
At BEACON STREET		
8-156	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
PLUMMER AVENUE	1 Locations	
At PARKING LOT		
5-34	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
WALNUT STREET	1 Locations	
At CALIFORNIA STREET		

	Proposed Number of Ramps	Cost
8-149	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
WOODLAND STREET	3 Locations	
At HOWARD STREET		
8-157	2	\$7,000.00
At PAYSON STREET		
8-144	2	\$7,000.00
At WALNUT STREET		
8-160	2	\$7,000.00
Estimated Street Total Cost:		\$21,000.00
ZABRISKIE DRIVE	1 Locations	
At ZABRISKIE DRIVE		
8-22	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
Ward: 5		
BAYBERRY ROAD	1 Locations	
At BAYBERRY ROAD		
6-4	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
GOLDSMITHS DRIVE	3 Locations	
At ANDERSON LANE		
13-5	2	\$7,000.00
At BRADBURY LANE		
12-26	2	\$7,000.00
At LAVALEE LANE		
12-25	2	\$7,000.00
Estimated Street Total Cost:		\$21,000.00
NORTH ATKINSON STREET	1 Locations	
At NORMAN AVENUE		
7-16	2	\$7,000.00
Estimated Street Total Cost:		\$7,000.00
STOREY AVENUE	1 Locations	
At FERRY ROAD		
4-24	4	\$14,000.00
Estimated Street Total Cost:		\$14,000.00
Ward: 6		
CHAIN BRIDGE DRIVE	1 Locations	
At SPOFFORD STREET		
4-79	1	\$3,500.00
Estimated Street Total Cost:		\$3,500.00

	Proposed Number of Ramps	Cost
DENNETT DRIVE	1 Locations	
At CHATIGNEY LANE		
6-13	1	\$3,500.00
Estimated Street Total Cost:		\$3,500.00
EVERETTE DRIVE	1 Locations	
At DENNETT DRIVE		
6-9	1	\$3,500.00
Estimated Street Total Cost:		\$3,500.00
FERRY ROAD	2 Locations	
At FERRY ROAD		
4-74	2	\$7,000.00
At MOULTON STREET		
4-28	2	\$7,000.00
Estimated Street Total Cost:		\$14,000.00
MOULTON STREET	1 Locations	
At CUSHING AVENUE		
4-50	1	\$3,500.00
Estimated Street Total Cost:		\$3,500.00
PHILLIPS DRIVE	1 Locations	
At RYAN STREET		
6-27	1	\$3,500.00
Estimated Street Total Cost:		\$3,500.00
TURKEY HILL ROAD	3 Locations	
At BAYBERRY ROAD		
6-3	1	\$3,500.00
At GOLDSMITHS DRIVE		
12-24	2	\$7,000.00
At STOREY AVENUE		
6-20	1	\$3,500.00
Estimated Street Total Cost:		\$14,000.00
Total Estimated Cost:		\$749,000.00

City of Newburyport, Massachusetts

Ramp Locations With Obstructions

Total: 93

	Obstruction	Obstruction Type	Material
BARTON STREET	3 Ramps Total		
At ALTER COURT	2 Ramps		
15-18-1	Yes	Curbing	Concrete
15-18-2	Yes	Curbing	Asphalt
At BARTON COURT	1 Ramps		
15-21-1	Yes	Curbing	Concrete
CARTER STREET	2 Ramps Total		
At EAGLE STREET	1 Ramps		
8-79-1	Yes	Curbing	Brick
At GRIFFINS COURT	1 Ramps		
8-118-1	Yes	Curbing	Brick
CHAPEL STREET	1 Ramps Total		
At MAGNOLIA STREET	1 Ramps		
8-155-1	Yes	Curbing	Asphalt
COLUMBUS AVENUE	1 Ramps Total		
At TRACY PLACE	1 Ramps		
8-138-2	Yes	Curbing	Asphalt
DENNETT DRIVE	1 Ramps Total		
At FINNEGAN WAY	1 Ramps		
6-15-1	Yes	Catch Basin	Asphalt
FAIR STREET	8 Ramps Total		
At MIDDLE STREET	4 Ramps		
9-20-1	Yes	Catch Basin	Concrete
9-20-2	Yes	Catch Basin	Concrete
9-20-4	Yes	Curbing	Concrete
9-20-5	Yes	Curbing	Concrete
At SPRING STREET	1 Ramps		
9-11-1	Yes	Catch Basin	Concrete
At TEMPLE STREET	2 Ramps		
15-87-1	Yes	Catch Basin	Concrete
15-87-2	Yes	Curbing	Concrete
At WATER STREET	1 Ramps		
9-39-1	Yes	Curbing	Concrete
FEDERAL STREET	5 Ramps Total		
At BECK STREET	3 Ramps		
9-9-1	Yes	Curbing	Brick
9-9-2	Yes	Curbing	Brick
9-9-3	Yes	Curbing	Brick
At MIDDLE STREET	1 Ramps		
9-8-1	Yes	Curbing	Brick

BETA Group, Inc.

	Obstruction	Obstruction Type	Material
At PROSPECT STREET	1 Ramps		
15-66-5	Yes	Curbing	Concrete
FERRY ROAD	1 Ramps Total		
At CHAISSON ROAD	1 Ramps		
4-26-2	Yes	Catch Basin	Asphalt
HANCOCK STREET	1 Ramps Total		
At MADISON STREET	1 Ramps		
15-33-1	Yes	Curbing	Concrete
HIGH STREET	25 Ramps Total		
At 0	1 Ramps		
15-A-2	Yes	Curbing	Brick
At COURT STREET	2 Ramps		
8-5-1	Yes	Curbing	Brick
8-5-2	Yes	Curbing	Brick
At FEDERAL STREET	1 Ramps		
15-46-2	Yes	Man Hole	Brick
At FRUIT STREET	2 Ramps		
15-62-1	Yes	Curbing	Brick
15-62-2	Yes	Curbing	Brick
At GREEN STREET	3 Ramps		
14-45-1	Yes	Curbing	Brick
14-45-2	Yes	Curbing	Brick
14-45-3	Yes	Curbing	Brick
At MARKET STREET	3 Ramps		
8-10-2	Yes	Curbing	Brick
8-10-3	Yes	Curbing	Brick
8-10-4	Yes	Curbing	Asphalt
At MARLBORO STREET	1 Ramps		
15-10-2	Yes	Curbing	Brick
At PARK STREET	2 Ramps		
14-42-1	Yes	Curbing	Brick
14-42-2	Yes	Curbing	Brick
At PLUMMER AVENUE	2 Ramps		
4-19-3	Yes	Man Hole	Concrete
4-19-4	Yes	Curbing	Concrete
At ROBERTS LANE	1 Ramps		
15-12-2	Yes	Man Hole	Concrete
At STATE STREET	2 Ramps		
14-34-7	Yes	Curbing	Brick
14-34-8	Yes	Curbing	Brick
At SUMMER STREET	2 Ramps		
8-17-3	Yes	Curbing	Brick
8-17-4	Yes	Curbing	Brick

BETA Group, Inc.

	Obstruction	Obstruction Type	Material
At TOPPAN'S LANE	1 Ramps		
8-87-4	Yes	Curbing	Brick
At TREMONT STREET	2 Ramps		
15-56-1	Yes	Curbing	Brick
15-56-2	Yes	Curbing	Brick
LIME STREET	1 Ramps Total		
At PURCHASE STREET	1 Ramps		
15-74-1	Yes	Curbing	Concrete
LOW STREET	1 Ramps Total		
At WILLIAMSON AVENUE	1 Ramps		
7-22-1	Yes	Man Hole	Asphalt
MERRIMAC STREET	10 Ramps Total		
At BROAD STREET	1 Ramps		
8-132-2	Yes	Man Hole	Asphalt
At GREEN STREET	2 Ramps		
8-44-3	Yes	Signal	Asphalt
8-44-5	Yes	Curbing	Brick
At MECHANICS COURT	3 Ramps		
8-67-2	Yes	Curbing	Brick
8-67-3	Yes	Curbing	Brick
8-72-1	Yes	Curbing	Brick
At SUMMER STREET	1 Ramps		
8-54-4	Yes	Sign	Concrete
At WARREN STREET	1 Ramps		
8-122-1	Yes	Curbing	Asphalt
At WOODLAND STREET	2 Ramps		
5-2-3	Yes	Curbing	Concrete
5-2-4	Yes	Curbing	Asphalt
MIDDLE STREET	1 Ramps Total		
At PARKING LOT	1 Ramps		
9-33-2	Yes	Curbing	Asphalt
MOSELEY AVENUE	1 Ramps Total		
At MOULTON STREET	1 Ramps		
4-39-2	Yes	Curbing	Asphalt
NORTH ATKINSON STREET	1 Ramps Total		
At TRACY STREET	1 Ramps		
8-147-1	Yes	Catch Basin	Asphalt
PLEASANT STREET	2 Ramps Total		
At TITCOMB STREET	2 Ramps		
8-36-1	Yes	Curbing	Concrete
8-36-2	Yes	Curbing	Brick
PRINCE PLACE	1 Ramps Total		

	Obstruction	Obstruction Type	Material
At HALE'S COURT	1 Ramps		
8-16-1	Yes	Curbing	Asphalt
PURCHASE STREET	3 Ramps Total		
At LUNT STREET	2 Ramps		
15-55-1	Yes	Curbing	Brick
15-55-2	Yes	Curbing	Concrete
At SALEM STREET	1 Ramps		
15-67-2	Yes	Curbing	Concrete
SIMMONS DRIVE	2 Ramps Total		
At GOLDEN DRIVE	2 Ramps		
8-111-1	Yes	Curbing	Concrete
8-111-2	Yes	Curbing	Concrete
STATE STREET	6 Ramps Total		
At BOYLSTON STREET	2 Ramps		
14-15-1	Yes	Curbing	Brick
14-15-2	Yes	Curbing	Brick
At GREENLEAF STREET	1 Ramps		
14-19-1	Yes	Curbing	Brick
At PLEASANT STREET	2 Ramps		
9-23-4	Yes	Curbing	Brick
9-23-5	Yes	Curbing	Brick
At TEMPLE STREET	1 Ramps		
9-13-1	Yes	Curbing	Brick
TOPPAN'S LANE	1 Ramps Total		
At SUMMIT PLACE	1 Ramps		
8-27-1	Yes	Gate	Concrete
TURKEY HILL ROAD	6 Ramps Total		
At BARTLETT DRIVE	2 Ramps		
12-29-3	Yes	Curbing	Concrete
12-29-4	Yes	Curbing	Concrete
At BOURBEAU TERRACE	4 Ramps		
6-2-1	Yes	Curbing	Concrete
6-2-2	Yes	Curbing	Concrete
6-5-1	Yes	Curbing	Concrete
6-5-2	Yes	Curbing	Concrete
TYNG STREET	1 Ramps Total		
At MUNROE STREET	1 Ramps		
8-124-4	Yes	Catch Basin	Concrete
WARREN STREET	2 Ramps Total		
At MUNROE STREET	1 Ramps		
8-93-5	Yes	Catch Basin	Concrete
At OCEAN STREET	1 Ramps		
8-80-1	Yes	Curbing	Concrete

BETA Group, Inc.

		Obstruction	Obstruction Type	Material
WASHINGTON STREET		2 Ramps Total		
At OLIVE STREET	1 Ramps			
8-45-1		Yes	Curbing	Concrete
At STRONG STREET	1 Ramps			
8-35-1		Yes	Curbing	Concrete
WATER STREET		4 Ramps Total		
At 0	1 Ramps			
9-A-1		Yes	Utility Access	Concrete
At FERRY WHARF	1 Ramps			
9-42-1		Yes	Curbing	Brick
At INDEPENDENT STREET	1 Ramps			
9-37-3		Yes	Curbing	Asphalt
At PARKING LOT	1 Ramps			
9-44-2		Yes	Curbing	Brick

City of Newburyport, Massachusetts

Ramp Inventory Tracking Form

Total: 798

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
ALLEN STREET		Total Ramps: 3								
15-23-1	At HIGH STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-23-2	At HIGH STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-44-1	At PROSPECT STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
ASHLAND STREET		Total Ramps: 3								
5-17-1	At COOLIDGE STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
5-19-1	At STANLEY STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
5-19-2	At STANLEY STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
AUBURN STREET		Total Ramps: 4								
14-28-1	At POND STREET	Poor	Concrete	No	No	0	0	Yes No	Yes No	
14-28-2	At POND STREET	Poor	Concrete	No	No	0	0	Yes No	Yes No	
8-9-1	At HIGH STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
8-9-2	At HIGH STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
AZALEA ROAD		Total Ramps: 2								
4-61-1	At FENDERS AVENUE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
4-61-2	At FENDERS AVENUE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
BARTLETT DRIVE		Total Ramps: 2								
6-1-1	At WANDOVER WAY	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
6-1-2	At WANDOVER WAY	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
BARTON STREET		Total Ramps: 5								
15-14-1	At HIGH STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-14-2	At HIGH STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-18-1	At ALTER COURT	Poor	Concrete	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
15-18-2	At ALTER COURT	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
15-21-1	At BARTON COURT	Poor	Concrete	No	No	0	0	Yes No	Yes No	
BEACON AVENUE Total Ramps: 2										
15-11-1	At OAK STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
15-11-2	At OAK STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
BECK STREET Total Ramps: 2										
15-89-1	At SMITH'S STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-89-2	At SMITH'S STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
BRICHER PLACE Total Ramps: 2										
14-13-1	At QUILL STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
14-13-2	At QUILL STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
BROMFIELD STREET Total Ramps: 13										
15-19-1	At HIGH STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-19-2	At HIGH STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
15-32-1	At BROMFIELD COURT	Poor	Concrete	No	No	0	0	Yes No	Yes No	
15-32-2	At BROMFIELD COURT	Poor	Concrete	No	No	0	0	Yes No	Yes No	
15-50-1	At HANCOCK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-50-2	At HANCOCK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-52-1	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-52-2	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-52-3	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-52-4	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-86-1	At WATER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-86-2	At WATER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-86-3	At WATER STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
CARTER STREET Total Ramps: 13										
8-106-1	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-106-2	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-106-3	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-106-4	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-106-5	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-106-6	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-106-7	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-106-8	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-110-1	At CUTTERS COURT	Poor	Concrete	No	No	0	0	Yes No	Yes No	
8-118-1	At GRIFFINS COURT	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-128-1	At MERRIMAC STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-128-2	At MERRIMAC STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-79-1	At EAGLE STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
CHAPEL STREET Total Ramps: 3										
8-155-1	At MAGNOLIA STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-162-1	At PAYSON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-162-2	At PAYSON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
CLIPPER WAY Total Ramps: 1										
4-2-1	At CLARK STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
COFFIN'S COURT Total Ramps: 2										
15-26-1	At HIGH STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
15-26-2	At HIGH STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
COLTIN DRIVE Total Ramps: 1										
8-12-1	At COLTIN DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
COLUMBUS AVENUE		Total Ramps: 3								
8-137-1	At FARRELL STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
8-138-1	At TRACY PLACE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-138-2	At TRACY PLACE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
CONGRESS STREET		Total Ramps: 4								
8-65-1	At MERRILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-65-2	At MERRILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-65-3	At MERRILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-65-4	At MERRILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
COOLIDGE STREET		Total Ramps: 1								
5-23-1	At DAWES STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
CROW LANE		Total Ramps: 1								
13-9-1	At KINGHTS LANE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
CUSHING AVENUE		Total Ramps: 1								
4-54-1	At HARDY STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
DANIEL LUCY WAY		Total Ramps: 5								
3-1-1	At CURZON'S MILL ROAD	Good	Concrete	No	No	0	0	Yes No	Yes No	
4-4-1	At WILLIAM HALL DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
4-4-2	At WILLIAM HALL DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
4-7-1	At ARTHUR WELCH DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
4-7-2	At ARTHUR WELCH DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
DENNETT DRIVE		Total Ramps: 2								
6-15-1	At FINNEGAN WAY	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
6-18-1	At STOREY AVENUE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
DOROTHY LUCY DRIVE		Total Ramps: 4								
4-59-1	At GOVE DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
4-59-2	At GOVE DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
4-81-1	At DONER DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
4-81-2	At DONER DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
FAIR STREET Total Ramps: 24										
15-80-1	At PROSPECT STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-87-1	At TEMPLE STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
15-87-2	At TEMPLE STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
15-87-3	At TEMPLE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-87-4	At TEMPLE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-87-5	At TEMPLE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-87-6	At TEMPLE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-11-1	At SPRING STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
9-11-2	At SPRING STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-20-1	At MIDDLE STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
9-20-2	At MIDDLE STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
9-20-3	At MIDDLE STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
9-20-4	At MIDDLE STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
9-20-5	At MIDDLE STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
9-26-1	At LIBERTY STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
9-26-2	At LIBERTY STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
9-26-3	At LIBERTY STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
9-26-4	At LIBERTY STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
9-39-1	At WATER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
9-39-2	At WATER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
9-4-1	At ORANGE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-4-2	At ORANGE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
9-7-1	At CHARTER STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-7-2	At CHARTER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	

FEDERAL STREET Total Ramps: 18

15-66-1	At PROSPECT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-66-2	At PROSPECT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-66-3	At PROSPECT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-66-4	At PROSPECT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-66-5	At PROSPECT STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
15-66-6	At PROSPECT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-75-1	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-75-2	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-75-3	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-77-1	At ORANGE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-77-2	At ORANGE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-82-1	At ATWOOD STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-90-1	At SCHOOL STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-15-1	At LIBERTY STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
9-8-1	At MIDDLE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-9-1	At BECK STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-9-2	At BECK STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-9-3	At BECK STREET	Good	Brick	No	No	0	0	Yes No	Yes No	

FERRY ROAD Total Ramps: 16

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
4-25-1	At HARNCHS WAY	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-25-2	At HARNCHS WAY	Fair	Concrete	No	No	0	0	Yes No	Yes No	
4-26-1	At CHAISSON ROAD	Fair	Concrete	No	No	0	0	Yes No	Yes No	
4-26-2	At CHAISSON ROAD	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-30-1	At LAWTON DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-31-1	At HARDY STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
4-49-1	At BOYD DRIVE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
4-49-2	At BOYD DRIVE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
4-68-1	At BRIGGS AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
4-68-2	At BRIGGS AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
4-70-1	At AZALEA ROAD	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
4-70-2	At AZALEA ROAD	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
4-72-1	At LAUREL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
4-72-2	At LAUREL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
4-72-3	At LAUREL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
4-72-4	At LAUREL STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
FORRESTER STREET		Total Ramps: 4								
5-12-1	At STANLEY STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
5-12-2	At STANLEY STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
5-26-1	At MERRIMAC STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-26-2	At MERRIMAC STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
FRANCES DRIVE		Total Ramps: 2								
12-5-1	At LAVALEE LANE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
12-5-2	At LAVALEE LANE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
FRUIT STREET		Total Ramps: 3								
15-79-1	At PROSPECT STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
15-79-2	At PROSPECT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-79-3	At PROSPECT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
GOLDEN DRIVE		Total Ramps: 6								
8-D-1	At 0	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-E-1	At 0	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-F-1	At 0	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-F-2	At 0	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-G-1	At 0	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-G-2	At 0	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
GOLDSMITHS DRIVE		Total Ramps: 2								
13-6-1	At BERRY DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
13-6-2	At BERRY DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
GREENLEAF STREET		Total Ramps: 3								
14-22-1	At FULTON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
14-23-1	At DALTON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
14-23-2	At DALTON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
HALE STREET		Total Ramps: 2								
12-3-1	At LAVALEE LANE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
12-3-2	At LAVALEE LANE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
HANCOCK STREET		Total Ramps: 3								
15-33-1	At MADISON STREET	Poor	Concrete	No	No	0	0	Yes No	Yes No	
15-42-1	At LUNT STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-42-2	At LUNT STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
HARNCHS WAY		Total Ramps: 2								
4-21-1	At STOREY AVENUE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
4-21-2	At STOREY AVENUE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
HIGH STREET		Total Ramps: 129								
14-34-1	At STATE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
14-34-2	At STATE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
14-34-3	At STATE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
14-34-4	At STATE STREET	Good	Brick	Yes	No	0	0	Yes No	Yes No	
14-34-5	At STATE STREET	Good	Brick	Yes	No	0	0	Yes No	Yes No	
14-34-6	At STATE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
14-34-7	At STATE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
14-34-8	At STATE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
14-41-1	At EPPA WAY	Good	Brick	No	No	0	0	Yes No	Yes No	
14-41-2	At EPPA WAY	Good	Brick	No	No	0	0	Yes No	Yes No	
14-42-1	At PARK STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
14-42-2	At PARK STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
14-42-3	At PARK STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
14-45-1	At GREEN STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
14-45-2	At GREEN STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
14-45-3	At GREEN STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
14-45-4	At GREEN STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-10-1	At MARLBORO STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-10-2	At MARLBORO STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-12-1	At ROBERTS LANE	Good	Concrete	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
15-12-2	At ROBERTS LANE	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-46-1	At FEDERAL STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-46-2	At FEDERAL STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-46-3	At FEDERAL STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-46-4	At FEDERAL STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-56-1	At TREMONT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-56-2	At TREMONT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-62-1	At FRUIT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-62-2	At FRUIT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-A-1	At 0	Good	Brick	No	No	0	0	Yes No	Yes No	
15-A-2	At 0	Good	Brick	No	No	0	0	Yes No	Yes No	
4-17-1	At UPLAND ROAD	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
4-17-2	At UPLAND ROAD	Poor	Concrete	No	No	0	0	Yes No	Yes No	
4-18-1	At CUTTING DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
4-18-2	At CUTTING DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-19-1	At PLUMMER AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
4-19-2	At PLUMMER AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
4-19-3	At PLUMMER AVENUE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
4-19-4	At PLUMMER AVENUE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
5-18-1	At JEFFERSON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-18-2	At JEFFERSON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-18-3	At JEFFERSON STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
5-18-4	At JEFFERSON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
5-21-1	At MYRTLE AVENUE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-21-2	At MYRTLE AVENUE	Poor	Concrete	No	No	0	0	Yes No	Yes No	
5-21-3	At MYRTLE AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-4-1	At NORTH ATKINSON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-4-2	At NORTH ATKINSON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-7-1	At ASHLAND STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-7-2	At ASHLAND STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-7-3	At ASHLAND STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-7-4	At ASHLAND STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-9-1	At BROOKS COURT	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-9-2	At BROOKS COURT	Fair	Concrete	No	No	0	0	Yes No	Yes No	
5-A-1	At 0	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-A-2	At 0	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-A-3	At 0	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-A-4	At 0	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-10-1	At MARKET STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-10-2	At MARKET STREET	Poor	Brick	No	No	0	0	Yes No	Yes No	
8-10-3	At MARKET STREET	Poor	Brick	No	No	0	0	Yes No	Yes No	
8-10-4	At MARKET STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-114-1	At OAKLAND STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
8-114-2	At OAKLAND STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
8-114-3	At OAKLAND STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-114-4	At OAKLAND STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-121-1	At ARLINGTON STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-121-2	At ARLINGTON STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-129-1	At LAFAYETTE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-129-2	At LAFAYETTE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-135-1	At RAWSON AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-135-2	At RAWSON AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-148-1	At CHAPEL STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-148-2	At CHAPEL STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-148-3	At CHAPEL STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-148-4	At CHAPEL STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-153-1	At COLUMBUS AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-153-2	At COLUMBUS AVENUE	Good	Brick	No	No	0	0	Yes No	Yes No	
8-154-1	At WILLOW AVENUE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
8-154-2	At WILLOW AVENUE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-154-3	At WILLOW AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-154-4	At WILLOW AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-159-1	At FORRESTER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-159-2	At FORRESTER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-17-1	At SUMMER STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-17-2	At SUMMER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-17-3	At SUMMER STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-17-4	At SUMMER STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-18-1	At WINTER STREET	Good	Brick	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-18-2	At WINTER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-18-3	At WINTER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-18-4	At WINTER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-19-1	At CAREY AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-19-2	At CAREY AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-26-1	At BOARDMAN STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-26-2	At BOARDMAN STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-26-3	At BOARDMAN STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-31-1	At OLIVE STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-31-2	At OLIVE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
8-31-3	At OLIVE STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-31-4	At OLIVE STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-38-1	At BUCK STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-38-2	At BUCK STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-40-1	At JOHNSON STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-40-2	At JOHNSON STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-40-3	At JOHNSON STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-40-4	At JOHNSON STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-48-1	At KENT STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-48-2	At KENT STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-48-3	At KENT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-48-4	At KENT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-5-1	At COURT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-5-2	At COURT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-60-1	At SUMMIT PLACE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-60-2	At SUMMIT PLACE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-73-1	At CARTER STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-73-2	At CARTER STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-81-1	At BROAD STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-81-2	At BROAD STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-81-3	At BROAD STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-81-4	At BROAD STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-87-1	At TOPPAN'S LANE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-87-2	At TOPPAN'S LANE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-87-3	At TOPPAN'S LANE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-87-4	At TOPPAN'S LANE	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-98-1	At TYNG STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
8-98-2	At TYNG STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
8-A-1	At 0	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-A-2	At 0	Good	Brick	No	No	0	0	Yes No	Yes No	

HIGHLAND AVENUE Total Ramps: 4

8-109-1	At RAWSON AVENUE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-90-1	At ARLINGTON STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-99-1	At LAFAYETTE STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
8-99-2	At LAFAYETTE STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	

HILL STREET Total Ramps: 8

14-10-1	At BOYLSTON STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
---------	--------------------	------	----------	----	----	---	---	--------	--------	--

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
14-10-2	At BOYLSTON STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
14-14-1	At BRICHER PLACE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
14-14-2	At BRICHER PLACE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
14-21-1	At DALTON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
14-21-2	At DALTON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
14-8-1	At ROUTE 1	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-8-2	At ROUTE 1	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
HOYTS LANE Total Ramps: 1										
6-24-1	At DREW STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
HUNTER DRIVE Total Ramps: 1										
8-82-1	At LOIS STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
JACKSON STREET Total Ramps: 4										
8-142-1	At COLLINS STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-142-2	At COLLINS STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-145-1	At CARLTON DRIVE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-145-2	At CARLTON DRIVE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
JEFFERSON STREET Total Ramps: 4										
5-31-1	At ADAMS STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
5-31-2	At ADAMS STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
5-33-1	At CHRISTOPHER STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
5-33-2	At CHRISTOPHER STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
KENT STREET Total Ramps: 5										
8-74-1	At MUNROE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-74-2	At MUNROE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-74-3	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-91-1	At CURRIERS COURT	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-91-2	At CURRIERS COURT	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
KNIGHTS LANE Total Ramps: 2										
7-1-1	At BARTLETT DRIVE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
7-1-2	At BARTLETT DRIVE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
LAVALEE LANE Total Ramps: 2										
12-9-1	At BRADBURY LANE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
12-9-2	At BRADBURY LANE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
LIBERTY STREET Total Ramps: 2										
9-22-1	At INDEPENDENT STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
9-31-1	At PIKE STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
LIME STREET Total Ramps: 19										
15-34-1	At HIGH STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-34-2	At HIGH STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-34-3	At HIGH STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-34-4	At HIGH STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-57-1	At PROSPECT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-57-2	At PROSPECT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-57-3	At PROSPECT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-57-4	At PROSPECT STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-57-5	At PROSPECT STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-64-1	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-64-2	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-64-3	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-64-4	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
15-64-5	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-64-6	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-64-7	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-64-8	At MILK STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-74-1	At PURCHASE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-74-2	At PURCHASE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	

LONGFELLOW DRIVE Total Ramps: 1

12-20-1	At TURKEY HILL ROAD	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
---------	---------------------	------	---------	----	----	---	---	--------	--------	--

LOW STREET Total Ramps: 32

14-40-1	At JOHNSON STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
14-40-2	At JOHNSON STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
14-A-1	At 0	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-A-2	At 0	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-B-1	At 0	Fair	Concrete	Yes	No	0	0	Yes No	Yes No	
14-B-2	At 0	Fair	Concrete	Yes	No	0	0	Yes No	Yes No	
7-13-1	At NORTH ATKINSON STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
7-13-2	At NORTH ATKINSON STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
7-17-1	At MURPHY AVENUE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
7-17-2	At MURPHY AVENUE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
7-18-1	At AVON STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
7-18-2	At AVON STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
7-19-1	At BRISSETTE AVENUE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
7-19-2	At BRISSETTE AVENUE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
7-21-1	At STICKNEY AVENUE	Good	Asphalt	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
7-21-2	At STICKNEY AVENUE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
7-22-1	At WILLIAMSON AVENUE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
7-22-2	At WILLIAMSON AVENUE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-15-1	At ZABRISKIE DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-15-2	At ZABRISKIE DRIVE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
8-37-1	At COLTIN DRIVE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-37-2	At COLTIN DRIVE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-39-1	At WILLIAM BASHAW JR WAY	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-39-2	At WILLIAM BASHAW JR WAY	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-61-1	At HUNTER DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-61-2	At HUNTER DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-68-1	At COURTS FARM LANE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
8-68-2	At COURTS FARM LANE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
8-8-1	At TOPPAN'S LANE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-8-2	At TOPPAN'S LANE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-8-3	At TOPPAN'S LANE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-8-4	At TOPPAN'S LANE	Fair	Concrete	No	No	0	0	Yes No	Yes No	

MARLBORO STREET Total Ramps: 5

15-16-1	At REILLY AVENUE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
15-16-2	At REILLY AVENUE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
15-31-1	At PINE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-49-1	At WATER STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
15-49-2	At WATER STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	

MERRIMAC STREET Total Ramps: 114

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
2-1-1	At CLARK STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
2-1-2	At CLARK STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
2-2-1	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-2-10	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-2-2	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-2-3	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-2-4	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-2-5	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-2-6	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-2-7	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-2-8	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-2-9	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
4-62-1	At MOULTON STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-62-2	At MOULTON STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-75-1	At CHRISTIE STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-82-1	At BAYNE LANE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
4-82-2	At BAYNE LANE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-83-1	At DONER DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
4-83-2	At DONER DRIVE	Good	Brick	No	No	0	0	Yes No	Yes No	
4-D-1	At 0	Good	Asphalt	No	No	0	0	Yes No	Yes No	
5-10-1	At SAVORY STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-10-2	At SAVORY STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-14-1	At BUTLER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
5-14-2	At BUTLER STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
5-14-3	At BUTLER STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-14-4	At BUTLER STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
5-16-1	At MERRIMAC COURT	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-20-1	At UNION PLACE	Poor	Concrete	No	No	0	0	Yes No	Yes No	
5-20-2	At UNION PLACE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
5-2-1	At WOODLAND STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-2-2	At WOODLAND STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-2-3	At WOODLAND STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
5-2-4	At WOODLAND STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-30-1	At ASHLAND STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-30-2	At ASHLAND STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-30-3	At ASHLAND STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
5-37-1	At JEFFERSON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
5-37-2	At JEFFERSON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
5-37-3	At JEFFERSON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
5-38-1	At JEFFERSON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
5-38-2	At JEFFERSON STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
5-41-1	At PLUMMER AVENUE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
5-41-2	At PLUMMER AVENUE	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-41-3	At PLUMMER AVENUE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
5-B-1	At 0	Good	Concrete	No	No	0	0	Yes No	Yes No	
5-C-1	At 0	Fair	Concrete	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-104-1	At POP CROWLEY WAY	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-104-2	At POP CROWLEY WAY	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-112-1	At KENT STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-117-1	At DOVE STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-117-2	At DOVE STREET	Poor	Concrete	No	No	0	0	Yes No	Yes No	
8-122-1	At WARREN STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-122-2	At WARREN STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-122-3	At WARREN STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-132-1	At BROAD STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-132-2	At BROAD STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-132-3	At BROAD STREET	Poor	Concrete	No	No	0	0	Yes No	Yes No	
8-139-1	At TYNG STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-139-2	At TYNG STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-139-3	At TYNG STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-139-4	At TYNG STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-143-1	At MANSON AVENUE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-143-2	At MANSON AVENUE	Poor	Concrete	No	No	0	0	Yes No	Yes No	
8-146-1	At OAKLAND STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-146-2	At OAKLAND STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-146-3	At OAKLAND STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
8-158-1	At CALIFORNIA STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-158-2	At CALIFORNIA STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-44-1	At GREEN STREET	Good	Brick	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-44-2	At GREEN STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-44-3	At GREEN STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-44-4	At GREEN STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-44-5	At GREEN STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-47-1	At TITCOMB STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
8-47-2	At TITCOMB STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-47-3	At TITCOMB STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-47-4	At TITCOMB STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-49-1	At BROWNS WHARF	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-49-2	At BROWNS WHARF	Good	Brick	No	No	0	0	Yes No	Yes No	
8-50-1	At MARKET STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-50-2	At MARKET STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
8-54-1	At SUMMER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-54-2	At SUMMER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-54-3	At SUMMER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-54-4	At SUMMER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-54-5	At SUMMER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-58-1	At WINTER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-58-2	At WINTER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-58-3	At WINTER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-58-4	At WINTER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-62-1	At STRONG STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-62-2	At STRONG STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-67-1	At MECHANICS COURT	Good	Brick	No	No	0	0	Yes No	Yes No	
8-67-2	At MECHANICS COURT	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-67-3	At MECHANICS COURT	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-72-1	At MECHANICS COURT	Fair	Brick	No	No	0	0	Yes No	Yes No	
8-76-1	At BOARDMAN STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-76-2	At BOARDMAN STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-77-1	At POP CROWLEY WAY	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-77-2	At POP CROWLEY WAY	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-83-1	At OLIVE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-83-2	At OLIVE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-89-1	At ELM STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-89-2	At ELM STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-92-1	At WHITES COURT	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-92-2	At WHITES COURT	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-97-1	At MERRILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-97-2	At MERRILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-B-1	At 0	Good	Brick	No	No	0	0	Yes No	Yes No	
9-B-2	At 0	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-C-1	At 0	Good	Brick	No	No	0	0	Yes No	Yes No	
9-C-2	At 0	Good	Brick	No	No	0	0	Yes No	Yes No	
9-C-3	At 0	Good	Brick	No	No	0	0	Yes No	Yes No	
9-C-4	At 0	Good	Brick	No	No	0	0	Yes No	Yes No	
MIDDLE STREET Total Ramps: 3										
9-28-1	At CENTER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
9-33-1	At PARKING LOT	Good	Asphalt	No	No	0	0	Yes No	Yes No	
9-33-2	At PARKING LOT	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
MILK STREET Total Ramps: 1										
15-58-1	At FRANKLIN STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
MOSELEY AVENUE Total Ramps: 11										
4-29-1	At CHASE STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
4-29-2	At CHASE STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-39-1	At MOULTON STREET	Good	Brick	Yes	No	0	0	Yes No	Yes No	
4-39-2	At MOULTON STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
4-44-1	At HARDY STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-45-1	At HARDY STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
4-45-2	At HARDY STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
4-52-1	At NEW STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-52-2	At NEW STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-56-1	At DOROTHY LUCY DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
4-56-2	At DOROTHY LUCY DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
MOULTON STREET Total Ramps: 1										
4-48-1	At GARNET STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
MUNROE STREET Total Ramps: 2										
8-85-1	At DOVE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-85-2	At DOVE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
MURPHY AVENUE Total Ramps: 4										
7-20-1	At NORMAN AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
7-20-2	At NORMAN AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
7-20-3	At NORMAN AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
7-20-4	At NORMAN AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
NOBLE STREET Total Ramps: 2										
4-32-1	At COOMBS CIRCLE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
4-32-2	At COOMBS CIRCLE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
NORTH ATKINSON STREE Total Ramps: 6										
7-15-1	At SIMMONS DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-136-1	At CHARRON DRIVE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
8-136-2	At CHARRON DRIVE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
8-147-1	At TRACY STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-C-1	At 0	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-C-2	At 0	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
NORTHERN BOULEVARD Total Ramps: 24										
11-14-1	At 56TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-14-2	At 56TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-18-1	At 58TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-18-2	At 58TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-23-1	At 60TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-23-2	At 60TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-28-1	At 62ND STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-28-2	At 62ND STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-31-1	At 64TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-31-2	At 64TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-35-1	At 66TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-35-2	At 66TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
11-39-1	At 68TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-39-2	At 68TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-42-1	At 70TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-42-2	At 70TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-47-1	At 72ND STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-47-2	At 72ND STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-53-1	At 74TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-53-2	At 74TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-55-1	At 76TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-55-2	At 76TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-65-1	At 78TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
11-65-2	At 78TH STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
OAKLAND STREET Total Ramps: 2										
8-133-1	At JACKSON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-133-2	At JACKSON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
OLIVE STREET Total Ramps: 4										
8-53-1	At CONGRESS STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-53-2	At CONGRESS STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-59-1	At RUSSIA STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-59-2	At RUSSIA STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
PARSONS STREET Total Ramps: 2										
15-25-1	At HIGH STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-25-2	At HIGH STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
PHEASANT RUN DRIVE Total Ramps: 1										
7-2-1	At QUAIL RUN HOLLOW	Fair	Asphalt	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
PHILLIPS DRIVE		Total Ramps: 5								
6-22-1	At SULLIVAN DRIVE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
6-23-1	At SULLIVAN DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
6-25-1	At DREW STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
6-26-1	At DREW STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
6-26-2	At DREW STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
PLEASANT STREET		Total Ramps: 13								
8-36-1	At TITCOMB STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-36-2	At TITCOMB STREET	Good	Brick	Yes	No	0	0	Yes No	Yes No	
8-42-1	At MARKET STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-42-2	At MARKET STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-42-3	At MARKET STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-42-4	At MARKET STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-42-5	At MARKET STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-42-6	At MARKET STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-42-7	At MARKET STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-25-1	At TRACY PLACE	Good	Brick	No	No	0	0	Yes No	Yes No	
9-25-2	At TRACY PLACE	Good	Brick	No	No	0	0	Yes No	Yes No	
9-32-1	At HALE'S COURT	Good	Brick	No	No	0	0	Yes No	Yes No	
9-32-2	At HALE'S COURT	Good	Brick	No	No	0	0	Yes No	Yes No	
PLUMMER AVENUE		Total Ramps: 2								
5-36-1	At CHRISTOPHER STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
5-36-2	At CHRISTOPHER STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
POND STREET		Total Ramps: 14								
14-26-1	At HILLSIDE AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
14-26-2	At HILLSIDE AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-27-1	At COTTAGE COURT	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-27-2	At COTTAGE COURT	Good	Concrete	No	No	0	0	Yes No	Yes No	
14-31-1	At HILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-31-2	At HILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-32-1	At GREENLEAF STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-32-2	At GREENLEAF STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-32-3	At GREENLEAF STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-32-4	At GREENLEAF STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-32-5	At GREENLEAF STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
14-36-1	At EPPA WAY	Good	Asphalt	No	No	0	0	Yes No	Yes No	
14-37-1	At HIGH STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
14-37-2	At HIGH STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
PRINCE PLACE Total Ramps: 1										
8-16-1	At HALE'S COURT	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
PROSPECT STREET Total Ramps: 5										
15-51-1	At PARSONS STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-51-2	At PARSONS STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-51-3	At PARSONS STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-85-1	At ORANGE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
15-85-2	At ORANGE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
PURCHASE STREET Total Ramps: 13										
15-47-1	At NEPTUNE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-53-1	At HARRISON STREET	Good	Brick	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
15-53-2	At HARRISON STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
15-55-1	At LUNT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
15-55-2	At LUNT STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
15-65-1	At FRANKLIN STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-65-2	At FRANKLIN STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-65-3	At FRANKLIN STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-65-4	At FRANKLIN STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-67-1	At SALEM STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-67-2	At SALEM STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-69-1	At CHARLES STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-69-2	At CHARLES STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
QUAIL RUN HOLLOW Total Ramps: 4										
13-11-1	At FOX RUN ROAD	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
13-7-1	At DOE RUN DRIVE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
7-3-1	At WILDWOOD DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
7-3-2	At WILDWOOD DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
RAWSON AVENUE Total Ramps: 1										
8-116-1	At FARRELL STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
RUSSIA STREET Total Ramps: 4										
8-70-1	At MERRILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-70-2	At MERRILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-70-3	At MERRILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-70-4	At MERRILL STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
SAVORY STREET Total Ramps: 2										
5-15-1	At RIVER STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
5-15-2	At RIVER STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
SIMMONS DRIVE Total Ramps: 4										
8-111-1	At GOLDEN DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-111-2	At GOLDEN DRIVE	Fair	Concrete	Yes	No	0	0	Yes No	Yes No	
8-120-1	At GOLDEN DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-120-2	At GOLDEN DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
SOUTH POND STREET Total Ramps: 1										
15-6-1	At BEACON AVENUE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
SPOFFORD STREET Total Ramps: 12										
2-3-1	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-3-10	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-3-2	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-3-3	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-3-4	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-3-5	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-3-6	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-3-7	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-3-8	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-3-9	At MOSELEY AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
2-4-1	At CLARK STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
2-4-2	At CLARK STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
SQUIRES GLEN Total Ramps: 2										
14-38-1	At HALE STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
14-38-2	At HALE STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
STATE STREET Total Ramps: 38										

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
14-15-1	At BOYLSTON STREET	Poor	Brick	No	No	0	0	Yes No	Yes No	
14-15-2	At BOYLSTON STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
14-19-1	At GREENLEAF STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
14-19-1	At BROWN STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
14-19-2	At GREENLEAF STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
14-19-2	At BROWN STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
14-24-1	At CENTRAL PLACE	Good	Concrete	No	No	0	0	Yes No	Yes No	
14-24-2	At CENTRAL PLACE	Good	Concrete	No	No	0	0	Yes No	Yes No	
14-3-1	At PARKER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
9-12-1	At PRINCE PLACE	Good	Brick	No	No	0	0	Yes No	Yes No	
9-12-2	At PRINCE PLACE	Good	Brick	No	No	0	0	Yes No	Yes No	
9-13-1	At TEMPLE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-13-2	At TEMPLE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-13-3	At TEMPLE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-13-4	At TEMPLE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-19-1	At CHARTER STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-19-2	At CHARTER STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-23-1	At PLEASANT STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-23-2	At PLEASANT STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-23-3	At PLEASANT STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-23-4	At PLEASANT STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-23-5	At PLEASANT STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-27-1	At ESSEX STREET	Good	Brick	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
9-27-2	At ESSEX STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-3-1	At HARRIS STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-3-2	At HARRIS STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-3-3	At HARRIS STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-35-1	At MIDDLE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-35-2	At MIDDLE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-35-3	At MIDDLE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-35-4	At MIDDLE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-38-1	At LIBERTY STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-38-2	At LIBERTY STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-38-3	At LIBERTY STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-38-4	At LIBERTY STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
9-6-1	At PROSPECT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-6-2	At PROSPECT STREET	Fair	Brick	Yes	No	0	0	Yes No	Yes No	
9-6-3	At PROSPECT STREET	Fair	Brick	Yes	No	0	0	Yes No	Yes No	
STOREY AVENUE Total Ramps: 4										
7-12-1	At DANIEL LUCY WAY	Good	Concrete	No	No	0	0	Yes No	Yes No	
7-12-2	At DANIEL LUCY WAY	Good	Concrete	No	No	0	0	Yes No	Yes No	
7-12-3	At DANIEL LUCY WAY	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
7-12-4	At DANIEL LUCY WAY	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
STOREY BROOK ROAD Total Ramps: 2										
7-10-1	At LT LEARY DRIVE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
7-11-1	At VIRGINIA LANE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
TILTON STREET Total Ramps: 2										

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-107-1	At RAWSON AVENUE	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
8-126-1	At MCCLINTOCK AVENUE	Good	Asphalt	No	No	0	0	Yes No	Yes No	
TOPPAN'S LANE Total Ramps: 6										
8-27-1	At SUMMIT PLACE	Poor	Concrete	No	No	0	0	Yes No	Yes No	
8-27-2	At SUMMIT PLACE	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-66-1	At HIGHLAND AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-66-2	At HIGHLAND AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-66-3	At HIGHLAND AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-66-4	At HIGHLAND AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
TURKEY HILL ROAD Total Ramps: 21										
12-15-1	At NEWHALL LANE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
12-15-2	At NEWHALL LANE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
12-2-1	At HALE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
12-2-2	At HALE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
12-28-1	At WINDWARD DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
12-28-2	At WINDWARD DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
12-29-1	At BARTLETT DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
12-29-2	At BARTLETT DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
12-29-3	At BARTLETT DRIVE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
12-29-4	At BARTLETT DRIVE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
12-4-1	At LONGFELLOW DRIVE	Good	Concrete	No	No	0	0	Yes No	Yes No	
12-4-2	At LONGFELLOW DRIVE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
12-8-1	At MARQUAND ROAD	Fair	Concrete	No	No	0	0	Yes No	Yes No	
12-8-2	At MARQUAND ROAD	Fair	Concrete	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
6-10-1	At EVERETTE DRIVE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
6-10-2	At EVERETTE DRIVE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
6-12-1	At HENDERSON CIRCLE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
6-2-1	At BOURBEAU TERRACE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
6-2-2	At BOURBEAU TERRACE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
6-5-1	At BOURBEAU TERRACE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
6-5-2	At BOURBEAU TERRACE	Fair	Concrete	No	No	0	0	Yes No	Yes No	
TYNG STREET Total Ramps: 8										
8-124-1	At MUNROE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-124-2	At MUNROE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-124-3	At MUNROE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-124-4	At MUNROE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-124-5	At MUNROE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
8-124-6	At MUNROE STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
8-124-7	At MUNROE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-124-8	At MUNROE STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
UNION STREET Total Ramps: 2										
15-17-1	At WATER STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
15-37-1	At WOODWELLS AVENUE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
UPLAND ROAD Total Ramps: 2										
5-32-1	At ADAMS STREET	Poor	Asphalt	No	No	0	0	Yes No	Yes No	
5-32-2	At ADAMS STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
VIRGINIA LANE Total Ramps: 1										
7-7-1	At MELVIN COURT	Good	Concrete	No	No	0	0	Yes No	Yes No	
WARREN STREET Total Ramps: 13										

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-100-1	At CUTTERS COURT	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-100-2	At CUTTERS COURT	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-108-1	At GRIFFINS COURT	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-108-2	At GRIFFINS COURT	Good	Brick	No	No	0	0	Yes No	Yes No	
8-80-1	At OCEAN STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-80-2	At OCEAN STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-88-1	At LAFAYETTE COURT	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-88-2	At LAFAYETTE COURT	Good	Asphalt	No	No	0	0	Yes No	Yes No	
8-93-1	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-93-2	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-93-3	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-93-4	At MUNROE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-93-5	At MUNROE STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
WASHINGTON STREET Total Ramps: 11										
8-20-1	At COURT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-20-2	At COURT STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-28-1	At SUMMER STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-28-2	At SUMMER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-28-3	At SUMMER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-32-1	At WINTER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-32-2	At WINTER STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-35-1	At STRONG STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
8-45-1	At OLIVE STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-B-1	At 0	Good	Concrete	Yes	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-B-2	At 0	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
WATER STREET Total Ramps: 33										
15-41-1	At WOODWELLS AVENUE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
15-41-2	At WOODWELLS AVENUE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
15-60-1	At MADISON STREET	Good	Brick	No	No	0	0	Yes No	Yes No	
15-60-2	At MADISON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-73-1	At HARRISON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-73-2	At HARRISON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-73-3	At HARRISON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
15-73-4	At HARRISON STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
9-1-1	At FRANKLIN STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-1-2	At FRANKLIN STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-18-1	At LIME STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-18-2	At LIME STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-18-3	At LIME STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-18-4	At LIME STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-18-5	At LIME STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-18-6	At LIME STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
9-24-1	At SHIP STREET	Fair	Concrete	No	No	0	0	Yes No	Yes No	
9-24-2	At SHIP STREET	Poor	Concrete	No	No	0	0	Yes No	Yes No	
9-30-1	At FEDERAL STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
9-30-2	At FEDERAL STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-37-1	At INDEPENDENT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-37-2	At INDEPENDENT STREET	Fair	Brick	No	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
9-37-3	At INDEPENDENT STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
9-41-1	At PIKE STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
9-41-2	At PIKE STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
9-42-1	At FERRY WHARF	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-42-2	At FERRY WHARF	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-43-1	At CENTER STREET	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
9-43-2	At CENTER STREET	Good	Asphalt	No	No	0	0	Yes No	Yes No	
9-44-1	At PARKING LOT	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-44-2	At PARKING LOT	Fair	Brick	No	No	0	0	Yes No	Yes No	
9-A-1	At 0	Good	Concrete	No	No	0	0	Yes No	Yes No	
9-A-2	At 0	Good	Concrete	No	No	0	0	Yes No	Yes No	
WHITES COURT Total Ramps: 2										
8-105-1	At POP CROWLEY WAY	Good	Brick	No	No	0	0	Yes No	Yes No	
8-105-2	At POP CROWLEY WAY	Good	Brick	No	No	0	0	Yes No	Yes No	
WILDWOOD DRIVE Total Ramps: 1										
7-4-1	At CHARMANSKI DRIVE	Fair	Asphalt	No	No	0	0	Yes No	Yes No	
WOODLAND STREET Total Ramps: 8										
8-134-1	At HIGH STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-134-2	At HIGH STREET	Good	Concrete	No	No	0	0	Yes No	Yes No	
8-140-1	At CARLTON DRIVE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-140-2	At CARLTON DRIVE	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-150-1	At DEXTER STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-150-2	At DEXTER STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
8-152-1	At JACKSON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	

Ramp ID	Intersecting Street	Ramp Condition	Ramp Material	Warning Panel	Warning Panel Damage	Ramp Compliance	Warning Panel Retro-Fit	Ramp Replaced	Ramp Retrofit	Date
8-152-2	At JACKSON STREET	Good	Concrete	Yes	No	0	0	Yes No	Yes No	
WOODMAN WAY Total Ramps: 1										
4-11-1	At CLIPPER WAY	Good	Asphalt	No	No	0	0	Yes No	Yes No	